

## **DILAPIDATION REPORT**

#### BLOCK 3 SECTION 488 NARRABUNDAH, ACT







# **DILAPIDATION REPORT**

### BLOCK 3 SECTION 488 NARRABUNDAH, ACT

Photo 2- Damage to SW sump



### Photo 3- Crack on the kerb and gutter



Photo 4 - Cracked verge crossing

