



ACT
Government

Transport Canberra and
City Services

FREEDOM OF INFORMATION COVERSHEET

The following information is provided pursuant to section 28 of the *Freedom of Information Act 2016*.

FOI reference: 22-046

Information to be published	Status
1. Access application	Published
2. Decision notice and schedule	Published
3. Documents	Published
4. Additional information identified	n/a
5. Fees	waived
6. Processing time (in working days)	44 days
7. Decision made by Ombudsman	n/a
8. Additional information identified by Ombudsman	n/a
9. Decision made by ACAT	n/a
10. Additional information identified by ACAT	n/a



Freedom of Information - Access Application to Transport Canberra and City Services - Submission confirmation

Your submission has been successful. Please keep a copy of this receipt for your records.

Date and time

Reference code

28 Mar 2022 4:11:57 PM

LH2MTPFP

Transport Canberra and City Services (TCCS)

GPO Box 158
Canberra ACT 2601

Phone 02 6207 2987

Email: TCCS.FOI@act.gov.au

Applicant details

Title

Given name

Family name

Mr

Preferred name

Preferred method of contact

Phone

Email

Post

Contact phone number

Contact email address

Contact postal address

Address line 1

Address line 2

Suburb

State

Postcode

Preferred method to receive information *

Email

Post

Same as contact email address

Information request

Who are you making the request on behalf of?

A third party

Attach evidence of authority to make this application *

[REDACTED].pdf

What type of information are you requesting access to? *

Other information

What information are you requesting access to under the Act? *

All document held by Transport Canberra and City Service relating to the paver located at Gunghalin Place (see attached image for precise location) limited to:

- Maintenance, cleaning, repair and similar records (including invoices, remittance advices and orders) from 1 January 2018 to 1 February 2022.
- Records of any complaints, notifications, internal correspondence and memorandum from 1 January 2018 to 1 February 2022.
- Any photos, videos or other audio, visual or audiovisual depictions of the pavers taken from 1 January 2018 to 1 February 2022.

Attach a description or additional details about the information you are requesting access to (optional)

[REDACTED].pdf

Do you have a similar or identical request currently under review by another ACT Government Directorate?

Yes No

Are you enquiring as

Other


Do you wish to apply for a waiver of fees associated with processing your application?

Yes No

Provide a statement about how the release of information is in the public interest (optional)

Would you like to provide any additional information? (optional)

Attach additional documents to support your application (optional)



BOTH AREAS



ACT
Government

Transport Canberra and
City Services

[REDACTED]

Dear [REDACTED]

Freedom of Information Request - Reference 22-046

I refer to your access application received by Transport Canberra and City Services (TCCS) on 29 March 2022 under the *Freedom of Information Act 2016* (FOI Act). It is my understanding that you are seeking access to the following government information:

“All documents held by Transport Canberra and City Services relating to the pavers located at Gungahlin Place (see attached image for precise location) limited to:

- Maintenance, cleaning, repair, and similar records (including invoices, remittance advices and orders) from 1 January 2018 to 1 February 2022.*
- Records of any complaints, notifications, internal correspondence, and memorandum from 1 January 2018 to 1 February 2022.*
- Any photos, videos or other audio, visual or audiovisual depictions of the pavers taken from 1 January 2018 to 1 February 2022.*

Authority

I am an Information Officer appointed by the Director-General under section 18 of the Act to deal with access applications made under Part 5 of the FOI Act.

Timeframes

A decision was due on your application by 29 April 2022. I thank you for agreeing to an extension until 3 June 2022.

Decision on access

In accordance with the FOI Act, a search was conducted of records held by TCCS and 15 records have been identified as relevant to your request.

In reviewing the information within this record, I have found on balance, it is in the public interest to provide you with:

- Partial access to 12 records; and
- Full access to 3 records.

A list of these records is enclosed at Attachment A and copy of these records with deletions applied to information which is contrary to the public interest is enclosed at Attachment B. My decision is further detailed in the below statement of reasons.

Statement of Reasons

In making my decision on disclosing government information, I must identify all relevant factors in schedule 2 of the FOI Act and determine, on balance, where the public interest lies. In reaching my access decision, I have taken the following into account:

Factors favouring disclosure in the public interest (Schedule 2, Section 2.1)

- Schedule 2.1(a)(i) - promote open discussion of public affairs and enhance the government's accountability;
- Schedule 2.1(a)(ii) - contribute to positive and informed debate on important issues or matters of public interest;
- Schedule 2.1(a)(iii) - inform the community of the government's operations, including the policies, guidelines and codes of conduct followed by the government in its dealings with members of the community;
- Schedule 2.1(a)(iv) - ensure effective oversight of expenditure of public funds; and
- Schedule 2.1(a)(viii) - reveal the reason for a government decision and any background or contextual information that informed the decision.

Factors favouring non-disclosure (Schedule 2, Section 2.2)

- Schedule 2.2(a)(ii) - prejudice the protection of an individual's right to privacy or any other right under the Human Rights Act 2004; and
- Schedule 2.2(a)(xi) - prejudice trade secrets, business affairs or research of an agency or person.

In reviewing the relevant record, personal information relating to third parties has been identified. I find that factor 2.2(a)(ii) is relevant to this information and I must consider if the disclosure is likely to prejudice the protection of an individual's right to privacy under the *Human Rights Act 2004*. In making this decision, I have considered that this information is not readily available to the public. I find that the protection of an individual's right to privacy under the *Human Rights Act 2004* carries significant weight. In this instance, I have found the disclosure of personal information to be, on balance, contrary to the public interest.

Further, information has been identified which relates financial methodology of costing service by third-party businesses; for example, hours, quantity, and unit pricing. I have found that the disclosure of this information is likely to prejudice the business affairs of relevant third-party businesses. I have decided, on balance, that the disclosure of this information is contrary to the public interest.

Deletions have also been applied to some information which is outside of the scope of your application.

As I have found that the factors favouring disclosure can be met in the remaining information, I have decided to provide you with partial access to the record at Attachment B.

Charges

Pursuant to *Freedom of Information (Fees) Determination 2018* a fee is applicable where the total number of pages to be disclosed exceeds 50. However, I have decided to waive any fees as some of the information provided to you is partially

duplicated elsewhere in the records. I note that the duplicate information provides context to the records and its removal would be impractical.

Online publishing – disclosure log

Under section 28 of the Act, TCCS maintains an online record of access applications called a disclosure log. Your original access application, my decision and documents will be published in the TCCS disclosure between 3 – 10 business days from the date of this decision.

Your personal contact details will not be published. You may view the TCCS' disclosure log at https://www.cityservices.act.gov.au/about-us/freedom_of_information/disclosure-log .

Ombudsman review

My decision on your access request is a reviewable decision as identified in Schedule 3 of the Act. You have the right to seek an Ombudsman review of this outcome under section 73 of the Act within 20 working days from the day that my decision is published in TCCS' disclosure log or a longer period allowed by the Ombudsman.

If you wish to request a review of my decision, you may write to the Ombudsman at:

The ACT Ombudsman
GPO Box 442
CANBERRA ACT 2601
Via email: actfoi@ombudsman.gov.au

ACT Civil and Administrative Tribunal (ACAT) review


Under section 84 of the Act, if a decision is made under section 82 on an Ombudsman review, you may apply to the ACAT for review of the Ombudsman decision.

Further information may be obtained from ACAT at:

ACT Civil and Administrative Tribunal
Level 4, 1 Moore Street
GPO Box 370
CANBERRA CITY ACT 2601
Telephone: (02) 6207 1740
www.acat.act.gov.au

If you have any queries concerning the directorate's processing of your request, or would like further information, please contact the TCCS FOI team on (02) 6207 2987 or email to tccs.foi@act.gov.au.

Yours sincerely



Meghan Oldfield
Information Officer

3 June 2022

FREEDOM OF INFORMATION REQUEST SCHEDULE

Please be aware that under the *Freedom of Information Act 2016*, some of the information provided to you will be released to the public through the ACT Government's Open Access Scheme. The Open Access release status column of the table below indicates what documents are intended for release online through open access.

Personal information or business affairs information will not be made available under this policy. If you think the content of your request would contain such information, please inform the contact officer immediately. Information about what is published on open access is available online at: https://www.tccs.act.gov.au/about-us/freedom_of_information/disclosure-log

Reasons for non-disclosure

- Schedule 2.2(a)(ii) - prejudice the protection of an individual's right to privacy or any other right under the Human Rights Act 2004.
- Schedule 2.2(a)(xi) - prejudice trade secrets, business affairs or research of an agency or person.
- Information is outside of the scope of the application.

Reference	Description of request
-----------	------------------------

FOI – 22-046	Maintenance of Gungahlin pavers
---------------------	--

Ref No	Page	Description	Date	Status	Reason for non-release or deferral	Open Access release status
1	1 - 9	CRM search results	Multiple	Partial access	Schedule 2.2(a)(ii)	Documents to be published on the TCCS Disclosure Log .
2	10 - 16	Salesforce search results	Multiple	Partial access	Schedule 2.2(a)(ii)	
3	17	IAMS defects search results	Multiple	Full access	Not applicable	
4	18 – 20	IAMS search results	Multiple	Partial access	Schedule 2.2(a)(ii)	
5	21 – 272	Work Orders	Multiple	Partial access	Schedule 2.2(a)(ii) Schedule 2.2(a)(xi)	
6	273 - 284	Work Requests	Multiple	Partial access	Schedule 2.2(a)(ii)	
7	285	00181675 - photo 1	Undated	Full access	Not applicable	

8	286 - 288	Re_Segmental paving 017 Weekly Report	11 March 2022	Partial access	Schedule 2.2(a)(ii)
9	289	Re_Segmental paving 017 Weekly Report - Attachment	11 March 2022	Partial access	Schedule 2.2(a)(ii)
10	290 - 291	Re_Invoice - TCCS Remediation Paving - Contract 2021-0017	30 March 2022	Partial access	Schedule 2.2(a)(xi)
11	292 - 293	Re_Invoice - TCCS Remediation Paving - Contract 2021-0017 - Attachment	30 March 2022	Partial access	Schedule 2.2(a)(ii)
12	294 - 295	FW_Aris Invoice #449	4 April 2022	Partial access	Schedule 2.2(a)(xi) Information out of scope
13	296	ACT NORTH RA2019-025 H0101 31MayRev2021	31 May 2021	Partial access	Schedule 2.2(a)(ii) Schedule 2.2(a)(xi)
14	297 - 300	RE_Variation	8 March 2022	Partial access	Schedule 2.2(a)(ii) Schedule 2.2(a)(xi)
15	301	Screenshot Assetic Work Request Map	Undated	Full access	Not applicable

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
181105-000096	5/11/2018	28/11/2018	<p>■■■■ wife ■■■■ sustained injury on Thursday 25th October at 5.20pm.</p> <p>■■■■ wife ■■■■ sustained injury on Thursday 25th October at 5.20pm. Approximately 3 metres from NAB approaching the crosswalk she tripped over raised pavement and fell forward hitting left shoulder on bollard and face on the pavement...</p>	<p>■■■■ wife ■■■■ sustained injury on Thursday 25th October at 5.20pm.</p> <p>Approximately 3 metres from NAB approaching the crosswalk she tripped over raised pavement and fell forward hitting left shoulder on bollard and face on the pavement.</p> <p>She has bruising, twisted back muscle and may have done significant damage to teeth.</p>	GUNGAHLIN	Gungahlin Place	<p>IAMS Generic Workspace: 1063070</p> <p>CGD Source: CRM_ACT_ROADS_INCIDENTS_V2</p>	Cycle & footpaths	
210310-000937	10/03/2021	14/04/2021	<p>FixMyStreet Submission: Cycle & footpaths; Shared paths; Damage to path or other;</p>	<p>Cycle & footpaths Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Unknown/other Could it cause a trip, fall or injury? * Yes Is it causing traffic or cyclists to swerve? * No Please provide more information The tiles designed for blind people to know that there is a crossing with their canes. Ate the crossing in Gunhalin next to The light rail stop going towards GuzmYGomez, the tiles are loose and causing a trip hazard.</p>	GUNGAHLIN	89 GUNGAHLIN PL, GUNGAHLIN ACT 2912	<p>Assetic Work Request: WR18227 Assetic Work Request Status: Resolved</p> <p>CGD Source: CRM_ACT_ROADS_INCIDENTS_V2</p>	Cycle & footpaths	Damage to path or other

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
190829-000731	29/08/2019	17/09/2019	FixMyStreet Submission: Cycle & footpaths > Shared paths > Damage to path or other	<p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?:</p> <p>The pavers in front of tenancies facing Gungahlin Place are extremely dirty and untidy, What is the issue?:</p> <p>Damage to path or other What is the damage?:</p> <p>Cracked, broken or uneven What is the material?:</p> <p>Brick or concrete pavers Could it cause a trip, fall or injury?:</p> <p>Yes</p> <p>Is it causing traffic or cyclists to swerve?:</p> <p>No</p> <p>Please provide more information:</p> <p>The shiny new bus shelter has not been maintained/cleaned since opening and the pavers are extremely dirty and require a pressure wash along Gungahlin Place. Also pavers require checking to ensure they are not a potential risk / trip hazard.</p>	GUNGAHLIN	Gungahlin Pl, Gungahlin ACT 2912, Australia	<p>IAMS Enquiry ID: 1077107, 1077821</p> <p>Original IAMS Enquiry ID: 1077107, 1077821</p> <p>Customer Requested Urgent: Yes</p>	Cycle & footpaths	Damage to path or other

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
191217-000956	17/12/2019	14/06/2020	FixMyStreet Submission: Cycle & footpaths > Shared paths > Damage to path or other	<p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Near the pedestrian walk way What is the issue?: Damage to path or other What is the damage?: Sunken or collapsed What is the material?: Brick or concrete pavers Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?: No Please provide more information: Phone Number: Verify Email Address: [REDACTED]@accesscanberra.act.gov.au.invalid</p>	GUNGAHLIN	WINYU HOUSE 125 GUNGAHLIN PL, GUNGAHLIN ACT 2912	IAMS Generic Workspace: Not Required CGD Source: CRM_ACT_ROADS_INCIDENTS_V2	Cycle & footpaths	Damage to path or other

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
200818-000245	18/08/2020	26/03/2021	FixMyStreet Submission: Cycle & footpaths > Shared paths > Damage to path or other	<p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: there are some uneven concrete pavers near way into lift towards BIGW car park behind SUBWAY store.</p> <p>What is the issue?: Damage to path or other</p> <p>What is the damage?: Cracked, broken or uneven</p> <p>What is the material?: Brick or concrete pavers</p> <p>Could it cause a trip, fall or injury?: Yes</p> <p>Is it causing traffic or cyclists to swerve?: Yes</p> <p>Please provide more information: there are some uneven concrete pavers near way into lift towards BIGW car park behind SUBWAY store.</p> <p>Phone Number: [REDACTED]</p> <p>Verify Email Address:</p>	GUNGAHLIN	GUNGAHLIN PL EAST	CGD Source: CRM_ACT_ROADS_INCIDENTS_V2	Cycle & footpaths	Damage to path or other

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
210405-000225	5/04/2021	22/04/2021	FixMyStreet Submission: Cycle & footpaths > On road cycle lanes > Damage to path or other	<p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Between Coles and Big W buildings</p> <p>What is the issue?: Damage to path or other</p> <p>What is the damage?: Cracked, broken or uneven</p> <p>What is the material?: Brick or concrete pavers</p> <p>Could it cause a trip, fall or injury?: Yes</p> <p>Is it causing traffic or cyclists to swerve?: No</p> <p>Please provide more information: Raised square pavement between Coles and Big W building in Gungahlin.</p> <p>Paver near seat and walk way, closer to the Coles building.</p> <p>Phone Number: + [REDACTED]</p> <p>Verify Email Address:</p>	GUNGAHLIN	CARNABY EAST UNIT 101 100 GUNGAHLIN PL, GUNGAHLIN ACT 2912	<p>Assetic Work Request: WR20372</p> <p>Assetic Work Request Status: Assigned</p> <p>CGD Source: CRM_AMIS_INCIDENTS_V2</p>	Cycle & footpaths	Damage to path or other

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
200224-000141	24/02/2020	10/03/2020	<p>■■■■ has called to report a fall that caused injury. On Friday, ■■■■ was walking along Gungahlin Place towards Hibberson Street, on the footpath there was a section that had been dug up and a metal piece had been placed across it, as ■■■■ was walking along her foot caught on the metal piece which caused her to fall and has fractured a finger on her right hand and grazed skin off her nose and face and sunglasses. The piece of metal is sitting 3 quarters of an inch above the rest of the footpath. ■■■■ was assisted by an off duty ambulance worker. ■■■■ states that there was no signage at all to indicate that there was works being done on the footpath and is concerned that a similar event could happen to somebody else unless something is done to make people aware of the works.</p> <p>■■■■ has called to report a fall that caused injury. On Friday, ■■■■ was walking along Gungahlin Place towards Hibberson Street, on the footpath there was a section that had been dug up and a metal piece had been placed across it, as ■■■■</p>		GUNGAHLIN	Gungahlin Place	CGD Source: CRM_ACT_ROADS_INCIDENTS_V2	Cycle & footpaths	
181115-001469	15/11/2018	17/11/2018	Near NAB at the Gungahlin market place Trees are lifting pavers. Could this please be investigated?...	Near NAB at the Gungahlin market place Trees are lifting pavers. Could this please be investigated?	GUNGAHLIN	Gungahlin Place	IAMS Enquiry ID: 1063711	Footpaths	

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
180122-000652	22/01/2018	24/01/2018	Footpaths : Fix My Street Report Submission	<p>Good morning</p> <p>The foot path on the west side of the Central Cafe in Gungahlin has pavers that have lifted. On Saturday 20 Jan 18 myself and my daughter were walking along this path when she tripped and almost fell flat on her face. While having a coffee in the Central Cafe we noticed another lady almost trip on the same paver.</p> <p>Can you please organise to have this trip hazard correct as a matter of urgency, if my daughter or some other person trips on this paver it will cause serious injuries.</p> <p>Kind regards</p>	GUNGAHLIN	Carnaby East, 100 Gungahlin Pl, Gungahlin ACT 2912, Australia	IAMS Enquiry ID: 1046169 Customer Requested Urgent: Yes	Footpaths	
180323-001394	23/03/2018	28/03/2018	Footpaths : Fix My Street Report Submission	<p>Footpath paving to the western side of Central Cafe at Gungahlin Village is very uneven and lifting possibly due to tree roots and badly laid pavers. The affected area is below in the shaded area refer attached file</p>	GUNGAHLIN	89 Gungahlin Pl, Gungahlin ACT 2912, Australia	IAMS Enquiry ID: 1052470	Footpaths	
180416-000469	16/04/2018	19/04/2018	Footpaths : Fix My Street Report Submission	<p>The pavers on the median strip in between between both sides of Gungahlin Place (between the Coles and Big W buildings) are raised and uneven. Because of this unevenness, I tripped over one causing me to fall and suffer scrapes and bruises to my hands and elbow, as well as jarring my shoulder. I d like to see these pavers evened out so no one else trips over them.</p>	GUNGAHLIN	100 Gungahlin Pl, Gungahlin ACT 2912, Australia	IAMS Enquiry ID: 1053932	Footpaths	

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
190423-003315	23/04/2019	24/04/2019	Footpath	<p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?:</p> <p>Trip hazard pavers on this walkway sticking up. I tried to straighten them but they re stuck</p> <p>Kind of material?: Pavers</p> <p>What is the issue?: Cracked, broken or uneven</p> <p>Verify Email Address:</p>	GUNGAHLIN	Carnaby East, 100 Gungahlin Pl, Gungahlin ACT 2912, Australia	IAMS Enquiry ID: 1071954 Customer Requested Urgent: Yes	Footpaths	
190506-000899	6/05/2019	6/05/2019	Footpath	<p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?:</p> <p>Tactile Pavers</p> <p>Kind of material?: Pavers</p> <p>What is the issue?: Dislodged pavers</p> <p>Verify Email Address:</p>	GUNGAHLIN	107 Gungahlin Pl, Gungahlin ACT 2912, Australia	IAMS Enquiry ID: 1072725 Customer Requested Urgent: Yes	Footpaths	

REFERENCE NUMBER	DATE CREATED	DATE LAST UPDATED	SUBJECT	DESCRIPTION	SUBURB	ADDRESS	ADDITIONAL INFORMATION	CATEGORY_LEVEL_2	CATEGORY_LEVEL_4
190502-002883	2/05/2019	10/05/2019	Graffiti : Fix My Street Report Submission	<p>Someone has painted political slogans Stop Adani on the footpath on the corner of Efkarpidis St and Gungahlin Place, Gungahlin. These slogans are directly outside Andrew Leigh s electoral office and are designed to lead directly to his office.</p> <p>I don t think Andrew Leigh owns the footpath. The rate payers paid for it. This is not a politically-based complaint, beyond that no politician or their supporters should be allowed to deface public property.</p> <p>You need to stamp on this, now, and clean it off. If Mr Leigh s office hasn t already reported it, there should be an investigation as to whether his staff were involved in this graffiti and, if found complicit, clean up should be billed to him personally.</p>	GUNGAHLIN	Gungahlin Pl and Valley Av Layover, Gungahlin ACT 2912, Australia	<p>Old Sub Topic: Unsure Graffiti Type: Other (please note in comments) Graffiti Details: Political</p> <p>IAMS Enquiry ID: 1072493 Customer Requested Urgent: Yes</p>	Graffiti	
200131-002567	31/01/2020	31/01/2020	FixMyStreet Submission: Parks & public spaces > Playgrounds & outdoor equipment > Report safety concern	<p>What is the issue?: Report safety concern What are you reporting?: Other Please provide more information Howdy guys! I almost tripped on a paver at Gungahlin the other day. For an able-bodied guy like me, it wasn't a problem. But for the elderly, it's a nightmare!</p> <p>My mother shattered her shoulder from falling on uneven pavement (elsewhere).</p>	GUNGAHLIN	100 GUNGAHLIN PL, GUNGAHLIN ACT 2912	<p>IAMS Enquiry ID: 1082872 Customer Requested Urgent: Yes</p>	Parks & public spaces	Report safety concern

Applied filters:SUBURB is GUNGAHLINADDRESS contains 'Gungahlin Pl'DATE CREATED is on or after 01/01/2018 00:00:00 and is before 26/05/2021 00:00:00

Salesforce case report

As of 2022-05-02 08:30:06 Australian Eastern Standard Time/AEST • Generated by Paula Ludvigson • Sorted by Date/Time Opened (Ascending)

Filtered By

Show: All cases

Units: Hours

Suburb contains Gungahlin

Incident Address contains Gungahlin Pl

Date/Time Opened	Case Number	Subject	ACTCCS Description	Incident Address	Suburb	Assetic Work Request ID	AC Case Number	Assetic Status Comments
21/06/2021	00086787	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	What is the material? Concrete What is the damage? Cracked, broken or uneven More Information Loose/uneven pavement in the alleway between NAB bank and Curst pizza on Gungahlin Pl.	CARNABY EAST UNIT 101 100 GUNGAHLIN PL, GUNGAHLIN ACT 2912	GUNGAHLIN	WR43929	00245561	
7/01/2022	00150367	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	What is the material? Brick or concrete pavers What is the damage? Cracked, broken or uneven More Information Loose tiles are a trip hazard @ Gungahlin Pl between Efkarpidis St & am	CARNABY EAST UNIT 101 100 GUNGAHLIN PL, GUNGAHLIN ACT 2912	GUNGAHLIN	WR43904	00399009	
5/04/2022	00181675	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	What is the material? Brick or concrete pavers What is the damage? Cracked, broken or uneven More Information Loose tile near Gungahlin Light Rail stop - caused a visually impaired	89 GUNGAHLIN PL, GUNGAHLIN ACT 2912	GUNGAHLIN	WR47462	00467586	
Total	3							

Confidential Information - Do Not Distribute

Copyright © 2000-2022 salesforce.com, inc. All rights reserved.



- [Close Window](#)
- [Print This Page](#)

Case: 00150367

Case Owner Roads ACT

Case Overview

Case Number 00150367

AC Case Number 00399009

Feedback Type

Priority

Subject Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other

Follow Up

Status Unassigned

Comment Category Request for Service

Sub Status Unresolved

Region

ACTCCS Description

What is the material?

Brick or concrete pavers

What is the damage?

Cracked, broken or uneven

More Information

Loose tiles are a trip hazard @ Gungahlin PI between Efkarpidis St & Hibberson St Gungahlin. Called in by [REDACTED]

Is it causing traffic or cyclists to swerve?

No

Could it cause a trip, fall or injury?

Yes

Assetic Detail

Assetic Status New

Assetic Queue TCCS AMIS Concrete

Assetic Work Request ID WR43904

Assetic Team Allocation Concrete City Industrial and Shopping Centres

Assetic Target Finish Date

Managing Platform Assetic

Assetic Status Comments

Work Details

Citizen Details

Account Name

Contact Email

Contact Phone

Case Details

Source	Access Canberra	Incident Address	CARNABY EAST UNIT 101 100 GUNGAHLIN PL, GUNGAHLIN ACT 2912
Case Origin	FMS Form	Suburb	GUNGAHLIN
Date/Time Opened	7/01/2022 12:33 PM	ACTCCS Longitude	149.13438241
Date/Time Closed		ACTCCS Latitude	-35.18616704

System Information

Created By AC TCCS Integration, 7/01/2022 12:33 PM

Last Modified By Assetic TCCS Integration, 14/02/2022 12:45 PM

Case History

11/02/2022 4:22 PM

User **Assetic TCCS Integration**
Action **Changed Assetic Status to New.**

7/01/2022 12:33 PM

User **AC TCCS Integration**
Action **Changed Sub Status to Unresolved. Changed Case Owner from AC TCCS Integration to Roads ACT. Deleted Medium in Priority. Changed Case Origin to FMS Form. Changed Case Record Type from TCCS General to ACT Roads. Created.**



- [Close Window](#)
- [Print This Page](#)

Case: 00086787

Case Owner Roads ACT

Case Overview

Case Number 00086787

AC Case Number 00245561

Feedback Type

Priority

Subject Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other

Follow Up

Status Unassigned

Comment Category

Sub Status Unresolved

Region

ACTCCS Description

What is the material?
Concrete

What is the damage?
Cracked, broken or uneven

More Information

Loose/uneven pavement in the alleyway between NAB bank and Curst pizza on Gungahlin PI. There is also loose pavement in front of Subway on Hibbison St. Requesting repair/maintenance of this pavement to prevent trip/injury.

Is it causing traffic or cyclists to swerve?
No

Could it cause a trip, fall or injury?
Yes

Assetic Detail

Assetic Status New

Assetic Queue TCCS AMIS Concrete

Assetic Work Request ID WR43929

Assetic Team Allocation Concrete City Industrial and Shopping Centres

Assetic Target Finish Date

Managing Platform Assetic

Assetic Status Comments

Work Details

Citizen Details

Account Name

Contact Email

Contact Phone

Case Details

Source Access Canberra

Incident Address CARNABY EAST UNIT 101 100 GUNGAHLIN PL,
GUNGAHLIN ACT 2912

Case Origin FMS Form

Suburb GUNGAHLIN

Date/Time Opened 21/06/2021 4:03 PM

ACTCCS Longitude 149.13438241

Date/Time Closed

ACTCCS Latitude -35.18616704

System Information

Created By AC TCCS Integration, 21/06/2021 4:03 PM

Last Modified By Assetic TCCS Integration, 14/02/2022 3:26 PM

Case History

11/02/2022 4:58 PM

User **Assetic TCCS Integration**

Action **Changed Assetic Status to New.**

22/06/2021 5:19 PM

User **Paul Dowling**

Action **Changed Case Record Type from TCCS General to ACT Roads.**

21/06/2021 5:32 PM

User **AC TCCS Integration**

Action **Changed Case Record Type from ACT Roads to TCCS General.**

21/06/2021 4:03 PM

User **AC TCCS Integration**

Action **Changed Sub Status to Unresolved. Changed Case Owner from AC TCCS Integration to Roads ACT. Deleted Medium in Priority. Changed Case Origin to FMS Form. Changed Case Record Type from TCCS General to ACT Roads. Created.**

00467586

Subject

Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other

Incident Address

89 GUNGAHLIN PL, GUNGAHLIN ACT 2912

ACTCCS Description

What is the material?

Brick or concrete pavers

What is the damage?

Cracked, broken or uneven

More Information

Loose tile near Gungahlin Light Rail stop - caused a visually impaired person to trip and fall this morning

Is it causing traffic or cyclists to swerve?

Yes

Could it cause a trip, fall or injury?

Yes

Case

Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other

+ Follow

Edit

Priority	Status	Case Number
	Unassigned	00181675

Unassigned

Assigned

Case Closed

Status: Unassigned

Mark Status as Complete

Details

Feed

Related

Case Owner
Roads ACT

Case Overview

Case Number
00181675

AC Case Number
00467586

Feedback Type

Priority

Subject

Status

Case Reassignment


Not handled by your Business Unit?


If you believe this Case has been incorrectly assigned, select Next to initiate the transfer to another Business Unit.

Next

[\(0\) \(/lightning/r/Case/500\)](#)

[\(2\) \(/lightning/r/Case/500\)](#)

 20220405_081035
05/04/2022 • 6.9MB • jpg
[\(/lightning/r/ContentDocument/0698w01\)](#)

 20220405_081038
05/04/2022 • 6.2MB • jpg
[\(/lightning/r/ContentDocument/0698w01\)](#)

[View All](#)

DEFECT_ID	STATUS	DESCRIPTION	ACTIVITY_TYPE	DEFECT_TYPE	DATE_INSPECTED	DATE_REPAIRED	LOCATION	ACTION	ACTION_DESCRIPTION	WO_NUMBER
91869	AVAILABLE	Relay displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced	2/03/2020		Gungahlin place in front of child care	PA - relay pavers	Relay displaced pavers	
73917	COMPLETED	Relay Paver	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	21/02/2018	2/21/2018	Cnr Efkarpidis st and Gungahlin place	Paver - Relay	Pavers, cnr Efkarpidis and Gungahlin place, Gungahlin	ACT/7476
73918	COMPLETED	Pavers Relay	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	21/02/2018	2/21/2018	Gungahlin place across from NAB bank, Gungahlin	Paver - Relay	Pavers, Gungahlin place across from NAB bank, Gungahlin	ACT/7477
73919	COMPLETED	Relay pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	21/02/2018	2/21/2018	Gungahlin place near wok it up Gungahlin	Paver - Relay	Pavers, Gungahlin place near wok it up, Gungahlin	ACT/7478
76079	COMPLETED	Displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	23/04/2018	5/17/2018	100 Gungahlin Pl, Gungahlin	Paver - Relay		ACT/7664
83060	COMPLETED	Displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	23/11/2018		Gungahlin Pl, East, Gungahlin. NAB	Paver - Relay		ACT/8527
83062	COMPLETED	Displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	23/11/2018		Gungahlin Pl, East, Gungahlin. MP Leigh	Paver - Relay		ACT/8528
85853	COMPLETED	Lifted Pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	1/05/2019	7/30/2019	Gungahlin Pl Gungahlin opp Velocity Conveyancing	Paver - Relay	Lifted pavers	
85990	COMPLETED	Lifted Pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	8/05/2019	7/30/2019	Gungahlin Pl Opp Crust Pizza	Paver - Relay	Lifted pavers	
90325	COMPLETED	Damaged pavers	Path/Pram Cross./Veh. Cross./Driveways/Kerb + Gutt./Con. Is	Paver - Displaced (relay)	18/12/2019		125 Gungahlin Pl Winyu House Cnr Efkaaidis	Paver - Relay	Damaged pavers	

Applied filters: DATE_INSPECTED is on or after 01/01/2018 LOCATION contains 'gungahlin pl' LOCATION contains 'gungahlin'

ENQUIRY ID	CREATED DATE	COMPLETE DATE	CLASS	STATUS	LOCATION	DESCRIPTION	ACTION
1087824	24/06/2020	13/10/2020 2:11:57 PM	Community Paths	Complete	north west corner of Gungahlin Place and Ernest Cavanagh St (next to Centrelink)	What is the issue?: Accessibility issues Please describe the issue transition from footpath to the pedestrian crossing is hampered by the awkwardness of using the step and the slope leading to it making it hazardous for general pedestrians and more so for people with mobility or sight issues or who are pushing pram	Tried calling [REDACTED] at 2:00pm 22/07/2020, no answer left a msg. Will review the area.
1071954	24/04/2019		Community Paths	Received	Gungahlin Place, Gungahlin	Trip hazard pavers on this walkway sticking up. I tried to straighten them but they're stuck	Attended location area is opp Velocity Conveyancing in centre median. Defect Raised.
1057567	3/07/2018		Community Paths	Open \ Inspected	125 Gungahlin Place, Gungahlin	There is a hole in the footpath where a sign was once installed, then moved, but the hole is still there. one of the members of the public informed me that they almost fell over when they stepped in it. It is a missing brick in the sidewalk, not concrete. It is on the very corner of Efkarpidis and Gungahlin Place.	Given to Tim Norton to replace paver, Mark Smith to find out if sign is meant to be re-installed or permanently deleted. 11/7/18 RH
1053932	19/04/2018	17/05/2018 9:12:26 AM	Community Paths	Complete	100 Gungahlin Place, Gungahlin	The pavers on the median strip in between between both sides of Gungahlin Place (between the Coles and Big W buildings) are raised and uneven. Because of this unevenness, I tripped over one causing me to fall and suffer scrapes and bruises to my hands and elbow, as well as jarring my shoulder. I'd like to see these pavers evened out so no one else trips over them.	
1072725	6/05/2019	30/07/2019 1:56:41 PM	Community Paths	Complete	Gungahlin Place, Gungahlin	Tactile pavers dislodged	Attended location pavers are lifted in the centre median strip area opp Crust Pizza.
1072493	3/05/2019	09/05/2019 12:00:00 AM	Community Paths	Complete	Efkarpidis St and Gungahlin Place, Gungahlin	Someone has painted political slogans 'Stop Adani' on the footpath on the corner of Efkarpidis St and Gungahlin Place, Gungahlin. These slogans are directly outside Andrew Leigh's electoral office and are designed to lead directly to his office.	Complete
1063711	17/11/2018		Community Paths	Work Instructed	Gungahlin Place	Near NAB at the Gungahlin market place Trees are lifting pavers. Could this please be investigated?	
1082872	31/01/2020		Community Paths	Received	100 Gungahlin Pl, Gungahlin	I almost tripped on a paver at Gungahlin the other day. For an able-bodied guy like me, it wasn't a problem. But for the elderly, it's a nightmare!	Inspected 03.01.20 photos taken and passed job onto Garry George to program. MC.

ENQUIRY ID	CREATED DATE	COMPLETE DATE	CLASS	STATUS	LOCATION	DESCRIPTION	ACTION
1052470	26/03/2018	04/04/2018 3:16:16 PM	Community Paths	Complete	89 Gungahlin Pl, Gungahlin	Footpath paving to the western side of Central Cafe at Gungahlin Village is very uneven and lifting possibly due to tree roots and badly laid pavers. The affected area is below in the shaded area refer attached file	
1068266	16/02/2019	18/02/2019 3:45:10 PM	Community Paths	Complete	Gungahlin Pl, GUNGAHLIN	Customer has contacted to report they have just fallen caused by uneven pavers on a footpath, outside Ginger and Spice restaurant	Attended location checked the area indicated no lifted pavers located called the customer who was unable to give a specific location.
1077821	17/09/2019	26/09/2019 8:56:36 AM	Community Paths	Complete	Gungahlin Pl, Gungahlin ACT 2912, Australia	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: The pavers in front of tenancies facing Gungahlin Place are extremely dirty and untidy, What is the issue?: Damage to path or other What is the damage?: Cracked, broken or uneven What is the material?: Brick or concrete pavers Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?: No Please provide more information: The shiny new bus shelter has not been maintained/cleaned since opening and the pavers are extremely dirty and require a pressure wash along Gungahlin Place. Also pavers require checking to ensure they are not a potential risk / trip hazard.	Pavers are washed cleaned every two weeks on Sunday
1063871	20/11/2018		Pedestrian Paving	Referred To Other B	Gungahlin Place opp National Bank pedestrian crossing near Gungaline stone metal sculpture	Can you identify any nearby notable landmarks?: Opposite National Aust Bank, near sculpture Kind of material?: Pavers What is the issue?: Cracked, broken or uneven Verify Email Address: [REDACTED]	

ENQUIRY ID	CREATED DATE	COMPLETE DATE	CLASS	STATUS	LOCATION	DESCRIPTION	ACTION
1077107	29/08/2019 11:02:38 AM	03/09/2019	Urban Open Space	Complete	Gungahlin PI, GUNGAHLIN	<p>The pavers in front of tenancies facing Gungahlin Place are extremely dirty and untidy,</p> <p>What is the issue?: Damage to path or other</p> <p>What is the damage?: Cracked, broken or uneven</p> <p>What is the material?: Brick or concrete pavers</p> <p>Could it cause a trip, fall or injury?: Yes</p> <p>Is it causing traffic or cyclists to swerve?: No</p> <p>Please provide more information: The shiny new bus shelter has not been maintained/cleaned since opening and the pavers are extremely dirty and require a pressure wash along Gungahlin Place. Also pavers require checking to ensure they are not a potential risk / trip hazard.</p>	Phoned [REDACTED] - Explained there is a current program to clean pavers which is happening now 30/8/19

Applied filters:LOCATION contains 'Gungahlin PI'CREATED DATE is on or after 01/01/2018 00:00:00 and is before 02/02/2022 00:00:00

Work_Order_ID	WO_Status	WO_SLA_Date	WO_Brief_Description	WO_Creation_Time	WO_Defect_Location	WO_Target_Start_Date	WO_Target_Finish_Date	SUPPORTING_INFORMATION	LAST_MODIFIED_DATE
WO13153	COMP	20/08/2018	Relay paver	21/02/2018	Cnr Efkarpidis st and Gungahlin place	2018-02-21 10:29:00	2018-03-23 10:19:00	WO13153 : 171219-001562 ***Last updated by Chris Nugent***7/07/2020 4:15:42 PM	2020-07-08 23:35:54
WO13252	COMP	20/08/2018	Pavers relay	21/02/2018	Gungahlin place across from NAB bank, Gungahlin	2018-02-21 10:33:00	2018-03-23 10:32:00		
WO13284	COMP	20/08/2018	Relay pavers	21/02/2018	Gungahlin place near wok it up Gungahlin	2018-02-21 10:38:00	2018-03-23 10:37:00		
WO14110	COMP	20/10/2018	displaced pavers	23/04/2018	100 Gungahlin Pl, Gungahlin	2018-04-23 08:36:00	2018-04-30 08:35:00	WO14110 : 180416-000469 - Relay pavers ***Last updated by Chris Nugent***7/07/2020 4:45:51 PM	2020-07-08 23:16:21
WO17092	COMP	22/05/2019	displaced pavers	23/11/2018	Gungahlin Pl, East, Gungahlin. NAB	2018-11-23 14:57:00	2018-12-23 14:56:00	WO17092 : 181105-000096 - Relay pavers ***Last updated by Chris Nugent***7/07/2020 6:15:54 PM	2020-07-08 21:54:41
WO17247	COMP	22/05/2019	displaced pavers	23/11/2018	Gungahlin Pl, East, Gungahlin. NAB	2018-11-23 14:57:00	2018-12-23 14:56:00	WO17247 : 181115-001469 - Relay pavers ***Last updated by Chris Nugent***7/07/2020 6:15:54 PM	2020-07-07 18:36:54
WO17309	COMP	22/05/2019	displaced pavers	23/11/2018	Gungahlin Pl, East, Gungahlin.MP Leigh	2018-11-23 15:01:00	2018-12-23 15:00:00	WO17309 : Relay pavers ***Last updated by Chris Nugent***7/07/2020 6:15:54 PM	2020-07-08 21:54:37
WO19136	COMP	28/10/2019	Lifted pavers	1/05/2019	Gungahlin Pl Gungahlin opp Velocity Conveyancing	2019-05-01 15:46:00	2019-10-28 15:45:00	WO19136 : Relay pavers ***Last updated by Chris Nugent***7/07/2020 7:02:59 PM	2020-07-08 20:41:56
WO18646	COMP	4/11/2019	Lifted pavers	8/05/2019	Gungahlin Pl Opp Crust Pizza	2019-05-08 07:56:00	2019-11-04 07:55:00	WO18646 : 190506-000899 - Re Lay pavers ***Last updated by Chris Nugent***7/07/2020 7:02:59 PM	2020-07-08 20:40:37
WO20748	COMP	15/06/2020	Damaged pavers	18/12/2019	125 Gungahlin Pl Winyu House Cnr Efkadaidis	2019-12-18 14:35:00	2020-01-01 14:33:00	WO20748 : Re lay pavers and replace broken ones. ***Last updated by Chris Nugent***7/07/2020 7:38:30 PM	2020-07-08 19:37:15
WO1182	TCOMP	28/08/2020	Relay displaced pavers	2/03/2020	Gungahlin place infront of child care	2020-03-02 00:00:00	2020-08-29 02:00:00	WO1182 : Scheduled by bulk scheduling operation. ***Last updated by Chris Nugent***2/07/2020 4:42:09 PM , WO1182 : Relay displaced pavers ***Last updated by Chris Nugent***29/06/2020 4:23:01 PM	2021-01-31 23:57:47
WO38104	TCOMP	12/10/2021	Relay pavers & tactiles between tree & and rock GungHlin Pl opposite Crust Pizza	15/04/2021	Shop B Gungahlin Place West, Gungahlin ACT 2912, Australia	2021-04-15 16:46:39	2021-10-12 17:46:39	WO38104 : Relay pavers opposite Crust ***Last updated by Garry George***15/04/2021 4:50:32 PM , WO38104 : Relay pavers Gungahlin Pl opposite Crust ***Last updated by Garry George***15/04/2021 4:49:34 PM	2021-06-16 11:34:32

Work_Order_ID	WO_Status	WO_SLA_Date	WO_Brief_Description	WO_Creation_Time	WO_Defect_Location	WO_Target_Start_Date	WO_Target_Finish_Date	SUPPORTING_INFORMATION	LAST_MODIFIED_DATE
WO45663	ASSESS	2/05/2022	Relay pavers Gungahlin Pl median between NRMA & Grilld restaurant 64m	3/11/2021	107 Gungahlin Pl, Gungahlin ACT 2912, Australia	2021-11-03 15:51:00	2022-05-02 14:51:00	WO45663 : Work is satisfactory. ***Last updated by Prakhar Srivastava***30/03/2022 3:49:27 PM , WO45663 : Relay pavers ***Last updated by Garry George***3/11/2021 3:55:54 PM , WO45663 : Relay pavers centre Gungahlin opposite NRMA 64m ***Last updated by Garry George***3/11/2021 3:54:46 PM	2022-03-30 15:49:35
WO46921	ASSESS	1/06/2022	Relay pavers, NRMA, Gungahlin Pl. 2sm	3/12/2021	Shop/31 Gungahlin Pl, Gungahlin ACT 2912, Australia	2021-12-03 15:04:00	2022-06-01 14:04:00	WO46921 : Work is satisfactory. ***Last updated by Prakhar Srivastava***30/03/2022 3:51:36 PM , WO46921 : Relay pavers Gungahlin Pl, @NRMA 2sm ***Last updated by Garry George***3/12/2021 3:06:36 PM	2022-03-30 15:51:48

Applied filters:Suburb is GUNGAHLINWO_Defect_Location contains 'Gungahlin Pl'WO_Creation_Time is on or after 01/01/2018 00:00:00 and is before 02/02/2022 00:00:00

Order Details	
Work Type	CM - Corrective
ID	WO1006
Creation Time	17/02/2020 12:00 AM
Requester	Garry George
Creator	Garry George
Brief Description	Relay pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	14/08/2020 11:00 PM	 
Target Start	17/02/2020 12:00 AM	 
Target Finish	15/08/2020 2:00 AM	 
Schedule Start	3/07/2020 12:00 AM	 
Schedule Finish	31/12/2020 12:00 AM	 
Actual Start	1/02/2021 12:24 AM	 
Actual Finish	1/02/2021 12:24 AM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

IAMS Pavers Work Order

External Id

91841

Work Order Source

Safety Inspection ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Scheduled by bulk scheduling operation.

Last updated by Chris Nugent 2/07/2020 4:42:04 PM


Displaced pavers relay

Last updated by Chris Nugent 29/06/2020 4:23:01 PM

4000 characters remaining

Tasks			
	Work Task Id	Lowest Maintainable Item	Brief Description
No items to display			

◀ ◁ 0 ▷ ▶ 10 items per page

No items to display 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

1 10 items per page 1 - 1 of 1 items

Resources


Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
--------------	-----------	-------	----------	--------------	-----------------

0 10 items per page No items to display

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
--------------	-------------	----------	--------------------	-----------------------	------------------	--------------	-----------------	-------------

◀ ◀ 0 ▶ ▶ 10 items per page

No items to display 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



DEC_31_2020

Defect Location



Location Description

Gungahlin place in front of NRMA

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO1086
Creation Time	17/02/2020 12:00 AM
Requester	Garry George
Creator	Garry George
Brief Description	Relay pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	14/08/2020 11:00 PM	 
Target Start	17/02/2020 12:00 AM	 
Target Finish	15/08/2020 2:00 AM	 
Schedule Start	3/07/2020 12:00 AM	 
Schedule Finish	31/12/2020 12:00 AM	 
Actual Start	1/02/2021 12:11 AM	 
Actual Finish	1/02/2021 12:11 AM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

IAMS Pavers Work Order

External Id

91844

Work Order Source

Safety Inspection ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.










Scheduled by bulk scheduling operation.

Last updated by Chris Nugent 2/07/2020 4:42:04 PM

Displaced pavers

Last updated by Chris Nugent 29/06/2020 4:23:01 PM

4000 characters remaining

Tasks			
		Work Task Id  	Lowest Maintainable Item 
		Brief Description	
  0  		10  items per page	No items to display 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD ⊖	0	01/02/2021

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	8	\$0.00	0	\$0.00

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------


◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



JAN_30_2021

Defect Location



Location Description

Gungahlin place in front of Jade dumpling noodle house

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO1104
Creation Time	17/02/2020 12:00 AM
Requester	Garry George
Creator	Garry George
Brief Description	Relay/replace broken moving and raised pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3014
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	14/08/2020 11:00 PM	 
Target Start	17/02/2020 12:00 AM	 
Target Finish	15/08/2020 2:00 AM	 
Schedule Start	3/07/2020 12:00 AM	 
Schedule Finish	31/12/2020 12:00 AM	 
Actual Start	28/02/2021 11:14 PM	 
Actual Finish	28/02/2021 11:14 PM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

IAMS Pavers Work Order

External Id

91850

Work Order Source

Safety Inspection ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.










Scheduled by bulk scheduling operation.

Last updated by Chris Nugent 2/07/2020 4:42:00 PM

Broken displaced rocking paver

Last updated by Chris Nugent 29/06/2020 4:23:01 PM

4000 characters remaining

Tasks			
		Work Task Id  	Lowest Maintainable Item 
		Brief Description	
  0  		10  items per page	No items to display 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources


Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD ●	0	28/02/2021

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	0	\$0.00	0	\$0.00


◀ ◀ 1 ▶ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page

No items to display 

Attachments



DEC_31_2020

Defect Location



Location Description

Median strip Gngln Mkt Pl nr cnr Efkapidis St

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO1119
Creation Time	17/02/2020 12:00 AM
Requester	Garry George
Creator	Garry George
Brief Description	Relay all displaced pavers 8m
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	14/08/2020 11:00 PM	 
Target Start	17/02/2020 12:00 AM	 
Target Finish	15/08/2020 2:00 AM	 
Schedule Start	3/07/2020 12:00 AM	 
Schedule Finish	31/12/2020 12:00 AM	 
Actual Start	1/02/2021 12:08 AM	 
Actual Finish	1/02/2021 12:08 AM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

IAMS Pavers Work Order

External Id

91849

Work Order Source

Safety Inspection ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.


Scheduled by bulk scheduling operation.

Last updated by Chris Nugent 2/07/2020 4:42:05 PM

Relay displaced pavers

Last updated by Chris Nugent 29/06/2020 4:23:01 PM

4000 characters remaining


Tasks			
		Work Task Id ↑	Lowest Maintainable Item
			Brief Description
◀ 0 ▶		10	items per page
			No items to display 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
--------------	------------	-------	------	----------------	----------------	--------------	--------------

◀ ◀ 0 ▶ ▶ 10 items per page
 No items to display 

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD 	0	01/02/2021

◀ ◀ 1 ▶ ▶ 10 items per page
 1 - 1 of 1 items 

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	0	\$0.00	0	\$0.00

1 items per page

1 - 1 of 1 items

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin Mkt PI plane tree & bench op Beyond Bnk

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	W03548
Creation Time	30/06/2015 8:17 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Raised pavers at sump lid.
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE1158
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK SHOP/BUILDING PAVEMENT
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Concrete
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	27/12/2015 9:17 AM	 
Target Start	30/06/2015 8:17 AM	 
Target Finish	7/07/2015 8:06 AM	 
Schedule Start	30/06/2015 8:17 AM	 
Schedule Finish	27/12/2015 7:17 AM	 
Actual Start	30/06/2015 8:17 AM	 
Actual Finish	17/07/2015 7:43 AM	 
Estimated Duration (hrs)	8.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/5280

External Id

55867

Work Order Source

Routine Inspection ▼




Supporting Information







Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Repair around sump lid

Last updated by Chris Nugent 7/07/2020 10:55:29 AM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	69 Gungahlin PI, Gungahlin. Pavers

  1   10  items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	G D Samaritan ⊖		17/07/2015

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	1452	\$0.00	0	\$0.00


1

 items per page

1 - 1 of 1 items

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

69 Gungahlin Pl, Gungahlin

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO3957
Creation Time	4/09/2015 9:24 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Displaced pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3014
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	2/03/2016 10:24 AM	 
Target Start	4/09/2015 9:24 AM	 
Target Finish	11/09/2015 9:23 AM	 
Schedule Start	4/09/2015 9:24 AM	 
Schedule Finish	2/03/2016 8:24 AM	 
Actual Start	4/09/2015 9:25 AM	 
Actual Finish	22/12/2015 11:45 AM	 
Estimated Duration (hrs)	9.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/5443

External Id

56957

Work Order Source

Routine Inspection ▼




Supporting Information







Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Relay pavers

Last updated by Chris Nugent 7/07/2020 11:25:20 AM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Gungahlin PI, Gungahlin. Linear Pk. Pavers

  1   10  items per page 1 - 1 of 1 items 

Labour

Work Task Id ↑	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Resources

Work Task Id ↑	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	G D Samaritan 		22/12/2015

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	2145	\$0.00	0	\$0.00

1 items per page

1 - 1 of 1 items

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display ↻

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin PI, Gungahlin. Linear Pk

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	W07559
Creation Time	22/04/2016 11:21 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Displaced pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE1152
Asset Name	GUNGAHLIN PLACE,ERNEST CAVANAGH STREET SHOP/BUILDING PAVEMENT
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Concrete
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	19/10/2016 12:21 PM	 
Target Start	22/04/2016 11:21 AM	 
Target Finish	29/04/2016 11:19 AM	 
Schedule Start	22/04/2016 11:21 AM	 
Schedule Finish	19/10/2016 10:21 AM	 
Actual Start	22/04/2016 11:22 AM	 
Actual Finish	9/05/2016 7:49 AM	 
Estimated Duration (hrs)	11.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/5942

External Id

61498

Work Order Source

Routine Inspection ▼




Supporting Information


Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

160411-000157 - Relay pavers

Last updated by Chris Nugent 7/07/2020 12:59:17 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Gungahlin PI, Gungahlin. North End. Pavers


◀ ◁ 1 ▷ ▶ 10 items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	G D Samaritan 		09/05/2016

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	2548	\$0.00	0	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◀ 0 ▶ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin PI, Gungahlin. North End

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO13023
Creation Time	21/12/2017 10:41 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Relay pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	19/06/2018 9:41 AM	 
Target Start	21/12/2017 10:41 AM	 
Target Finish	20/01/2018 10:40 AM	 
Schedule Start	21/12/2017 10:41 AM	 
Schedule Finish	19/06/2018 9:41 AM	 
Actual Start	21/12/2017 10:42 AM	 
Actual Finish	10/01/2018 3:02 PM	 
Estimated Duration (hrs)	10.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/7363

External Id

73153

Work Order Source

Public Enquiry ▼





Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

171212-000061

Last updated by Chris Nugent 7/07/2020 4:15:42 PM

4000 characters remaining

Tasks			
		Work Task Id  	Lowest Maintainable Item 
No items to display 			

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
--------------	------------	-------	------	----------------	----------------	--------------	--------------

◀◀ 0 ▶▶ 10 items per page No items to display 

Resources


Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
--------------	-----------	-------	----------	--------------	-----------------

◀◀ 0 ▶▶ 10 items per page No items to display 

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
--------------	-------------	----------	--------------------	-----------------------	------------------	--------------	-----------------	-------------


◀ ◁ 0 ▷ ▶ 10 items per page

No items to display 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page

No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin place Between Efkarpidis and hibberson

Cost

Total Planned Cost

Total Actual Cost

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO13153
Creation Time	21/02/2018 10:29 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Relay paver
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3014
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	20/08/2018 9:29 AM	 
Target Start	21/02/2018 10:29 AM	 
Target Finish	23/03/2018 10:19 AM	 
Schedule Start	21/02/2018 10:29 AM	 
Schedule Finish	20/08/2018 9:29 AM	 
Actual Start	21/02/2018 10:30 AM	 
Actual Finish	21/02/2018 10:31 AM	 
Estimated Duration (hrs)	10.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/7476

External Id

73917

Work Order Source

Public Enquiry ▼




Supporting Information







Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

171219-001562

Last updated by Chris Nugent 7/07/2020 4:15:42 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Pavers, cnr Efkarpidis and Gungahlin place, Gungahlin

  1   10  items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

⏪ ⏩ 1 ⏪ ⏩ 10 items per page 1 - 1 of 1 items 🔄

Resources


Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD ⊖		21/02/2018

⏪ ⏩ 1 ⏪ ⏩ 10 items per page 1 - 1 of 1 items 🔄

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	6655	\$0.00	0	\$0.00

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display ↻

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Cnr Efkarpidis st and Gungahlin place

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO13252
Creation Time	21/02/2018 10:33 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Pavers Relay
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	20/08/2018 9:33 AM	 
Target Start	21/02/2018 10:33 AM	 
Target Finish	23/03/2018 10:32 AM	 
Schedule Start	21/02/2018 10:33 AM	 
Schedule Finish	20/08/2018 9:33 AM	 
Actual Start	21/02/2018 10:35 AM	 
Actual Finish	21/02/2018 10:36 AM	 
Estimated Duration (hrs)	10.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/7477

External Id

73918

Work Order Source




Public Enquiry ▼







Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Pavers, Gungahlin place across from NAB bank, Gungahlin

  1   10  items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD ⊖		21/02/2018

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	7645	\$0.00	0	\$0.00

1 items per page

1 - 1 of 1 items

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin place across from NAB bank, Gungahlin

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO14110
Creation Time	23/04/2018 8:36 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Displaced pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	20/10/2018 9:36 AM	 
Target Start	23/04/2018 8:36 AM	 
Target Finish	30/04/2018 8:35 AM	 
Schedule Start	23/04/2018 8:36 AM	 
Schedule Finish	20/10/2018 7:36 AM	 
Actual Start	23/04/2018 8:37 AM	 
Actual Finish	17/05/2018 9:12 AM	 
Estimated Duration (hrs)	8.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/7664

External Id

76079

Work Order Source

Routine Inspection ▼




Supporting Information


Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

180416-000469 - Relay pavers

Last updated by Chris Nugent 7/07/2020 4:45:51 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	100 Gungahlin PI, Gungahlin. Pavers

◀ ◁ 1 ▷ ▶ 10 items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD ⊖		17/05/2018

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	968	\$0.00	0	\$0.00

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

100 Gungahlin Pl, Gungahlin

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO14154
Creation Time	3/04/2018 9:58 AM
Requester	Historical IAMS User
Creator	Historical IAMS User
Brief Description	Displaced pavers
Reference Work Order	
Work Request ID	<u>WR18227</u>

















Asset Details

Asset ID	PAVE2837
Asset Name	GUNGAHLIN TOWN CENTRE SHOP/BUILDING PAVEMENT
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	30/09/2018 9:58 AM	 
Target Start	3/04/2018 9:58 AM	 
Target Finish	10/04/2018 9:56 AM	 
Schedule Start	3/04/2018 9:58 AM	 
Schedule Finish	30/09/2018 8:58 AM	 
Actual Start	3/04/2018 9:59 AM	 
Actual Finish	4/04/2018 3:16 PM	 
Estimated Duration (hrs)	9.00	 

Additional Info

Responsible Officer	<input type="text" value="Please type to search for Responsible Officer (Optional)"/>
Reference Number	<input type="text" value="ACT/7607"/>
External Id	<input type="text" value="75351"/>
Work Order Source	<input type="text" value="Routine Inspection"/>

Supporting Information




Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.







WR18227 : Oracle CRM Reference : 210310-000937
Requester Contact Name: anonymous anonymous

Initial enquiry info only. See CRM for additional correspondence.
Defect location info may be incorrect (address validation limitations).

Cycle & footpaths

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	89 Gungahlin Nth PI, Gungahlin. Central cafe. Pavers

  1   10  items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Paver Contractor	ACT Property Service ⊖		04/04/2018

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	17	\$0.00	0	\$0.00

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

89 Gungahlin Nth Pl, Gungahlin. Central cafe

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO18646
Creation Time	8/05/2019 7:56 AM
Requester	Andrew Melville
Creator	Andrew Melville
Brief Description	Lifted pavers
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	4/11/2019 8:56 AM	 
Target Start	8/05/2019 7:56 AM	 
Target Finish	4/11/2019 7:55 AM	 
Schedule Start	8/05/2019 7:56 AM	 
Schedule Finish	4/11/2019 6:56 AM	 
Actual Start	8/05/2019 7:56 AM	 
Actual Finish	4/11/2019 6:56 AM	 
Estimated Duration (hrs)	7.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

190506-000899

External Id

85990

Work Order Source

Routine Inspection ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.


190506-000899 - Re Lay pavers

Last updated by Chris Nugent 7/07/2020 7:02:59 PM

4000 characters remaining

Tasks			
	Work Task Id	Lowest Maintainable Item	Brief Description
No items to display			

◀ ◁ 0 ▷ ▶ 10 items per page

No items to display 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Concrete Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Concrete Contractor	Paths Contractor		04/11/2019

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Materials


Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	24	\$0.00	0	\$0.00

⏪
⏩
1
⏪
⏩
10
▼
 items per page

1 - 1 of 1 items 🔄

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin Pl Opp Crust Pizza

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO19136
Creation Time	1/05/2019 3:46 PM
Requester	Andrew Melville
Creator	Andrew Melville
Brief Description	Lifted pavers
Reference Work Order	
Work Request ID	

Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation	
WO Priority	5
SLA Due Date	28/10/2019 4:46 PM
Target Start	1/05/2019 3:46 PM
Target Finish	28/10/2019 3:45 PM
Schedule Start	1/05/2019 3:46 PM
Schedule Finish	28/10/2019 2:46 PM
Actual Start	1/05/2019 3:46 PM
Actual Finish	28/10/2019 2:46 PM
Estimated Duration (hrs)	15.00

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

External Id

85853

Work Order Source

Routine Inspection ▼


Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Relay pavers

Last updated by Chris Nugent 7/07/2020 7:02:59 PM

4000 characters remaining

Tasks			
		Work Task Id ↑	Lowest Maintainable Item
			Brief Description
◀ 0 ▶		10	items per page
			No items to display 

Labour

Work Task Id ↑	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Concrete Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id ↑	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Concrete Contractor	Paths Contractor ●		28/10/2019

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	10	\$0.00	0	\$0.00

⏪
⏩
1
▶
⏭
10
▼
 items per page

1 - 1 of 1 items 🔄

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin Pl Gungahlin opp Velocity Conveyancing

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO22170
Creation Time	27/02/2020 12:00 AM
Requester	Waliul Shaju
Creator	Waliul Shaju
Brief Description	Grinding , location lat & long not correct
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3014
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	GRD, Grind
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	24/08/2020 11:00 PM	 
Target Start	27/02/2020 12:00 AM	 
Target Finish	12/03/2020 2:00 AM	 
Schedule Start	27/02/2020 12:00 AM	 
Schedule Finish	7/03/2020 11:00 PM	 
Actual Start	13/03/2020 9:49 AM	 
Actual Finish	18/03/2020 12:00 AM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

ACT/9265

External Id

91817

Work Order Source

Safety Inspection ▼




Supporting Information


Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Grinding

Last updated by Chris Nugent 7/07/2020 7:45:20 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Gizzard street, nearby carpark - Grinding

◀ ◁ 1 ▷ ▶ 10 ▼ items per page 1 - 1 of 1 items 

Labour

Work Task Id ↑	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
10	Concrete - RM	Grinding Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Resources


Work Task Id ↑	Status Id	Craft	Resource	Actual Hours	Completion Date
10	Completed	Grinding Contractor	Australian Grinding Company		18/03/2020

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Metre)	Grind	Metre	<input checked="" type="checkbox"/>	1	\$0.00	0	\$0.00

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gizzard street, nearby carpark

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO23959
Creation Time	17/02/2020 12:00 AM
Requester	Garry George
Creator	Garry George
Brief Description	Relay displaced & moving paver
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	14/08/2020 11:00 PM	 
Target Start	17/02/2020 12:00 AM	 
Target Finish	15/08/2020 2:00 AM	 
Schedule Start	17/02/2020 12:00 AM	 
Schedule Finish	14/08/2020 11:00 PM	 
Actual Start	17/02/2020 12:00 AM	 
Actual Finish	8/07/2020 12:00 AM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

External Id

91845

Work Order Source

Safety Inspection ▼








Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Displaced paver rocking 20mm high

Last updated by Chris Nugent 8/07/2020 1:57:03 PM

4000 characters remaining

Tasks			
		Work Task Id  	Lowest Maintainable Item 
		Brief Description	
 0  10  items per page		No items to display 	

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Concrete Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Concrete Contractor	Paths Contractor		08/07/2020

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	0	\$0.00	1	\$0.00

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display ↻

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin Mkt PI @wood pergola op Beyond Bnk

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO23965
Creation Time	17/02/2020 12:00 AM
Requester	Garry George
Creator	Garry George
Brief Description	Relay pavers to bring level up to NAB floor level
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	14/08/2020 11:00 PM	 
Target Start	17/02/2020 12:00 AM	 
Target Finish	15/08/2020 2:00 AM	 
Schedule Start	17/02/2020 12:00 AM	 
Schedule Finish	14/08/2020 11:00 PM	 
Actual Start	17/02/2020 12:00 AM	 
Actual Finish	8/07/2020 12:00 AM	 
Estimated Duration (hrs)	2.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

External Id

91854

Work Order Source

Safety Inspection ▼










Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Relay pavers along NAB bank boundary to level

Last updated by Chris Nugent 8/07/2020 1:57:03 PM

4000 characters remaining

Tasks			
		Work Task Id  	Lowest Maintainable Item 
			Brief Description
  0  		10  items per page	No items to display 

Labour

Work Task Id ↑	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Concrete Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Resources

Work Task Id ↑	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Concrete Contractor	Paths Contractor ●		08/07/2020

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items ↻

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
	Concrete - RM (Square Metre)	Relay Pavers	Square Metre	<input checked="" type="checkbox"/>	0	\$0.00	8	\$0.00

⏪
⏩
1
▶
⏭
10
▼
 items per page

1 - 1 of 1 items 🔄

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



◀ ◀ 0 ▶ ▶

No items to display

Defect Location



Location Description

Gungahlin Mkt PI

Cost

Total Planned Cost

0

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	W027710
Creation Time	30/10/2020 12:56 PM
Requester	Vivien McLeary
Creator	Vivien McLeary
Brief Description	Grass, trees & shrubs Grass & weeds Report weed infestation
Reference Work Order	
Work Request ID	<u>WR5883</u>

Asset Details

Asset ID	UOS18296
Asset Name	GUNGAHLIN PLACE ROAD MEDIAN
Asset Category	Land
Maintenance Asset Type	Land
Maintenance Asset Sub Type	Urban Open Space
Work Group	PM Gungahlin Operations
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	VEG,VEG-01, Vegetation Issue, Weeds present
Cause Code	ENV,ENV-02, Environmental, Vegetation
Remedy Code	RCW, Remove or Control Weeds
Loss Of Service Required	<input type="checkbox"/>

Prioritisation	
WO Priority	4
SLA Due Date	9/11/2020 12:56 PM
Target Start	30/10/2020 12:56 PM
Target Finish	9/11/2020 12:56 PM
Schedule Start	11/11/2020 9:00 AM
Schedule Finish	11/11/2020 10:00 AM
Actual Start	11/11/2020 7:00 AM
Actual Finish	11/11/2020 8:00 AM
Estimated Duration (hrs)	1.00

Additional Info

Responsible Officer	Vivien McLeary
Reference Number	201028-001777
External Id	9714582
Work Order Source	Public Enquiry










Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

WR5883 : Linked Work Order WO27710 has been assessed.
Last updated by Vivien Mcleary 11/11/2020 10:39:19 AM
WR5883 : CRM Reference : 201028-001777


Initial enquiry info only. See CRM for additional correspondence.
Defect location info may be incorrect (address validation limitations).

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
  0  		10 	items per page	No items to display 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	PM Gungahlin Operations	Mowing	Hours (\$)	1	1	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Resources


Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Mowing	<div style="background-color: black; width: 100px; height: 15px;"></div>	1	11/11/2020

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
--------------	-------------	----------	--------------------	-----------------------	------------------	--------------	-----------------	-------------

◀ ◁ 0 ▷ ▶ 10 items per page

No items to display 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
--------------	--------	----------	---------	----------	----------	------	---------	---------	---------	---------	--------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Attachments



20201028_114329

Order Details	
Work Type	CM - Corrective
ID	WO38104
Creation Time	15/04/2021 4:46 PM
Requester	Garry George
Creator	Garry George
Brief Description	Relay pavers & tactiles between tree & and rock GungHlin Pl opposite Crust Pizza
Reference Work Order	
Work Request ID	

















Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	ENV,ENV-01, Environmental, Weather
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	12/10/2021 7:46 AM	 
Target Start	15/04/2021 4:46 PM	 
Target Finish	12/10/2021 5:46 PM	 
Schedule Start	15/04/2021 4:46 PM	 
Schedule Finish	12/10/2021 5:46 PM	 
Actual Start	14/04/2021 10:50 AM	 
Actual Finish	7/06/2021 8:42 AM	 
Estimated Duration (hrs)	1.00	 

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

External Id

Work Order Source

Public Enquiry ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.




Relay pavers opposite Crust


Last updated by Garry George 15/04/2021 4:50:32 PM

Relay pavers Gungahlin PI opposite Crust

Last updated by Garry George 15/04/2021 4:49:34 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Relay pavers

◀ ◁ 1 ▷ ▶ 10 items per page 1 - 1 of 1 items 

Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Paver Contractor	Hours (\$)	1	0	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Paver Contractor	AN ENVIRONMENTAL DESIGN PTY LTD	0	07/06/2021

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
No items to display 								

◀ ◁ 0 ▷ ▶ 10 items per page

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
	Relay			Each		\$1,540.00			\$1,540.00	BRRL	

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items

Attachments



WO38104(AFTER COMPLETION)



MAY_16_2021



APR_23_2021



APR_15_2021

Defect Location



Location Description

Shop B Gungahlin Place West, Gungahlin ACT 2912, Australia

Cost

Total Planned Cost

1540

Total Actual Cost

1540

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO45663
Creation Time	3/11/2021 3:51 PM
Requester	Garry George
Creator	Garry George
Brief Description	Relay pavers Gungahlin PI median between NRMA & Grilld restaurant 64m
Reference Work Order	
Work Request ID	

Asset Details

Asset ID	PAVE3013
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DMG,DMG-01, Damaged, Damaged
Cause Code	UNK,UNK-01, Unknown Cause, Unknown Cause
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation	
WO Priority	5
SLA Due Date	2/05/2022 3:51 AM
Target Start	3/11/2021 3:51 PM
Target Finish	2/05/2022 2:51 PM
Schedule Start	28/02/2022 12:00 AM
Schedule Finish	28/02/2022 12:00 AM
Actual Start	2/03/2022 7:00 PM
Actual Finish	4/03/2022 11:00 AM
Estimated Duration (hrs)	7.00

Additional Info

Responsible Officer

Reference Number

External Id

Work Order Source

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.

Work is satisfactory.

Last updated by Prakhar Srivastava 30/03/2022 3:49:27 PM




Relay pavers


Last updated by Garry George 3/11/2021 3:55:54 PM

Relay pavers centre Gungahlin opposite NRMA 64m

Last updated by Garry George 3/11/2021 3:54:46 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Relay pavers


◀ ◁ 1 ▷ ▶ 10 items per page 1 - 1 of 1 items 


Labour

Work Task Id	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Paver Contractor	Hours (\$)	1	7	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Resources

Work Task Id	Status Id	Craft	Resource	Actual Hours	Completion Date
	Completed	Paver Contractor	ARIS Building Services Pty Ltd 	24	04/03/2022

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items 

Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
--------------	-------------	----------	--------------------	-----------------------	------------------	--------------	-----------------	-------------

◀ ◁ 0 ▷ ▶ 10 items per page No items to display 

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
	Relay Pavers			Square Centimetre		\$7,040.00	0		\$0.00	RP13	

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Attachments



NOV_03_2021



MAR_25_2022



MAR_25_2022



MAR_11_2022



MAR_11_2022



MAR_11_2022



MAR_11_2022



IMAGE004



IMAGE003



IMAGE002



7D698236-08F2-4C1F-907E-1C945B7AA2A4



79E80D9E-9381-4693-A153-E088049BA3AB

Defect Location



Location Description

107 Gungahlin Pl, Gungahlin ACT 2912, Australia

Cost

Total Planned Cost

7040

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)

Order Details	
Work Type	CM - Corrective
ID	WO52308
Creation Time	14/04/2022 12:32 PM
Requester	Garry George
Creator	Garry George
Brief Description	Relay pavers Gungahlin PI between Andrew Leigh office & maths tutors. 4sm.
Reference Work Order	
Work Request ID	

Asset Details

Asset ID	PAVE3014
Asset Name	GUNGAHLIN CENTRAL LINEAR PARK PAVERS OR CONCRETE BLOCKS FOOTPATH
Asset Category	Hard Surfaces
Maintenance Asset Type	Hard Surface
Maintenance Asset Sub Type	Pavers
Work Group	Concrete - RM
Asset Criticality	Medium

Categorisation

Budget Type	OPEX
Failure Code	DSP,DSP-01, Displaced, Displaced
Cause Code	WER,WER-01, Wear, General Wear
Remedy Code	REL, Relay
Loss Of Service Required	<input type="checkbox"/>

Prioritisation

WO Priority	5	
SLA Due Date	11/10/2022 1:32 PM	
Target Start	14/04/2022 12:32 PM	
Target Finish	11/10/2022 1:32 PM	
Schedule Start		
Schedule Finish		
Actual Start		
Actual Finish		
Estimated Duration (hrs)	2.00	

Additional Info

Responsible Officer

Please type to search for Responsible Officer (Optional) ▼

Reference Number

External Id

Work Order Source

Routine Inspection ▼

Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.




Relay pavers Gungahlin. PI Leigh office to maths tutor.


Last updated by Garry George 14/04/2022 12:35:56 PM

Relay pavers Gungahlin. PI between Leigh & maths tutor 4sm

Last updated by Garry George 14/04/2022 12:34:41 PM

4000 characters remaining

Tasks				
		Work Task Id  	Lowest Maintainable Item	Brief Description 
		10	Select item	Relay pavers

◀ ◁ 1 ▷ ▶ 10 ▼ items per page 1 - 1 of 1 items 

Labour

Work Task Id ↑	Work Group	Craft	Unit	Craft Quantity	Hours Required	Planned Cost	Actual Costs
	Concrete - RM	Paver Contractor	Hours (\$)	1	2	\$0.00	\$0.00

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items

Resources

Work Task Id ↑	Status Id	Craft	Resource	Actual Hours	Completion Date
	Unassigned	Paver Contractor	Unassigned		

◀ ◀ 1 ▶ ▶ 10 items per page 1 - 1 of 1 items


Materials

Work Task Id	Description	Material	Material Unit Type	Material Availability	Planned Quantity	Planned Cost	Actual Quantity	Actual Cost
No items to display 								

Services

Work Task Id	Des...	Servi...	Purc...	Unit ...	Unit ...	Cost	Actu...	Actu...	Actu...	Cost...	Gen...
	Relay Pavers	4		Square Centimetre			0		\$0.00	RP13	

◀ ◁ 1 ▷ ▶ 10 items per page

1 - 1 of 1 items 

Attachments




APR_14_2022



APR_14_2022

Defect Location



Location Description

125 Gungahlin Pl, Gungahlin ACT 2912, Australia

Cost

Total Planned Cost

4

Total Actual Cost

0

All Rights Reserved © 2022 by Brightly Software, Inc. | Privacy Policy | Release 2022.8.1 (ede84d5)





Work_Req est_ID	Work_Order_Pr iority	Work_Order _ID	WR_Status	WR_Defect_Location	WR_Brief_Description	WR_Reference_N umber	WR_Created_ Date	WR_Resolutio n_Due_Date	SUPPORTING_INFORMATION	LAST_MODIFI ED_DATE
WR20372	Urgent		ASSIGNED		Cycle & footpaths On road	210405-000225	5/04/2021	12/04/2021	<p>WR20372 : Oracle CRM Reference : 210405-000225</p> <p>Initial enquiry info only. See CRM for additional correspondence.</p> <p>Defect location info may be incorrect (address validation limitations).</p> <p>Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?:</p> <p>Between Coles and Big W buildings</p> <p>What is the issue?:</p> <p>Damage to path or other</p> <p>What is the damage?:</p> <p>Cracked, broken or uneven</p> <p>What is the material?:</p> <p>Brick or concrete pavers</p>	2022-04-13 15:37:37
WR20372 cont									<p>Could it cause a trip, fall or injury?:</p> <p>Yes</p> <p>Is it causing traffic or cyclists to swerve?:</p> <p>No</p> <p>Please provide more information:</p> <p>Raised square pavement between Coles and Big W building in Gungahlin.</p> <p>Paver near seat and walk way, closer to the Coles building.</p> <p>***Last updated by TCCS.ICX Integrations***5/04/2021 3:27:38 PM</p>	

Work_Req est_ID	Work_Order_Pr iority	Work_Order _ID	WR_Status	WR_Defect_Location	WR_Brief_Description	WR_Reference_N umber	WR_Created_ Date	WR_Resolutio n_Due_Date	SUPPORTING_INFORMATION	LAST_MODIFI ED_DATE
WR1082	Serious		CANCELLED	GUNGAHLIN PL EAST	Cycle & footpaths Shared p	200818-000245	18/08/2020	25/08/2020	<p>WR1082 : Work Request has been cancelled.No maintenance work required, pavers already been fixed, photos attached from the inspection. Thanks ***Last updated by Rama Khatri***26/03/2021 7:41:17 AM , WR1082 : No maintenance work required, pavers already been fixed, photos attached from the inspection. Thanks ***Last updated by Rama Khatri***26/03/2021 7:40:48 AM , WR1082 : CRM Reference : 200818-000245 Requester Contact Name: Initial enquiry info only. See CRM for additional correspondence. Defect location info may be incorrect (address validation limitations). Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: there are some uneven concrete pavers near way into lift towards BIGW car park behind SUBWAY store.</p>	2022-04-08 12:43:52
WR1082 cont									<p>What is the issue?: Damage to path or other What is the damage?: Cracked, broken or uneven What is the material?: Brick or concrete pavers Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?: Yes Please provide more information: there are some uneven concrete pavers near way into lift towards BIGW car park behind SUBWAY store.</p> <p>***Last updated by TCCS.ICX Integrations***18/08/2020 9:00:49 AM</p>	

Work_Req est_ID	Work_Order_Pr iority	Work_Order _ID	WR_Status	WR_Defect_Location	WR_Brief_Description	WR_Reference_N umber	WR_Created_ Date	WR_Resolutio n_Due_Date	SUPPORTING_INFORMATION	LAST_MODIFI ED_DATE
WR18227	Urgent	WO14154	RESOLVED	89 GUNGAHLIN PL, GUNGAHLIN AC	Cycle & footpaths; Shared p	210310-000937	10/03/2021	17/03/2021	<p>WR18227 : Oracle CRM Reference : 210310-000937 Requester Contact Name: anonymous anonymous</p> <p>Initial enquiry info only. See CRM for additional correspondence. Defect location info may be incorrect (address validation limitations).</p> <p>Cycle & footpaths Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Unknown/other</p>	2022-04-08 12:47:58
WR18227 cont									<p>Could it cause a trip, fall or injury?*</p> <p>Yes</p> <p>Is it causing traffic or cyclists to swerve?*</p> <p>No</p> <p>Please provide more information The tiles designed for blind people to know that there is a crossing with their canes. Ate the crossing in Gunhalin next to The light rail stop going towards GuzmYGomez, the tiles are loose and causing a trip hazard.</p> <p>***Last updated by TCCS.ICX Integrations***10/03/2021 12:03:45 PM</p>	

Applied filters:Suburb is GUNGAHLINWR_Created_Date is on or after 01/10/2016 00:00:00 and is before 02/02/2022 00:00:00WR_Defect_Location contains 'Gungahlin PI'

Request Details

Request ID	WR18227
Creation Time	10/03/2021 12:03 PM  
Created By	TCCS.ICX Integrations
Source	External CRM 
Any immediate risk?	Select Risk 
Work Order ID	<u>W014154</u>

Asset Details

Asset ID

PAVE2837



Asset Name

GUNGAHLIN TOWN CENTRE SHOP/BUILDING PAVEMENT

Asset Category

Hard Surfaces

Maintenance Asset Type

Hard Surface

Work Group

Concrete - RM

Asset Criticality

Medium

Requestor Details

Resource Name

anonymous anonymous



Firstname

Surname

Company

Requestor External ID

Preferred Method

None

Additional Info

Request Type

Responsible Officer

External ID

Reference #

Brief Description

193 characters remaining

Reactive Inspection

Reactive Inspector

Please type to search for Inspector (Optional)



Inspection Date



Request Priority

Work Order Priority

2



Acknowledgement Due Date

13/03/2021 12:03 PM



Resolution Due Date

17/03/2021



Supporting Information

Example; The main office front door is faulty as it has come away from the frame and requires replacement or repair by a service technician.


Oracle CRM Reference : 210310-000937

Requester Contact Name: anonymous anonymous

Initial enquiry info only. See CRM for additional correspondence.

Defect location info may be incorrect (address validation limitations).

Cycle & footpaths

4000 characters remaining 

Defect Location



Location Description

89 GUNGAHLIN PL, GUNGAHLIN ACT 2912

Attachments



◀ ◀ 0 ▶ ▶

No items to display



From: [REDACTED]
To: [Halgren, Luke](#)
Cc: [Moradi, Maryam](#)
Subject: Re: Segmental paving 017 Weekly Report
Date: Friday, 11 March 2022 3:51:44 PM
Attachments: [11th MARCH Weekly Report - Aris RA2021-0017.docx](#)
[PastedGraphic-1.png](#)

CAUTION: This email originated from outside of the ACT Government. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hi Luke,

See attached weekly report.

Kind regards,

[REDACTED]

Project Manager

Mob: [REDACTED]

[Email:](#) [REDACTED]



On 7 Mar 2022, at 11:42 am, [REDACTED] wrote:

Hi Luke,

See attached weekly report. Unable to complete any works during the week but Gungahlin work orders are underway.

2 week programme 7th-18th Feb 2022

Expected work orders complete by 18th:

WO45617

WO45619

WO49905

WO45663

WO49907

WO49913

WO45625

WO46921

Kind regards,

[REDACTED]

Project Manager

Mob: [REDACTED]

[Email:](#) [REDACTED]

<PastedGraphic-1.png>

<4th MARCH Weekly Report - Aris RA2021-0017.docx>

On 25 Feb 2022, at 3:18 pm, Reuben Lawler [REDACTED] wrote:

Hi Luke,

See attached weekly report.

Kind regards,

[REDACTED]

Project Manager



<PastedGraphic-1.png>
<25 FEB Weekly Report - Aris RA2021-0017.docx>

On 25 Feb 2022, at 11:40 am, Halgren, Luke <Luke.Halgren@act.gov.au> wrote:

OFFICIAL



Can you please submit the report a MS Word file.

Kind Regards
Luke Halgren

From: [Redacted]
Sent: Friday, 25 February 2022 8:17 AM
To: Halgren, Luke <Luke.Halgren@act.gov.au>
Cc: Moradi, Maryam <Maryam.Moradi@act.gov.au>
Subject: Segmental paving 017 Weekly Report

CAUTION: This email originated from outside of the ACT Government. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hi Luke,

Week ending 25th Feb 2022.

1	<u>WHS Issues</u> Nil
2	<u>Weekly Progress</u> 10m2 at Gungahlin Dobsinsons
3	<u>Contract Management - Delays</u> 3 rain days - 23,24,25 Feb 2022
4	<u>Contract Management - Variations</u> Nil
5	<u>Program</u> Gungahlin next week, now that we have access to work orders on desktop and mobile Asstic App, we are able to schedule works accordingly.
6	<u>Community Consultation</u> Gave dobinsons 1 days notice before attending urgent work order
7	<u>Other Items</u>

Kind regards,



Project Manager
Mob: [Redacted]



<image001.png>

This email, and any attachments, may be confidential and also privileged. If you are not the intended recipient, please notify the sender and delete all copies of this transmission along with any attachments immediately. You should not copy or use it for any purpose, nor disclose its contents to any other person.

Weekly Report

Segmental Paving Remediation (RA2021-0017)

Aris Building Solutions

Particulars	
Week Ending	11 th March 2022
Prepared by	
Attention	Luke Halgren

Item No.	Item
1	<u>WHS Issues</u> <ul style="list-style-type: none">• Nil
2	<u>Weekly Progress</u> <ul style="list-style-type: none">• WO45619, WO46912, WO45663, WO49913, WO45617 TOTAL M2 126
3	<u>Contract Management - Delays</u> <ul style="list-style-type: none">• Rain day Tuesday 8th March
4	<u>Contract Management - Variations</u> <ul style="list-style-type: none">• Increase in qty for WO45663 from 64m2 to 100m2, inspected by Prakhar and approved by Luke Halgren.
5	<u>Program</u> <ul style="list-style-type: none">• Gungahlin park, hinder st Gungahlin.
6	<u>Community Consultation</u> <ul style="list-style-type: none">•
7	<u>Other Items</u>

From: [Srivastava, Prakhar](#)
To: [Halgren, Luke](#)
Subject: Re: Invoice - TCCS Remediation Paving - Contract 2021-0017
Date: Wednesday, 30 March 2022 4:08:29 PM
Attachments: [image001.jpg](#)

OFFICIAL

Hello Luke,

I have assessed the work order mentioned in invoice from Aris for segmental paving. The work done by Aris are satisfactory and acceptable. Please let me know if there is additional information needed.

Kind Regards,
Prakhar Srivastava

From: Halgren, Luke <Luke.Halgren@act.gov.au>
Sent: 30 March 2022 08:13
To: Srivastava, Prakhar <Prakhar.Srivastava@act.gov.au>
Subject: FW: Invoice - TCCS Remediation Paving - Contract 2021-0017

OFFICIAL

Good Morning Prakhar

Can you please undertake an audit of the attached invoice from Aris for segmental paving. If you are satisfied the works are done, can you please update the Work Orders to complete.

Kind Regards

Luke Halgren | Asset Officer – Program Delivery, Road Maintenance
Mobile: [REDACTED] Email: luke.halgren@act.gov.au
Roads ACT | Transport Canberra and City Services Directorate | ACT Government
255 Canberra Avenue Fyshwick | PO Box 777 Fyshwick ACT 2609 | www.act.gov.au

From: Aris Contact <contact@arisbuilding.com.au>
Sent: Tuesday, 29 March 2022 11:43 AM
To: Halgren, Luke <Luke.Halgren@act.gov.au>
Subject: Invoice - TCCS Remediation Paving - Contract 2021-0017
Importance: High

CAUTION: This email originated from outside of the ACT Government. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hi Luke,

Attached is an invoice for Contract 2021-0017 from Aris Building Services.

Please don't hesitate to contact me for any further information or changes required if necessary.

Have a great day!

██████████
Administration Manager
Aris Building Services
██████████



83 Kendall Ave, Queanbeyan NSW 2620

Email: contact@arisbuilding.com.au
Office: 02 6299 6299

A.B.N. 70 063 338 456

A.C.N.

ACT Builders Licence 2008465



TAX INVOICE

Invoice No.: 00000449

Date: 29/03/2022

Bill To:

TCCS - Transport Canb City Services
255 Canberra Avenue
Fyshwick ACT 2609

CONTACT: Luke Halaren

RELATED W/O #: Contract RA No. 2021-0017

DESCRIPTION	AMOUNT
TCCS - Remediation Paving Repairs	
Chisholm- Comm Centre path to Coles Work Order No.50454 Quantity- [REDACTED]	
City Renewal- Cycle & Footpaths shared path Work Order No.37785 Quantity - [REDACTED]	
City Walk - Dosa Hut Abundant St Work Order No.47471 Quantity - [REDACTED]	
City Walk - Side of Tree @Ivan's Work Order No.47480 Quantity - [REDACTED]	
City Walk-@T2 Tea Entrance Canberra Centre Work Order No.47482 Quantity - [REDACTED]	
City Walk- DJ's Entrance near tree Work Order No.47483 Quantity - [REDACTED]	
Childers St - Court Entry Ramp Court Building Work Order No.49351 Quantity [REDACTED]	
Childers St- Childers St to New Acton Commwth Court Bridge Work Order No.49353 Quantity [REDACTED]	
City -Adjacent Nigel Brown Building Entry to University Ave Work Order No.49361 Quantity [REDACTED]	
	GST:

Total Inc GST:

83 Kendall Ave, Queanbeyan NSW 2620

Email: contact@arisbuilding.com.au
Office: 02 6299 6299

A.B.N. 70 063 338 456

A.C.N.

ACT Builders Licence 2008465



TAX INVOICE

Invoice No.: 00000449

Date: 29/03/2022

Bill To:

TCCS - Transport Canb City Services
255 Canberra Avenue
Fyshwick ACT 2609

CONTACT: Luke Halaren

RELATED W/O #: Contract RA No. 2021-0017

DESCRIPTION	AMOUNT
Gungahlin- Crm Ernst Cavangh @ Continental Groceries Work Order No.45617 Quantity: [REDACTED]	[REDACTED]
Gungahlin - Near Ernst Cavanagh @ Onson Massage Work Order No.45619 Quantity: [REDACTED]	[REDACTED]
Gungahlin- Entry Gate 12 Maria Smith Lane Work Order No.45625 Quantity: [REDACTED]	[REDACTED]
Gungahlin- Between NRMA & Grilld Work Order No.45663 Quantity: [REDACTED]	[REDACTED]
Gungahlin- @ Dobbinsons Bakery Work Order No.46919 Quantity: [REDACTED]	[REDACTED]
Gungahlin- Gungahlin Place Work Order No.46921 Quantity: [REDACTED]	[REDACTED]
Gungahlin- Near Dobbinsons Cafe Lagos End Work Order No.49905 Quantity: [REDACTED]	[REDACTED]
Gungahlin - Ernst Cavanagh St in Front of Carpark Work Order No. 49907 Quantity: [REDACTED]	[REDACTED]
Gungahlin - Hinders St near Laverty Pathology Work Order No.49913 Quantity: [REDACTED]	[REDACTED]
GST:	[REDACTED]

Total Inc GST: \$37,300.00

From: [Moradi, Maryam](#)
To: [TCCS_RA RMAdmin](#)
Cc: [Halgren, Luke](#)
Subject: FW: Aris Invoice #449
Date: Monday, 4 April 2022 9:43:38 AM
Attachments: [00000449.pdf.pdf](#)

OFFICIAL

Approved under my financial delegation

Maryam Moradi | Assistant Director – Program Delivery, Road Maintenance(P29018)

Mobile: [REDACTED] | Email: maryam.moradi@act.gov.au

Roads ACT | Transport Canberra and City Services Directorate | ACT Government

255 Canberra Avenue Fyshwick | PO Box 777 Fyshwick ACT 2609 | www.act.gov.au

From: Halgren, Luke <Luke.Halgren@act.gov.au>
Sent: Monday, 4 April 2022 8:35 AM
To: Moradi, Maryam <Maryam.Moradi@act.gov.au>
Subject: Aris Invoice #449

OFFICIAL

Good Morning

I can confirm goods/services had been received for the attached invoice(s). Please approve under your financial delegation.

Goods / Services described on invoice (mandatory field)		Segmental paving rectification works, under contract RA/2021-0017									
Received Date (mandatory field)		29/03/2022									
Supplier Name: Invoice Number: (mandatory field)		Aris Building Services - 449									
Purchase Order Number		CLD14337									
are in satisfactory condition and the invoice has been rendered in accordance with the contract rates and conditions.											
I am sending this invoice for approval by the financial delegate.											
BU	Cost Centre	Account	IT	Project	Program	Spare	Oracle Project code	Task	Production output	Amount (including GST)	Notes
										\$37,300.00	For all contract works up to 28/03/2022

Kind Regards

Luke Halgren | Asset Officer – Program Delivery, Road Maintenance

Mobile: [REDACTED] | Email: luke.halgren@act.gov.au

Roads ACT | Transport Canberra and City Services Directorate | ACT Government

255 Canberra Avenue Fyshwick | PO Box 777 Fyshwick ACT 2609 | www.act.gov.au



an
environmental
design (Aust) P/L

[Redacted]

Ph: [Redacted]

GPO Box 796

Canberra ACT 2601

Lic B #200313328

DATE: 31/05/2021

INVOICE H0101

TAX INVOICE

RA/2019-025 NORTH

Purchase Order : **Z7022489**

Attention: Mr Garry George
Transport Canberra and City Services Directorate
255 Canberra Avenue ACT

Temporary Traffic Management Plan Card No: 0041802054

Location : Various

Work Description : Relay Pavers /Tactiles

Tactile Defects:

[Redacted]
[Redacted]
[Redacted]
[Redacted]
[Redacted]
WO38104 GunghPl(28. 0m²); WO1118 Gung Twn(15. 0m²) WO38103 GungTwn Sq(28. 0m²)

[Redacted]

GST

\$ 11,055. 00

\$ 1,105. 50

Gross Total

\$ 12,160. 50

Yours Sincerely,

[Redacted]

From: [Halgren, Luke](#)
To: [REDACTED]
Cc: [Srivastava, Prakhar](#)
Subject: RE: Variation
Date: Tuesday, 8 March 2022 8:31:00 AM
Attachments: [image001.png](#)
[image002.jpg](#)
[image003.jpg](#)
[image004.jpg](#)

OFFICIAL

Good Morning

The additional works in the below variation are approved.

Kind Regards

Luke Halgren | Asset Officer – Program Delivery, Road Maintenance
Mobile [REDACTED] | Email: luke.halgren@act.gov.au
Roads ACT | Transport Canberra and City Services Directorate | ACT Government
255 Canberra Avenue Fyshwick | PO Box 777 Fyshwick ACT 2609 | www.act.gov.au

From: [REDACTED]
Sent: Monday, 7 March 2022 11:55 AM
To: Halgren, Luke <Luke.Halgren@act.gov.au>
Cc: Srivastava, Prakhar <Prakhar.Srivastava@act.gov.au>
Subject: Variation

CAUTION: This email originated from outside of the ACT Government. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hi Luke,

Please see attached images, we have estimated a total m2 for WO45663 is [REDACTED] up from [REDACTED] as stated on work order. Prakhar has been to site to inspect.

Kind regards,

[REDACTED]

Project Manager

Mob [REDACTED]


Email: [REDACTED]




70m2 seen in this image.



15m2







Medical Gungahlin

MatchWorks

Gungahlin Montessori Academy Child Care...

Embrace Orthodontists Gungahlin

Capital Pathology Gungahlin - Hinder S

Hibberson St

Hibberson St

Hibberson St

4

Lavery Pathology

2

3

Gungahlin Place

2

Anytime Fitness

Gungahlin Skin Clinic

My GP Gungahlin

Gungahlin Pl

Gungahlin Pl

Gungahlin Pl

Gungahlin Place Playground

Office of Andrew Leigh MP

Anytime Fitness

Efkarpidis St

Efkarpidis St

Efkarpidis St

Efkarpidis St

Hinder St

