



ACT
Government

Transport Canberra and
City Services

FREEDOM OF INFORMATION COVERSHEET

The following information is provided pursuant to section 28 of the *Freedom of Information Act 2016*.

FOI reference: TCCSFOI 20-096

Information to be published	Status
1. Access application	Published
2. Decision notice and schedule	Published
3. Documents	Published
4. Additional information identified	n/a
5. Fees	Waived
6. Processing time (in working days)	30 days
7. Decision made by Ombudsman	n/a
8. Additional information identified by Ombudsman	n/a
9. Decision made by ACAT	n/a
10. Additional information identified by ACAT	n/a

From: [REDACTED]@gmail.com
To: [TCCS_FreedomOfInformation](#)
Subject: FOI request - Theodore Shops Playground
Date: Sunday, 20 December 2020 7:20:20 PM
Attachments: [Freedom_of_Information_Access_Application_Form.docx](#)

CAUTION: This email originated from outside of the ACT Government. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Hello,

Please find my completed FOI request form attached for documents relating to the Theodore Shops Playground. Please let me know if you require any further information.

Regards,

[REDACTED]

[REDACTED]



ACT
Government

Transport Canberra
and City Services

Freedom of Information – Access Application Form

Privacy notice

The personal information you supply on this form will only be used for the purpose of processing your request. Your application must include an email or postal address to which the respondent can send notices under the *Freedom of Information Act 2016* (the Act). If all or some of this information is not collected, Transport Canberra and City Services may not be able to communicate with you, inhibiting their obligations under the Act. This could mean the request cannot be dealt with. Your personal information will not be disclosed to a third party without your consent unless statutory obligations require otherwise.

The Transport Canberra and City Services Privacy Policy contains information on how you can access or seek to correct any of your personal information that is held by the Transport Canberra and City Services, as well as the process for lodging a complaint about an alleged breach of the *Information Privacy Act 2014*. The Privacy Policy can be found at www.cityservices.act.gov.au.

Applicant details

I wish to make an access application to Transport Canberra and City Services under the *Freedom of Information Act 2016*.

Name	[REDACTED]
Address (where notices relating to this request can be sent – either postal or electronic)	[REDACTED]@gmail.com
Telephone (Business hours)	[REDACTED]
Telephone (Mobile)	[REDACTED]
Email	[REDACTED]@gmail.com

What documents are you requesting under the Act?

Documents relating to maintenance checks or safety inspections of the 'Theodore Shops Playground' (corner of Lawrence Wackett Crescent and Chippindall Circuit, Theodore), specifically: the date of inspection; type of inspection (level 1, level 2 or level 3); what faults or problems were recorded (if any); and what action or repairs were taken (if any).

I am seeking documents from 1 October 2019 to 30 November 2020 (inclusive).

These documents are in the public interest as the ACT Government endeavours to achieve the Australian Playground Standards and the above documents will provide evidence of whether City Services is meeting the recommended minimum standards.

Fee waver


If you wish to apply for a fee waiver, the Act sets out a number of provisions to do so:

- The information being requested was previously publicly available but no longer is.
- The information being requested is of special benefit to the public (Ombudsman guidelines see Section 66).
- The applicant is a concession card holder and demonstrates a material connection with the information requested (concession cards include a current health care or pensioner card issued under the [Social Security Act 1991](#); a current pensioner concession card issued in relation to a pension under the [Veterans' Entitlements Act 1986](#) or [the Military Rehabilitation and Compensation Act 2004](#); a current gold card; or a card prescribed by regulation).
- The applicant is a not-for-profit organisation and the application relates to the activities or purposes of the organisation.
- The applicant is a member of the Legislative Assembly.

Transport Canberra and City Services must waive any fees for providing information if the information was not publicly available and the agency makes the information publicly available before or within 3 working days after giving it to the applicant.

To apply for a fee waver please complete the following.

I would like to apply for a fee waiver because (state reason/s from the list above). [provide details and evidence of how this reason applies]	
I would like	a copy of these documents sent to the above address

Applicant's signature	Date of request
	20 December 2020



ACT
Government

Transport Canberra and
City Services

Ms [REDACTED]
By email: [REDACTED] gmail.com

Dear [REDACTED]

Freedom of Information Request - Reference 20-096

I refer to your application for access to government information received by Transport Canberra and City Services (TCCS) on 21 December 2020 under the *Freedom of Information Act 2016* (FOI Act). It is my understanding you are seeking to access the following government information:

“Documents relating to maintenance checks or safety inspections of the ‘Theodore Shops Playground’ (corner of Lawrence Wackett Crescent and Chippindall Circuit, Theodore), specifically: the date of inspection; type of inspection (level 1, level 2 or level 3); what faults or problems were recorded (if any); and what action or repairs were taken (if any). I am seeking documents from 1 October 2019 to 30 November 2020 (inclusive).”

I am an Information Officer appointed by the Director-General under section 18 of the Act to deal with access applications made under Part 5 of the FOI Act.

Thank you for agreeing to an extension of time to decide on your access application. A decision is due by agreement on 5 February 2021.

Decision on access

A search of records held by TCCS has been completed and 24 records (242 pages) have been identified as relevant to your request.

In accordance with section 17 of the Act, I have considered the public interest in relation to information within the records identified as relevant to your access application. In this instance, I have not identified any factors favouring non-disclosure, and therefore have decided to release the information to you in full. My decision is detailed further in the following statement of reasons.

As several of the records are inclusive of inspections undertaken at other playgrounds, the document at Attachment B has been bookmarked to improve the ease of locating Theodore shops playground inspection information.

Statement of Reasons

In making my decision on disclosing government information, I must identify all relevant factors in schedule 2 of the FOI Act and determine, on balance, where the public interest lies. In reaching my access decision, I have taken the following into account:

Factors favouring disclosure in the public interest (Schedule 2.1)

- Schedule 2.1(a)(i) - promote open discussion of public affairs and enhance the government's accountability;
- Schedule 2.1(a)(iii) - inform the community of the government's operations, including the policies, guidelines and codes of conduct followed by the government in its dealings with members of the community;
- Schedule 2.1(a) (xi) - reveal environmental or health risks or measures relating to public health and safety; and
- Schedule 2.1(a)(viii) - reveal the reason for a government decision and any background or contextual information that informed the decision.

Factors favouring non-disclosure (Schedule 2.2)

- No factors favouring non-disclosure were identified as relevant to this application.

I have considered the public interest in relation to information about the ACT Government's operations pertaining to the maintenance of suburban playgrounds and find that the disclosure of the information enclosed with this notice is in the public interest to disclose in full.

Charges

The *Freedom of Information (Fees) Determination 2018* contains provisions for \$0.35 per page over 50 pages to be applied to documents being released under the FOI Act. In this instance, I have decided to waive the fee of \$67.20.

Disclosure Log

In accordance with section 28 of the Act, TCCS maintains an online record of access applications called a disclosure log, which is accessible at https://www.cityservices.act.gov.au/about-us/freedom_of_information/disclosure-log.

Your access application, this notice of decision and records released to you will be published on the disclosure log within 3 – 10 business days. Your personal information will be removed from these documents prior to publication.

Ombudsman review

My decision on your access application is a reviewable decision as identified in Schedule 3 of the Act. You have the right to seek an Ombudsman review my decision under section 73 of the Act within 20 working days from the day that my decision is made or a longer period if allowed by the Ombudsman.

If you wish to request a review of my decision, you may write to the Ombudsman at:

The ACT Ombudsman
GPO Box 442
CANBERRA ACT 2601
Via email: actfoi@ombudsman.gov.au

ACT Civil and Administrative Tribunal (ACAT) review

Under section 84 of the Act, if a decision is made under section 82(1) on an Ombudsman review, you may apply to the ACAT for review of the Ombudsman decision.

Further information may be obtained from ACAT at:

ACT Civil and Administrative Tribunal
Level 4, 1 Moore Street
GPO Box 370
CANBERRA CITY ACT 2601
Telephone: (02) 6207 1740
www.acat.act.gov.au

If you have any queries about the directorate's processing of your request, or would like further information, please contact the TCCS FOI team on (02) 6207 2987 or email tccs.foi@act.gov.au.

Yours sincerely



Cherie Hughes
Information Officer

5 February 2021

FREEDOM OF INFORMATION REQUEST SCHEDULE

Please be aware that under the *Freedom of Information Act 2016*, some of the information provided to you will be released to the public through the ACT Government's Open Access Scheme. The Open Access release status column of the table below indicates what documents are intended for release online through open access.

Personal information or business affairs information will not be made available under this policy. If you think the content of your request would contain such information, please inform the contact officer immediately.

Information about what is published on open access is available online at www.tccs.act.gov.au/about-us/freedom_of_information

File No			WHAT ARE THE PARAMETERS OF THE REQUEST			
20-096			Theodore Shops Playground			
Record Number	Page Number	Description	Date	Status	Reason for non-release or deferral	Open Access release status
1	1 - 15	201909 - Tuggeranong Playground Inspection Report <i>Note: see page 3</i>	Various, September 2019	Full access	N/A	Documents will be published on the TCCS Disclosure Log
2	16 - 31	201910 - Tuggeranong Playground Inspection Report <i>Note: see page 18</i>	Various, October 2019	Full access	N/A	
3	32	20191008 - Tuggeranong Playground Inspection Report (Level 2)	8 October 2019	Full access	N/A	
4	33 - 48	201911 - Tuggeranong Playground Inspection Report <i>Note: see page 35</i>	Various, November 2019	Full access	N/A	

5	49	20191106 - Repair - Theodore - Chippindall Circ	6 November 2019	Full access	N/A
6	50	20191125 - Tuggeranong Playground Inspection Report (Level 2)	25 November 2019	Full access	N/A
7	51 - 66	201912 - Tuggeranong Playground Inspection Report <i>Note: see page 53</i>	Various, December 2019	Full access	N/A
8	67 - 73	2020 Playground Inventory Report	April 2020	Full access	N/A
9	74 - 90	202001 - Tuggeranong Playground Inspection Report <i>Note: see page 76</i>	Various, January 2020	Full access	N/A
10	91 - 106	202002 - Tuggeranong Playground Inspection Report <i>Note: see page 93</i>	Various, February 2020	Full access	N/A
11	107 - 122	202003 - Tuggeranong Playground Inspection Report <i>Note: see page 109</i>	Various, March 2020	Full access	N/A
12	123	20200323 - Tuggeranong Playground Inspection Report (Level 2)	23 March 2020	Full access	N/A
13	124 - 139	202004 - Tuggeranong Playground Inspection Report <i>Note: see page 126</i>	Various, April 2020	Full access	N/A

14	140 - 155	202005 - Tuggeranong Playground Inspection Report <i>Note: see page 142</i>	Various, May 2020	Full access	N/A
15	156	20200525 - Tuggeranong Playground Inspection Report (Level 2)	25 May 2020	Full access	N/A
16	157 - 172	202006 - Tuggeranong Playground Inspection Report <i>Note: see page 159</i>	Various, June 2020	Full access	N/A
17	173 - 188	202007 - Tuggeranong Playground Inspection Report <i>Note: see page 174</i>	July 2020	Full access	N/A
18	189	20200720 - Tuggeranong Playground Inspection Report (Level 2)	20 July 2020	Full access	N/A
19	190	20200724 - Repair - Theodore - Chippindall Circ	24 July 2020	Full access	N/A
20	191 - 205	202008 - Tuggeranong Playground Inspection Report <i>Note: see page 192</i>	Various, August 2020	Full access	N/A
21	206	20200817 - Tuggeranong Playground Inspection Report (Level 2)	17 August 2020	Full access	N/A
22	207 - 221	202010 - Tuggeranong Playground Inspection Report	October 2020	Full access	N/A

		<i>Note: see page 208</i>				
23	222 - 241	202011 - Tuggeranong Playground Inspection Report <i>Note: see page 223</i>	November 2020	Full access	N/A	
24	242	20201116 - Tuggeranong Playground Inspection Report (Level 2)	16 November 2020	Full access	N/A	
Total records: 24 (242 pages)						



Name Of Inspector **James** Month of Inspection **May-20**

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report									
				Level 1 or Level 2			/	x	/	x	/	x	/	x	/	x	/	x			Hazard	Action							
1	BANKS PLGR 413	Pocket Ave		1	10:29	04-May	/		/		/				X	X	Loose slide leg	Monitor											
				1	10:32	11-May	/		/		/				X	X	Chain net links/mounts worn	Monitor / Needs Repair LAZ											
				1	10:37	18-May	/		/		/				X	X													
				2	10:30	25-May	/		/		/				X	X	Border concrete cracking / lifting	Needs Repair PCL											
				1			/		/		/				X	X	Small plastic slide damaged	Monitor											
2	BONYTHON PLGR 535	Burgoyne St					/		/		/						Titer toters arms missing	Removed until further notice - PCL											
				1	9:37	04-May	/		/		/					X	Ropes worn on climb net	Monitor											
				1	9:30	11-May	/		/		/					X	Swing mounts worn	Monitor											
				1	9:40	18-May	/		/		/					X	Graffiti on fire truck	Needs Removal PCL											
				2	9:34	25-May	/		/		/					X	Collar pins worn	Monitor											
3	FADDEN PLGR 228	Coyne St		1			/		/		/					X	X	Ropes worn on small single swing	Monitor										
				1	11:40	04-May	/		/		/					X	X	Black rubber mount points melting	Monitor										
				1	11:37	11-May	/		/		/					X	X	Swing mounts worn	Monitor										
				1	11:26	18-May	/		/		/					X	X	Cracked welds on slide entry	Monitor										
				2	11:32	25-May	/		/		/					X	X	Worn links bridge/climb chains	Monitor										
4	GORDON PLGR 278	McGillvray Circ		1			/		/		/							X	X	Timber split on panels	Monitor								
				1	9:55	01-May	/		/		/								X	X	Border logs splitting	Monitor							
				1	10:00	04-May	/		/		/								X	X	Holes in softfall / splitting	Needs repair - PCL							
				1	12:25	08-May	/		/		/									X	X	Footpath lifting	Needs repair - PCL						
				1	10:06	11-May	/		/		/									X	X	Slide footing loose	Monitor						
				1	8:25	15-May	/		/		/									X	X	Spinning seesaw hanger has worn mount/handle	Monitor						
				1	10:10	18-May	/		/		/									X	X	Hose splitting on chain covers	Monitor						
				1	8:07	22-May	/		/		/									X	X	Movement in brackets on web towers	Monitor						
				2	9:47	25-May	/		/		/									X	X	Fibreglass on tea cup spinner cracking	Monitor						
				1	11:00	29-May	/		/		/									X	X	Swing mounts worn x 2	Needs Repair - J&E						
							/		/		/										X	X	Damaged see-saw brackets x 3	Needs Repair - J&E					
							/		/		/										X	X	Rope climb net worn 80%	Needs Repair - J&E					
							/		/		/										X	X	Spinner top bearings loose	Monitor					
							/		/		/										X	X	Damaged super nova	Monitor					
							/		/		/										X	X	Border logs splitting	Monitor					
			/		/		/										X	X	Roman triangles worn links	Needs repair - LAZ									
			/		/		/										X	X	Wire walk cable worn	Monitor									
5	GOWRIE PLGR 328	Jeffries St					/		/		/									X	X	Decking worn on tower	Monitor						
				1	12:08	04-May	/		/		/											X	X	Wire bridge mount worn/chain low links worn	Needs repair - LAZ				
				1	11:54	11-May	/		/		/												X	X	Cracked welds in tower/rust	Needs repair - LAZ			
				1	11:48	18-May	/		/		/												X	X	Rubber Soft fall splitting/holes	Needs repair - PCL			
				2	11:50	25-May	/		/		/												X	X	Swing chains/brackets/mounts	Monitor			
			/		/		/															X	X	bench below tea cup playground coming out of footing	Needs repair - PCL				
			/		/		/																X	X	Hole in shade sail	Monitor			
			/		/		/																	X	X	Softfall splitting / holes forming	Needs Repair PCL		
			/		/		/																		X	X	Timber worn on carousel	Monitor	
			/		/		/																			X	X	Spider net worn	Monitor



Name Of Inspector: James Month of Inspection: May-20

	Suburb	Street	Level 1/2	Time	Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard	Action	
						/	x	/	x	/	x	/	x	/	x	/	x			
6	GREENWAY PLGR 242	Anketell St	1			/		/		/		/		/			X			
			1	9:24	01-May	/		/		/		/		X		X	Border sleepers missing and rotten	Needs Repair - PCL		
			1	9:02	04-May	/		/		/		/		X		X	Swings removed for repair	J&E - 8/05/20		
			1	12:00	08-May	/		/		/		/		X		X	Swing brackets/mounts worn	Needs Repair - J&E		
			1	8:58	11-May	/		/		/		/		X		X	Digger bucket has a hole	Needs Repair - LAZ		
			1	7:55	15-May	/		/		/		/		X		X	Worn ropes on bridge	Monitor		
			1	8:45	18-May	/		/		/		/		X		X	Worn balance rope	Monitor		
			1	7:43	22-May	/		/		/		/		X		X	Tyre swing mounts worn/crossbar movement in sleeve/s hooks	Monitor		
			2	8:26	25-May	/		/		/		/		X		X	Log steps/posts splitting on tower	Monitor		
7	GREENWAY PLGR 240	De Little Circ PLAR 286	1	12:47	04-May	/		/		/		/			X	Spider net worn	Monitor			
			1	12:30	11-May	/		/		/		/			X	Handle rubber split on Spring Carousel	Monitor			
			1	12:25	18-May	/		/		/		/			X	Graffiti on post	Remove - PCL			
			2	12:23	25-May	/		/		/		/			X	Spring boat loose footings	Monitor			
			1			/		/		/		/			X	Holes in softfall	Needs repair - PCL			
8	GREENWAY PLGR 417	Eileen Good St	1	9:18	04-May	/		/		/		/		X	X	Swing seat/bracket/links worn	Monitor			
			1	9:10	11-May	/		/		/		/		X	X	Bark low	Needs Top up - PCL			
			1	9:00	18-May	/		/		/		/		X	X	Border logs splitting	Monitor			
			2	8:55	25-May	/		/		/		/		X	X	Baby seat worn	Monitor			
			1			/		/		/		/		X	X	Fort/seesaw timber splitting	Monitor			
9	GREENWAY PLGR 240	Florence Taylor St PLAR 288	1	8:50	04-May	/		/		/		/		X	X	Decking worn	Monitor			
			1	8:45	11-May	/		/		/		/		X	X	Bark low	Needs Top up - PCL			
			1	8:32	18-May	/		/		/		/		X	X	Concrete border lifting	Monitor			
			2	8:17	25-May	/		/		/		/		X	X	Crack in slide plastic	Monitor			
			1			/		/		/		/		X	X					
124	GREENWAY PLGR	Limburg Way	1	9:28	04-May	/		/		/		/			X	Timber decking splitting	Monitor			
			1	9:19	11-May	/		/		/		/			X	Climb wall timber splitting	Monitor			
			1	9:12	18-May	/		/		/		/			X	Swing seat brackets worn	Monitor			
			2	9:08	25-May	/		/		/		/			X					
			1			/		/		/		/			X					
10	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	1	12:36	04-May	/		/		/		/		X	X	Bark low	Needs Top up - PCL			
			1	12:40	11-May	/		/		/		/		X	X	Decks rusted/plastic worn	Monitor			
			1	12:36	18-May	/		/		/		/		X	X	Bridge plastic worn	Monitor			
			2	12:34	25-May	/		/		/		/		X	X	Swing seat/brackets/mounts/s-hooks worn	Monitor			
			1			/		/		/		/		X	X	Stair footing loose	Monitor			
						/		/		/		/					loose bolt fort roof (nutsert)	Monitor		
11	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET																	
			1	7:48	04-May	/		/		/		/		X	X	Bearings/guide rollers worn on fly fox	Monitor			



Name Of Inspector: James
Month of Inspection: May-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
	PLGR 203		1			/		/		/		/		/			X	Tree branch stuck in shade sail	Needs Removal PCL
																		Holes in shade sail	Monitor
																		Low bark	Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	10:54	04-May	/		/		/		/			X	X		Weld cracking at slide entry	Needs Repair - LAZ
			1	11:12	11-May	/		/		/		/			X	X		Decking plastic worn/surface rust	Monitor
			1	10:59	18-May	/		/		/		/			X	X		Swing/Chain bridge links/mounts worn	Monitor
			2	10:56	25-May	/		/		/		/			X	X		Movement in frog footing	Monitor
			1			/		/		/		/			X	X		Border concrete cracking	Needs Repair - PCL
20	WANNIASSA PLGR 271	Sangster PI	1	12:22	04-May	/		/		/		/		X	X			Swing mounts brackets worn	Monitor
			1	12:10	11-May	/		/		/		/			X	X		Decking worn	Monitor
			1	12:10	18-May	/		/		/		/			X	X		Hole in chain wire fence	Needs Repair - LAZ
			2	12:05	25-May	/		/		/		/			X	X		Park bench missing arm rest	Needs Repair - PCL
			1			/		/		/		/			X	X		Holes and splitting in softfall	Needs repair - PCL

Inspectors Signature: J.Gardner

PCL LAZ J&E



Name Of Inspector **James** Month of Inspection **May-20**

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
						/	x	/	x	/	x	/	x	/	x	/	x				
1	BANKS PLGR 213	Menzies Court	1	12:46	06-May	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																			Decking plastic worn/surface rust	Monitor	
			2	9:34	20-May	/		/		/		/				X		X			
																				Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	1	12:55	06-May	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																			Swing seat brackets worn	Monitor	
			2	9:22	20-May	/		/		/		/				X		X	Decking worn	Monitor	
																				Dints in slide bed	Monitor
																		Border concrete cracking	Needs Repair - PCL		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	11:30	06-May	/		/		/		/					X	Posts handrails split/rotting	Monitor		
																			4 x Post damaged/split on fort	Monitor	
			2	11:39	20-May	/		/		/		/						X	Chain net links and mounts worn	Monitor	
																				Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	11:00	06-May	/		/		/		/			X		X	Border logs splitting	Monitor		
			2	11:15	20-May	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																		Slide has crack at entry/movement	Monitor		
7	BONYTHON PLGR 586	Morice Pl	1	11:13	06-May	/		/		/		/					X				
																				Swing seat brackets worn	Monitor
			2	11:28	20-May	/		/		/		/						X	Worn / missing rope on net	Monitor	
																					Worn links/mounts on pommel/ climb chain

Name Of Inspector		James		Month of Inspection								May-20		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
8	CALWELL PLGR 322	Beckett St	1	9:46	15-May	/	/	/	/	/	/	/	/	X	Decking plastic worn	Monitor									
																Swing mounts worn	Monitor								
			1	10:49	22-May	/	/	/	/	/	/	/	/	/	X	Bent monkey bars	Monitor								
																	Slide weld cracking at top	Needs Repair - LAZ							
																	Chain walk hand rail bent	Needs Repair - LAZ							
																	Bent deck poles	Needs Repair - LAZ							
																	Low tree branches	Needs Removal PCL							
9	CALWELL PLGR 321	Casey Cres	1	8:50	15-May	/	/	/	/	/	/	/	X	Swing mounts worn	Monitor										
															Decking plastic worn/decks rusting	Monitor									
			1	10:02	22-May	/	/	/	/	/	/	/	/	X	Chain net links/coating on chains worn	Monitor									
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)													See saw timber splitting	Monitor									
			1	9:35	15-May	/	/	/	/	/	/	X	X	Decking plastic worn	Monitor										
																Swing mounts/seat/links worn	Monitor								
			1	10:40	22-May	/	/	/	/	/	/	X	X		Low branches	Needs cut back back-PCL									
11	CALWELL PLGR 319	Samuel Cl													Side leg bent	Monitor									
			1	9:00	15-May	/	/	/	/	/	/	X	X	Border logs splitting	Monitor										
																Swing mounts worn	Monitor								
			1	10:12	22-May	/	/	/	/	/	/	X	X		Bent monkey bars	Monitor									
12	CALWELL PLGR 644	Shopping Centre													Park bench missing timber	Needs Repair - PCL									
			1	9:18	15-May	/	/	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor										
																Bark low	Top up bark PCL								
13	CALWELL PLGR 320	Were St	1	10:29	22-May	/	/	/	/	/	/	/	X		Carousel movement in bearing	Monitor									
																Border logs splitting/ missing	Needs Repair - PCL								
			1	9:07	15-May	/	/	/	/	/	/	X	X		Swing links/mounts worn	Monitor									
																	Tire worn on tyre swing	Monitor							
14	CHISHOLM PLGR 234	Alston St																							
			1	11:07	15-May	/	/	/	/	/	/	/	X		Swing mounts worn	Monitor									
			1	12:46	22-May	/	/	/	/	/	/	/	X		Damaged tic tac toe	Monitor									

Name Of Inspector		James		Month of Inspection							May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
													Baby seat chain cover worn	Monitor		
													Fly fox handle plastic worn	Monitor		
15	CHISHOLM PLGR 233	Dalyell St	1	11:16	15-May	/	/	/	/	/		X	Timber decking splitting	Needs repair - J&E		
														Tyre swing mounts worn	Monitor	
			1	12:55	22-May	/	/	/	/	/	/		X	Fly fox links worn	Monitor	
															Chain net mounts worn	Monitor
															Fly fox nylon guides worn	Needs Repair - J&E
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	1	11:44	15-May	/	/	/	/	/		X	Timber decking splitting	Monitor		
														Track ride not gliding with ease	Needs Repair - J&E	
			1	1:22	22-May		/	/	/	/	/		X	Swing seat damaged/brackets/links worn	Monitor	
															Post loose in footing	Monitor
													Uneven paving around playground	Needs Repair PCL		
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	1	11:35	15-May	/	/	/	/	/		X	Timber decking splitting	Monitor		
														Slide damaged at exit	Monitor	
			1	1:13	22-May		/	/	/	/	/		X	Log steps splitting	Monitor	
															Damaged park bench	Needs Repair - PCL
															Tyre /s hooks wearing on tire swing	Monitor
													Graffiti on slide	Remove - PCL		
18	CHISHOLM PLGR 235	Kirkcaldie Circ	1	12:03	15-May	/	/	/	/	/		X	Swing mounts/links worn	Monitor		
														Decking plastic worn/rusting	Monitor	
			1	12:37	22-May		/	/	/	/	/		X	Climb net mounts/plastic worn	Monitor	
															Plastic at slide exit damaged	Needs Repair J&E
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	1	11:26	15-May	/	/	/	/	/		X	Decking plastic worn	Monitor		
														Tyre swing mounts worn	Monitor	
			1	1:05	22-May		/	/	/	/	/		X	Climb net links worn	Monitor	
															Damaged park bench	Monitor
															Plastic panel damaged	Monitor
															Concrete border damaged	Needs repair - J&E
													Bent/damaged deck poles	Needs repair - LAZ		
20	CHISHOLM PLGR 236	Proctor St	1	11:54	15-May	/	/	/	/	/		X	Swing mounts/links/seat worn	Monitor		
															Low bark	Needs top up - PCL
			1	12:28	22-May		/	/	/	/	/		X	Dints in slide	Monitor	
													Fly fox handle plastic worn	Monitor		

Name Of Inspector		James		Month of Inspection						May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	1:40	15-May	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor		
			1	3:04	22-May	/	/	/	/	X	X	Movement in carousel base	Monitor		
													Decking timber splitting	Monitor	
													Chain net links / mounts worn	Monitor	
													Lichen growing on decks	Monitor	
29	FADDEN PLGR 509	Nicklin Cres	1	1:31	15-May	/	/	/	/	X	X	Rocks missing in border wall	Needs Repair - PCL		
													Rope bridge mount broken/rope worn	Needs Repair PCL	
			1	3:13	22-May	/	/	/	/	X	X	Climbing nets rope worn	Monitor		
													Panel/ roof panels cracked on fort	Monitor	
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	1:46	15-May	/	/	/	/	X	X	Swing mounts/ links worn	Monitor		
													Damaged baby swing	Monitor	
			1	2:55	22-May	/	/	/	/	X	X	Border logs worn	Monitor		
31	GILMORE PLGR 238	Hogue Pl										Dent in parallel bars/swing post	Monitor		
			1	12:30	15-May	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor		
													Rubber frog damaged	Monitor	
			1	1:39	22-May	/	/	/	/	X	X	Low bark	Needs Top up - PCL		
32	GILMORE PLGR 239	Rosman Circ	1	12:21	15-May	/	/	/	/	X	X	Fence damaged	Monitor		
													Spinner seats worn/ rusting	Monitor	
			1	1:31	22-May	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL		
33	GORDON PLGR 215	Iredale Pl										Bark low	Top up bark PCL		
			1	12:12	15-May	/	/	/	/	/	X	X	Bridge timber splitting	Monitor	
			1	1:47	22-May	/	/	/	/	/	X	X	Concrete at bench lifting	Needs Repair PCL	
33	GORDON PLGR 215	Iredale Pl										Damaged rock wall	Needs Repair PCL		
			1	12:07	06-May	/	/	/	/	/	X	X	Swing seat brackets worn	Monitor	
														Chain net/ladder links worn/plastic	Monitor
			2	10:28	20-May	/	/	/	/	/	X	X	Damaged post caps x 4	Monitor	
											Slide damaged	Monitor			



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection						May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
41	PLGR 328			MONDAY RUN										
	GOWRIE	Howell Pl	1	12:57	15-May	/	/	/	/	/	/			
			1	2:10	22-May	/	/	/	/	/	/			
42	GOWRIE PLGR 333	Middleton Circ	1	12:40	15-May	/	/	/	/		X	X	Swing mounts/ links worn Border concrete cracking	Monitor Monitor
			1	2:28	22-May	/	/	/	/		X	X		
43	GOWRIE PLGR 335	Weathers St	1	1:16	15-May	/	/	/	/	/		X	Swing mounts/links worn/rusty Slide dented	Monitor Monitor
			1	2:46	22-May	/	/	/	/	/		X		
44	GOWRIE PLGR 334	Wray Pl	1	1:08	15-May	/	/	/	/		X	X	Swing posts splitting Swing mounts/ links worn	Monitor Monitor
			1	2:37	22-May	/	/	/	/		X	X	Border sleepers splitting Concrete border cracked/lifting	Monitor Monitor
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN											
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN											
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN											
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN											

Name Of Inspector		James			Month of Inspection					May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN												
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET												
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	10:17	15-May	/	/	/	/		X	X	Ropes worn on web	Monitor	
			1	11:22	22-May	/	/	/	/		X	X	Decks/Posts splitting/rotten	Monitor	
														Swing mounts/seat worn	Monitor
														Concrete border lifting	Needs Repair PCL
												Gaps were slide joins	Monitor		
												Swing timber splitting	Monitor		
53	ISABELLA PLAINS PLGR 281	Keeverstone Circ	1	9:56	15-May	/	/	/	/	/		X	Swing mounts worn	Monitor	
			1	11:05	22-May	/	/	/	/	/		X	Plastic slide cracked	Monitor	
														Movement in swing posts	Monitor
														Frog plastic worn around handle	Monitor
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	10:07	15-May	/	/	/	/		X	X	Border path concrete cracking	Monitor	
			1	11:14	22-May	/	/	/	/		X	X	Slide surface worn	Monitor	
														Chain net links	Monitor
														Playground under repair on inspection - 22/05/20	
												Spring animal missing	Needs repair - J&E		
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	2:58	11-May	/	/	/	/	/		X	Slide leg loose in footing	Monitor	
			1	1:20	21-May	/	/	/	/	/		X	Low bark	Top - PCL	
														Spring animal loose in footing	Monitor
												Angle bar missing at climbing net damaged	Needs repair - LAZ		
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	7:30	05-May	/	/	/	/	/	X	X	Border logs splitting	Monitor	
														Swing mounts/brackets worn	Monitor
			1	7:30	21-May	/	/	/	/	/	X	X	Concrete lifting quad hoop game	Monitor	
														Chain net links / mounts worn	Monitor
												Slide surface worn	Monitor		
			1	2:35	11-May	/	/	/	/	/	X	X	Border logs damaged	Needs Repair PCL	
													Swing mounts worn/loose due to timber shrinking	Monitor	

Name Of Inspector		James		Month of Inspection								May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
57	KAMBAH PLGR 313	Attiwell Circ	1	12:54	21-May	/	/	/	/	/	X	X	Swing timber damage/splitting	Monitor	
														Asphalt cracking / lifting	Needs Repair PCL
															See-saw footrest damaged
58	KAMBAH PLGR 314	Barritt St	1	2:26	11-May	/	/	/	/	/		X	Damaged flat swing	Monitor	
														Bridge plastic worn/ rusted	Monitor
			1	12:45	21-May	/	/	/	/	/		X	Welds cracked on chain net	Needs Repair - LAZ	
												Fort panel movement	Monitor		
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	1:59	11-May	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Damaged plastic on stairs	Monitor
			1	11:46	21-May	/	/	/	/		X	X	Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	8:47	05-May	/	/	/	/		X	X	Timber decking splitting	Monitor	
														Swing posts splitting and rotten	Monitor
			1	9:13	21-May	/	/	/	/		X	X	Movement in ladder plate to decking	Monitor	
															Timber border lifting/damaged
													Bark washed out	Needs Repair - PCL	
63	KAMBAH PLGR 317	Bullock Circ	1	2:17	11-May	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Rubber on stairs splitting	Monitor
			1	12:33	21-May	/	/	/	/		X	X	Worn rubber on deck	Needs Repair LAZ	
															Climb chain/bridge links worn
													Smoking sign pulled out	Repaired by J&E on 8/4/2020	
													Swing mounts/brackets worn	Monitor	
64	KAMBAH PLGR 200	Coghill Cl	1	7:23	06-May	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Border logs splitting	Monitor
			1	10:24	21-May	/	/	/	/		X	X	Carousel loose - movement in bearing	Monitor	

Name Of Inspector		James		Month of Inspection						May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	1:42	11-May	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Swing mounts worn	Monitor
			1	12:04	21-May	/	/	/	/	X	X	Decking plastic worn	Monitor
												Low bark	Needs Top up - PCL
												flying fox handle/mount/links worn	Monitor
												Bridge timber splitting	Monitor
												Bridge/climbing net links worn	Monitor
66	KAMBAH PLGR 304	Dale Circ	1	12:55	11-May	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Decks rusty/ plastic peeling	Needs Repair LAZ
			1	11:13	21-May	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor
												Swing brackets/mounts worn	Monitor
67	KAMBAH PLGR 291	Deuchar Cl	1	7:32	06-May	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor
												Border sleepers splitting	Monitor
			1	10:42	21-May	/	/	/	/	X	X	Swing mounts worn	Monitor
												Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	2:45	11-May	/	/	/	/	X	X	Border logs splitting	Monitor
												Decking plastic worn	Monitor
			1	1:06	21-May	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ
												Swing mounts worn	Monitor
												Bark low	Needs top up - PCL
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	7:45	05-May	/	/	/	/	X	X	Rocks missing on rock wall	Needs Repair PCL
												Damaged bolt caps	Monitor
			1	8:25	21-May	/	/	/	/	X	X	Swing chain binding on s hoc	Repaired - J&E 5/05/20
												Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs Pl	1	8:35	05-May	/	/	/	/	/	X	Knots and crosses cracking	Monitor
												Bolt caps brittle/damaged on tower	Monitor
			1	9:03	21-May	/	/	/	/	/	X		
71	KAMBAH	Horton Cl	1	7:15	06-May	/	/	/	/	X	X	Chain net links worn	Monitor
												Decking plastic worn/rusting	Needs Repair LAZ
			1	10:33	21-May	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL

Name Of Inspector		James		Month of Inspection						May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
71	PLGR 289											Parallel slide bar bent	Monitor	
												Wearing swing brackets	Monitor	
72	KAMBAH PLGR 287	1	8:00	05-May	/	/	/	/		X	X	Border sleepers splitting	Monitor	
		1	8:35	21-May	/	/	/	/		X	X	Bridge/ chain net links worn	Monitor	
73	KAMBAH PLGR 307	1	2:28	05-May	/	/	/	/		X	X	Border sleepers splitting	Monitor	
		1	9:33	21-May	/	/	/	/		X	X	Swing mounts/brackets worn	Monitor	
													Slide dented	Monitor
												Low bark	Needs Repair - PCL	
74	KAMBAH PLGR 318	1	2:08	11-May	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor	
													Deck/bridge plastic worn	Monitor
		1	12:24	21-May	/	/	/	/	/		X	Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	1	8:19	05-May	/	/	/	/		X	X	Border Sleepers splitting	Monitor	
													See saw Top centre plate cracked	Needs Repair - LAZ
		1	8:53	21-May	/	/	/	/		X	X	Low branches	Cut back - PCL	
													Bridge slats splitting/links worn/movement	Monitor
													Chain net links worn	Monitor
											Decking plastic worn	Monitor		
76	KAMBAH PLGR 325	1	1:24	11-May	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor	
													Climb net ropes worn	Monitor
		1	11:37	21-May	/	/	/	/		X	X	Timber posts splitting	Monitor	
													Rock wall missing rocks	Monitor
													Damaged bolt caps on equipment	Monitor
77	KAMBAH PLGR 309													
		1	2:59	05-May	/	/	/	/		X	X	Border sleepers splitting	Monitor	
		2	10:12	21-May	/	/	/	/		X	X	Burn marks on post / slide	Monitor	
													Bridge/Climb net links worn	Monitor
												Bridge slats splitting/movement worn timber	Monitor	

Name Of Inspector		James		Month of Inspection								May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	2:40	05-May	/	/	/	/	/	/	X	Monitor all links in hosing	Monitor			
														Damaged rubber chain hose	Monitor		
			1	9:54	21-May	/	/	/	/	/	/	/	X	Bench seat slat damaged	Needs Repair PCL		
79	KAMBAH PLGR 314	Mannheim St	1	2:15	05-May	/	/	/	/	/	X	X	Border logs splitting	Monitor			
														Bridge slats splitting	Monitor		
			1	9:22	21-May	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
															Welds cracked at slide entry	Needs Repair - LAZ	
													Bridge links worn	Monitor			
80	KAMBAH PLGR 285	Marconi Cres	1	8:10	05-May	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor			
															Gravel washed/weeds into bark	Needs Removal - PCL	
			1	8:44	21-May	/	/	/	/	/	/	/	X	Deck edge wear	Monitor		
													Spring bear loose in footing	Monitor			
81	KAMBAH PLGR 308	Maxworthy St	1	2:48	05-May	/	/	/	/	/	/	X	Swing mounts worn	Monitor			
															Bark low	Needs Top up - PCL	
			1	10:02	21-May	/	/	/	/	/	/	/	X				
													Damaged spinner seats x 2	Needs Repair - J&E			
82	KAMBAH PLGR 292	McKillop Pl	1	1:51	11-May	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
			1	12:13	21-May	/	/	/	/	/	/	X	X	Swing seat/brackets worn	Monitor		
																Bridge/decks rusting	Needs repair - LAZ
													Flat swing seat damaged	Monitor			
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	1:34	11-May	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															Slide has small dents	Monitor	
			1	11:54	21-May	/	/	/	/	/	/	X	X	Split rubber on stairs	Monitor		
													Graffiti on panel	Needs Removal PCL			
84	KAMBAH PLGR 302	Pinkerton Circ	1	12:54	11-May	/	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL			
															Decking plastic worn/surface rust	Monitor	
			1	11:02	21-May	/	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor		
																Low tree branches	Needs removal- PCL
																Exposed tree roots in bark	Needs removal- PCL
													Bark low	Needs Top up - PCL			
																Loose eyelet on climb net	Repaired - J&E 21/05/20

Name Of Inspector		James		Month of Inspection								May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
85	KAMBAH PLGR 306	Primmer Court	1	7:43	21-May	/	/	/	/	/	/	/	/	New playground equipment installed	Has it been certified		
86	KAMBAH PLGR 303	Rounsevell St	1	1:15	11-May	/	/	/	/		X	X	Border sleepers splitting	Monitor			
														Swing mounts worn	Monitor		
			1	11:29	21-May	/	/	/	/		X	X	Slide metal rusting/ dented	Monitor			
														spring animal footing loose	Monitor		
												Lap seat worn	Monitor				
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN														
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN														
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN														
90	KAMBAH PLGR 290	Toole Pl	1	1:04	11-May	/	/	/	/		X	X	Swing posts splitting	Monitor			
														Swing mounts/brackets worn	Monitor		
			1	11:23	21-May	/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor			
															Bridge links worn	Monitor	
															Climb net links/mounts worn	Monitor	
															Slide loose at entry bracket	Monitor	
												Star pickets in bark	Needs Removal PCL				
												Border sleepers splitting	Monitor				
91	KAMBAH PLGR 202	Vanzetti Cres	1	7:05	06-May	/	/	/	/		X	X	Border sleepers splitting	Monitor			
														Decking worn/rusting in corners	Needs repair - LAZ		
			1	9:44	21-May	/	/	/	/		X	X	Movement in stair footing	Monitor			
												Bridge plastic worn/rusting	Monitor				



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection				May-20				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
												Swing mounts/brackets worn	Monitor	
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN											
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	12:35	16-Apr	/	/	/	/	X	X	Decking worn	Monitor	
			1	1:58	22-May	/	/	/	/	X	X	Chain net links/mounts worn	Monitor	
												Bent deck poles	Monitor	
												Border damaged/rotted	Needs Repair - PCL	
												Worn timber on spring horse	Monitor	
												Bark low	Needs Top up - PCL	
94	MONASH PLGR 252	Alabaster St	1	2:01	04-May	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			2	1:26	20-May	/	/	/	/	X	X	Swing mounts/ links worn	Monitor	
												Bite marks in swing seat	Monitor	
												Damaged spiral ladder	Monitor	
												Damaged tic tac toe	Monitor	
												Worn/rusting bridge	Monitor	
95	MONASH PLGR 248	Charleston St	1	1:39	04-May	/	/	/	/	/		X	Posts splitting and rotten	Monitor
												Swing mounts/links/brackets worn	Monitor	
			1	1:50	20-May	/	/	/	/	/		X	Bridge mounts/chain worn	Needs Repair LAZ
													Bridge timber splitting	Monitor
													Fibreglass damaged/cracking/worn on slides	Monitor
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	1:50	04-May	/	/	/	/	X	X	Steering wheel bracket worn	Monitor	
			2	1:37	20-May	/	/	/	/	X	X	Border timber splitting/missing	Needs Repair - PCL	
												Dirt washed into bark	Needs repair - PCL	
												Slide surface worn	Monitor	
97	MONASH PLGR 247	Cockcroft Ave	1	2:12	04-May	/	/	/	/	/		X	Swing mounts/ links worn	Monitor
			2	1:13	20-May	/	/	/	/	/		X	Concrete stump at bench	Needs Removal - PCL
													Low hanging branches	Needs Removal - PCL
													Tree sapplings growing in bark	Needs Removal - PCL
98	MONASH PLGR 250	Hallstrom Circ	1	1:30	04-May	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor	
			2	2:12	20-May	/	/	/	/	X	X	Concrete border lifting	Needs Repair PCL	

Name Of Inspector		James		Month of Inspection								May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	2:27	04-May	/	/	/	/			X	X	Movement in swing crossbar	Monitor		
															Bridge links/mounts worn/movement	Monitor	
			2	1:00	20-May	/	/	/	/			X	X	Swing mounts worn	Monitor		
																Bent bar/cracked welds on bridge	Needs Repair - LAZ
																Bark low	Needs Top up - PCL
													Bridge slats splitting / lichen	Monitor			
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	1:20	04-May	/	/	/	/	/			X	Decking plastic worn/rusting	Monitor		
															Triangles worn plastic	Monitor	
			2	2:02	20-May	/	/	/	/	/				X	Swing mounts/brackets worn	Monitor	
													Spring animal crack in foot rest/head loose	Monitor			
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin Pl)	1	1:08	04-May	/	/	/	/	/			X	New timber border lifting	Monitor		
															Horse head splitting	Monitor	
			2	2:22	20-May	/	/	/	/	/			X	Damaged tyre swing	Monitor		
102	OXLEY PLGR 255	Newman Morris Circ	1	12:59	04-May	/	/	/	/			X	X	Swing mounts worn	Monitor		
															Bite marks in swing seat	Monitor	
			2	2:31	20-May	/	/	/	/			X	X	Bark washing out	Needs repair PCL		
													Border concrete damaged	Needs Repair PCL			
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	10:58	15-May	/	/	/	/			X	X	Border sleepers damaged	Needs Repair J&E		
															Deck plastic worn	Monitor	
			1	12:10	22-May	/	/	/	/			X	X	Carousel rusting/loose in footing	Monitor		
													Spring frog handle loose	Monitor			
													Pod mounts worn (eyelet)	Needs repair - LAZ			
104	RICHARDSON PLGR 258	Chauncy Cres	1	10:30	15-May	/	/	/	/	/			X	Decking plastic worn	Monitor		
															Swing mounts worn	Monitor	
			1	11:37	22-May	/	/	/	/	/				X	Cuts on slide (smoothed)	Monitor	
													Star picks in bark	Needs removal - PCL			
105	RICHARDSON PLGR 259	Clift Cres	1	10:47	15-May	/	/	/	/	/			X				
															Worn swing chains/mounts/movement in post	Monitor	
			1	11:57	22-May	/	/	/	/	/				X	Bark low / dirt in bark	Top up bark - PCL	
			1	10:38	15-May	/	/	/	/	/			X	Decking plastic worn/rusting	Monitor		
														Climb net mounts worn	Needs Repair LAZ		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James			Month of Inspection					May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
106	RICHARDSON PLGR 257	Vidal St	1	11:46	22-May	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor		
												Climb net links worn	Monitor		
													Climb net bar bent	Monitor	
													Tyre swing links worn	Monitor	
													Bark low	Needs top up - PCL	
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN												
108	THEODORE PLGR 265	Dyett Circ	1	12:23	15-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Decking timber splitting	Monitor	
			1	9:44	22-May	/	/	/	/	X	X	Chain net links worn	Monitor		
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN												
110	THEODORE PLGR 261	Louis Loder St	1	12:14	15-Apr	/	/	/	/	X	X	Border logs splitting	Monitor		
													Decking timber splitting	Monitor	
			1	9:35	22-May	/	/	/	/	X	X	Slide f breglass cracking/worn	Monitor		
111	THEODORE PLGR 264	Scantleberry St	1	12:38	15-Apr	/	/	/	/	X	X	Border logs splitting	Monitor		
			1	9:52	22-May	/	/	/	/	X	X	Slide damaged at top	Monitor		
														Spring animal timber worn	Monitor
														Decking timber/panel splitting	Monitor
112	WANNIASSA PLGR 270	Billson Pl	1	7:51	06-May	/	/	/	/	/	X				
													Decking plastic worn	Monitor	
			1	1:55	21-May	/	/	/	/	/	X		Bridge plastic worn	Needs Repair LAZ	
														Damaged tic tac toe	Monitor
												Worn rubber on spike spinner	Needs Repair J&E		
			1	8:10	06-May	/	/	/	/	X	X	Decking timber worn	Monitor		

Name Of Inspector		James		Month of Inspection								May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
113	WANNIASSA PLGR 267	Bussau CI	1	1:24	25-May	/	/	/	/	/	X	X	Chain net links worn/plastic peeling	Monitor	
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	3:00	04-May	/	/	/	/	/		X	Decking plastic worn x 1	Needs Repair - LAZ	
			1	1:01	25-May	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor	
													Grab handle loose	Monitor	
115	WANNIASSA PLGR 275	Hervey Pl	1	8:35	06-May	/	/	/	/		X	X	Border sleepers/braces splitting	Needs Repair PCL	
			2	2:53	20-May	/	/	/	/		X	X	Decking plastic rust / peeling	Monitor	
													Smoking sign loose in footing	Needs Repair PCL	
													Swing seat damaged/mounts/links worn	Monitor	
116	WANNIASSA PLGR 266	Lansell Circ	1	2:38	04-May	/	/	/	/		X	X	Swing mounts worn	Monitor	
			1	1:43	25-May	/	/	/	/		X	X	Movement in spring animal	Monitor	
													Border fence panels damaged	Monitor	
117	WANNIASSA PLGR 269	Sainsbury St	1	7:43	06-May	/	/	/	/		X	X	Border logs splitting	Monitor	
			1	1:45	21-May	/	/	/	/		X	X	Holes in shade sail	Monitor	
													Bum marks on tic tac toe	Monitor	
													Bench seat slats damaged	Needs Repair PCL	
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN												
119	WANNIASSA PLGR 276	Steinfeld Circ	1	8:20	06-May	/	/	/	/		X	X	Border Sleepers splitting	Monitor	
			2	2:42	20-May	/	/	/	/		X	X	Bench seat slats splitting	Monitor	
													Cracked welds on bridge hand rail	Needs Repair - LAZ	
													Decks worn x 2	Needs Repair - LAZ	
													Bridge slats splitting	Monitor	
													Bridge/Chain net links worn/plastic	Monitor	
													Bearings / wheels damaged on fly fox trolley	Needs Repair J&E	
120	WANNIASSA	Sullivan Cree	1	8:01	06-May	/	/	/	/		X	X	Border logs splitting	Monitor	
													Bridge/chain links worn	Monitor	

Name Of Inspector		James		Month of Inspection								May-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
120	PLGR 268	Sumivan Cres	1	1:12	25-May	/	/	/	/	/	X	X	Handle plastic worn on flying fox	Monitor	
													Swing seats/mounts worn/splitting	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St	1	3:10	04-May	/	/	/	/		X	X	Border sleepers damaged	Needs Repair - PCL	
														Swing mounts worn	Monitor
			1	12:50	25-May	/	/	/	/		X	X	Bridge timber splitting	Monitor	
															Park bench missing / damaged timber
													Decking worn/lichen growing	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres	1	8:44	06-May	/	/	/	/		X	X	Decking worn / rusting	Monitor	
														Swing mounts/ links worn	Monitor
			2	3:04	20-May	/	/	/	/		X	X	Fireman pole damaged	Monitor	
															Roman triangles links worn plastic worn
													Chain net links worn	Monitor	
123	WANNIASSA PLGR 272	Whiteman St	1	2:48	04-May	/	/	/	/		X	X	Swing mounts/s hooks/ chains worn	Monitor	
			1	1:33	25-May	/	/	/	/		X	X	Border logs splitting	Monitor	



Name Of Inspector: James Month of Inspection: May-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
						/	x	/	x	/	x	/	x	/	x	/	x			/	x	Hazard
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	2:28	15-May	/		/		/		/		/			X	Checker plate on decking	Patched by Jason - Urban			
																			Awning ladders mounts rusting	Monitor		
			1	2:40	25-May	/		/		/		/		/				X	Bridge mounts worn	Monitor		
																				Pommels links/mounts worn/ hosing split	Monitor	
																				Swing mounts/brackets worn	Monitor	
																				2 x tread caps missing on surfer	Monitor	
																				Bridge metal slip hazard	Angle / monitor	
																				Basketball backboard worn	Monitor	
																				Climb chain mounts/links worn/hosing split	Monitor	
																				Rubber soft fall worn	Monitor	
2	COTTER PLGR 539	CASURINA SANDS	1	2:14	15-May	/		/		/		/		/			X	Post timber splitting	Monitor			
																			Decking timber splitting	Monitor		
			1	2:24	25-May	/		/		/		/		/				X	Rope bridge wearing	Monitor		
3	GREENWAY PLGR 538	Pine Island Rd	1	9:48	04-May	/		/		/		/			X	X		Border logs splitting	Monitor			
			1	9:42	11-May	/		/		/		/			X	X		Climbing wall worn/rusting	Monitor			
			1	9:53	18-May	/		/		/		/			X	X		Movement in staircase footing	Monitor			
			2	9:21	25-May	/		/		/		/			X	X			Swing mounts/chains worn	Monitor		
			1			/		/		/		/			X	X						
																				Decks/bridge worn/rusting	Monitor	
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	1	1:20	15-Apr	/		/		/		/			X	X		Fence timber splitting around water tanks	Monitor			
																			Timber splitting on large spring platform	Monitor		
			2			/		/		/		/			X	X		Water tanks decking timber splitting/worn	Monitor			
																				Flying fox posts splitting	Monitor	
																				Spider climb net rope frayed	Monitor	
																				Tree roots lifting paths	Needs Repair PCL	
																				Rubber soft fall splitting	Needs Repair PCL on going problem	
																				Timber seating at BBQ missing bolts	Needs Repair PCL	
																					Reserve shut due to Covid-19	15/04/2020



Name Of Inspector

James

Month of Inspection

May-20

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

Inspectors Signature: J.Gardner

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.



Name Of Inspector: James Month of Inspection: Jun-20

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
				Level 1 or Level 2			Level 1/2	/	x	/	x	/	x	/	x	/	x	/			x
1	BANKS PLGR 413	Pocket Ave		1	2:15	02-Jun	/		/		/				X	X	Loose slide leg	Monitor			
				1	8:35	09-Jun	/		/		/				X	X	Chain net links/mounts worn	Monitor / Needs Repair LAZ			
				1	10:45	15-Jun	/		/		/				X	X	Baby seat damaged	Monitor			
				2	1:10	22-Jun	/		/		/				X	X	Border concrete cracking / lifting	Needs Repair PCL			
				1	11:06	29-Jun	/		/		/				X	X	Small plastic slide damaged	Monitor			
2	BONYTHON PLGR 535	Burgoyne St														Titer toters arms missing	Removed until further notice - PCL				
				1	9:18	02-Jun	/		/		/				X	X	Ropes worn on climb net	Monitor			
				1	1:12	09-Jun	/		/		/					X	X	Swing mounts worn	Monitor		
				1	9:49	15-Jun	/		/		/					X	X	Timber worn on fort/equipment	Monitor		
				2	9:52	22-Jun	/		/		/					X	X	Collar pins worn	Monitor		
3	FADDEN PLGR 228	Coyne St		1	8:30	03-Jun	/		/		/			X	X	Ropes worn on small single swing	Monitor				
				1	9:35	09-Jun	/		/		/				X	X	Black rubber mount points melting	Monitor			
				1	1:42	15-Jun	/		/		/				X	X	Swing mounts worn	Monitor			
				2	2:15	22-Jun	/		/		/				X	X	Cracked welds on slide entry	Monitor			
				1	12:03	29-Jun	/		/		/				X	X	Worn links bridge/climb chains	Monitor			
4	GORDON PLGR 278	McGillvray Circ														Timber split on panels	Monitor				
																		Border logs splitting	Monitor		
																			Holes in softfall / splitting/low bark	Needs repair - PCL	
																			Footpath lifting	Needs repair - PCL	
																			Slide footing loose	Monitor	
																			Spinning seesaw hanger has worn mount/handle	Monitor	
																			Hose splitting on chain covers	Monitor	
																			Movement in brackets on web towers	Monitor	
																				Fibreglass on tea cup spinner cracking	Monitor
																				Swing mounts worn x 2	Needs Repair - J&E
																				Damaged see-saw brackets x 3	Needs Repair - J&E
																				Rope climb net worn 80%	Needs Repair - J&E
				5	GOWRIE PLGR 328	Jeffries St		1	8:18	03-Jun	/		/		/				X	X	Spinner top bearings loose
1	9:54	09-Jun	/						/		/				X	X	Damaged super nova	Monitor			
1	1:30	15-Jun	/						/		/				X	X	Border logs splitting	Monitor			
2	2:39	22-Jun	/						/		/				X	X	Roman triangles worn links	Needs repair - LAZ			
																			Wire walk cable worn	Monitor	
																Decking worn on tower	Monitor				
																Wire bridge mount worn/chain low links worn	Needs repair - LAZ				
																Cracked welds in tower/rust	Needs repair - LAZ				
																Rubber Soft fall splitting/holes	Needs repair - PCL				
																Swing chains/brackets/mounts	Monitor				
																bench below tea cup playground coming out of footing	Needs repair - PCL				
																Hole in shade sail	Monitor				
																Softfall splitting / holes forming	Needs Repair PCL				
																Timber worn on carousel	Monitor				
																Spider net worn	Monitor				



Name Of Inspector: James Month of Inspection: Jun-20

	Suburb	Street	Level 1/2	Time	Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
						/	x	/	x	/	x	/	x	/	x	/	x			
			1	12:24	29-Jun	/		/		/		/		/			X			
6	GREENWAY PLGR 242	Anketell St	1	8:41	02-Jun	/		/		/		/		X		X		Border sleepers missing and rotten	Needs Repair - PCL	
			1	8:17	05-Jun	/		/		/		/		X	X		Swing mounts/bushings replaced	J&E - 19/06/20		
			1	12:34	09-Jun	/		/		/		/		X	X					
			1	8:08	12-Jun	/		/		/		/		X	X		Digger bucket has a hole	Needs Repair - LAZ		
			1	9:10	15-Jun	/		/		/		/		X	X		Worn ropes on bridge/damaged	Monitor		
			1	1:20	19-Jun	/		/		/		/		X	X		Worn balance rope	Monitor		
			2	9:04	22-Jun	/		/		/		/		X	X		Tyre swing mounts worn/crossbar movement in sleeve/s hooks	Monitor		
			1	10:36	26-Jun	/		/		/		/		X	X		Log steps/posts splitting on tower	Monitor		
			1	9:10	29-Jun	/		/		/		/		X	X		Tower fort movement in footing	Monitor		
7	GREENWAY PLGR 240	De Little Circ PLAR 286	1	1:30	02-Jun	/		/		/		/		/		X		Spider net worn	Monitor	
			1	10:30	09-Jun	/		/		/		/		/		X		Handle rubber split on Spring Carousel	Monitor	
			1	1:02	15-Jun	/		/		/		/		/		X		Graffiti on post	Remove - PCL	
			2	10:16	22-Jun	/		/		/		/		/		X		Spring boat loose footings	Monitor	
			1	12:52	29-Jun	/		/		/		/		/		X		Holes in softfall	Needs repair - PCL	
8	GREENWAY PLGR 417	Eileen Good St	1	8:55	02-Jun	/		/		/		/		X	X		Swing seat/bracket/links worn	Monitor		
			1	12:49	09-Jun	/		/		/		/		X	X		Bark low	Needs Top up - PCL		
			1	9:26	15-Jun	/		/		/		/		X	X		Border logs splitting	Monitor		
			2	9:16	22-Jun	/		/		/		/		X	X		Baby seat worn	Monitor		
			1	9:27	29-Jun	/		/		/		/		X	X		Fort/seesaw timber splitting	Monitor		
9	GREENWAY PLGR 240	Florence Taylor St PLAR 288	1	8:33	02-Jun	/		/		/		/		X	X		Decking worn	Monitor		
			1	12:25	09-Jun	/		/		/		/		X	X					
			1	8:58	15-Jun	/		/		/		/		X	X					
			2	8:55	22-Jun	/		/		/		/		X	X		Crack in slide plastic	Monitor		
124	GREENWAY PLGR	Limburg Way	1	9:06	02-Jun	/		/		/		/		X	X		Timber decking splitting	Monitor		
			1	1:00	09-Jun	/		/		/		/		X	X		Climb wall timber splitting	Monitor		
			1	9:37	15-Jun	/		/		/		/		X	X		Swing seat brackets worn	Monitor		
			2	9:27	22-Jun	/		/		/		/		X	X					
			1	9:36	29-Jun	/		/		/		/		X	X					
10	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	1	1:42	02-Jun	/		/		/		/		X	X		Bark low	Needs Top up - PCL		
			1	10:40	09-Jun	/		/		/		/		X	X		Decks rusted/plastic worn	Monitor		
			1	12:50	15-Jun	/		/		/		/		X	X		Bridge plastic worn	Monitor		
			2	10:07	22-Jun	/		/		/		/		X	X		Swing seat/brackets/mounts/s-hooks worn	Monitor		
			1	1:03	29-Jun	/		/		/		/		X	X		Stair footing loose	Monitor		
11	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET																	
			1	7:23	02-Jun	/		/		/		/		X	X		Bearings/guide rollers worn on fly fox	Monitor		



Name Of Inspector **James** Month of Inspection **Jun-20**

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
				Level 1 or Level 2			Level 1/2	/	x	/	x	/	x	/	x	/	x	/			x
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	11:18	09-Jun	/		/		/				X	X			Swing mounts/brackets worn	Monitor	
				1	7:52	15-Jun	/		/		/		/			X	X			Concrete border lifting	Monitor
				2	7:45	22-Jun	/		/		/		/			X	X			Bridge slats splitting	Monitor
				1	7:38	29-Jun	/		/		/		/			X	X			Movement in see saw base	Monitor
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	7:10	02-Jun	/		/		/				X	X			Damaged concrete border	Monitor	
				1	11:06	09-Jun	/		/		/		/			X	X			Damaged park seat	Needs repair - PCL
				1	7:40	15-Jun	/		/		/		/			X	X			baby swing damaged	Monitor
				2	7:30	22-Jun	/		/		/		/			X	X			Plastic Rock on climb wall cracking	Monitor
				1	7:27	29-Jun	/		/		/		/			X	X			Movement in base of carousel	Needs repair - J&E
14	KAMBAH PLGR 305	Springbett St		1	7:34	02-Jun	/		/		/				X	X					
				1	8:39	05-Jun	/		/		/		/			X	X			Swing seat/brackets/links/mounts worn	Monitor
				1	11:30	09-Jun	/		/		/		/			X	X			Super nova damaged	Monitor
				1	7:37	12-Jun	/		/		/		/			X	X			Spinner bearings worn	Monitor
				1	8:05	15-Jun	/		/		/		/			X	X			Mount worn on large fly fox	Monitor
				1	12:45	19-Jun	/		/		/		/			X	X			Border logs splitting	Monitor
				2	7:58	22-Jun	/		/		/		/			X	X			Sml fly fox movement in bolt	Monitor
				1	10:58	26-Jun	/		/		/		/			X	X			Tic Tac Toe damaged - Smashed/brittle (taped)	Needs Repair J&E
				1	7:50	29-Jun	/		/		/		/			X	X			Damage panel on quad hoops	Monitor
																					Low branches at swings & fly fox/grass in bark
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	8:12	02-Jun	/		/		/				X	X			Burn marks at liberty swing seat	Monitor	
				1	12:02	09-Jun	/		/		/		/			X	X			Bark low/ washed out	Needs repair - PCL
				1	8:37	15-Jun	/		/		/		/			X	X			Bark low	Needs Top up - PCL
				2	8:43	22-Jun	/		/		/		/			X	X			Burn mark seesaw	Monitor
				1	8:48	29-Jun	/		/		/		/			X	X			Swing mounts	Monitor
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	8:22	02-Jun	/		/		/				X	X			Timber swing posts splitting/ missing swings	?	
				1	12:11	09-Jun	/		/		/		/			X	X			Worn decks/ bridge	Monitor
				1	8:46	15-Jun	/		/		/		/			X	X			Damaged rock wall	Monitor
				2	8:32	22-Jun	/		/		/		/			X	X			Rope worn on carousel	Monitor
				1	8:37	29-Jun	/		/		/		/			X	X			Swing seat / brackets worn	Monitor
17	MACARTHUR PLGR 327	Bayly Pl		1	2:50	02-Jun	/		/		/				X	X			Bark low	Needs Repair PCL	
				1	9:24	09-Jun	/		/		/		/			X	X			Worn swing links/brackets	Monitor
				1	1:58	15-Jun	/		/		/		/			X	X			Rope worn on climbing net/carousel	Monitor
				2	2:04	22-Jun	/		/		/		/			X	X			Movement in base towards post of carousel	Needs repair - J&E
				1	11:49	29-Jun	/		/		/		/			X	X			Gravel washed into bark	Needs removal PCL
18	THEODORE PLGR 263	Chippindall Circ		1	2:26	02-Jun	/		/		/				X	X			Low bark	Needs Top up - PCL	
				1	8:51	09-Jun	/		/		/		/			X	X			Softfall patches lifting under birds nest swing	Needs Repair PCL
				1	11:22	15-Jun	/		/		/		/			X	X			Swing mounts/bushes worn	Monitor
				2	1:25	22-Jun	/		/		/		/			X	X			Carousel seat worn/rusting	Monitor
																	Worn/damaged deck/bridge	Monitor			
																		Loose handle/footings on spring animal x 2	Monitor		



Name Of Inspector: James Month of Inspection: Jun-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action
	PLGR 205		1	11:23	29-Jun	/		/		/		/		/			X	Tree branch stuck in shade sail	Needs Removal PCL
																		Holes in shade sail	Monitor
																		Low bark	Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	2:36	02-Jun	/		/		/		/			X	X		Weld cracking at slide entry	Needs Repair - LAZ
			1	9:02	09-Jun	/		/		/		/			X	X		Decking plastic worn/surface rust	Monitor
			1	11:33	15-Jun	/		/		/		/			X	X		Swing/Chain bridge links/mounts worn	Monitor
			2	1:38	22-Jun	/		/		/		/			X	X		Movement in frog footing	Monitor
			1	11:34	29-Jun	/		/		/		/			X	X		Border concrete cracking	Needs Repair - PCL
20	WANNIASSA PLGR 271	Sangster PI	1	8:00	03-Jun	/		/		/		/		X	X			Swing mounts brackets worn	Monitor
			1	10:16	09-Jun	/		/		/		/			X	X		Decking worn	Monitor
			1	1:14	15-Jun	/		/		/		/			X	X		Hole in chain wire fence	Needs Repair - LAZ
			2	10:29	22-Jun	/		/		/		/			X	X		Park bench missing arm rest	Needs Repair - PCL
			1	12:37	29-Jun	/		/		/		/			X	X		Holes and splitting in softfall	Needs repair - PCL

Inspectors Signature: J.Gardner

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector **James** Month of Inspection **Jun-20**

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
						/	x	/	x	/	x	/	x	/	x	/	x				
1	BANKS PLGR 213	Menzies Court	1	1:06	03-Jun	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																			Decking plastic worn/surface rust	Monitor	
			2	9:25	23-Jun	/		/		/		/				X		X			
																				Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	1	1:15	03-Jun	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																			Swing seat brackets worn	Monitor	
			2	9:34	23-Jun	/		/		/		/				X		X	Decking worn	Monitor	
																				Dints in slide bed	Monitor
																		Border concrete cracking	Needs Repair - PCL		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	12:00	03-Jun	/		/		/		/					X	Posts handrails split/rotting	Monitor		
																			4 x Post damaged/split on fort	Monitor	
			2	6:54	23-Jun	/		/		/		/						X	Chain net links and mounts worn	Monitor	
																				Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	11:40	03-Jun	/		/		/		/			X		X	Border logs splitting	Monitor		
			2	6:30	23-Jun	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																		Slide has crack at entry/movement	Monitor		
7	BONYTHON PLGR 586	Morice Pl	1	11:51	03-Jun	/		/		/		/					X				
																				Swing seat brackets worn	Monitor
			2	6:42	23-Jun	/		/		/		/						X	Worn / missing rope on net	Monitor	
																				Worn links/mounts on pommel/ climb chain	Monitor



Name Of Inspector		James		Month of Inspection								Jun-20		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
8	CALWELL PLGR 322	Beckett St	1	7:55	04-Jun	/	/	/	/	/	/	/	X	Decking plastic worn	Monitor										
															Swing mounts worn	Monitor									
			2	9:58	25-Jun	/	/	/	/	/	/	/	/	X	Bent monkey bars	Monitor									
																Slide weld cracking at top	Needs Repair - LAZ								
																Chain walk hand rail bent	Needs Repair - LAZ								
																Bent deck poles	Needs Repair - LAZ								
																Low tree branches	Needs Removal PCL								
													Fenced off on inspection	04/06/2020											
9	CALWELL PLGR 321	Casey Cres	1	2:54	03-Jun	/	/	/	/	/	/	X	Swing mounts worn	Monitor											
														Decking plastic worn/decks rusting	Monitor										
			2	9:03	25-Jun	/	/	/	/	/	/	X	Chain net links/coating on chains worn	Monitor											
													See saw timber splitting	Monitor											
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	1	7:44	04-Jun	/	/	/	/		X	X	Decking plastic worn	Monitor											
														Swing mounts/seat/links worn	Monitor										
			2	9:47	25-Jun	/	/	/	/		X	X	Low branches	Needs cut back back-PCL											
													Side leg bent	Monitor											
11	CALWELL PLGR 319	Samuel Cl	1	3:05	03-Jun	/	/	/	/		X	X	Border logs splitting	Monitor											
														Swing mounts worn	Monitor										
			2	9:14	25-Jun	/	/	/	/		X	X	Bent monkey bars	Monitor											
													Park bench missing timber	Needs Repair - PCL											
12	CALWELL PLGR 644	Shopping Centre	1	7:30	04-Jun	/	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor											
														Bark low	Top up bark PCL										
			2	9:34	25-Jun	/	/	/	/	/	/	X	Carousel movement in bearing	Monitor											
13	CALWELL PLGR 320	Were St	1	3:12	03-Jun	/	/	/	/		X	X	Border logs splitting/ missing	Needs Repair - PCL											
														Swing links/mounts worn	Monitor										
			2	9:22	25-Jun	/	/	/	/		X	X	Tire worn on tyre swing	Monitor											
14	CHISHOLM PLGR 234	Alston St	1	10:11	03-Jun	/	/	/	/	/	/	X	Rope net install satisfactory?	Level 3 ?											
														Swing mounts worn	Monitor										
			2	11:37	25-Jun	/	/	/	/	/	/	X	Damaged tic tac toe	Monitor											

Name Of Inspector		James		Month of Inspection							Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
												Baby seat chain cover worn	Monitor		
												Fly fox handle plastic worn	Monitor		
15	CHISHOLM PLGR 233	Dalyell St	1	10:02	03-Jun	/	/	/	/	/	X	Timber decking splitting	Needs repair - J&E		
			2	11:46	25-Jun	/	/	/	/	/	/	X	Tyre swing mounts worn	Monitor	
														Fly fox links worn	Monitor
														Chain net mounts worn	Monitor
														Fly fox nylon guides worn	Needs Repair - J&E
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	1	9:33	03-Jun	/	/	/	/	/	X	Timber decking splitting	Monitor		
														Track ride not gliding with ease	Needs Repair - J&E
			2	12:15	25-Jun		/	/	/	/	/	X	Swing seat damaged/brackets/links worn	Monitor	
														Post loose in footing	Monitor
											Uneven paving around playground	Needs Repair PCL			
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	1	9:42	03-Jun	/	/	/	/	/	X	Timber decking splitting	Monitor		
														Slide damaged at exit	Monitor
			2	12:08	25-Jun		/	/	/	/	/	X	Log steps splitting	Monitor	
														Damaged park bench	Needs Repair - PCL
														Tyre /s hooks wearing on tire swing	Monitor
											Graffiti on slide	Remove - PCL			
18	CHISHOLM PLGR 235	Kirkcaldie Circ	1	10:21	03-Jun	/	/	/	/	/	X	Swing mounts/links worn	Monitor		
														Decking plastic worn/rusting	Monitor
			2	11:26	25-Jun		/	/	/	/	/	X	Climb net mounts/plastic worn	Monitor	
														Plastic at slide exit damaged	Needs Repair J&E
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	1	9:52	03-Jun	/	/	/	/	/	X	Decking plastic worn	Monitor		
														Tyre swing mounts worn	Monitor
			2	11:57	25-Jun		/	/	/	/	/	X	Climb net links worn	Monitor	
														Damaged park bench	Monitor
														Plastic panel damaged	Monitor
														Concrete border damaged	Needs repair - J&E
											Bent/damaged deck poles	Needs repair - LAZ			
20	CHISHOLM PLGR 236	Proctor St	1	10:29	03-Jun	/	/	/	/	/	X	Swing mounts/links/seat worn	Monitor		
														Low bark	Needs top up - PCL
			2	11:15	25-Jun		/	/	/	/	/	X	Dints in slide	Monitor	
											Fly fox handle plastic worn	Monitor			

Name Of Inspector		James		Month of Inspection								Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	11:44	04-Jun	/	/	/	/		X	X	Swing mounts worn/links worn	Monitor	
			2	12:56	26-Jun	/	/	/	/		X	X	Movement in carousel base	Monitor	
														Decking timber splitting	Monitor
														Chain net links / mounts worn	Monitor
														Lichen growing on decks	Monitor
29	FADDEN PLGR 509	Nicklin Cres	1	11:34	04-Jun	/	/	/	/		X	X	Rocks missing in border wall	Needs Repair - PCL	
													Rope bridge mount broken/rope worn	Needs Repair PCL	
			2	12:46	26-Jun	/	/	/	/		X	X	Climbing nets rope worn	Monitor	
														Panel/ roof panels cracked on fort	Monitor
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	11:52	04-Jun	/	/	/	/		X	X	Swing mounts/ links worn	Monitor	
													Damaged baby swing	Monitor	
			2	1:05	26-Jun	/	/	/	/		X	X	Border logs worn	Monitor	
31	GILMORE PLGR 238	Hogue Pl											Dent in parallel bars/swing post	Monitor	
			1	9:16	03-Jun	/	/	/	/		X	X	Concrete border damaged/lifting	Monitor	
														Rubber frog damaged	Monitor
			2	12:34	25-Jun	/	/	/	/		X	X	Low bark	Needs Top up - PCL	
32	GILMORE PLGR 239	Rosman Circ	1	9:24	03-Jun	/	/	/	/		X	X	Fence damaged	Monitor	
														Spinner seats worn/ rusting	Monitor
			2	12:25	25-Jun	/	/	/	/		X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL	
33	GORDON PLGR 215	Iredale Pl											Bark low	Top up bark PCL	
			1	9:05	03-Jun	/	/	/	/		/		X	Bridge timber splitting	Monitor
															Concrete at bench lifting
33	GORDON PLGR 215	Iredale Pl	2	12:43	25-Jun	/	/	/	/		/		X	Damaged rock wall	Needs Repair PCL
			1	12:26	03-Jun	/	/	/	/		/		X	Swing seat brackets worn	Monitor
															Chain net/ladder links worn/plastic
													Damaged post caps x 4	Monitor	
													Slide damaged	Monitor	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection							Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
41	PLGR 328			MONDAY RUN										
	GOWRIE	Howell Pl	1	10:35	04-Jun	/	/	/	/	/	/			
			2	11:34	26-Jun	/	/	/	/	/	/			
42	GOWRIE PLGR 333	Middleton Circ	1	10:53	04-Jun	/	/	/	/		X	X	Swing mounts/ links worn Border concrete cracking	Monitor Monitor
			2	12:02	26-Jun	/	/	/	/		X	X		
43	GOWRIE PLGR 335	Weathers St	1	11:11	04-Jun	/	/	/	/	/		X	Swing mounts/links worn/rusty Slide dented	Monitor Monitor
			2	12:22	26-Jun	/	/	/	/	/		X		
44	GOWRIE PLGR 334	Wray Pl	1	11:02	04-Jun	/	/	/	/		X	X	Swing posts splitting Swing mounts/ links worn	Monitor Monitor
			2	12:13	26-Jun	/	/	/	/		X	X	Border sleepers splitting Concrete border cracked/lifting	Monitor Monitor
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN											
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN											
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN											
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN											



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James			Month of Inspection								Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN													
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET													
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	8:26	04-Jun	/	/	/	/		X	X	Ropes worn on web	Monitor		
			2	11:20	23-Jun	/	/	/	/		X	X	Decks/Posts splitting/rotten	Monitor		
														Swing mounts/seat worn	Monitor	
														Concrete border lifting	Needs Repair PCL	
												Gaps were slide joins	Monitor			
												Swing timber splitting	Monitor			
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	8:05	04-Jun	/	/	/	/	/		X	Swing mounts worn	Monitor		
			2	10:52	23-Jun	/	/	/	/	/		X	Plastic slide cracked	Monitor		
														Movement in swing posts	Monitor	
														Frog plastic worn around handle	Monitor	
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	8:14	04-Jun	/	/	/	/		X	X	Border path concrete cracking	Monitor		
													Slide surface worn	Monitor		
			2	11:04	23-Jun	/	/	/	/		X	X	Chain net links	Monitor		
														Damaged post	Monitor	
												Spring animal missing	Needs repair - J&E			
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	3:51	05-Jun	/	/	/	/	/		X	Slide leg loose in footing	Monitor		
													Low bark	Top - PCL		
			2	10:37	24-Jun	/	/	/	/	/		X	Spring animal loose in footing	Monitor		
												Angle bar missing at climbing net damaged	Needs repair - LAZ			
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	1:57	09-Jun	/	/	/	/		X	X	Border logs splitting	Monitor		
													Swing mounts/brackets worn	Monitor		
			2	6:35	24-Jun	/	/	/	/		X	X	Concrete lifting quad hoop game	Monitor		
														Chain net links / mounts worn	Monitor	
												Slide surface worn	Monitor			
												Border logs damaged	Needs Repair PCL			
												Swing mounts worn/loose due to timber shrinking	Monitor			

Name Of Inspector		James		Month of Inspection								Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
57	KAMBAH PLGR 313	Attiwell Circ	2	11:01	24-Jun	/	/	/	/	/	X	X	Swing timber damage/splitting	Monitor	
														Asphalt cracking / lifting	Needs Repair PCL
															See-saw footrest damaged
58	KAMBAH PLGR 314	Barritt St	1	3:24	05-Jun	/	/	/	/	/		X	Damaged flat swing	Monitor	
														Bridge plastic worn/ rusted	Monitor
			2	10:50	24-Jun	/	/	/	/	/		X	Welds cracked on chain net	Needs Repair - LAZ	
												Fort panel movement	Monitor		
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	2:32	05-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Damaged plastic on stairs	Monitor
			2	2:10	23-Jun	/	/	/	/		X	X	Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	12:36	05-Jun	/	/	/	/		X	X	Timber decking splitting	Monitor	
														Swing posts splitting and rotten	Monitor
			2	8:03	24-Jun	/	/	/	/		X	X	Movement in ladder plate to decking	Monitor	
														Timber border lifting/damaged	Monitor
														Fenced off for repair - 5/06/20	
												Bark washed out	Needs Repair - PCL		
63	KAMBAH PLGR 317	Bullock Circ	1	3:16	05-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Rubber on stairs splitting	Monitor
			2	11:13	24-Jun	/	/	/	/		X	X	Worn rubber on deck	Needs Repair LAZ	
														Climb chain/bridge links worn	Monitor
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 200	Coghill Cl	1	2:17	04-Jun	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Border logs splitting	Monitor
			2	9:20	24-Jun	/	/	/	/		X	X	Carousel loose - movement in bearing	Monitor	

Name Of Inspector		James		Month of Inspection						Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	2:49	05-Jun	/	/	/	/	X	X	Border sleepers splitting	Monitor
			2	11:32	24-Jun	/	/	/	/	X	X	Swing mounts worn	Monitor
												Decking plastic worn	Monitor
												Low bark	Needs Top up - PCL
												flying fox handle/mount/links worn	Monitor
												Bridge timber splitting	Monitor
												Bridge/climbing net links worn	Monitor
66	KAMBAH PLGR 304	Dale Circ	1	1:55	05-Jun	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Decks rusty/ plastic peeling	Needs Repair LAZ
			1	3:22	22-Jun	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor
												Swing brackets/mounts worn	Monitor
67	KAMBAH PLGR 291	Deuchar Cl	1	2:24	04-Jun	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor
												Border sleepers splitting	Monitor
			2	9:28	24-Jun	/	/	/	/	X	X	Swing mounts worn	Monitor
												Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	3:41	05-Jun	/	/	/	/	X	X	Border logs splitting	Monitor
												Decking plastic worn	Monitor
			2	10:25	24-Jun	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ
												Swing mounts worn	Monitor
												Bark low	Needs top up - PCL
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	1:26	05-Jun	/	/	/	/	X	X	Rocks missing on rock wall	Needs Repair PCL
												Damaged bolt caps	Monitor
			2	7:00	24-Jun	/	/	/	/	X	X	Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs Pl	1	12:47	05-Jun	/	/	/	/		X	Knots and crosses cracking	Monitor
												Bolt caps brittle/damaged on tower	Monitor
			2	7:44	24-Jun	/	/	/	/		X		
71	KAMBAH	Horton Cl	1	2:09	04-Jun	/	/	/	/	X	X	Chain net links worn	Monitor
												Decking plastic worn/rusting	Needs Repair LAZ
			2	9:11	24-Jun	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL

Name Of Inspector		James		Month of Inspection						Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
71	PLGR 289	Horton Cr										Parallel slide bar bent	Monitor	
													Wearing swing brackets	Monitor
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	1	1:18	05-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor
			2	7:11	24-Jun	/	/	/	/		X	X	Bridge/ chain net links worn	Monitor
73	KAMBAH PLGR 307	Humble Court	1	12:24	05-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor
			2	8:24	24-Jun	/	/	/	/		X	X	Slide dented	Monitor
												Low bark	Needs Repair - PCL	
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	3:07	05-Jun	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor
			2	2:19	23-Jun	/	/	/	/	/		X	Deck/bridge plastic worn	Monitor
												Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	Lascelles Circ	1	12:56	05-Jun	/	/	/	/		X	X	Border Sleepers splitting	Monitor
			2	7:32	24-Jun	/	/	/	/		X	X	See saw Top centre plate cracked	Needs Repair - LAZ
												Low branches	Cut back - PCL	
												Bridge slats splitting/links worn/movement	Monitor	
												Chain net links worn	Monitor	
												Decking plastic worn	Monitor	
76	KAMBAH PLGR 325	Learmonth Dr	1	2:23	05-Jun	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor
			2	1:45	23-Jun	/	/	/	/		X	X	Climb net ropes worn	Monitor
												Timber posts splitting	Monitor	
												Rock wall missing rocks	Monitor	
												Damaged bolt caps on equipment	Monitor	
												Spring motorcycle panels worn	Monitor	
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	1	2:33	04-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor
			2	9:00	24-Jun	/	/	/	/		X	X	Burn marks on post / slide	Monitor
												Bridge/Climb net links worn	Monitor	
												Bridge slats splitting/movement worn timber	Monitor	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection								Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
85	KAMBAH PLGR 306	Primmer Court	2	6:47	24-Jun	/	/	/	/	/	/	/	/	New playground equipment installed	Has it been certified		
86	KAMBAH PLGR 303	Rounsevell St	1	2:12	05-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor			
														Swing mounts worn	Monitor		
			2	1:58	23-Jun	/	/	/	/		X	X	Slide metal rusting/ dented	Monitor			
														spring animal footing loose	Monitor		
												Lap seat worn	Monitor				
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN														
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN														
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN														
90	KAMBAH PLGR 290	Toole Pl	1	2:03	05-Jun	/	/	/	/		X	X	Swing posts splitting	Monitor			
														Swing mounts/brackets worn	Monitor		
			1	3:35	22-Jun	/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor			
															Bridge links worn	Monitor	
															Climb net links/mounts worn	Monitor	
															Slide loose at entry bracket	Monitor	
												Star pickets in bark	Needs Removal PCL				
												Border sleepers splitting	Monitor				
91	KAMBAH PLGR 202	Vanzetti Cres	1	3:05	04-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor			
														Decking worn/rusting in corners	Needs repair - LAZ		
			2	9:39	24-Jun	/	/	/	/		X	X	Movement in stair footing	Monitor			
												Bridge plastic worn/rusting	Monitor				

Name Of Inspector		James		Month of Inspection						Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
												Swing mounts/brackets worn	Monitor		
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN												
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	8:50	03-Jun	/	/	/	/		X	X	Decking worn	Monitor	
			2	1:17	26-Jun	/	/	/	/		X	X	Chain net links/mounts worn	Monitor	
														Bent deck poles	Monitor
														Border damaged/rotted	Needs Repair - PCL
												Worn timber on spring horse	Monitor		
												Bark low	Needs Top up - PCL		
94	MONASH PLGR 252	Alabaster St	1	9:05	04-Jun	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Swing mounts/ links worn	Monitor
			2	12:10	23-Jun	/	/	/	/		X	X	Bite marks in swing seat	Monitor	
														Damaged spiral ladder	Monitor
														Damaged tic tac toe	Monitor
												Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	1	9:29	04-Jun	/	/	/	/	/		X	Posts splitting and rotten	Monitor	
														Swing mounts/links/brackets worn	Monitor
			2	12:39	23-Jun	/	/	/	/	/			X	Bridge mounts/chain worn	Needs Repair LAZ
														Bridge timber splitting	Monitor
												Fibreglass damaged/cracking/worn on slides	Monitor		
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	9:17	04-Jun	/	/	/	/		X	X	Steering wheel bracket worn	Monitor	
														Border timber splitting/missing	Needs Repair - PCL
			2	12:26	23-Jun	/	/	/	/		X	X	Dirt washed into bark	Needs repair - PCL	
												Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	8:37	04-Jun	/	/	/	/	/		X	Swing mounts/ links worn	Monitor	
														Concrete stump at bench	Needs Removal - PCL
			2	11:45	23-Jun	/	/	/	/	/			X	Low hanging branches	Needs Removal - PCL
												Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	1	9:45	04-Jun	/	/	/	/		X	X	Swing brackets/mounts/links worn	Monitor	
			2	1:04	23-Jun	/	/	/	/		X	X	Concrete border lifting	Needs Repair PCL	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James			Month of Inspection					Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with sofffall	Sofffall free of litter glass/sharp objects	Sofffall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
106	RICHARDSON PLGR 257	Vidal St	2	10:34	25-Jun	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor	
												Climb net links worn	Monitor	
													Climb net bar bent	Monitor
													Tyre swing links worn	Monitor
													Bark low	Needs top up - PCL
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN											
108	THEODORE PLGR 265	Dyett Circ	1	2:33	03-Jun	/	/	/	/	X	X	Border sleepers splitting	Monitor	
												Decking timber splitting	Monitor	
			2	8:42	25-Jun	/	/	/	/	X	X	Chain net links worn	Monitor	
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN											
110	THEODORE PLGR 261	Louis Loder St	1	2:22	03-Jun	/	/	/	/	X	X	Border logs splitting	Monitor	
												Decking timber splitting	Monitor	
			2	8:30	25-Jun	/	/	/	/	X	X	Slide f breglass cracking/worn	Monitor	
111	THEODORE PLGR 264	Scantleberry St	1	2:44	03-Jun	/	/	/	/	X	X	Fenced off for repairs	03/06/2020	
												Border logs splitting	Monitor	
			2	8:51	25-Jun	/	/	/	/	X	X	Slide damaged at top	Monitor	
													Spring animal timber worn	Monitor
													Decking timber/panel splitting	Monitor
112	WANNIASSA PLGR 270	Billson Pl	1	12:49	04-Jun	/	/	/	/	/	X			
													Decking plastic worn	Monitor
			2	1:24	24-Jun	/	/	/	/	/	X		Bridge plastic worn	Needs Repair LAZ
													Damaged tic tac toe	Monitor
											Worn rubber on spike spinner	Needs Repair J&E		
											Decking timber worn	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection								Jun-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
120	PLGR 268	Sumivan Cres	2	1:47	24-Jun	/	/	/	/			X	X	Handle plastic worn on flying fox Swing seats/mounts worn/splitting	Monitor Monitor
0:00	WANNIASSA PLGR 277	Watkins St	1	1:20	04-Jun	/	/	/	/			X	X	Border sleepers damaged Swing mounts worn	Needs Repair - PCL Monitor
			2	12:50	24-Jun	/	/	/	/			X	X	Bridge timber splitting Park bench missing / damaged timber Decking worn/lichen growing	Monitor Needs Repair - PCL Monitor
122	WANNIASSA PLGR 274	Wheeler Cres	1	1:55	04-Jun	/	/	/	/			X	X	Decking worn / rusting Swing mounts/ links worn	Monitor Monitor
			2	12:15	24-Jun	/	/	/	/			X	X	Fireman pole damaged Roman triangles links worn plastic worn Chain net links worn	Monitor Monitor Monitor
123	WANNIASSA PLGR 272	Whiteman St	1	1:11	04-Jun	/	/	/	/			X	X	Swing mounts/s hooks/ chains worn	Monitor
			2	1:02	24-Jun	/	/	/	/			X	X	Border logs splitting	Monitor



Name Of Inspector: James Month of Inspection: Jun-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report					
						/	x	/	x	/	x	/	x	/	x	/	x			/	x	Hazard	Action	
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	10:02	05-Jun	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban				
																				Awning louver mounts rusting	Monitor			
			2	7:32	26-Jun	/		/		/		/		/						X				
																						Pommel links/mounts worn/hosing split	Monitor	
																						Swing mounts/brackets worn	Monitor	
																							2 x tread caps missing on surfer	Monitor
																							Bridge metal slip hazard	Angle / monitor
																							Basketball backboard worn	Monitor
																							Climb chain mounts/links worn/hosing split	Monitor
																							Rubber soft fall worn	Monitor
2	COTTER PLGR 539	CASURINA SANDS	1	9:46	05-Jun	/		/		/		/		/				X	Post timber splitting	Monitor				
																					Decking timber splitting	Monitor		
			2	7:15	26-Jun	/		/		/		/		/					X	Rope bridge wearing	Monitor			
3	GREENWAY PLGR 538	Pine Island Rd	1	9:35	02-Jun	/		/		/		/			X	X				Border logs splitting	Monitor			
			1	1:23	09-Jun	/		/		/		/			X	X					Climbing wall worn/rusting	Monitor		
			1	10:03	15-Jun	/		/		/		/			X	X					Movement in staircase footing	Monitor		
			2	9:39	22-Jun	/		/		/		/			X	X					Swing mounts/chains worn	Monitor		
			1	9:47	29-Jun	/		/		/		/			X	X								
																							Decks/bridge worn/rusting	Needs repair - LAZ
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	1	1:20	15-Apr	/		/		/		/			X	X					Fence timber splitting around water tanks	Monitor		
																						Timber splitting on large spring platform	Monitor	
			2	8:14	26-Jun	/		/		/		/				X	X					Water tanks decking timber splitting/worn	Monitor	
																							Flying fox posts splitting	Monitor
																							Spider climb net rope frayed	Monitor
																							Water tanks damaged - Siliconed	Monitor
																							Tree roots lifting paths	Needs Repair PCL
																							Rubber soft fall splitting	Needs Repair PCL on going problem
																								Timber bridges splitting/damaged/lifti
																					Side of small slides has cracked welds	Needs repair - LAZ		
																						Flying fox cable detached	Needs repair - LAZ	



Name Of Inspector

James

Month of Inspection

Jun-20

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

Inspectors Signature: J.Gardner

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.



Name Of Inspector: James Month of Inspection: Jul-20

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
				Level 1 or Level 2			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/			x	/	x
1	BANKS PLGR 413	Pocket Ave		1	10:30	06-Jul	/		/		/				X	X			Loose slide leg	Monitor			
				1	10:08	13-Jul	/		/		/					X	X			Chain net links/mounts worn	Monitor / Needs Repair LAZ		
				2	10:24	20-Jul	/		/		/		/				X	X			Baby seat damaged	Monitor	
				1	10:32	27-Jul	/		/		/		/				X	X			Border concrete cracking / lifting	Needs Repair PCL	
				1	11:06	29-Jun	/		/		/		/				X	X			Small plastic slide damaged	Monitor	
2	BONYTHON PLGR 535	Burgoyne St																	Titer toters arms missing	Removed until further notice - PCL			
				1	9:22	06-Jul	/		/		/		/					X		Ropes worn on climb net	Monitor		
				1	9:19	13-Jul	/		/		/		/						X		Swing mounts worn	Monitor	
				2	9:49	20-Jul	/		/		/		/						X		Timber worn on fort/equipment	Monitor	
				1	9:47	27-Jul	/		/		/		/						X		Collar pins worn	Monitor	
3	FADDEN PLGR 228	Coyne St		1	8:10	08-Jul	/		/		/				X	X			Swing mounts worn	Monitor			
				1	11:10	13-Jul	/		/		/		/			X	X			Cracked welds on slide entry	Monitor		
				2	11:35	20-Jul	/		/		/		/			X	X			Worn links bridge/climb chains	Monitor		
				1	11:39	27-Jul	/		/		/		/				X	X			Timber split on panels	Monitor	
				1	12:03	29-Jun	/		/		/		/				X	X			Border logs splitting	Monitor	
4	GORDON PLGR 278	McGillvray Circ																	Holes in softfall / splitting/low bark	Needs repair - PCL			
																				Footpath lifting	Needs repair - PCL		
																					Slide footing loose	Monitor	
																						Spinning seesaw hanger has worn mount/handle	Monitor
																						Hose splitting on chain covers	Monitor
																						Movement in brackets on web towers	Monitor
																						Fibreglass on tea cup spinner cracking	Monitor
																						Swing mounts worn x 2	Needs Repair - J&E
																						Damaged see-saw brackets x 3	Needs Repair - J&E
																						Rope climb net worn 80%	Monitor - No Sharps
																						Spinner top bearings loose	Monitor
																						Damaged super nova	Monitor
																						Border logs splitting	Monitor
5	GOWRIE PLGR 328	Jeffries St																		Roman triangles worn links	Needs repair - LAZ - Parawebb		
																					Wire walk cable worn	Monitor	
																					Decking worn on tower	Monitor	
																						Wire bridge mount worn/chain low links worn	Needs repair - LAZ
																						Cracked welds in tower/rust	Needs repair - LAZ
																			Rubber Soft fall splitting/holes	Needs repair - PCL			
																			Swing chains/brackets/mounts	Monitor			
																			bench below tea cup playground coming out of footing	Needs repair - PCL			
																			Hole in shade sail	Monitor			
																			Softfall splitting / holes forming	Needs Repair PCL			
																			Timber worn on carousel	Monitor			
																			Spider net worn	Monitor			



Name Of Inspector: James Month of Inspection: Jul-20

Suburb	Street	Level 1/2	Time	Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
					/	x	/	x	/	x	/	x	/	x	/	x						
6	GREENWAY PLGR 242	Anketell St	1	12:24	29-Jun	/		/		/		/		/			X					
			1	8:07	03-Jul	/		/		/			X		X				Border sleepers missing and rotten	Needs Repair - PCL		
			1	8:43	06-Jul	/		/		/			X		X							
			1	10:09	10-Jul	/		/		/			X		X							
			1	8:34	13-Jul	/		/		/			X		X					Digger bucket has a hole	Needs Repair - LAZ	
			1	8:40	17-Jul	/		/		/			X		X						Worn ropes on bridge/damaged	Monitor
			2	9:10	20-Jul	/		/		/			X		X						Worn balance rope	Monitor
			1	9:50	24-Jul	/		/		/			X		X						Tyre swing mounts worn/crossbar movement in sleeve/s hooks	Monitor
			1	8:54	27-Jul	/		/		/			X		X						Log steps/posts splitting on tower	Monitor
			1	8:17	31-Jul	/		/		/			X		X						Tower fort movement in footing	Monitor
7	GREENWAY PLGR 240	De Little Circ PLAR 286	1	7:24	08-Jul	/		/		/		/				X			Spider net worn	Monitor		
			1	1:46	13-Jul	/		/		/		/				X			Handle rubber split on Spring Carousel	Monitor		
			2	12:50	20-Jul	/		/		/		/				X				Graffiti on post	Remove - PCL	
			1	12:29	27-Jul	/		/		/		/				X				Spring boat loose footings	Monitor	
			1	12:52	29-Jun	/		/		/		/				X					Holes in softfall	Needs repair - PCL
8	GREENWAY PLGR 417	Eileen Good St	1	8:54	06-Jul	/		/		/		/		X		X			Swing seat/bracket/links worn	Monitor		
			1	8:47	13-Jul	/		/		/		/			X		X			Bark low	Needs Top up - PCL	
			2	9:24	20-Jul	/		/		/		/			X		X			Border logs splitting	Monitor	
			1	9:10	27-Jul	/		/		/		/			X		X			Baby seat worn	Monitor	
			1	9:27	29-Jun	/		/		/		/			X		X			Fort/seesaw timber splitting	Monitor	
9	GREENWAY PLGR 240	Florence Taylor St PLAR 288	1	8:35	06-Jul	/		/		/		/		X		X			Decking worn	Monitor		
			1	8:23	13-Jul	/		/		/		/			X		X					
			2	8:59	20-Jul	/		/		/		/			X		X					
			1	8:45	27-Jul	/		/		/		/			X		X				Crack in slide plastic	Monitor
124	GREENWAY PLGR	Limburg Way	1	9:05	06-Jul	/		/		/		/				X			Timber decking splitting	Monitor		
			1	8:56	13-Jul	/		/		/		/					X			Climb wall timber splitting	Monitor	
			2	9:37	20-Jul	/		/		/		/					X			Swing seat brackets worn	Monitor	
			1	9:22	27-Jul	/		/		/		/					X					
			1	9:36	29-Jun	/		/		/		/					X					
10	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	1	7:13	08-Jul	/		/		/		/		X		X				Bark low	Needs Top up - PCL	
			1	1:55	13-Jul	/		/		/		/			X		X			Decks rusted/plastic worn	Monitor	
			2	1:02	20-Jul	/		/		/		/			X		X			Bridge plastic worn	Monitor	
			1	12:40	27-Jul	/		/		/		/			X		X			Swing seat/brackets/mounts/s-hooks worn	Monitor	
			1	1:03	29-Jun	/		/		/		/			X		X				Stair footing loose	Monitor
11	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET																			
			1	7:31	06-Jul	/		/		/		/			X		X			Bearings/guide rollers worn on fly fox	Monitor	



Name Of Inspector: James Month of Inspection: Jul-20

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
							/	x	/	x	/	x	/	x	/	x	/	x			/	x
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	7:24	13-Jul	/	/	/	/	/	/	/	/	X	X			Swing mounts/brackets worn	Monitor		
				2	7:37	20-Jul	/	/	/	/	/	/	/	/	/	X	X			Concrete border lifting	Monitor	
				1	7:36	27-Jul	/	/	/	/	/	/	/	/	/	/	X	X			Bridge slats splitting	Monitor
				1	7:38	29-Jun	/	/	/	/	/	/	/	/	/	/	X	X			Movement in see saw	Needs repair - LAZ
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	7:20	06-Jul	/	/	/	/	/	/	/	/	X	X			Damaged concrete border	Monitor		
				1	7:15	13-Jul	/	/	/	/	/	/	/	/	/	X	X			Damaged park seat	Needs repair - PCL	
				2	7:26	20-Jul	/	/	/	/	/	/	/	/	/	X	X			baby swing damaged	Monitor	
				1	7:28	27-Jul	/	/	/	/	/	/	/	/	/	X	X			Plastic Rocks on climb wall cracking/brittle	Monitor	
14	KAMBAH PLGR 305	Springbett St		1	7:30	03-Jul	/	/	/	/	/	/	/	/	X	X			flying fox mount worn/Large flying fox cable	Needs welding - filling - LAZ		
				1	7:42	06-Jul	/	/	/	/	/	/	/	/	/	X	X			Swing seat/brackets/links/mounts worn	Monitor	
				1	10:37	10-Jul	/	/	/	/	/	/	/	/	/	X	X			Super nova damaged	Monitor	
				1	7:33	13-Jul	/	/	/	/	/	/	/	/	/	X	X			Spinner bearings worn	Monitor	
				1	7:30	17-Jul	/	/	/	/	/	/	/	/	/	X	X			Mount worn on large fly fox	Monitor	
				2	7:49	20-Jul	/	/	/	/	/	/	/	/	/	X	X			Border logs splitting	Monitor	
				1	9:15	24-Jul	/	/	/	/	/	/	/	/	/	X	X			Small fly fox movement in bolt/pommel wood	Monitor	
				1	7:47	27-Jul	/	/	/	/	/	/	/	/	/	X	X			Tic Tac Toe damaged - Smashed/brittle (taped)	Needs Repair J&E	
				1	7:30	31-Jul	/	/	/	/	/	/	/	/	/	X	X			Damage panel on quad hoops	Monitor	
																					Low branches at Large flyfox/ Small fly fox grass in bark	Cut back/remove - PCL
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	8:16	06-Jul	/	/	/	/	/	/	/	/	X	X			Bark low	Needs repair - PCL		
				1	8:02	13-Jul	/	/	/	/	/	/	/	/	/	X	X			Burn mark seesaw	Needs Top up - PCL	
				2	8:34	20-Jul	/	/	/	/	/	/	/	/	/	X	X			Swing mounts	Monitor	
				1	8:25	27-Jul	/	/	/	/	/	/	/	/	/	X	X			Timber swing posts splitting/ missing swings	?	
				1	8:48	29-Jun	/	/	/	/	/	/	/	/	/	X	X			Worn decks/ bridge	Monitor	
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	8:25	06-Jul	/	/	/	/	/	/	/	/	X	X			Damaged rock wall	Monitor		
				1	8:11	13-Jul	/	/	/	/	/	/	/	/	/	X	X			Rope worn on carousel	Monitor	
				2	8:44	20-Jul	/	/	/	/	/	/	/	/	/	X	X			Swing seat / brackets worn	Monitor	
				1	8:34	27-Jul	/	/	/	/	/	/	/	/	/	X	X					
				1	8:37	29-Jun	/	/	/	/	/	/	/	/	/	X	X			Bark low	Needs Repair PCL	
17	MACARTHUR PLGR 327	Bayly Pl		1	11:26	06-Jul	/	/	/	/	/	/	/	/	X	X			Worn swing links/brackets	Monitor		
				1	10:58	13-Jul	/	/	/	/	/	/	/	/	/	X	X			Rope worn on climbing net/carousel	Monitor	
				2	11:20	20-Jul	/	/	/	/	/	/	/	/	/	X	X			Movement in base towards post of carousel	Needs repair - J&E	
				1	11:28	27-Jul	/	/	/	/	/	/	/	/	/	X	X			Gravel washed into bark	Needs removal PCL	
				1	11:49	29-Jun	/	/	/	/	/	/	/	/	/	X	X			Low bark	Needs Top up - PCL	
18	THEODORE PLGR 263	Chippindall Circ		1	11:00	06-Jul	/	/	/	/	/	/	/	/	X	X			Swing mounts/bushes worn	Monitor		
				1	10:30	13-Jul	/	/	/	/	/	/	/	/	/	X	X			Carousel seat worn/rusting	Monitor	
				2	10:36	20-Jul	/	/	/	/	/	/	/	/	/	X	X			Worn/damaged deck/bridge	Monitor	
				1	10:50	27-Jul	/	/	/	/	/	/	/	/	/	X	X			Loose handle/footings on spring animal x 2	Monitor	



Name Of Inspector: James Month of Inspection: Jul-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
	PLGR 205		1	11:23	29-Jun	/		/		/		/		/			X	Tree branch stuck in shade sail	Needs Removal PCL
																		Holes in shade sail	Monitor
																		Low bark	Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	11:09	06-Jul	/		/		/		/			X	X	Weld cracking at slide entry	Needs Repair - LAZ	
			1	10:40	13-Jul	/		/		/		/			X	X	Decking plastic worn/surface rust	Monitor	
			2	10:47	20-Jul	/		/		/		/			X	X	Swing/Chain bridge links/mounts worn	Monitor	
			1	11:01	27-Jul	/		/		/		/			X	X	Movement in frog footing	Monitor	
			1	11:34	29-Jun	/		/		/		/			X	X	Border concrete cracking	Needs Repair - PCL	
20	WANNIASSA PLGR 271	Sangster PI	1	7:40	08-Jul	/		/		/		/		X	X	Swing mounts brackets worn	Monitor		
			1	12:35	13-Jul	/		/		/		/		X	X	Decking worn	Monitor		
			2	12:28	20-Jul	/		/		/		/		X	X	Hole in chain wire fence	Needs Repair - LAZ		
			1	12:17	27-Jul	/		/		/		/		X	X	Park bench missing arm rest	Needs Repair - PCL		
			1	12:37	29-Jun	/		/		/		/		X	X	Holes and splitting in softfall	Needs repair - PCL		

Inspectors Signature: J.Gardner

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection												Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition						
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action		
1	BANKS PLGR 213	Menzies Court	1	12:20	08-Jul	/		/		/		/			X		Fort panel cracked/stairs damaged	Monitor		
																		Decking plastic worn/surface rust	Monitor	
			1	8:36	22-Jul	/		/		/		/				X				
																			Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																	
3	BANKS PLGR 212	Wilson Cres	1	12:29	08-Jul	/		/		/		/			X	X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																		Swing seat brackets worn	Monitor	
			1	8:45	22-Jul	/		/		/		/				X	X	Decking worn	Monitor	
																			Dints in slide bed	Monitor
																	Border concrete cracking	Needs Repair - PCL		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	11:07	08-Jul	/		/		/		/				X	Posts handrails split/rotting	Monitor		
																		4 x Post damaged/split on fort	Monitor	
			1	2:39	21-Jul	/		/		/		/		/			X	Chain net links and mounts worn	Monitor	
																			Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																	
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	10:57	08-Jul	/		/		/		/			X	X	Border logs splitting	Monitor		
			1	2:20	21-Jul	/		/		/		/		/		X	X	Border decking lifting / splitting/structure s	Needs Repair - J&E - Rebuild	
																	Slide has crack at entry/movement	Monitor		
7	BONYTHON PLGR 586	Morice Pl	1	11:06	08-Jul	/		/		/		/				X				
																			Swing seat brackets worn	Monitor
			1	2:30	21-Jul	/		/		/		/		/			X		Worn / missing rope on net	Monitor
																				Worn links/mounts on pome/ climb chain

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
8	CALWELL PLGR 322	Beckett St	1	8:09	09-Jul	/	/	/	/	/	/	X	Decking plastic worn	Monitor		
														Swing mounts worn	Monitor	
			1	11:13	22-Jul	/	/	/	/	/	/	/	X	Bent monkey bars	Monitor	
															Flat seat brackets worn	Replaced brackets - J&E 22/07/20
															Slide weld cracking at top	Needs Repair - LAZ
															Chain walk hand rail bent	Needs Repair - LAZ
															Bent deck poles	Needs Repair - LAZ
													Low tree branches	Needs Removal PCL		
9	CALWELL PLGR 321	Casey Cres	1	2:43	08-Jul	/	/	/	/	/	/	X	Swing mounts worn	Monitor		
														Decking plastic worn/decks rusting	Monitor	
			1	10:20	22-Jul	/	/	/	/	/	/	X	Chain net links/coating on chains worn	Monitor		
												See saw timber splitting	Monitor			
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	1	7:58	09-Jul	/	/	/	/		X	X	Decking plastic worn	Monitor		
														Swing mounts/seat/links worn	Monitor	
			1	11:04	22-Jul	/	/	/	/		X	X	Low branches	Needs cut back back-PCL		
												Side leg bent	Monitor			
11	CALWELL PLGR 319	Samuel Cl	1	7:43	09-Jul	/	/	/	/		X	X	Border logs splitting	Monitor		
														Swing mounts worn	Monitor	
			1	10:30	22-Jul	/	/	/	/		X	X	Bent monkey bars	Monitor		
												Park bench missing timber	Needs Repair - PCL			
12	CALWELL PLGR 644	Shopping Centre	1	7:25	09-Jul	/	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor		
														Bark low	Top up bark PCL	
			1	10:49	22-Jul	/	/	/	/	/	/	X		Monitor		
												Carousel movement in bearing	Monitor			
13	CALWELL PLGR 320	Were St	1	7:36	09-Jul	/	/	/	/		X	X	Border logs splitting/ missing	Needs Repair - PCL		
														Swing links/mounts worn	Monitor	
			1	10:37	22-Jul	/	/	/	/		X	X	Tire worn on tyre swing	Monitor		
14	CHISHOLM PLGR 234	Alston St	1	9:35	08-Jul	/	/	/	/	/	/	X	Rope net install satisfactory?	Level 3 ?		
														Swing mounts worn	Monitor	
			1	12:26	22-Jul	/	/	/	/	/	/	X		Damaged tic tac toe	Monitor	

Name Of Inspector		James		Month of Inspection							Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
												Baby seat chain cover worn	Monitor		
												Fly fox handle plastic worn	Monitor		
15	CHISHOLM PLGR 233	Dalyell St	1	9:26	08-Jul	/	/	/	/	/	X	Timber decking splitting	Needs repair - J&E		
			1	12:17	22-Jul	/	/	/	/	/	/	X	Tyre swing mounts worn	Monitor	
														Fly fox links worn	Monitor
														Chain net mounts worn	Monitor
														Fly fox nylon guides worn	Needs Repair - J&E
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	1	8:58	08-Jul	/	/	/	/	/	X	Timber decking	Monitor		
													Track ride not gliding with ease	Needs Repair - J&E	
			1	1:29	22-Jul		/	/	/	/	/	X	Swing seat damaged/brackets/links worn	Monitor	
														Post loose in footing	Monitor
											Uneven paving around playground	Needs Repair PCL			
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	1	9:07	08-Jul	/	/	/	/	/	X	Timber decking splitting	Monitor		
													Slide damaged at exit	Monitor	
			1	1:40	22-Jul		/	/	/	/	/	X	Log steps splitting	Monitor	
														Worn park bench	Monitor
														Tyre /s hooks wearing on tire swing/worn/ damaged	Monitor
18	CHISHOLM PLGR 235	Kirkcaldie Circ	1	9:46	08-Jul	/	/	/	/	/	X	Swing mounts/links worn	Monitor		
													Decking plastic worn/rusting	Monitor	
			1	12:38	22-Jul		/	/	/	/	/	X	Climb net mounts/plastic worn	Monitor	
														Plastic at slide exit damaged	Needs Repair J&E
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	1	9:16	08-Jul	/	/	/	/	/	X	Decking plastic worn	Monitor		
													Tyre swing mounts worn	Monitor	
			1	12:06	22-Jul		/	/	/	/	/	X	Climb net links worn	Monitor	
														Damaged park bench	Monitor
														Plastic panel damaged	Monitor
														Concrete border damaged	Needs repair - J&E
											Bent/damaged deck poles	Needs repair - LAZ			
20	CHISHOLM PLGR 236	Proctor St	1	9:55	08-Jul	/	/	/	/	/	X	Swing mounts/links/seat worn	Monitor		
														Low bark	Needs top up - PCL
			1	12:46	22-Jul		/	/	/	/	/	X	Dints in slide	Monitor	
											Fly fox handle plastic worn	Monitor			

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	9:19	09-Jul	/	/	/	/		X	X	Swing mounts worn/links worn	Monitor	
			1	11:33	23-Jul	/	/	/	/		X	X	Movement in carousel base	Monitor	
														Decking timber splitting	Monitor
														Chain net links / mounts worn	Monitor
														Lichen growing on decks	Monitor
29	FADDEN PLGR 509	Nicklin Cres	1	9:39	09-Jul	/	/	/	/		X	X	Rocks missing in border wall	Needs Repair - PCL	
													Rope bridge mount broken/rope worn	Needs Repair PCL	
			1	11:42	23-Jul	/	/	/	/		X	X	Climbing nets rope worn	Monitor	
														Panel/ roof panels cracked on fort	Monitor
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	9:30	09-Jul	/	/	/	/		X	X	Swing mounts/ links worn	Monitor	
													Damaged baby swing	Monitor	
			1	11:24	23-Jul	/	/	/	/		X	X	Border logs worn	Monitor	
31	GILMORE PLGR 238	Hogue Pl											Dent in parallel bars/swing post	Monitor	
			1	8:41	08-Jul	/	/	/	/		X	X	Concrete border damaged/lifting	Monitor	
														Rubber frog damaged	Monitor
			1	1:10	22-Jul	/	/	/	/		X	X	Low bark	Needs Top up - PCL	
32	GILMORE PLGR 239	Rosman Circ	1	8:49	08-Jul	/	/	/	/		X	X	Fence damaged	Monitor	
														Spinner seats worn/ rusting	Monitor
			1	1:18	22-Jul	/	/	/	/		X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL	
33	GORDON PLGR 215	Iredale Pl											Bark low	Top up bark PCL	
			1	8:30	08-Jul	/	/	/	/			X	Bridge timber splitting	Monitor	
			1	12:58	22-Jul	/	/	/	/			X	Concrete at bench lifting	Needs Repair PCL	
33	GORDON PLGR 215	Iredale Pl											Damaged rock wall	Needs Repair PCL	
			1	11:39	08-Jul	/	/	/	/			X	Swing seat brackets worn	Monitor	
			1	7:52	22-Jul	/	/	/	/			X	Chain net/ladder links worn/plastic	Monitor	
												Damaged post caps x 4	Monitor		
													Slide damaged	Monitor	

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
34	GORDON PLGR 216	Kirkwood Cres	1	11:47	08-Jul	/	/	/	/		X	X	Swing seat brackets/mounts wearing	Monitor	
														Slide surface dented	Monitor
			1	8:04	22-Jul	/	/	/	/		X	X	Dent in swing crossbar/see saw seat	Monitor	
														Border sleeper damaged near slide	Needs Repair PCL
												Tyre swing mounts worn	Monitor		
35	GORDON PLGR 279	Evan Pl	1	11:30	08-Jul	/	/	/	/	/		X	Chain climb net links wearing	Monitor	
														Bridge/deck plastic worn/rusting in corners	Monitor
			1	7:44	22-Jul	/	/	/	/	/		X			
36	GORDON PLGR 218	Knoke Ave	1	12:06	08-Jul	/	/	/	/	/		X	Decking plastic worn	Monitor	
			1	8:24	22-Jul	/	/	/	/	/		X	Climb net links/mounts/plastic worn	Monitor	
37	GORDON PLGR 278	McGilvray Circ	MONDAY RUN												
38	GORDON PLGR 217	Popplewell Pl (Tallon Pl)	1	11:57	08-Jul	/	/	/	/	/		X	Tic tac damaged	Monitor	
														Dents in slide	Monitor
			1	8:15	22-Jul	/	/	/	/	/		X	Decking worn/surface rust	Monitor	
												Chain net mounts worn	monitor		
39	GORDON PLGR 214	Noel Ryan Gardens	1	11:19	08-Jul	/	/	/	/		X	X	Fort post splitting	Monitor	
														Plastic slide cracked/worn	Monitor
			1	7:35	22-Jul	/	/	/	/		X	X	Tree roots in bark	Needs Removal - PCL	
														Seesaw seat cracked	Needs Repair LAZ
														Log steps splitting and rotten	Monitor
												Concrete border lifting	Monitor		
												Chain bridge links worn	Monitor		
40	GOWRIE PLGR 332	Inwood Pl (Sadlier St)	1	10:27	09-Jul	/	/	/	/		X	X	Border logs splitting	Needs repair - PCL	
														Seesaw timber worn	complete rebuild - J&E 29/07/20
1	GOWRIE	Taffias St	MONDAY RUN												



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection							Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
41	PLGR 328			MONDAY RUN										
	GOWRIE	Howell Pl	1	10:38	09-Jul	/	/	/	/	/	/			
			1	2:10	22-Jul	/	/	/	/	/	/			
42	GOWRIE PLGR 333	Middleton Circ	1	10:18	09-Jul	/	/	/	/		X	X	Swing mounts/ links worn Border concrete cracking	Monitor Monitor
			1	2:30	22-Jul	/	/	/	/		X	X		
43	GOWRIE PLGR 335	Weathers St	1	10:00	09-Jul	/	/	/	/	/		X	Swing mounts/links worn/rusty Slide dented	Monitor Monitor
			1	2:55	22-Jul	/	/	/	/	/		X		
44	GOWRIE PLGR 334	Wray Pl	1	10:09	09-Jul	/	/	/	/		X	X	Swing posts splitting Swing mounts/ links worn	Monitor Monitor
			1	2:39	22-Jul	/	/	/	/		X	X	Border sleepers splitting Concrete border cracked/lifting	Monitor Monitor
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN											
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN											
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN											
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN											

Name Of Inspector		James			Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN													
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET													
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	10:05	08-Jul	/	/	/	/		X	X	Ropes worn on web	Monitor		
													Decks/Posts splitting/rotten	Monitor		
			1	3:08	21-Jul	/	/	/	/		X	X	Swing mounts/seat worn	Monitor		
														Concrete border lifting	Needs Repair PCL	
												Gaps were slide joins	Monitor			
												Swing timber splitting	Monitor			
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	10:35	08-Jul	/	/	/	/	/		X	Swing mounts worn	Monitor		
													Plastic slide cracked	Monitor		
			1	2:50	21-Jul	/	/	/	/	/		X	Movement in swing posts	Monitor		
														Frog plastic worn around handle	Monitor	
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	10:24	08-Jul	/	/	/	/		X	X	Border path concrete cracking	Monitor		
													Slide surface worn	Monitor		
			1	2:59	21-Jul	/	/	/	/		X	X	Chain net links	Monitor		
														Damaged post	Monitor	
												Spring animal missing	Needs repair - J&E			
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	11:08	10-Jul	/	/	/	/	/		X	Slide leg loose in footing	Monitor		
													Low bark	Top - PCL		
			1	11:06	21-Jul	/	/	/	/	/		X	Spring animal loose in footing	Monitor		
												Angle bar missing at climbing net damaged	Needs repair - LAZ			
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	11:22	10-Jul	/	/	/	/		X	X	Border logs splitting	Monitor		
													Swing mounts/brackets worn	Monitor		
			1	11:23	21-Jul	/	/	/	/		X	X	Concrete lifting quad hoop game	Monitor		
														Chain net links / mounts worn	Monitor	
												Slide surface worn	Monitor			
			1	2:41	09-Jul	/	/	/	/		X	X	Border logs damaged	Needs Repair PCL		
													Swing mounts worn/loose due to timber shrinking	Monitor		

Name Of Inspector		James		Month of Inspection							Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
57	KAMBAH PLGR 313	Attiwell Circ	1	10:38	21-Jul	/	/	/	/	/	X	X	Swing timber damage/splitting	Monitor	
														Asphalt cracking / lifting	Needs Repair PCL
															See-saw footrest damaged
58	KAMBAH PLGR 314	Barritt St	1	2:28	09-Jul	/	/	/	/	/		X	Damaged flat swing	Monitor	
														Bridge plastic worn/ rusted	Monitor
			1	10:25	21-Jul	/	/	/	/	/		X	Welds cracked on chain net	Needs Repair - LAZ	
												Fort panel movement	Monitor		
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	1:25	09-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Damaged plastic on stairs	Monitor
			1	2:46	20-Jul	/	/	/	/		X	X	Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	2:08	13-Jul	/	/	/	/		X	X	Timber decking splitting	Monitor	
														Swing posts splitting and rotten	Monitor
			1	2:05	21-Jul	/	/	/	/		X	X	Movement in ladder plate to decking	Monitor	
63	KAMBAH PLGR 317	Bullock Circ	1	2:17	09-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Rubber on stairs splitting	Monitor
			1	10:12	21-Jul	/	/	/	/		X	X	Worn rubber on deck	Needs Repair LAZ	
														Climb chain/bridge links worn	Monitor
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 200	Coghill Cl	1	1:41	10-Jul	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Border logs splitting	Monitor
			1	1:35	21-Jul	/	/	/	/		X	X	Carousel loose - movement in bearing	Monitor	

Name Of Inspector		James		Month of Inspection						Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	1:42	09-Jul	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Swing mounts worn	Monitor
			1	2:54	20-Jul	/	/	/	/	X	X	Decking plastic worn	Monitor
												Low bark	Needs Top up - PCL
												flying fox handle/mount/links worn	Monitor
												Bridge timber splitting	Monitor
												Bridge/climbing net links worn	Monitor
												Flat seat chain cut	Replaced with new chain + S hooks - J&E 21/07/20
66	KAMBAH PLGR 304	Dale Circ	1	12:45	09-Jul	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Decks rusty/ plastic peeling	Needs Repair LAZ
			1	2:06	20-Jul	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor
												Swing brackets/mounts worn	Monitor
67	KAMBAH PLGR 291	Deuchar Cl	1	1:33	10-Jul	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor
												Border sleepers splitting	Monitor
			1	1:51	21-Jul	/	/	/	/	X	X	Swing mounts worn	Monitor
												Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	2:50	09-Jul	/	/	/	/	X	X	Border logs splitting	Needs Repair PCL
												Decking plastic worn	Monitor
			1	10:49	21-Jul	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ
												Swing mounts worn	Monitor
												Bark low	Needs top up - PCL
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	11:50	10-Jul	/	/	/	/	X	X	Rocks missing on rock wall	Needs Repair PCL
												Damaged bolt caps	Monitor
			1	11:46	21-Jul	/	/	/	/	X	X	Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs Pl	1	12:32	10-Jul	/	/	/	/	/	X	Knots and crosses cracking	Monitor
												Bolt caps brittle/damaged on tower	Monitor
			1	12:23	21-Jul	/	/	/	/	/	X		
71	KAMBAH	Horton Cl	1	1:24	10-Jul	/	/	/	/	X	X	Chain net links worn	Monitor
												Decking plastic worn/rusting	Needs Repair LAZ
			1	1:43	21-Jul	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL

Name Of Inspector		James		Month of Inspection						Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
71	PLGR 289											Parallel slide bar bent	Monitor	
													Wearing swing brackets	Monitor
72	KAMBAH PLGR 287	1	12:01	10-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor	
		1	11:55	21-Jul	/	/	/	/		X	X	Bridge/ chain net links worn	Monitor	
73	KAMBAH PLGR 307	1	12:51	10-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor	
												Swing mounts/brackets worn	Monitor	
		1	12:41	21-Jul	/	/	/	/		X	X	Slide dented	Monitor	
												Low bark	Needs Repair - PCL	
74	KAMBAH PLGR 318	1	2:05	09-Jul	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor	
		1	10:00	21-Jul	/	/	/	/	/		X	Deck/bridge plastic worn	Monitor	
												Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	1	12:21	10-Jul	/	/	/	/		X	X	Border Sleepers splitting	Monitor	
													See saw Top centre plate cracked	Needs Repair - LAZ
		1	12:12	21-Jul	/	/	/	/		X	X	Low branches	Cut back - PCL	
													Bridge slats splitting/links worn/movement	Monitor
												Chain net links worn	Monitor	
												Decking plastic worn	Monitor	
76	KAMBAH PLGR 325	1	1:14	05-Jun	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor	
													Climb net ropes worn	Monitor
		1	2:36	20-Jul	/	/	/	/		X	X	Timber posts splitting	Monitor	
													Rock wall missing rocks	Monitor
													Damaged bolt caps on equipment	Monitor
												Spring motorcycle panels worn	Monitor	
77	KAMBAH PLGR 309	1	1:16	10-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor	
		1	1:04	21-Jul	/	/	/	/		X	X	Burn marks on post / slide	Monitor	
														Bridge/Climb net links worn
													Bridge slats splitting/movement worn timber	Monitor



CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition									
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	1:00	10-Jul	/	/	/	/	/	/	X	Monitor all links in hosing	Monitor				
														Damaged rubber chain hose	Monitor			
			1	1:24	21-Jul	/	/	/	/	/	/	X	Bench seat slat damaged	Needs Repair PCL				
79	KAMBAH PLGR 314	Mannheim St	1	12:42	10-Jul	/	/	/	/		X	X	Border logs splitting	Monitor				
														Bridge slats splitting	Monitor			
			1	12:32	21-Jul	/	/	/	/			X	X	Swing mounts worn	Monitor			
															Welds cracked at slide entry	Needs Repair - LAZ		
													Bridge links worn	Monitor				
80	KAMBAH PLGR 285	Marconi Cres	1	12:12	10-Jul	/	/	/	/	/		X	Swing brackets/mounts worn	Monitor				
														Gravel washed/weeds into bark	Needs Removal - PCL			
			1	12:04	21-Jul	/	/	/	/	/		X	X	Deck edge wear	Monitor			
													Spring bear loose in footing	Monitor				
81	KAMBAH PLGR 308	Maxworthy St	1	1:07	10-Jul	/	/	/	/	/		X	Swing mounts worn	Monitor				
															Bark low	Needs Top up - PCL		
			1	1:13	21-Jul	/	/	/	/	/		X						
													Damaged spinner seats x2	Monitor - Siliconed holes				
82	KAMBAH PLGR 292	McKillop Pl	1	1:51	09-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor				
			1	9:48	21-Jul	/	/	/	/			X	X	Swing seat/brackets worn	Monitor			
																	Bridge/decks rusting	Needs repair - LAZ
														Flat swing seat damaged	Monitor			
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	1:33	09-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor				
																Slide has small dents	Monitor	
			1	9:40	21-Jul	/	/	/	/			X	X	Split rubber on stairs	Monitor			
														Graffiti on panel	Needs Removal PCL			
84	KAMBAH PLGR 302	Pinkerton Circ	1	12:36	09-Jul	/	/	/	/		X	X	Border timber splitting/damaged	Needs Repair - PCL				
																Decking plastic worn/surface rust	Monitor	
			1	1:57	20-Jul	/	/	/	/			X	X	Swing mounts/links/brackets worn	Monitor			
																	Low tree branches	Needs removal- PCL
																	Exposed tree roots in bark	Needs removal- PCL
														Bark low	Needs Top up - PCL			
			1	11:34	10-Jul	/	/	/	/	/	/							



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
85	KAMBAH PLGR 306	Primmer Court	1	11:35	21-Jul	/	/	/	/	/	/	/	/	New playground equipment installed	Has it been certified		
86	KAMBAH PLGR 303	Rounsevell St	1	1:05	09-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor			
														Swing mounts worn	Monitor		
			1	2:27	20-Jul	/	/	/	/		X	X	Slide metal rusting/ dented	Monitor			
														spring animal footing loose	Monitor		
												Lap seat worn	Monitor				
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN														
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN														
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN														
90	KAMBAH PLGR 290	Toole Pl	1	12:55	09-Jul	/	/	/	/		X	X	Swing posts splitting	Monitor			
														Swing mounts/brackets worn	Monitor		
			1	2:15	20-Jul	/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor			
															Bridge links worn	Monitor	
															Climb net links/mounts worn	Monitor	
															Slide loose at entry bracket	Monitor	
												Star pickets in bark	Needs Removal PCL				
												Border sleepers splitting	Monitor				
91	KAMBAH PLGR 202	Vanzetti Cres	1	1:50	09-Jul	/	/	/	/		X	X	Border sleepers splitting	Monitor			
														Decking worn/rusting in corners	Needs repair - LAZ		
			1	12:53	21-Jul	/	/	/	/		X	X	Movement in stair footing	Monitor			
												Bridge plastic worn/rusting	Monitor				

Name Of Inspector		James		Month of Inspection							Jul-20			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
										Swing mounts/brackets worn	Monitor			
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN											
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	9:05	09-Jul	/	/	/	/	X	X	Decking worn	Monitor	
												Chain net links/mounts worn	Monitor	
			1	1:55	22-Jul	/	/	/	/	X	X	Bent deck poles	Monitor	
												Border damaged/rotted	Needs Repair - PCL	
												Worn timber on spring horse	Monitor	
												Bark low	Needs Top up - PCL	
94	MONASH PLGR 252	Alabaster St	1	11:10	09-Jul	/	/	/	/	X	X	Border sleepers splitting	Monitor	
												Swing mounts/ links worn	Monitor	
			1	9:43	23-Jul	/	/	/	/	X	X	Bite marks in swing seat	Monitor	
												Damaged spiral ladder	Monitor	
												Damaged tic tac toe	Monitor	
												Worn/rusting bridge	Monitor	
95	MONASH PLGR 248	Charleston St	1	11:34	09-Jul	/	/	/	/		X	Posts splitting and rotten	Monitor	
												Swing mounts/links/brackets worn	Monitor	
			1	10:07	23-Jul	/	/	/	/		X	Bridge mounts/chain worn	Needs Repair LAZ	
												Bridge timber splitting	Monitor	
												Fibreglass damaged/cracking/worn on slides	Monitor	
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	11:20	09-Jul	/	/	/	/	X	X	Steering wheel bracket worn	Monitor	
												Border timber splitting/missing	Needs Repair - PCL	
			1	9:56	23-Jul	/	/	/	/	X	X	Dirt washed into bark	Needs repair - PCL	
												Slide surface worn	Monitor	
97	MONASH PLGR 247	Cockcroft Ave	1	11:01	09-Jul	/	/	/	/		X	Swing mounts/ links worn	Monitor	
												Concrete stump at bench	Needs Removal - PCL	
			1	9:34	23-Jul	/	/	/	/		X	Low hanging branches	Needs Removal - PCL	
												Tree sapplings growing in bark	Needs Removal - PCL	
98	MONASH PLGR 250	Hallstrom Circ	1	12:06	09-Jul	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor	
												Concrete border lifting	Needs Repair PCL	
			1	10:31	23-Jul	/	/	/	/	X	X			

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	10:50	09-Jul	/	/	/	/			X	X	Movement in swing crossbar	Monitor		
															Bridge links/mounts worn/movement	Monitor	
			1	10:47	23-Jul	/	/	/	/			X	X	Swing mounts worn	Monitor		
																Bent bar/cracked welds on bridge	Needs Repair - LAZ
																Bark low	Needs Top up - PCL
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	11:56	09-Jul	/	/	/	/	/			X	Decking plastic worn/rusting	Monitor		
															Triangles worn plastic	Monitor	
			1	10:20	23-Jul	/	/	/	/	/				X	Swing mounts/brackets worn	Monitor	
																Spring animal crack in foot rest/head loose	Monitor
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin Pl)	1	12:14	09-Jul	/	/	/	/	/			X	New timber border lifting	Monitor		
															Horse head splitting	Monitor	
			1	1:30	20-Jul	/	/	/	/	/				X	Damaged tyre swing	Monitor	
102	OXLEY PLGR 255	Newman Morris Circ	1	12:23	09-Jul	/	/	/	/			X	X	Swing mounts worn	Monitor		
															Bite marks in swing seat	Monitor	
			1	1:41	20-Jul	/	/	/	/			X	X	Bark washing out	Needs repair PCL		
													Border concrete damaged	Needs Repair PCL			
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	8:52	09-Jul	/	/	/	/			X	X	Border sleepers	Needs Repair PCL		
															Deck plastic worn	Monitor	
			1	11:57	22-Jul	/	/	/	/			X	X	Carousel rusting/loose in footing	Monitor		
																Spring frog handle loose	Monitor
													Pod mounts worn (eyelet)	Needs repair - LAZ			
104	RICHARDSON PLGR 258	Chauncy Cres	1	8:21	09-Jul	/	/	/	/	/			X	Decking plastic worn	Monitor		
															Swing mounts worn	Monitor	
			1	11:28	22-Jul	/	/	/	/	/				X	Cuts on slide (smoothed)	Monitor	
													Star picks in bark	Needs removal - PCL			
105	RICHARDSON PLGR 259	Clift Cres	1	8:40	09-Jul	/	/	/	/	/			X				
															Worn swing chains/mounts/movement in post	Monitor	
			1	11:46	22-Jul	/	/	/	/	/				X	Bark low / dirt in bark	Top up bark - PCL	
													X	Decking plastic worn/rusting	Monitor		
														Climb net mounts worn	Needs Repair LAZ		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
106	RICHARDSON PLGR 257	Vidal St	1	11:37	22-Jul	/	/	/	/	/	/	X	Damaged spring animal foot rest	Needs Repair LAZ		
														Climb net links worn	Monitor	
															Climb net bar bent/deck poles	Monitor
															Tyre swing links worn	Monitor
												Bark low/tree debris stacked next to p	Needs top up/removal - PCL			
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN													
108	THEODORE PLGR 265	Dyett Circ	1	2:23	08-Jul	/	/	/	/	X	X	Border sleepers splitting	Monitor			
			1	9:58	22-Jul	/	/	/	/	X	X	Decking timber splitting	Monitor			
												Chain net links worn	Monitor			
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN													
110	THEODORE PLGR 261	Louis Loder St	1	2:02	08-Jul	/	/	/	/	X	X	Border logs splitting	Monitor			
														Decking timber splitting	Monitor	
			1	9:49	22-Jul	/	/	/	/	X	X	Slide f breglass cracking/worn	Monitor			
111	THEODORE PLGR 264	Scantleberry St	1	2:30	08-Jul	/	/	/	/	X	X	Fenced off for repairs	03/06/2020			
														Border logs splitting	Monitor	
			1	10:07	22-Jul	/	/	/	/	X	X	Slide damaged at top	Monitor			
															Spring animal timber worn	Monitor
												Decking timber/panel splitting	Monitor			
112	WANNIASSA PLGR 270	Billson Pl	1	12:24	13-Jul	/	/	/	/	/	X	Decking plastic worn	Monitor			
														Bridge plastic worn	Needs Repair LAZ	
			1	12:51	23-Jul	/	/	/	/	/	X	Damaged tic tac toe	Monitor			
												Worn rubber on spike spinner	Needs Repair J&E			
												Decking timber worn	Monitor			

Name Of Inspector		James		Month of Inspection								Jul-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
120	PLGR 268	Sumivan Cres	1	12:28	23-Jul	/	/	/	/	/	X	X	Handle plastic worn on flying fox	Monitor	
													Swing seats/mounts worn/splitting	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St	1	1:01	13-Jul	/	/	/	/		X	X	Border sleepers damaged	Needs Repair - PCL	
														Swing mounts worn	Monitor
			1	1:18	23-Jul	/	/	/	/		X	X	Bridge timber splitting	Monitor	
															Park bench missing / damaged timber
													Decking worn/lichen growing	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres	1	1:34	13-Jul	/	/	/	/		X	X	Decking worn / rusting	Monitor	
														Swing mounts/ links worn	Monitor
			1	1:46	23-Jul	/	/	/	/		X	X	Fireman pole damaged	Monitor	
															Roman triangles links worn plastic worn
													Chain net links worn	Monitor	
123	WANNIASSA PLGR 272	Whiteman St	1	12:53	13-Jul	/	/	/	/		X	X	Swing mounts/s hooks/ chains worn	Monitor	
			1	1:11	23-Jul	/	/	/	/		X	X	Border logs splitting	Monitor	



Name Of Inspector

James

Month of Inspection

Jul-20

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
				Level 1or Level 2			Level 1/2	/	x	/	x	/	x	/	x	/	x	/			x	/	x
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	7:59	10-Jul	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban			
																				Awning louver mounts rusting	Monitor		
			1	7:52	23-Jul	/		/		/		/		/					X				
																					Pommels links/mounts worn/ hosing split	Monitor	
																					Swing mounts/brackets worn	Monitor	
																					2 x tread caps missing on surfer	Monitor	
																					Bridge metal slip hazard	Angle / monitor	
																					Basketball backboard worn	Monitor	
																					Climb chain mounts/links worn/hosing split	Monitor	
																					Rubber soft fall worn	Monitor	
2	COTTER PLGR 539	CASURINA SANDS	1	7:40	10-Jul	/		/		/		/		/				X	Post timber splitting	Monitor			
																				Decking timber splitting	Monitor		
			1	7:30	23-Jul	/		/		/		/		/					X	Rope bridge wearing	Monitor		
3	GREENWAY PLGR 538	Pine Island Rd	1	9:16	06-Jul	/		/		/		/			X	X			Border logs splitting	Monitor			
			1	9:08	13-Jul	/		/		/		/			X	X			Climbing wall worn/rusting	Monitor			
			2	10:01	20-Jul	/		/		/		/			X	X			Movement in staircase footing	Monitor			
			1	9:34	27-Jul	/		/		/		/			X	X				Swing mounts/chains worn	Monitor		
			1	9:47	29-Jun	/		/		/		/			X	X				Staircase edges cracking	Needs repair - LAZ		
																					Decks/bridge worn/rusting	Needs repair - LAZ	
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND																					
			1	8:40	10-Jul	/		/		/		/			X	X				Fence timber splitting around water tanks	Monitor		
																					Timber splitting on large spring platform	Monitor	
			1	8:38	23-Jul	/		/		/		/			X	X					Water tanks decking timber splitting/worn	Monitor	
																						Flying fox posts splitting	Monitor
																						Spider climb net rope frayed	Monitor
																						Water tanks damaged - Siliconed	Monitor
																						Tree roots lifting paths	Needs Repair PCL
																						Rubber soft fall splitting	Needs Repair PCL on going problem
																						Slide beds damaged	Monitor
																			Timber bridges splitting/damaged/lifting/	Needs repair - PCL			
																			Tightened handrails on tank equipment	Repaired - J&E 23/07/20			
																				Side of small slides has cracked welds	Needs repair - LAZ		
																				Flying fox cable detached	Needs repair - LAZ		



Name Of Inspector

James

Month of Inspection

Jul-20

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

Inspectors Signature: J.Gardner

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.



Name Of Inspector: James Month of Inspection: Aug-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
						/	x	/	x	/	x	/	x	/	x	/	x			/	x	Hazard
1	BANKS PLGR 413	Pocket Ave	1	1:00	03-Aug	/		/		/		/			X		X	Loose slide leg	Monitor			
			1	10:46	10-Aug	/		/		/		/			X		X	Chain net links/mounts worn	Monitor / Needs Repair LAZ			
			2	10:43	17-Aug	/		/		/		/			X		X	Baby seat damaged	Monitor			
			1	10:20	24-Aug	/		/		/		/			X		X	Border concrete cracking / lifting	Needs Repair PCL			
			1	11:35	31-Aug	/		/		/		/			X		X	Small plastic slide damaged	Monitor			
2	BONYTHON PLGR 535	Burgoyne St															Titer toters arms missing	Removed until further notice - PCL				
			1	12:05	03-Aug	/		/		/		/				X	Ropes worn on climb net	Monitor				
			1	9:47	10-Aug	/		/		/		/					X	Swing mounts worn	Monitor			
			2	10:04	17-Aug	/		/		/		/					X	Timber worn on fort/equipment	Monitor			
			1	9:52	24-Aug	/		/		/		/					X	Collar pins worn	Monitor			
3	FADDEN PLGR 228	Coyne St	1	9:47	31-Aug	/		/		/		/					X	Ropes worn on small single swing	Monitor			
																			Black rubber mount points melting	Monitor		
			1	2:12	03-Aug	/		/		/		/				X	X	Swing mounts worn	Monitor			
			1	11:43	10-Aug	/		/		/		/				X	X	Cracked welds on slide entry	Monitor			
			2	11:56	17-Aug	/		/		/		/				X	X	Worn links bridge/climb chains	Monitor			
4	GORDON PLGR 278	McGillvray Circ	1	11:30	24-Aug	/		/		/		/			X	X	Timber split on panels	Monitor				
			1	12:31	31-Aug	/		/		/		/			X	X	Border logs splitting	Monitor				
																			Holes in softfall / splitting/low bark	Needs repair - PCL		
																				Footpath lifting	Needs repair - PCL	
																				Slide footing loose	Monitor	
																				Spinning seesaw hanger has worn mount/handle	Monitor	
																				Hose splitting on chain covers	Monitor	
																				Movement in brackets on web towers	Monitor	
																					Fibreglass on tea cup spinner cracking	Monitor
																					Swing mounts worn x 2	Mount pairs on flat seats in kids
5	GOWRIE PLGR 328	Jeffries St	1	10:10	10-Aug	/		/		/		/			X	X	Damaged see-saw brackets x 3	Needs Repair - J&E				
			1	9:00	14-Aug	/		/		/		/			X	X	Rope climb net worn 80%	Monitor - No Sharps				
			2	8:20	18-Aug	/		/		/		/			X	X	Spinner top bearings loose	Monitor				
			1	8:32	21-Aug	/		/		/		/			X	X	Damaged super nova	Monitor - Siliconed				
			1	1:00	25-Aug	/		/		/		/			X	X	Border logs splitting	Monitor				
																		Border logs splitting	Monitor			
																			Roman triangles worn links	Needs repair - LAZ - Parawebb		
																			Wire walk cable worn	Monitor		
																			Decking worn on tower	Monitor		
																			Wire bridge mount worn/chain low links worn	Needs repair - LAZ		
																			Cracked welds in tower/rust	Needs repair - LAZ		
																			Rubber Soft fall splitting/holes	Needs repair - PCL		
																			Swing chains/brackets/mounts	Monitor		
																			bench below tea cup playground coming out of footing	Needs repair - PCL		
																			Hole in shade sail	Monitor		
																			Softfall splitting / holes forming	Needs Repair PCL		
																			Timber worn on carousel	Monitor		
																			Spider net worn	Monitor		



Name Of Inspector **James** Month of Inspection **Aug-20**

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection Time	Date of Inspection Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description Hazard	Action Taken- For full details please refer to attached Playground Safety Inspection Report Action		
							/	x	/	x	/	x	/	x	/	x	/	x				
6	GREENWAY PLGR 242	Anketell St		1	1:10	31-Aug	/		/		/		/		/			X				
				1	11:10	03-Aug	/		/		/		/			X		X	Border sleepers missing and rotten	Needs Repair - PCL		
				1	11:00	07-Aug	/		/		/		/			X		X				
				1	8:45	10-Aug	/		/		/		/			X		X				
				1	9:42	14-Aug	/		/		/		/			X		X	Digger bucket has a hole	Needs Repair - LAZ		
				2	9:20	17-Aug	/		/		/		/			X		X	Worn ropes on bridge/damaged	Monitor		
				1	8:04	21-Aug	/		/		/		/			X		X	Worn balance rope	Monitor		
				1	8:48	24-Aug	/		/		/		/			X		X	Tyre swing mounts worn/crossbar movement in sleeve/s hooks	Monitor		
				1	8:19	28-Aug	/		/		/		/			X		X	Log steps/posts splitting on tower	Monitor		
				1	9:02	31-Jul	/		/		/		/			X		X	Tower fort movement in footing	Monitor		
7	GREENWAY PLGR 240	De Little Circ PLAR 286		1	3:06	03-Aug	/		/		/		/				X	Spider net worn	Monitor			
				1	12:55	10-Aug	/		/		/		/				X	Handle rubber split on Spring Carousel	Monitor			
				2	1:09	17-Aug	/		/		/		/				X	Graffiti on post	Remove - PCL			
				1	12:25	24-Aug	/		/		/		/				X	Spring boat loose footings	Monitor			
				1	2:03	31-Aug	/		/		/		/				X	Holes in softfall	Needs repair - PCL			
8	GREENWAY PLGR 417	Eileen Good St		1	11:23	03-Aug	/		/		/		/			X	X	Swing seat/bracket/links worn	Monitor			
				1	9:00	10-Aug	/		/		/		/			X	X	Bark low	Needs Top up - PCL			
				2	9:32	17-Aug	/		/		/		/			X	X	Border logs splitting	Monitor			
				1	9:06	24-Aug	/		/		/		/			X	X	Baby seat worn	Monitor			
				1	9:26	31-Aug	/		/		/		/			X	X	Fort/seesaw timber splitting	Monitor			
9	GREENWAY PLGR 240	Florence Taylor St PLAR 288		1	11:00	03-Aug	/		/		/		/		X	X	Decking worn	Monitor				
				1	8:36	10-Aug	/		/		/		/			X	X					
				2	9:10	17-Aug	/		/		/		/			X	X					
				1	8:36	24-Aug	/		/		/		/			X	X	Crack in slide plastic	Monitor			
124	GREENWAY PLGR	Limburg Way		1	11:35	03-Aug	/		/		/		/				X	Timber decking splitting	Monitor			
				1	9:13	10-Aug	/		/		/		/				X	Climb wall timber splitting	Monitor			
				2	9:43	17-Aug	/		/		/		/				X	Swing seat brackets worn	Monitor			
				1	9:20	24-Aug	/		/		/		/				X					
				1	9:35	31-Aug	/		/		/		/				X	X				
10	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807		1	3:20	03-Aug	/		/		/		/			X	X	Bark low	Needs Top up - PCL			
				1	12:44	10-Aug	/		/		/		/			X	X	Decks rusted/plastic worn	Monitor			
				2	1:24	17-Aug	/		/		/		/			X	X	Bridge plastic worn	Monitor			
				1	12:34	24-Aug	/		/		/		/			X	X	Swing seat/brackets/mounts/s-hooks worn	Monitor			
				1	1:50	31-Aug	/		/		/		/			X	X	Stair footing loose	Monitor			
11	GREENWAY PLGR 538	Pine Island Rd		MONDAY RUN / RURAL SHEET																		
				1	9:51	03-Aug	/		/		/		/				X	X	Bearings/guide rollers worn on fly fox	Monitor		



Name Of Inspector **James** Month of Inspection **Aug-20**

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
							/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x		
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	7:29	10-Aug	/		/		/		/				X		X							Swing mounts/brackets worn	Monitor					
				2	7:40	17-Aug	/		/		/		/		/			X		X							Concrete border lifting	Monitor				
				1	7:27	24-Aug	/		/		/		/		/			X		X								Bridge slats splitting	Monitor			
				1	2:42	31-Aug	/		/		/		/		/			X		X								Movement in see saw	Needs repair - LAZ			
																													Slide plastic worn	Monitor		
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	9:40	03-Aug	/		/		/		/			X		X								Damaged concrete border	Monitor					
				1	7:20	10-Aug	/		/		/		/		/		X		X								Damaged park seat	Needs repair - PCL				
				2	7:28	17-Aug	/		/		/		/		/		X		X									baby swing damaged	Monitor			
				1	7:16	24-Aug	/		/		/		/		/		X		X									Plastic Rocks on climb wall cracking/brittle	Monitor			
				1	2:50	31-Aug	/		/		/		/		/		X		X									Movement in base of carousel	Needs repair - J&E			
14	KAMBAH PLGR 305	Springbett St		1	10:03	03-Aug	/		/		/		/			X		X								fly fox mount worn/Large flying fox cable	Needs welding/ filing and					
				1	10:20	07-Aug	/		/		/		/		/		X		X								Swing seat/brackets/links/mounts worn	Monitor				
				1	7:41	10-Aug	/		/		/		/		/		X		X									Super nova damaged	Monitor			
				1	9:58	14-Aug	/		/		/		/		/		X		X									Spinner bearings worn	Monitor			
				2	7:57	17-Aug	/		/		/		/		/		X		X										Mount worn on large fly fox	Monitor		
				1	7:26	21-Aug	/		/		/		/		/		X		X										Border logs splitting	Monitor		
				1	7:37	24-Aug	/		/		/		/		/		X		X										fly fox movement in bolt/pommel worn/h	Monitor - Taped		
				1	7:35	28-Aug	/		/		/		/		/		X		X										Tic Tac Toe damaged - Smashed/brittle (taped)	Needs Repair J&E		
				1	7:45	31-Aug	/		/		/		/		/		X		X										Damage panel on quad hoops	Monitor		
																														Low branches at Large flyfox/ Small fly fox grass in bark	Cut back/remove - PCL	
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)																								Burn marks at liberty swing seat	Monitor					
																													Bark low/ washed out/weeds in bark - flyfoxs, large	Needs repair - PCL		
				1	10:40	03-Aug	/		/		/		/		/			X		X									Bark low	Needs Top up - PCL		
				1	8:15	10-Aug	/		/		/		/		/			X		X									Burn mark seesaw	Monitor		
				2	8:48	17-Aug	/		/		/		/		/			X		X										Swing mounts	Monitor	
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	8:14	24-Aug	/		/		/		/		X		X											Timber swing posts splitting/ missing swings	?			
				1	2:26	31-Aug	/		/		/		/		/		X		X										Worn decks/ bridge - plastic	Needs Repair - LAZ		
																														Damaged rock wall	Monitor	
				1	10:49	03-Aug	/		/		/		/		/					X										Rope worn on carousel	Monitor	
				1	8:24	10-Aug	/		/		/		/		/					X										Swing seat / brackets worn	Monitor	
17	MACARTHUR PLGR 327	Bayly Pl		1	2:34	31-Aug	/		/		/		/				X											Bark low	Needs Repair PCL			
				1	1:56	03-Aug	/		/		/		/		/				X										Worn swing links/brackets	Monitor		
				1	11:30	10-Aug	/		/		/		/		/					X										Rope worn on climbing net/carousel	Monitor	
				2	11:40	17-Aug	/		/		/		/		/					X										Movement in base towards post of carousel	Needs repair - J&E	
				1	11:19	24-Aug	/		/		/		/		/					X										Gravel washed into bark	Needs removal PCL	
18	THEODORE PLGR 263	Chippindall Circ		1	12:58	31-Aug	/		/		/		/				X											Low bark	Needs Top up - PCL			
																														Softfall patches lifting under birds nest swing	Needs Repair PCL	
				1	1:22	03-Aug	/		/		/		/		/					X										Swing mounts/bushes worn	Monitor	
				1	11:04	10-Aug	/		/		/		/		/					X										Carousel seat worn/rusting	Monitor	
																												Worn/damaged deck/bridge	Monitor			
																												Loose handle/footings on spring animal x 2	Monitor			



Name Of Inspector: James Month of Inspection: Aug-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
						/	x	/	x	/	x	/	x	/	x	/	x			Hazard
	PLGR 203		1	11:59	31-Aug	/		/		/		/		/			X	Tree branch stuck in shade sail	Needs Removal PCL	
																		Holes in shade sail	Monitor	
																		Low bark	Needs Top up - PCL	
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	1:33	03-Aug	/		/		/		/			X	X		Weld cracking at slide entry	Needs Repair - LAZ	
			1	11:13	10-Aug	/		/		/		/			X	X		Decking plastic worn/surface rust	Monitor	
			2	11:19	17-Aug	/		/		/		/				X	X		Swing/Chain bridge links/mounts worn	Monitor
			1	11:00	24-Aug	/		/		/		/				X	X		Movement in frog footing	Monitor
			1	12:10	31-Aug	/		/		/		/				X	X		Border concrete cracking	Needs Repair - PCL
20	WANNIASSA PLGR 271	Sangster PI	1	2:50	03-Aug	/		/		/		/			X	X		Swing mounts brackets worn	Monitor	
			1	12:26	10-Aug	/		/		/		/			X	X		Decking worn	Monitor	
			2	12:38	17-Aug	/		/		/		/			X	X		Hole in chain wire fence	Needs Repair - LAZ	
			1	12:12	24-Aug	/		/		/		/				X	X		Park bench missing arm rest	Needs Repair - PCL
			1	2:15	31-Aug	/		/		/		/				X	X		Holes and splitting in softfall	Needs repair - PCL

Inspectors Signature: J.Gardner

PCL LAZ J&E



Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition				Equipment in safe and satisfactory condition			
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action	
1	BANKS PLGR 213	Menzies Court	1	9:22	04-Aug	/		/		/		/		X		X	Fort panel cracked/stairs damaged	Monitor	
																		Decking plastic worn/surface rust	Monitor
			2	9:27	18-Aug	/		/		/		/		X		X			
																			Border concrete cracking
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																
3	BANKS PLGR 212	Wilson Cres	1	9:30	04-Aug	/		/		/		/		X		X	Bench seat slats loose / missing bolts	Needs Repair PCL	
																		Swing seat brackets worn	Monitor
			2	9:38	18-Aug	/		/		/		/		X		X	Decking worn	Monitor	
																			Dints in slide bed
																	Border concrete cracking	Needs Repair - PCL	
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	7:58	04-Aug	/		/		/		/				X	Posts handrails split/rotting	Monitor	
																		4 x Post damaged/split on fort	Monitor
			2	11:26	19-Aug	/		/		/		/		/			X	Chain net links and mounts worn	Monitor
																			Swing mounts worn
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	7:19	04-Aug	/		/		/		/		X		X	Border logs splitting	Needs repair - PCL	
			2	11:48	19-Aug	/		/		/		/		X		X	Border decking lifting / splitting/structure s	Needs Repair - J&E - Rebuild	
																			Slide has crack at entry/movement
																	Swing mounts worn	Monitor	
7	BONYTHON PLGR 586	Morice Pl	1	7:31	04-Aug	/		/		/		/				X	Large blue post end caps on	Repaired - J&E 4/08/20	
																		Swing seat brackets worn	Monitor
			2	11:37	19-Aug	/		/		/		/		/			X	Worn / missing rope on net	Monitor
																			Worn links/mounts on pommel/ climb chain
																	Mount on pommel worn	Needs Repair - LAZ	

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
8	CALWELL PLGR 322	Beckett St	1	12:26	04-Aug	/	/	/	/	/		X	Decking plastic worn	Monitor		
														Swing mounts worn	Monitor	
			2	10:19	19-Aug	/	/	/	/	/			X	Bent monkey bars	Monitor	
															Slide weld cracking at top/side	Needs Repair - LAZ
															Chain walk hand rail bent	Needs Repair - LAZ
															Bent deck poles	Needs Repair - LAZ
													Low tree branches	Needs Removal PCL		
9	CALWELL PLGR 321	Casey Cres	1	11:35	04-Aug	/	/	/	/	/		X	Swing mounts worn	Monitor		
														Decking plastic worn/decks rusting	Monitor	
			2	9:55	19-Aug	/	/	/	/	/			X	Chain net links/coating on chains worn	Monitor	
													See saw timber splitting	Monitor		
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	1	12:17	04-Aug	/	/	/	/		X	X	Decking plastic worn	Monitor		
														Swing mounts/seat/links worn	Monitor	
			2	10:08	19-Aug	/	/	/	/		X	X		Low branches	Needs cut back back-PCL	
													Side leg bent	Monitor		
11	CALWELL PLGR 319	Samuel Cl	1	11:45	04-Aug	/	/	/	/		X	X	Border logs splitting	Monitor		
														Swing mounts worn	Monitor	
			2	9:40	19-Aug	/	/	/	/		X	X		Bent monkey bars	Monitor	
													Park bench missing timber	Needs Repair - PCL		
12	CALWELL PLGR 644	Shopping Centre	1	12:03	04-Aug	/	/	/	/	/		X	Swing mounts/seat/S hooks worn	Monitor		
															Bark low	Top up bark PCL
			2	9:15	19-Aug	/	/	/	/	/			X		Carousel movement in bearing	Monitor
13	CALWELL PLGR 320	Were St	1	11:52	04-Aug	/	/	/	/		X	X	Border logs splitting/ missing	Needs Repair - PCL		
															Swing links/mounts worn	Monitor
			2	9:30	19-Aug	/	/	/	/		X	X		Tire worn on tyre swing	Monitor	
14	CHISHOLM PLGR 234	Alston St	1	12:44	06-Aug	/	/	/	/	/		X	Rope net install satisfactory?	Level 3 ?		
															Swing mounts worn	Monitor
			2	10:57	20-Aug	/	/	/	/	/			X		Damaged tic tac toe	Monitor

Name Of Inspector		James		Month of Inspection							Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
												Baby seat chain cover worn	Monitor		
												Fly fox handle plastic worn	Monitor		
15	CHISHOLM PLGR 233	Dalyell St	1	12:35	06-Aug	/	/	/	/	/	X	Timber decking splitting	Needs repair - J&E		
			2	10:47	20-Aug	/	/	/	/	/	/	X	Tyre swing mounts worn	Monitor	
														Fly fox links worn	Monitor
														Chain net mounts worn	Monitor
														Fly fox nylon guides worn	Needs Repair - J&E
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	1	1:50	06-Aug	/	/	/	/	/	X	Timber decking	Monitor		
														Track ride not gliding with ease	Needs Repair - J&E
			2	12:03	20-Aug		/	/	/	/	/	X	Swing seat damaged/brackets/links worn	Monitor	
														Post loose in footing	Monitor
											Uneven paving around playground	Needs Repair PCL			
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	1	1:58	06-Aug	/	/	/	/	/	X	Timber decking splitting	Monitor		
														Slide damaged at exit	Monitor
			2	12:14	20-Aug		/	/	/	/	/	X	Log steps splitting	Monitor	
														Worn park bench	Monitor
											Tyre worn/ damaged	placed tyre + x3 locknuts - J&E 25/08			
18	CHISHOLM PLGR 235	Kirkcaldie Circ	1	1:00	06-Aug	/	/	/	/	/	X	Swing mounts/links worn	Monitor		
														Decking plastic worn/rusting	Monitor
			2	11:09	20-Aug		/	/	/	/	/	X	Climb net mounts/plastic worn	Monitor	
											Plastic at slide exit damaged	Needs Repair J&E			
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	1	12:26	06-Aug	/	/	/	/	/	X	Decking plastic worn	Monitor		
														Tyre swing mounts worn	Monitor
			2	10:36	20-Aug		/	/	/	/	/	X	Climb net links worn	Monitor	
														Damaged park bench	Monitor
														Plastic panel damaged	Monitor
											Concrete border damaged	Needs repair - J&E			
											Bent/damaged deck poles	Needs repair - LAZ			
20	CHISHOLM PLGR 236	Proctor St	1	1:10	06-Aug	/	/	/	/	/	X	Swing mounts/links/seat worn	Monitor		
														Low bark	Needs top up - PCL
			2	11:23	20-Aug		/	/	/	/	/	X	Dints in slide	Monitor	
											Fly fox handle plastic worn	Monitor			

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	2:30	06-Aug	/	/	/	/		X	X	Swing mounts worn/links worn	Monitor	
			2	1:23	18-Aug	/	/	/	/		X	X	Movement in carousel base	Monitor	
														Decking timber splitting	Monitor
														Chain net links / mounts worn	Monitor
														Lichen growing on decks	Monitor
29	FADDEN PLGR 509	Nicklin Cres	1	2:38	06-Aug	/	/	/	/		X	X	Rocks missing in border wall	Needs Repair - PCL	
													Rope bridge mount broken/rope worn	Needs Repair PCL	
			2	1:09	18-Aug	/	/	/	/		X	X	Climbing nets rope worn	Monitor	
														Panel/ roof panels cracked on fort	Monitor
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	2:23	06-Aug	/	/	/	/		X	X	Swing mounts/ links worn	Monitor	
													Damaged baby swing	Monitor	
			2	1:35	18-Aug	/	/	/	/		X	X	Border logs worn	Monitor	
31	GILMORE PLGR 238	Hogue Pl											Dent in parallel bars/swing post	Monitor	
			1	1:34	06-Aug	/	/	/	/		X	X	Concrete border damaged/lifting	Monitor	
														Rubber frog damaged	Monitor
			2	11:45	20-Aug	/	/	/	/		X	X	Low bark	Needs Top up - PCL	
32	GILMORE PLGR 239	Rosman Circ	1	1:42	06-Aug	/	/	/	/		X	X	Fence damaged	Monitor	
													Spinner seats worn/ rusting	Monitor	
			2	11:54	20-Aug	/	/	/	/		X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL	
33	GORDON PLGR 215	Iredale Pl											Bark low	Top up bark PCL	
			1	1:22	06-Aug	/	/	/	/		/	X	Bridge timber splitting	Monitor	
			2	11:35	20-Aug	/	/	/	/		/	X	Concrete at bench lifting	Needs Repair PCL	
33	GORDON PLGR 215	Iredale Pl											Damaged rock wall	Needs Repair PCL	
			1	8:35	04-Aug	/	/	/	/		/	X	Swing seat brackets worn	Monitor	
			2	8:09	18-Aug	/	/	/	/		/	X	Chain net/ladder links worn/plastic	Monitor	
												Damaged post caps x 4	Monitor		
													Slide damaged	Monitor	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection						Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
41	PLGR 328			MONDAY RUN									
	GOWRIE	Howell Pl	1	1:25	07-Aug	/	/	/	/	/	/		
			2	12:05	18-Aug	/	/	/	/	/	/		
42	GOWRIE PLGR 333	Middleton Circ	1	1:41	07-Aug	/	/	/	/		X	X	Swing mounts/ links worn Border concrete cracking Monitor Monitor
			2	12:29	18-Aug	/	/	/	/		X	X	
43	GOWRIE PLGR 335	Weathers St	1	1:58	07-Aug	/	/	/	/	/		X	Swing mounts/links worn/rusty Slide dented Monitor Monitor
			2	12:46	18-Aug	/	/	/	/	/		X	
44	GOWRIE PLGR 334	Wray Pl	1	1:50	07-Aug	/	/	/	/		X	X	Swing posts splitting Swing mounts/ links worn Monitor Monitor
			2	12:37	18-Aug	/	/	/	/		X	X	Border sleepers splitting Concrete border cracked/lifting Monitor Monitor
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN										
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN										
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN										
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN										



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James			Month of Inspection					Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN												
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET												
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	1:10	04-Aug	/	/	/	/		X	X	Ropes worn on web	Monitor	
			2	11:03	19-Aug	/	/	/	/		X	X	Decks/Posts splitting/rotten	Monitor	
														Swing mounts/seat damaged	placed with new unit - J&E 4/08
														Concrete border lifting	Needs Repair PCL
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	12:42	04-Aug	/	/	/	/	/		X	Gaps were slide joins	Monitor	
			2	10:36	19-Aug	/	/	/	/	/		X	Swing timber splitting	Monitor	
														Swing mounts worn	Monitor
														Plastic slide cracked	Monitor
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	12:53	04-Aug	/	/	/	/		X	X	Movement in swing posts	Monitor	
			2	10:46	19-Aug	/	/	/	/		X	X	Frog plastic worn around handle	Monitor	
														Border path concrete cracking	Monitor
														Slide surface worn	Monitor
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	12:43	05-Aug	/	/	/	/	/		X	Chain net links	Monitor	
			2	9:50	25-Aug	/	/	/	/	/		X	Damaged post	Monitor	
														Spring animal missing	Needs repair - J&E
														Slide leg loose in footing	Monitor
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	7:30	05-Aug	/	/	/	/	/		X	X	Low bark	Top - PCL
			2	9:38	25-Aug	/	/	/	/	/		X	X	Spring animal loose in footing	Monitor
														Angle bar missing at climbing net damaged	Needs repair - LAZ
														Border logs splitting	Monitor
												Swing mounts/brackets worn	Monitor		
												Concrete lifting quad hoop game	Monitor		
												Chain net links / mounts worn	Monitor		
												Slide surface worn	Monitor		
			1	12:16	05-Aug	/	/	/	/	/		X	X	Border logs damaged	Needs Repair PCL
														Swing mounts worn/loose due to timber shrinking	Monitor

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
57	KAMBAH PLGR 313	Attiwell Circ	2	10:13	25-Aug	/	/	/	/	/	X	X	Swing timber damage/splitting	Monitor	
														Asphalt cracking / lifting	Needs Repair PCL
															See-saw footrest damaged
58	KAMBAH PLGR 314	Barritt St	1	12:05	05-Aug	/	/	/	/	/		X	Damaged flat swing	Monitor	
														Bridge plastic worn/ rusted	Monitor
			2	10:22	25-Aug	/	/	/	/	/		X	Welds cracked on chain net	Needs Repair - LAZ	
												Fort panel movement	Monitor		
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	3:16	04-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Damaged plastic on stairs	Monitor
			2	3:08	17-Aug	/	/	/	/		X	X	Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	9:03	05-Aug	/	/	/	/		X	X	Timber decking splitting	Monitor	
														Swing posts splitting and rotten	Monitor
			2	2:06	24-Aug	/	/	/	/		X	X	Movement in ladder plate to decking	Monitor	
63	KAMBAH PLGR 317	Bullock Circ	1	11:53	05-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Rubber on stairs splitting	Monitor
			2	1:20	20-Aug	/	/	/	/		X	X	Worn rubber on deck	Needs Repair LAZ	
														Climb chain/bridge links worn	Monitor
												Spring animal spring plate weld c	Needs Repair LAZ		
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 200	Coghill Cl	1	10:11	05-Aug	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Border logs splitting/damage	Needs repair - PCL
			2	12:47	24-Aug	/	/	/	/		X	X	Carousel loose - movement in bearing	Monitor	

Name Of Inspector		James		Month of Inspection						Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with sofffall	Sofffall free of litter glass/sharp objects	Sofffall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	10:50	05-Aug	/	/	/	/	X	X	Border sleepers splitting	Monitor
			2	12:50	20-Aug	/	/	/	/	X	X	Swing mounts worn	Monitor
												Decking plastic worn	Monitor
												Low bark	Needs Top up - PCL
												flying fox handle/mount/links worn	Monitor
												Bridge timber splitting	Monitor
												Bridge/climbing net links worn	Monitor
66	KAMBAH PLGR 304	Dale Circ	1	2:39	04-Aug	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Decks rusty/ plastic peeling	Needs Repair LAZ
			2	2:24	17-Aug	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor
												Swing brackets/mounts worn	Monitor
67	KAMBAH PLGR 291	Deuchar Cl	1	10:26	05-Aug	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor
												Border sleepers splitting	Monitor
			2	1:03	24-Aug	/	/	/	/	X	X	Swing mounts worn	Monitor
												Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	12:28	05-Aug	/	/	/	/	X	X	Border logs splitting	Needs Repair PCL
												Decking plastic worn	Monitor
			1	10:02	25-Aug	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ
												Swing mounts worn	Monitor
												Bark low	Needs top up - PCL
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	8:12	05-Aug	/	/	/	/	X	X	Rocks missing on rock wall	Needs Repair PCL
												Damaged bolt caps	Monitor
			2	2:47	24-Aug	/	/	/	/	X	X	Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs Pl	1	8:54	05-Aug	/	/	/	/	/	X	Knots and crosses cracking	Monitor
												Bolt caps brittle/damaged on tower	Monitor
			2	2:12	24-Aug	/	/	/	/	/	X		
71	KAMBAH	Horton Cl	1	10:18	05-Aug	/	/	/	/	X	X	Chain net links worn	Monitor
												Decking plastic worn/rusting	Needs Repair LAZ
			2	12:54	24-Aug	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL

Name Of Inspector		James		Month of Inspection						Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
71	PLGR 289	Horton Cr										Parallel slide bar bent	Monitor	
													Wearing swing brackets	Monitor
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	1	8:23	05-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor
			2	2:39	24-Aug	/	/	/	/		X	X	Bridge/ chain net links worn	Monitor
73	KAMBAH PLGR 307	Humble Court	1	9:24	05-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor
			2	1:46	24-Aug	/	/	/	/		X	X	Slide dented	Monitor
												Low bark	Needs Repair - PCL	
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	11:40	05-Aug	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor
			2	10:34	25-Aug	/	/	/	/	/		X	Deck/bridge plastic worn	Monitor
												Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	Lascelles Circ	1	8:44	05-Aug	/	/	/	/		X	X	Border Sleepers splitting	Monitor
			2	2:21	24-Aug	/	/	/	/		X	X	See saw Top centre plate cracked	Needs Repair - LAZ
												Low branches	Cut back - PCL	
												Bridge slats splitting/links worn/movement	Monitor	
												Chain net links worn	Monitor	
												Decking plastic worn	Monitor	
76	KAMBAH PLGR 325	Learmonth Dr	1	3:07	04-Aug	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor
			2	2:46	17-Aug	/	/	/	/		X	X	Climb net ropes worn	Monitor
												Timber posts splitting	Monitor	
												Rock wall missing rocks	Monitor	
												Damaged bolt caps on equipment	Monitor	
												Spring motorcycle panels worn	Monitor	
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	1	10:02	05-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor
			2	1:10	24-Aug	/	/	/	/		X	X	Burn marks on post / slide	Monitor
												Bridge/Climb net links worn	Monitor	
												Bridge slats splitting/movement worn timber	Monitor	

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition									
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	9:45	05-Aug	/	/	/	/	/	/		X	Monitor all links in hosing	Monitor			
															Damaged rubber chain hose	Monitor		
			2	1:28	24-Aug	/	/	/	/	/	/	/		X	Bench seat slat damaged	Needs Repair PCL		
79	KAMBAH PLGR 314	Mannheim St	1	9:15	05-Aug	/	/	/	/	/		X	X	Border logs splitting	Monitor			
															Bridge slats splitting	Monitor		
			2	1:57	24-Aug	/	/	/	/	/	/		X	X	Swing mounts worn	Monitor		
																Welds cracked at slide entry	Needs Repair - LAZ	
														Bridge links worn	Monitor			
80	KAMBAH PLGR 285	Marconi Cres	1	8:35	05-Aug	/	/	/	/	/			X	Swing brackets/mounts worn	Monitor			
															Gravel washed/weeds into bark	Needs Removal - PCL		
			2	2:30	24-Aug	/	/	/	/	/	/			X	Deck edge wear	Monitor		
														Spring bear loose in footing	Monitor			
81	KAMBAH PLGR 308	Maxworthy St	1	9:53	05-Aug	/	/	/	/	/			X	Swing mounts worn	Monitor			
																Bark low	Needs Top up - PCL	
			2	1:19	24-Aug	/	/	/	/	/	/			X				
														Damaged spinner seats x2	Monitor - Siliconed holes			
82	KAMBAH PLGR 292	McKillop Pl	1	11:05	05-Aug	/	/	/	/	/		X	X	Border sleepers splitting	Monitor			
			2	1:02	20-Aug	/	/	/	/	/	/		X	X	Swing seat/brackets worn	Monitor		
																	Bridge/decks rusting	Needs repair - LAZ
														Flat swing seat damaged	Monitor			
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	11:23	05-Aug	/	/	/	/	/		X	X	Border sleepers splitting	Monitor			
																Slide has small dents	Monitor	
			2	1:11	20-Aug	/	/	/	/	/	/		X	X	Split rubber on stairs	Monitor		
														Graffiti on panel	Needs Removal PCL			
84	KAMBAH PLGR 302	Pinkerton Circ	1	2:30	04-Aug	/	/	/	/	/		X	X	Border timber splitting/damaged	Needs Repair - PCL			
																Decking plastic worn/surface rust	Monitor	
			2	2:12	17-Aug	/	/	/	/	/	/		X	X	Swing mounts/links/brackets worn	Monitor		
																	Low tree branches	Needs removal- PCL
																	Exposed tree roots in bark	Needs removal- PCL
														Bark low	Needs Top up - PCL			
														Spinner bolts de threaded/coming	Replaced x2 t45 - J&E 5/08/20			



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
85	KAMBAH PLGR 306	Primmer Court	2	2:56	24-Aug	/	/	/	/	/	/	/	New playground equipment installed	Has it been certified		
86	KAMBAH PLGR 303	Rounsevell St	1	3:00	04-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Swing mounts worn	Monitor	
			2	2:58	17-Aug	/	/	/	/		X	X	Slide metal rusting/ dented	Monitor		
														spring animal footing loose	Monitor	
												Lap seat worn	Monitor			
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN													
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN													
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN													
90	KAMBAH PLGR 290	Toole Pl	1	2:48	04-Aug	/	/	/	/		X	X	Swing posts splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			2	2:35	17-Aug	/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor		
															Bridge links worn	Monitor
															Climb net links/mounts worn	Monitor
															Slide loose at entry bracket	Monitor
												Seesaw centre plate bolt/mount	Needs repair - LAZ			
												Border sleepers splitting	Monitor			
91	KAMBAH PLGR 202	Vanzetti Cres	1	9:36	05-Aug	/	/	/	/		X	X	Border sleepers splitting	Monitor		
			2	1:36	24-Aug	/	/	/	/		X	X	Movement in stair footing	Monitor		
												Bridge plastic worn/rusting	Monitor			

Name Of Inspector		James		Month of Inspection				Aug-20				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
												Swing mounts/brackets worn	Monitor	
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN											
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	2:12	06-Aug	/	/	/	/	X	X	Decking worn	Monitor	
			2	11:50	18-Aug	/	/	/	/	X	X	Chain net links/mounts worn	Monitor	
													Bent deck poles	Monitor
													Border damaged/rotted	Needs Repair - PCL
											Worn timber on spring horse	Monitor		
											Bark low	Needs Top up - PCL		
94	MONASH PLGR 252	Alabaster St	1	12:25	07-Aug	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			2	12:35	19-Aug	/	/	/	/	X	X	Swing mounts/ links worn	Monitor	
													Bite marks in swing seat	Monitor
													Damaged spiral ladder	Monitor
													Damaged tic tac toe	Monitor
											Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	1	12:45	07-Aug	/	/	/	/	/	X	Posts splitting and rotten	Monitor	
												Swing mounts/links/brackets worn	Monitor	
			2	1:00	19-Aug	/	/	/	/	/	X	Bridge mounts/chain worn	Needs Repair LAZ	
													Bridge timber splitting	Monitor
											Fibreglass damaged/cracking/worn on slides	Monitor		
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	12:36	07-Aug	/	/	/	/	X	X	Steering wheel bracket worn	Monitor	
			2	12:48	19-Aug	/	/	/	/	X	X	Border timber splitting/missing	Needs Repair - PCL	
													Dirt washed into bark	Needs repair - PCL
											Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	12:14	07-Aug	/	/	/	/	/	X	Swing mounts/ links worn	Monitor	
													Concrete stump at bench	Needs Removal - PCL
			2	12:08	19-Aug	/	/	/	/	/	X	X	Low hanging branches	Needs Removal - PCL
											Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	1	1:02	07-Aug	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor	
			2	1:19	19-Aug	/	/	/	/	X	X	Concrete border lifting	Needs Repair PCL	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		James		Month of Inspection						Aug-20			Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
99	MONASH PLGR 254	Sturdee Cres/ Victor PI	1	1:12	07-Aug	/	/	/	/	/	X	X	Movement in swing crossbar	Monitor		
														Bridge links/mounts worn/movement	Monitor	
			2	12:19	19-Aug	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
															Bent bar/cracked welds on bridge	Needs Repair - LAZ
															Bark low	Needs Top up - PCL
												Bridge slats splitting / lichen	Monitor			
100	MONASH PLGR 249	William Hudson Cres (Thompson PI)	1	12:53	07-Aug	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor		
														Triangles worn plastic	Monitor	
			2	1:10	19-Aug	/	/	/	/	/			X	Swing mounts/brackets worn	Monitor	
															Spring animal crack in foot rest/head loose	Monitor
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin PI)	1	2:09	04-Aug	/	/	/	/	/		X	New timber border lifting	Monitor		
														Horse head splitting	Monitor	
			2	1:49	17-Aug	/	/	/	/	/			X	Damaged tyre swing	Monitor	
102	OXLEY PLGR 255	Newman Morris Circ	1	2:00	04-Aug	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
														Bite marks in swing seat	Monitor	
			2	1:39	17-Aug	/	/	/	/	/	X	X	Bark washing out	Needs repair PCL		
															Border concrete damaged	Needs Repair PCL
103	RICHARDSON PLGR 501	Casson St (Kennewell PI)	1	12:14	06-Aug	/	/	/	/	/	X	X	Border sleepers	Needs Repair PCL		
														Deck plastic worn	Monitor	
			2	10:24	20-Aug	/	/	/	/	/	X	X	Carousel rusting/loose in footing	Monitor		
															Spring frog handle loose	Monitor
												Pod mounts worn (eyelet)	Needs repair - LAZ			
104	RICHARDSON PLGR 258	Chauncy Cres	1	11:40	06-Aug	/	/	/	/	/		X	Decking plastic worn	Monitor		
														Swing mounts worn	Monitor	
			2	9:50	20-Aug	/	/	/	/	/			X	Cuts on slide (smoothed)	Monitor	
															Star picks in bark	Needs removal - PCL
105	RICHARDSON PLGR 259	Clift Cres	1	12:03	06-Aug	/	/	/	/	/		X				
														Worn swing chains/mounts/movement in post	Monitor	
			2	10:11	20-Aug	/	/	/	/	/			X	Bark low / dirt in bark	Top up bark - PCL	
													Decking plastic worn/rusting	Monitor		
													Climb net mounts worn	Needs Repair LAZ		

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
106	RICHARDSON PLGR 257	Vidal St	2	10:00	20-Aug	/	/	/	/	/	/	X	Damaged spring animal foot rest	Needs Repair LAZ		
														Climb net links worn	Monitor	
															Climb net bar bent/deck poles	Monitor
															Tyre swing links worn	Monitor
												Bark low/tree debris stacked next to p	Needs top up/removal - PCL			
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN													
108	THEODORE PLGR 265	Dyett Circ	1	11:12	04-Aug	/	/	/	/	X	X	Border sleepers splitting	Monitor			
			2	11:15	18-Aug	/	/	/	/	X	X	Decking timber splitting	Monitor			
												Chain net links worn	Monitor			
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN													
110	THEODORE PLGR 261	Louis Loder St	1	11:01	04-Aug	/	/	/	/	X	X	Border logs splitting	Monitor			
			2	11:04	18-Aug	/	/	/	/	X	X	Decking timber splitting	Monitor			
												Slide f breglass cracking/worn	Monitor			
111	THEODORE PLGR 264	Scantleberry St	1	11:23	04-Aug	/	/	/	/	X	X	Fenced off for repairs	03/06/2020			
														Border logs splitting	Monitor	
			2	11:26	18-Aug	/	/	/	/	X	X	Slide damaged at top	Monitor			
															Spring animal timber worn	Monitor
												Decking timber/panel splitting	Monitor			
112	WANNIASSA PLGR 270	Billson Pl	1	1:42	05-Aug	/	/	/	/	/	X	Baby seat clip broken	Replaced baby clip - J&E			
														Decking plastic worn	Monitor	
			2	1:45	19-Aug	/	/	/	/	/	X	Bridge plastic worn	Needs Repair LAZ			
												Damaged tic tac toe	Monitor			
												Worn rubber on spike spinner	Needs Repair J&E			
			1	2:14	05-Aug	/	/	/	/	X	X	Decking timber worn	Monitor			

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with sofffall	Sortfall free of litter glass/sharp objects	Sortfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
113	WANNIASSA PLGR 267	Bussau Cl	2	2:10	18-Aug	/	/	/	/			X	X	Chain net links worn/plastic peeling	Monitor	
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	2:27	05-Aug	/	/	/	/	/			X	Decking plastic worn x 1	Needs Repair - LAZ	
			2	2:30	18-Aug	/	/	/	/	/			X	Swing mounts/brackets worn	Monitor	
														Grab handle loose	Monitor	
115	WANNIASSA PLGR 275	Hervey Pl	1	1:09	05-Aug	/	/	/	/			X	X	Border sleepers/braces splitting	Needs Repair PCL	
			2	3:01	18-Aug	/	/	/	/			X	X	Decking plastic rust / peeling	Monitor	
														Smoking sign loose in footing	Needs Repair PCL	
														Swing seat damaged/mounts/links worn	Monitor	
116	WANNIASSA PLGR 266	Lansell Circ	1	2:36	05-Aug	/	/	/	/			X	X	Swing mounts worn	Monitor	
			2	1:55	18-Aug	/	/	/	/			X	X	Movement in spring animal	Monitor	
														Border fence panels damaged	Monitor	
117	WANNIASSA PLGR 269	Sainsbury St	1	1:52	05-Aug	/	/	/	/			X	X	Border logs splitting	Monitor	
			2	1:58	19-Aug	/	/	/	/			X	X	Holes in shade sail	Monitor	
														Bum marks on tic tac toe	Monitor	
														Bench seat slats damaged	Needs Repair PCL	
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN													
119	WANNIASSA PLGR 276	Steinfeld Circ	1	1:18	05-Aug	/	/	/	/			X	X	Border Sleepers splitting	Monitor	
			2	2:51	18-Aug	/	/	/	/			X	X	Bench seat slats splitting	Monitor	
														Cracked welds on bridge hand rail	Needs Repair - LAZ	
														Decks worn x 2	Needs Repair - LAZ	
														Bridge slats splitting	Monitor	
														Bridge/Chain net links worn/plastic	Monitor	
														Bearings / wheels damaged on fly fox trolley	Needs Repair J&E	
120	WANNIASSA	Sullivan Cree	1	2:03	05-Aug	/	/	/	/			X	X	Border logs splitting	Monitor	
														Bridge/chain links worn	Monitor	

Name Of Inspector		James		Month of Inspection								Aug-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
120	PLGR 268	Sumivan Cres	2	1:35	19-Aug	/	/	/	/		X	X	Handle plastic worn on flying fox	Monitor	
													Swing seats/mounts worn/splitting	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St	1	1:30	05-Aug	/	/	/	/		X	X	Border sleepers damaged	Needs Repair - PCL	
														Swing mounts worn	Monitor
			2	2:40	18-Aug	/	/	/	/		X	X	Bridge timber splitting	Monitor	
															Park bench missing / damaged timber
													Decking worn/lichen growing	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres	1	1:00	05-Aug	/	/	/	/		X	X	Decking worn / rusting	Monitor	
														Swing mounts/ links worn	Monitor
			2	3:10	18-Aug	/	/	/	/		X	X	Fireman pole damaged	Monitor	
															Roman triangles links worn plastic worn
													Chain net links worn	Monitor	
123	WANNIASSA PLGR 272	Whiteman St	1	2:21	05-Aug	/	/	/	/		X	X	Swing mounts/s hooks/ chains worn	Monitor	
			2	2:21	18-Aug	/	/	/	/		X	X	Border logs splitting	Monitor	



Name Of Inspector: James Month of Inspection: Aug-20

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
						/	x	/	x	/	x	/	x	/	x	/	x			/	x	Hazard
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	10:18	06-Aug	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban		
																				Awning louver mounts rusting	Monitor	
			2	7:37	19-Aug	/		/		/		/		/					X			
																					Pommel links/mounts worn/hosing split	Monitor
																					Swing mounts/brackets worn	Monitor
																					2 x tread caps missing on surfer	Monitor
																					Bridge metal slip hazard	Angle / monitor
																					Basketball backboard worn	Monitor
																					Climb chain mounts/links worn/hosing split	Monitor
																					Rubber soft fall worn	Monitor
2	COTTER PLGR 539	CASURINA SANDS	1	9:50	06-Aug	/		/		/		/		/				X	Post timber splitting	Monitor		
																				Decking timber splitting	Monitor	
			2	7:18	19-Aug	/		/		/		/		/					X	Rope bridge wearing	Monitor	
3	GREENWAY PLGR 538	Pine Island Rd	1	11:53	03-Aug	/		/		/		/			X	X			Border logs splitting	Monitor		
			1	9:35	10-Aug	/		/		/		/			X	X			Climbing wall worn/rusting	Monitor		
			2	10:19	17-Aug	/		/		/		/			X	X			Movement in staircase footing	Monitor		
			1	9:38	24-Aug	/		/		/		/			X	X				Swing mounts/chains worn	Monitor	
			1	9:59	31-Aug	/		/		/		/			X	X				Staircase edges cracking	Needs repair - LAZ	
																					Decks/bridge worn/rusting	Needs repair - LAZ
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND																	Tightened loose swing bolts	Repaired - J&E 17/08/20		
																				Bark low/roots in bark	Needs Top up/removal - PCL	
			1	10:56	06-Aug	/		/		/		/			X	X				Fence timber splitting around water tanks	Monitor	
																					Timber splitting on large spring platform	Monitor
			2	8:21	19-Aug	/		/		/		/			X	X					Water tanks decking timber splitting/worn	Monitor
																					Flying fox posts splitting	Monitor
																					Spider climb net rope frayed	Monitor
																					Water tanks damaged - Siliconed	Monitor
																					Tree roots lifting paths	Needs Repair PCL
																					Rubber soft fall splitting	Needs Repair PCL on going problem
																		Slide beds damaged	Monitor			
																		Timber bridges splitting/damaged/lifting/	Needs repair - PCL			
																		Flat seat swing mounts worn	Monitor			
																		Swing links/seats/brackets worn	Monitor			
																			Side of small slides has cracked welds	Needs repair - LAZ		
																			Flying fox cable detached	Needs repair - LAZ		



Name Of Inspector

James

Month of Inspection

Aug-20

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

Inspectors Signature: J.Gardner

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.



Name Of Inspector Domenik Month of Inspection Sep-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection Time	Date of Inspection Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description Hazard	Action Taken- For full details please refer to attached Playground Safety Inspection Report Action			
							/	x	/	x	/	x	/	x	/	x	/	x			/	x	
1	BANKS PLGR 413	Pocket Ave		1	800	04-Sep	/		/		/		/			X	X		Loose slide leg	Monitor			
				1	1130	09-Sep	/		/		/		/		/		X	X		Chain net links/mounts worn	Monitor / Needs Repair LAZ		
				1	1120	18-Sep	/		/		/		/		/		X	X		Track ride worn links	Monitor		
				2	1350	23-Sep	/		/		/		/		/		X	X		Border concrete cracking / lifting	Needs Repair PCL		
							/		/		/		/		/		X	X		Small plastic slide damaged	Monitor		
																		Tiger totes arms missing	07/01/2019				
2	BONYTHON PLGR 535	Burgoyne St		1	1600	04-Sep	/		/		/		/				X		Ropes worn on climb net	Monitor			
				1	630	09-Sep	/		/		/		/		/			X		Spinner seat small crack in plastic	Monitor		
				1	700	18-Sep	/		/		/		/		/			X		Chain/mounts worn	Monitor		
				2	1430	23-Sep	/		/		/		/		/			X		Collar pins worn	Monitor		
							/		/		/		/		/			X			Swing end caps missin x2	Monitor	
																		Black rubber mount points melting	Monitor				
3	FADDEN PLGR 228	Coyne St		1	907	04-Sep	/		/		/		/			X	X		Swing mounts worn	Monitor			
				1	1000	09-Sep	/		/		/		/		/		X	X		Cracked welds on slide entry	Monitor		
				1	1010	18-Sep	/		/		/		/		/		X	X		Worn links bridge/climb chains	Monitor		
				2	740	23-Sep	/		/		/		/		/		X	X		Timber split on panels	Monitor		
							/		/		/		/		/		X	X		Border logs splitting	Monitor		
																						Holes in softfall / splitting	Needs repair - PCL
																						Footpath lifting	Needs repair - PCL
																						Slide footing loose	Monitor
																		Spinning seesaw hanger has worn bolts/handle	Monitor				
																		Hose splitting on chain covers	Monitor				
																		Movement in brackets on web towers	Monitor				
4	GORDON PLGR 278	McGilvray Circ		1	700	04-Sep	/		/		/		/			X	X		Fibreglass on tea cup spinner cracking	Monitor			
				1	700	06-Sep	/		/		/		/		/		X	X		Swing mounts worn x 2	Needs Repair - J&E		
				1	1145	09-Sep	/		/		/		/		/		X	X		Damaged see-saw brackets x 3	Needs Repair - J&E		
				1	700	13-Sep	/		/		/		/		/		X	X		Climb net rope worn	Monitor		
				1	1130	18-Sep	/		/		/		/		/		X	X		Spinner top bearings loose	Monitor		
				1	600	20-Sep	/		/		/		/		/		X	X		Damaged super nova	Monitor		
				2	1405	23-Sep	/		/		/		/		/		X	X		Border logs splitting	Monitor		
				1	600	27-Sep	/		/		/		/		/		X	X		Roman triangles worn links	Needs repair - LAZ		
							/		/		/		/		/		X	X		Wire walk cable worn	Monitor		
																						Decking worn on tower	Monitor
																						Wire bridge mount worn/chain low links worn	Needs repair - LAZ
																						Cracked welds in tower/rust	Needs repair - LAZ
																						Rubber Soft fall splitting/holes	Needs repair - PCL
																		Swing chains/brackets/mounts	Monitor				
																		bench below tea cup playground coming out of footing	Needs repair - PCL				
																		Hole in shade sail	Monitor				
5	GOWRIE PLGR 328	Jeffries St		1	925	04-Sep	/		/		/		/				X		Softfall splitting / holes forming	Needs Repair PCL			
				1	944	09-Sep	/		/		/		/		/				X		Timber worn on carousel	Monitor	
				1	1000	18-Sep	/		/		/		/		/				X		Spider net worn	Monitor	
				2	820	23-Sep	/		/		/		/		/				X				



Name Of Inspector		Domenik		Month of Inspection								Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Suburb	Street	Level 1/2	Time	Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition			Equipment in safe and satisfactory condition	Hazard	Action
					/	x	/	x	/	x	/	x	/	x	/	x		
6	GREENWAY PLGR 242	Anketell St	1	1505	04-Sep	/		/		/		/		X	X	Border sleepers missing and rotten	Needs Repair - PCL	
			1	800	06-Sep	/		/		/		/		X	X			
			1	742	09-Sep	/		/		/		/		X	X	Swing brackets/mounts worn	Needs Repair - J&E	
			1	743	13-Sep	/		/		/		/		X	X	Digger bucket has a hole	Needs Repair - LAZ	
			1	750	18-Sep	/		/		/		/		X	X	Worn ropes on bridge	Monitor	
			1	630	20-Sep	/		/		/		/		X	X	Bolt caps missing on see saw	Repaired by J&E 27/9/19	
			2	1205	23-Sep	/		/		/		/		X	X	Tyre swing mounts worn/crossbar movement in sleeve/s hooks	Monitor	
			1	800	27-Sep	/		/		/		/		X	X	Log steps/posts splitting on tower	Monitor	
								/		/		/		X	X	Tower fort movement in footing	Monitor	
														Seesaw panels worn	Monitor			
7	GREENWAY PLGR 240	De Little Circ PLAR 286	1	1340	04-Sep	/		/		/		/		X	X	Spider net worn	Monitor	
			1	815	09-Sep	/		/		/		/		X	X	Handle rubber split on Spring Carousel	Monitor	
			1	820	18-Sep	/		/		/		/		X	X	Graffiti on post	Remove - PCL	
			2	1110	23-Sep	/		/		/		/		X	X	Spring boat loose footings	Monitor	
								/		/		/		X	X	Holes in softfall	Needs repair - PCL	
8	GREENWAY PLGR 417	Eileen Good St	1	1515	04-Sep	/		/		/		/		X	X	Swing seat/bracket/links worn	Monitor	
			1	735	09-Sep	/		/		/		/		X	X	Bark low	Needs Top up - PCL	
			1	730	18-Sep	/		/		/		/		X	X	Border logs splitting	Monitor	
			2	1225	23-Sep	/		/		/		/		X	X	Baby seat worn	Monitor	
								/		/		/		X	X	Fort/seesaw timber splitting	Monitor	
9	GREENWAY PLGR 240	Florence Taylor St PLAR 288	1	1455	04-Sep	/		/		/		/		X	X	Decking worn	Monitor	
			1	759	09-Sep	/		/		/		/		X	X	Bark low	Needs Top up - PCL	
			1	800	18-Sep	/		/		/		/		X	X	Concrete border lifting	Monitor	
			2	1147	23-Sep	/		/		/		/		X	X	Crack in slide plastic	Monitor	
								/		/		/		X	X			
124	GREENWAY PLGR	Limburg Way	1	1525	04-Sep	/		/		/		/		X	X	Timber decking splitting	Monitor	
			1	715	09-Sep	/		/		/		/		X	X	Climb wall timber splitting	Monitor	
			1	726	18-Sep	/		/		/		/		X	X	Swing seat brackets worn	Monitor	
			2	1235	23-Sep	/		/		/		/		X	X	Part playground fenced off	New rubber and equipment being installed	
					/		/		/		X	X						
10	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	1	1338	04-Sep	/		/		/		/		X	X	Bark low	Needs Top up - PCL	
			1	825	09-Sep	/		/		/		/		X	X	Decks rusted/plastic worn	Monitor	
			1	830	18-Sep	/		/		/		/		X	X	Bridge plastic worn	Monitor	
			2	1130	23-Sep	/		/		/		/		X	X	Swing seat/brackets/mounts/s-hooks worn	Monitor	
								/		/		/		X	X	Stair footing loose	Monitor	
																	loose bolt fort roof (nutsert)	Monitor
														Movement in swing frame	Monitor			
11	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET															
			1	1153	04-Sep	/		/		/		/		X	X	Bearings/guide rollers worn on fly fox	Monitor	



Name Of Inspector Domenik Month of Inspection Sep-19

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
				Level 1 or Level 2			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/			x	/
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	850	09-Sep	/		/		/				X		X		Swing mounts/brackets worn	Monitor		
				1	900	18-Sep	/		/		/		/			X		X		Concrete border lifting	Monitor	
				2	1000	23-Sep	/		/		/		/			X		X		Bridge slats splitting	Monitor	
							/		/		/		/				X		X		Movement in see saw base	Monitor
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	1140	04-Sep	/		/		/				X		X		Damaged concrete border	Monitor		
				1	855	09-Sep	/		/		/		/			X		X		Damaged park seat	Needs repair - PCL	
				1	905	18-Sep	/		/		/		/			X		X		baby swing damaged	Monitor	
				2	940	23-Sep	/		/		/		/			X		X		Plastic Rock on climb wall cracking	Monitor	
							/		/		/		/				X		X		Movement in base of carousel	Needs repair - J&E
14	KAMBAH PLGR 305	Springbett St		1	1150	04-Sep	/		/		/				X		X		Twin S/S slide has crack in surface	Monitor		
				1	840	06-Sep	/		/		/		/			X		X		Swing seat/brackets/links/mounts worn	Monitor	
				1	835	09-Sep	/		/		/		/			X		X		Super nova damaged	Monitor	
				1	900	13-Sep	/		/		/		/			X		X		Hosing split on carousel	Monitor (taped)	
				1	840	18-Sep	/		/		/		/			X		X		Mount worn on large fly fox	Monitor	
				1	650	20-Sep	/		/		/		/			X		X		Border logs splitting	Monitor	
				2	1025	23-Sep	/		/		/		/				X		X		Sml fly fox movement in bolt	Monitor
				1	850	27-Sep	/		/		/		/				X		X		Tic Tac Toe damaged (taped)	Needs Repair J&E
							/		/		/		/				X		X		Damage panel on quad hoops	Monitor
																					Low branches at swings & fly fox/grass in bark	Cut back/remove - PCL
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	1030	04-Sep	/		/		/				X		X		Burn marks at liberty swing seat	Monitor		
				1	921	09-Sep	/		/		/		/			X		X		Bark low/ washed out	Needs repair - PCL	
				1	935	18-Sep	/		/		/		/			X		X		Bark low	Needs Top up - PCL	
				2	910	23-Sep	/		/		/		/			X		X		Burn mark seesaw	Monitor	
							/		/		/		/				X		X		Swing mounts	Monitor
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	1040	04-Sep	/		/		/						X		Timber swing posts splitting/ missing swings	?		
				1	916	09-Sep	/		/		/		/					X		Worn decks/ bridge	Monitor	
				1	930	18-Sep	/		/		/		/					X		Damaged rock wall	Monitor	
				2	925	23-Sep	/		/		/		/						X		Rope worn on carousel	Monitor
							/		/		/		/						X		Swing seat / brackets worn	Monitor
17	MACARTHUR PLGR 327	Bayly Pl		1	850	04-Sep	/		/		/						X		Bark low	Needs Repair PCL		
				1	1030	09-Sep	/		/		/		/					X		Worn swing links/brackets	Monitor	
				1	1030	18-Sep	/		/		/		/					X		Rope worn on climbing net/carousel	Monitor	
				2	720	23-Sep	/		/		/		/						X		Movement in base towards post of carousel	Needs repair - J&E
							/		/		/		/						X		Gravel washed into bark	Needs removal PCL
18	THEODORE PLGR 263	Chippindall Circ		1	820	04-Sep	/		/		/						X		Low bark	Needs Top up - PCL		
				1	1115	09-Sep	/		/		/		/					X		Softfall patches lifting under birds nest swing	Needs Repair PCL	
				1	1050	18-Sep	/		/		/		/					X		Swing mounts/brackets worn	Monitor	
				2	615	23-Sep	/		/		/		/					X		Carousel seat worn/rusting	Monitor	
																	Worn/damaged deck/bridge	Monitor				
																		Loose handle/footings on spring animal x 2	Monitor			



Name Of Inspector

Domenik

Month of Inspection

Sep-19

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action
	PLGR 205					/		/		/		/		/			X		
																		Holes in shade sail	Monitor
																		Low bark	Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	830	04-Sep	/		/		/		/			X	X		Weld cracking at slide entry	Needs Repair - LAZ
			1	1105	09-Sep	/		/		/		/			X	X		Decking plastic worn/surface rust	Monitor
			1	1040	18-Sep	/		/		/		/			X	X		Swing/Chain bridge links/mounts worn	Monitor
			2	630	23-Sep	/		/		/		/			X	X		Movement in frog footing	Monitor
						/		/		/			X	X			Border concrete cracking	Needs Repair - PCL	
20	WANNIASSA PLGR 271	Sangster Pl	1	945	04-Sep	/		/		/		/		X	X			Swing mounts brackets worn	Monitor
			1	930	09-Sep	/		/		/		/			X	X		Decking worn	Monitor
			1	950	18-Sep	/		/		/		/			X	X		Hole in chain wire fence	Needs Repair - LAZ
			2	839	23-Sep	/		/		/		/			X	X		Park bench missing arm rest	Needs Repair - PCL
						/		/		/			X	X			Holes and splitting in softfall	Needs repair - PCL	

Inspectors Signature: D.Radman

Name Of Inspector		Domenik		Month of Inspection								Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report						
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition				Equipment in safe and satisfactory condition					
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action			
1	BANKS PLGR 213	Menzies Court	1	1230	05-Sep	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																			Decking plastic worn/surface rust	Monitor	
			2	705	24-Sep	/		/		/		/				X		X			
																				Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	1	1240	05-Sep	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																			Swing seat brackets worn	Monitor	
			2	700	24-Sep	/		/		/		/				X		X	Decking worn	Monitor	
																				Dints in slide bed	Monitor
																		Border concrete cracking	Needs Repair - J&E		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	1045	05-Sep	/		/		/		/					X	Posts/handrail split/rotting	Monitor		
																			4 x Post damaged/split on fort	Monitor	
			2	1210	19-Sep	/		/		/		/						X	Chain net links and mounts worn	Monitor	
																				Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	1000	05-Sep	/		/		/		/			X		X	Border logs splitting	Monitor		
																			Swing seat/brackets damaged /worn	Monitor	
			2	1230	19-Sep	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																		Slide has crack at entry/movement	Monitor		
7	BONYTHON PLGR 586	Morice Pl	1	1010	05-Sep	/		/		/		/					X	Hosing loose on pommel	Repaired by J&E 5/9/19		
																				Swing seat brackets worn	Monitor
			2	1220	19-Sep	/		/		/		/						X	Worn / missing rope on net	Monitor - taped / Removed	
																		Worn links	Monitor		

Name Of Inspector		Domenik		Month of Inspection						Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
8	CALWELL PLGR 322	Beckett St	1	1215	09-Sep	/	/	/	/	/	X	Decking plastic worn	Monitor	
												Swing mounts worn	Monitor	
			2	1040	19-Sep	/	/	/	/	/	X	Bent monkey bars	Monitor	
													Baby swing safety chain clip damaged	Repaired by J&E 9/9/19
													Slide weld cracking at top	Needs Repair - LAZ
													Chain wa k hand rail bent	Needs Repair - LAZ
													Bent deck poles	Needs Repair - LAZ
										Low tree branches	Needs Removal PCL			
9	CALWELL PLGR 321	Casey Cres	1	1305	09-Sep	/	/	/	/	/	X	Swing mounts worn	Monitor	
												Decking plastic worn/decks rusting	Monitor	
			2	1000	19-Sep	/	/	/	/	/	X	Chain net links worn/coating on chains	Monitor	
													See saw timber splitting	Monitor
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	1	1230	09-Sep	/	/	/	/	/	X	Decking plastic worn	Monitor	
												Swing mounts/seat/links worn	Monitor	
			2	1030	19-Sep	/	/	/	/	/	X	Low branches	Needs cut back back-PCL	
										Side leg bent	Monitor			
11	CALWELL PLGR 319	Samuel Cl	1	1300	09-Sep	/	/	/	/	X	X	Border logs splitting	Monitor	
												Swing mounts worn	Monitor	
			2	1005	19-Sep	/	/	/	/	X	X	Bent monkey bars	Monitor	
													Park bench missing timber	Needs Repair - PCL
12	CALWELL	Shopping Centre	1	1244	09-Sep	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor	
												Bark low	Top up bark PCL	
			2	1015	19-Sep	/	/	/	/	/	X			
											Courousel movement in bearing	Monitor		
13	CALWELL PLGR 320	Were St	1	1250	09-Sep	/	/	/	/	X	X	Border logs splitting	Monitor	
												Swing links/mounts worn	Monitor	
			2	1010	19-Sep	/	/	/	/	X	X	Tire worn on tyre swing	Monitor	
14	CHISHOLM	Alton St	1	850	19-Sep	X	/	/	/	/	X	Swing mounts worn	Monitor	
			2	720	25-Sep	X	/	/	/	/	X	Bent deck poles	Needs Repair - LAZ	

Name Of Inspector		Domenik		Month of Inspection							Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
14	PLGR 234												Damaged tic tac toe	Monitor
													Baby seat chain cover worn	Monitor
													Fly fox handle plastic worn	Monitor
15	CHISHOLM PLGR 233	1	825	19-Sep	/	/	/	/	/	/	X		Timber decking splitting	Needs repair - J&E
													Tyre swing mounts worn	Monitor
		2	715	25-Sep	/	/	/	/	/	/	X		Fly fox links worn	Monitor
													Chain net mounts worn	Monitor
													Fly fox nylon guides worn	Needs Repair - J&E
													Bench seat damaged	Needs Repair PCL
16	CHISHOLM PLGR 232	1	805	19-Sep	/	/	/	/	/	/	X		Timber decking splitting	Monitor
													Track ride not gliding with ease	Needs Repair - J&E
		2	645	25-Sep	/	/	/	/	/	/	X		Swing seat damaged/brackets/links worn	Monitor
													Post loose in footing	Monitor
													Uneven paving around playground	Needs Repair PCL
17	CHISHOLM PLGR 231	1	810	19-Sep	/	/	/	/	/	/	X		Timber decking splitting	Monitor
													Slide damaged at exit	Monitor
		2	700	25-Sep	/	/	/	/	/	/	X		Log steps splitting	Monitor
													Damaged park bench	Needs Repair - PCL
													Tyre /s hooks wearing on tire swing	Monitor
													Graffiti on slide	Remove - PCL
18	CHISHOLM PLGR 235	1	835	19-Sep	/	/	/	/	/	/	X		Swing mounts/links worn	Monitor
													Decking plastic worn/rusting	Monitor
		2	738	25-Sep	/	/	/	/	/	/	X		Climb net mounts/plastic worn	Monitor
													Plastic at slide exit damaged	Needs Repair J&E
19	CHISHOLM PLGR 230	1	815	18-Sep	/	/	/	/	/	/	X		Decking plastic worn	Monitor
													Tyre swing mounts worn	Monitor
		2	708	25-Sep	/	/	/	/	/	/	X		Climb net links worn	Monitor
													Damaged park bench	Monitor
													Plastic panel damaged	Monitor
													Concrete border damaged	Needs repair - J&E
													Bent/damaged deck poles	Needs repair - LAZ
20	CHISHOLM PLGR 236	1	830	18-Sep	/	/	/	/	/	/	X		Swing mounts/links/seat worn	Monitor
													Low bark	Needs top up - PCL
		2	745	25-Sep	/	/	/	/	/	/	X		Dints in slide	Monitor



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik			Month of Inspection				Sep-19				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
27	PLGR 228	Coyne St	MONDAY RUN											
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	705	19-Sep	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor	
												Border timber damaged	Needs Repair PCL	
			2	845	25-Sep	/	/	/	/	X	X	Movement in carousel base	Monitor	
												Decking timber splitting	Monitor	
												Chain net links / mounts worn	Monitor	
29	FADDEN PLGR 509	Nicklin Cres										Lichen growing on decks	Monitor	
			1	655	19-Sep	/	/	/	/	X	X	Border timber splitting	Monitor	
												Rocks missing in border wall	Needs Repair - J&E	
			2	855	25-Sep	/	/	/	/	X	X	Rope bridge mount broken/rope worn	Needs Repair J&E	
												Climbing nets rope worn	Monitor	
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)										Panel/ roof panels cracked on fort	Monitor	
			1	715	19-Sep	/	/	/	/	X	X	Tower posts splitting	Monitor	
												Swing mounts/ links worn	Monitor	
			2	836	25-Sep	/	/	/	/	X	X	Border logs worn	Monitor	
												Dent in parallel bars/swing pos	Monitor	
31	GILMORE PLGR 238	Heagney Cres	1	743	19-Sep	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor	
												Rubber frog damaged	Monitor	
			2	615	25-Sep	/	/	/	/	X	X	Low bark	Needs Top up - PCL	
32	GILMORE PLGR 239	Hogue Pl	1	748	19-Sep	/	/	/	/	X	X	Fence damaged	Monitor	
												Spinner seats worn/ rusting	Monitor	
			2	628	25-Sep	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL	
												Bark low	Top up bark PCL	
33	GORDON PLGR 215	Rosman Circ	1	755	19-Sep	/	/	/	/	/	/	Bridge timber splitting	Monitor	
												Concrete at bench lifting	Needs Repair PCL	
			2	635	25-Sep	/	/	/	/	/	/			
33	GORDON PLGR 215	Iredale Pl	1	1115	05-Sep	/	/	/	/	/	X	Swing seat brackets worn	Monitor	
												Chain net/ladder links worn/plastic	Monitor	
			2	815	24-Sep	/	/	/	/	/	X	Damaged post caps x 4	Monitor	
												Slide damaged	Monitor	

Name Of Inspector		Domenik		Month of Inspection						Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
34	GORDON PLGR 216	Kirkwood Cres	1	1150	05-Sep	/	/	/	/	X	X	Swing seat brackets/mounts wearing	Monitor		
													Slide surface dented	Monitor	
			2	755	24-Sep	/	/	/	/	X	X	Dent in swing crossbar/see saw seat	Monitor		
													Border sleeper damaged near slide	Needs Repair PCL	
												Tyre swing mounts worn	Monitor		
			35	GORDON PLGR 279	Evan Pl	1	1135	05-Sep	/	/	/	/	X	Chain climb net links wearing	Monitor
															Bridge/deck plastic worn/rusting in corners
			2	805	24-Sep	/	/	/	/	X					
36	GORDON PLGR 218	Knoke Ave	1	1220	05-Sep	/	/	/	/		X	Decking plastic worn	Monitor		
												Bolt caps damaged on see saw	Repaired by J&E 24/9/19		
			2	725	24-Sep	/	/	/	/	/	X	Climb net links/mounts/plastic worn	Monitor		
											Bench seat slat damaged	Needs Repair PCL			
37	GORDON PLGR 278	McGilvray Circ	MONDAY RUN												
38	GORDON PLGR 217	Popplewell Pl (Tallon Pl)	1	1159	05-Sep	/	/	/	/	/	X	Tic tac damaged	Monitor		
													Dents in slide	Monitor	
			2	750	24-Sep	/	/	/	/	/	X	Decking worn/surface rust	Monitor		
											Chain net mounts worn	monitor			
39	GORDON PLGR 214	Noel Ryan Gardens	1	1058	05-Sep	/	/	/	/	X	X	Fort post splitting	Monitor		
													Slide crack at entry/worn	Removed for Repair J&E	
			2	825	24-Sep	/	/	/	/	X	X	Tree roots in bark/ at bottom of slide	Needs Removal - PCL		
													Seesaw seat cracked	Needs Repair LAZ	
													Log steps splitting and rotten	Monitor	
											Concrete border lifting	Monitor			
											Chain bridge links worn	Monitor			
40	GOWRIE PLGR 332	Inwood Pl (Sadlier St)	1	620	19-Sep	/	/	/	/	X	X	Border logs splitting	Monitor		
													Seesaw timber worn	Monitor	
			2	950	25-Sep	/	/	/	/	X	X	Bolt caps damaged on see saw	Needs Repair J&E		



Name Of Inspector		Domenik			Month of Inspection					Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
41	GOWRIE PLGR 328	Jeffries St	MONDAY RUN											
	GOWRIE	Howell Pl	1	600	19-Sep	/	/	/	/	/		X	Smoking sign missing	Needs Repair PCL
			2	1010	25-Sep	/	/	/	/	/		X		
42	GOWRIE PLGR 333	Middleton Circ	1	616	19-Sep	/	/	/	/		X	X	Swing mounts/ links worn	Monitor
			2	955	25-Sep	/	/	/	/		X	X	Border concrete cracking	Monitor
43	GOWRIE PLGR 335	Weathers St	1	630	19-Sep	/	/	/	/	/		X	Swing mounts/links worn/rusty	Monitor
			2	920	25-Sep	/	/	/	/	/		X	Slide dented	Monitor
													Pickets / sign at park	Needs Removal PCL
44	GOWRIE PLGR 334	Wray Pl	1	624	19-Sep	/	/	/	/		X	X	Swing posts splitting	Monitor
			2	940	25-Sep	/	/	/	/		X	X	Swing mounts/ links worn	Monitor
													Border sleepers splitting	Monitor
													Concrete border cracked/lifting	Monitor
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN											
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN											
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN											
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN											



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik			Month of Inspection				Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN												
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET												
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	750	05-Sep	/	/	/	/		X	X	Ropes worn on web	Monitor	
			2	1120	19-Sep	/	/	/	/		X	X	Posts splitting/rotten	Monitor	
														Swing mounts/seat worn	Monitor
														Decking posts bent	Needs Repair J&E
														Concrete border lifting	Needs Repair PCL
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	735	05-Sep	/	/	/	/	/		X	Slide surface worn	Monitor	
			2	1110	19-Sep	/	/	/	/	/		X	Decking timber splitting	Monitor	
														Bark low	Monitor
														Swing mounts worn	Monitor
														Plastic slide cracked	Monitor
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	720	05-Sep	/	/	/	/		X	X	Movement in swing posts	Monitor	
			2	1100	19-Sep	/	/	/	/		X	X	Frog plastic worn around handle	Monitor	
														Border path concrete cracking	Monitor
														Slide surface worn	Monitor
														Chain net links/mounts worn	Monitor
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	1138	13-Sep	/	/	/	/	/		X	Spring animal missing	Needs repair - J&E	
			2	1320	24-Sep	/	/	/	/	/		X	Slide leg loose in footing	Monitor	
														Low bark / concrete exposed	Top - PCL
														Spring animal loose in footing	Monitor
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	1151	13-Sep	/	/	/	/		X	X	Angle bar missing at climbing net damaged	Needs repair - LAZ	
			2	1330	24-Sep	/	/	/	/		X	X	Border logs splitting	Monitor	
														Swing mounts worn	Monitor
														Concrete lifting quad hoop game	Monitor
														Chain net links / mounts worn	Monitor
												Swing seat brackets worn	Monitor		
			1	1110	13-Sep	/	/	/	/		X	X	Border logs damaged	Needs Repair PCL	

Name Of Inspector		Domenik		Month of Inspection								Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
57	KAMBAH PLGR 313	Attiwell Circ	2	1300	24-Sep	/	/	/	/		X	X	Swing mounts worn/loose due to timber shrinking	Monitor		
														Bench seat frame bent	Monitor	
															Swing timber damage/splitting	Monitor
															Asphalt cracking / lifting	Needs Repair PCL
												See-saw footrest damaged	Monitor			
58	KAMBAH PLGR 314	Barritt St	1	1120	13-Sep	/	/	/	/	/		X	2 x Decking plastic worn > 60%	Needs Repair - LAZ		
														Bridge plastic worn/ rusted	Monitor	
			2	1250	24-Sep	/	/	/	/	/		X		Welds cracked on chain ne	Needs Repair - LAZ	
												Fort panel movement	Monitor			
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN													
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN													
61	KAMBAH PLGR 301	Boustead Circ	1	1013	13-Sep	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Damaged plastic on stairs	Monitor	
			2	1140	24-Sep	/	/	/	/		X	X		Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	1300	13-Sep	/	/	/	/		X	X	Timber decking splitting	Monitor		
														Swing posts splitting and rotten	Monitor	
			2	955	26-Sep	/	/	/	/		X	X		Movement in ladder plate to decking	Monitor	
															Timber border lifting/damaged	Monitor
															Swing mounts/brackets worn/small movement	Monitor
												Bark washed out	Needs Repair - PCL			
63	KAMBAH PLGR 317	Bullock Circ	1	1047	13-Sep	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Rubber on stairs splitting	Monitor	
			2	1240	24-Sep	/	/	/	/		X	X		Worn rubber on deck	Needs Repair J&E	
															Climb chain links worn	Monitor
															Bridge links worn	Monitor
												Swing mounts/brackets worn	Monitor			
	KAMBAH		1	1420	13-Sep	/	/	/	/		X	X	Swing mounts worn	Monitor		
													Border logs splitting	Monitor		

Name Of Inspector		Domenik		Month of Inspection								Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
71	KAMBAH PLGR 289	Horton Cl	2	820	26-Sep	/	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL		
														Parallel slide bar bent	Monitor	
															Wearing swing brackets	Monitor
															Tyre swing tyre worn	Needs Repair J&E
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	1	1219	13-Sep	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
														Bridge slats splitting	Needs Repair J&E	
			2	1355	24-Sep	/	/	/	/	/	X	X				
															Bridge/ chain net links worn	Monitor
73	KAMBAH PLGR 307	Humble Court	1	1345	13-Sep	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			2	910	26-Sep	/	/	/	/	/	X	X	Slide dented	Monitor		
															Low bark	Needs Repair - PCL
													Brunt out car near playground	Needs Removal PCL		
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	1034	13-Sep	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
														Deck plastic worn	Monitor	
			2	1135	24-Sep	/	/	/	/	/		X	Handle loose on turtle	Monitor		
75	KAMBAH PLGR 286	Lascelles Circ	1	1250	13-Sep	/	/	/	/	/	X	X	Border Sleepers splitting	Monitor		
														See saw Top centre plate cracked	Needs Repair - LAZ	
			2	1010	26-Sep	/	/	/	/	/	X	X	Low branches	Cut back - PCL		
															Bridge slats splitting/links worn/movement	Monitor
													Chain net links worn	Monitor		
													Decking plastic worn	Monitor		
76	KAMBAH PLGR 325	Learmonth Dr	1	1020	13-Sep	/	/	/	/	/	X	X	Fort Timber panels worn/split	Monitor		
														Climb net ropes worn	Monitor	
			2	1150	24-Sep	/	/	/	/	/	X	X	Timber posts splitting	Monitor		
															Rock wall missing rocks	Needs Repair J&E
													Spring motorcycle panels worn	Monitor		
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	1	1410	13-Sep	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
														Decking plastic worn	Monitor	
			2	840	26-Sep	/	/	/	/	/	X	X	Burn marks on post / slide	Monitor		
															Fly fox handle broken off	Needs Repair J&E
													Bridge/Climb net links worn	Monitor		

Name Of Inspector		Domenik		Month of Inspection						Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
												Bridge slats splitting/movement worn timber	Monitor
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	1405	13-Sep	/	/	/	/	/	X	Monitor all links in hosing	Monitor
			2	850	26-Sep	/	/	/	/	/	X	Damaged rubber chain hose Bench seat slat damaged	Monitor Needs Repair PCL
79	KAMBAH PLGR 314	Mannheim St	1	1317	13-Sep	/	/	/	/	X	X	Border logs splitting Bridge slats splitting	Monitor Monitor
			2	920	26-Sep	/	/	/	/	X	X	Swing mounts worn Welds cracked at slide entry Bridge links worn	Monitor Needs Repair - LAZ Monitor
80	KAMBAH PLGR 285	Marconi Cres	1	1225	13-Sep	/	/	/	/	/	X	Swing brackets/mounts worn Gravel washed/weeds into bark	Monitor Needs Removal - PCL
			2	1400	24-Sep	/	/	/	/	/	X	Deck edge wear Spring bear loose in footing	Monitor Monitor
81	KAMBAH PLGR 308	Maxworthy St	1	1330	13-Sep	/	/	/	/	/	X	Swing mounts worn Bark low	Monitor Needs Top up - PCL
			2	905	26-Sep	/	/	/	/	/	X	Damaged spinner seats x 2	Needs Repair - J&E
82	KAMBAH PLGR 292	McKillop Pl	1	954	13-Sep	/	/	/	/	X	X	Border sleepers splitting 2 x decks plastic worn	Monitor Needs Repair - LAZ
			2	1115	24-Sep	/	/	/	/	X	X	Swing seat/brackets worn Bridge/decks rusting Flat swing seat damaged	Monitor Monitor Monitor
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	1009	13-Sep	/	/	/	/	X	X	Border sleepers splitting Slide has small dents	Monitor Monitor
			2	1125	24-Sep	/	/	/	/	X	X	Split rubber on stairs Graffiti on panel	Monitor Needs Removal PCL
84	KAMBAH PLGR 302	Pinkerton Circ	1	930	13-Sep	/	/	/	/	X	X	Border timber splitting/damaged Decking plastic worn/surface rust	Needs Repair - PCL Monitor
			2	1100	24-Sep	/	/	/	/	X	X	Swing mounts/links/brackets worn Low tree branches Exposed tree roots in bark	Monitor Needs removal- PCL Needs removal- PCL
			1	1157	13-Sep							Bark low new playground under construction	Needs Top up - PCL Fenced off

Name Of Inspector		Domenik		Month of Inspection				Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
85	KAMBAH PLGR 306	Primmer Court	2	1340	24-Sep										
86	KAMBAH PLGR 303	Rounsevell St	1	1027	13-Sep	/	/	/	/	X	X	Border logs splitting	Monitor		
													Swing mounts worn	Monitor	
			2	1155	24-Sep	/	/	/	/	X	X	Slide metal rusting/ dented	Monitor		
													spring animal footing loose	Needs Repair J&E	
											Lap seat worn	Monitor			
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN												
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN												
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN												
90	KAMBAH PLGR 290	Toole Pl	1	945	13-Sep	/	/	/	/	X	X	Swing posts splitting	Monitor		
													Swing mounts/brackets worn	Monitor	
			2	1110	24-Sep	/	/	/	/	X	X	Swing Mounts have small movement due to worn timber	Monitor		
														Bridge links worn	Monitor
														Climb net links/mounts worn	Monitor
														Star pickets in bark	Needs Removal PCL
											Border sleepers splitting	Monitor			
			1	1351	13-Sep	/	/	/	/	X	X	Border sleepers splitting	Monitor		
												Decking / bridge plastic worn	Monitor		
			2	857	26-Sep	/	/	/	/	X	X	Movement in stair footing	Monitor		

Name Of Inspector		Domenik		Month of Inspection				Sep-19				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
91	MONASH PLGR 293	Vanzetti Cres										Bridge plastic worn	Monitor	
												Swing mounts worn	Monitor	
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN											
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	730	19-Sep	/	/	/	/	X	X	Decking worn	Monitor	
			2	825	25-Sep	/	/	/	/	X	X	Chain net links/mounts worn	Monitor	
													Bent deck poles	Monitor
													Border damaged/rotted	Needs Repair - PCL
											Worn timber on spring horse	Monitor		
											Bark low and footings exposed	Needs Top up - PCL		
94	MONASH PLGR 252	Alabaster St	1	1410	18-Sep	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			2	630	26-Sep	/	/	/	/	X	X	Swing mounts/ links worn	Monitor	
													Damaged spiral ladder	Monitor
													Damaged tic tac toe	Monitor
											Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	1	1430	18-Sep	/	/	/	/	/	X	Posts splitting and rotten	Monitor	
												Swing mounts/links/brackets worn	Monitor	
			2	1245	25-Sep	/	/	/	/	/	X	Bridge mounts/chain worn	Monitor	
													Bridge timber splitting	Monitor
											Fibreglass damaged/cracking/worn on slides	Monitor		
96	Monash	Clive Steele Ave (Harkness St)	1	1420	18-Sep	/	/	/	/	X	X	Steering wheel bracket worn	Monitor	
			2	1300	25-Sep	/	/	/	/	X	X	Border timber splitting/missing	Needs Repair - PCL	
													Dirt washed into bark	Needs repair - PCL
											Slide plastic worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	1400	18-Sep	/	/	/	/	/	X	Swing mounts/ links worn	Monitor	
			2	600	26-Sep	/	/	/	/	/	X	Concrete stump at bench	Needs Removal - PCL	
												Low hanging branches	Needs Removal - PCL	
98	MONASH	Hallstrom Cres	1	1430	18-Sep	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor	
													Concrete border lifting	Needs Repair PCL

Name Of Inspector		Domenik		Month of Inspection							Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
98	PLGR 250	Transfront Circ	2	1225	25-Sep	/	/	/	/	/	X	X	Damaged bolt caps on spring toy	Needs Repair J&E		
													Bench seat slats splitting	Monitor		
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	1350	18-Sep	/	/	/	/	/	X	X	Movement in swing crossbar	Monitor		
														Bridge links/mounts worn/movement	Monitor	
			2	617	26-Sep	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
															Bent bar/cracked welds on bridge	Needs Repair - LAZ
													Bark low	Needs Top up - PCL		
													Bridge slats splitting / lichen	Monitor		
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	1435	18-Sep	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor		
														Triangles worn plastic	Monitor	
			2	1230	25-Sep	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
													Spring animal crack in foot rest/head loose	Monitor		
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin Pl)	1	1215	18-Sep	/	/	/	/	/	X	X	Border sleepers damaged	Needs Repair - PCL		
															Horse head splitting	Monitor
			2	1220	25-Sep	/	/	/	/	/	X	X	Damaged tyre swing	Monitor		
													Gravel washed into bark/low bark	Needs repair PCL		
102	OXLEY PLGR 255	Newman Morris Circ	1	1220	18-Sep	/	/	/	/	/		X	Swing mounts worn	Monitor		
															Bite marks in swing seat	Monitor
			2	1210	25-Sep	/	/	/	/	/		X	Bark washing out	Needs repair PCL		
													Border concrete damaged	Needs Repair PCL		
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	1420	09-Sep	/	/	/	/	/	X	X	Border sleepers damaged	Needs Repair J&E		
															Deck plastic worn	Monitor
			2	850	19-Sep	/	/	/	/	/	X	X	Carousel rusting/loose in footing	Monitor		
															Spring frog handle loose	Monitor
													Pod mounts worn (eyelet)	Needs repair - LAZ		
104	RICHARDSON PLGR 258	Chauncy Cres	1	1355	09-Sep	/	/	/	/	/		X	Decking plastic worn	Monitor		
															Swing mounts worn	Monitor
			2	910	19-Sep	/	/	/	/	/		X	Cuts on slide (smoothed)	Monitor		
105	RICHARDSON PLGR 259	Clift Cres	1	1410	09-Sep	/	/	/	/	/	X	X	Swing posts rusting / movement in bolts	Monitor		
															Worn swing chains/mounts/movement in post	Monitor
			2	900	19-Sep	/	/	/	/	/	X	X	Cracked welds on slide entry	Needs repair - LAZ		
															Bark low / dirt in bark	Top up bark - PCL
													Bolt caps damaged on spring animal	Needs Repair J&E		
			1	1402	09-Sep	/	/	/	/	/		X	Decking plastic worn/surface rust	Monitor		

Name Of Inspector		Domenik		Month of Inspection				Sep-19				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
106	RICHARDSON PLGR 257	Vidal St										Climb net mounts worn	Needs Repair LAZ		
			2	905	19-Sep	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor		
														Climb net links worn	Monitor
														Climb net bar bent	Monitor
														Tyre swing links worn	Monitor
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN												
108	THEODORE PLGR 265	Dyett Circ	1	1325	09-Sep	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Decking timber splitting	Monitor	
			2	930	19-Sep	/	/	/	/	X	X	Chain net links worn	Monitor		
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN												
110	THEODORE PLGR 261	Louis Loder St	1	1335	09-Sep	/	/	/	/	X	X	Border logs splitting	Monitor		
													Decking timber splitting	Monitor	
			2	940	19-Sep	/	/	/	/	X	X	Cracks at slide entry	Monitor		
														Chain net links worn	Monitor
											Bark low	Needs Top up - PCL			
111	THEODORE PLGR 264	Scantleberry St	1	1310	09-Sep	/	/	/	/	X	X	Border concrete broken/lifting	Needs Repair - PCL		
													Border logs splitting	Monitor	
			2	920	19-Sep	/	/	/	/	X	X	Trees growing in bark	Needs Removal - PCL		
														Slide damaged at top	Monitor
														Spring animal timber worn	Monitor
														Decking timber splitting/panel	Monitor
112	WANNIASSA PLGR 270	Billson Pl	1	1300	18-Sep	/	/	/	/	/	X	Barrier logs removed	Needs Repair PCL		
													Decking plastic worn	Monitor	
			2	1045	25-Sep	/	/	/	/	/	X	Bridge plastic worn	Needs Repair LAZ		
														Damaged tic tac toe	Monitor
											Worn rubber on spike spinner	Needs Repair J&E			



Name Of Inspector		Domenik		Month of Inspection								Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
113	WANNIASSA PLGR 267	Bussau CI	1	1315	18-Sep	/	/	/	/	/	X	X	Decking timber worn	Monitor		
														Chain net links worn/plastic peeling	Monitor	
			2	1010	25-Sep	/	/	/	/	/	X	X	Damaged/rotting borders	Monitor		
															Concrete path lifting	Needs Repair PCL
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	1255	18-Sep	/	/	/	/	/		X	Decking plastic worn x 1	Needs Repair - LAZ		
														Swing mounts/brackets worn	Monitor	
			2	1050	25-Sep	/	/	/	/	/			X	Grab handle loose	Monitor	
115	WANNIASSA PLGR 275	Hervey Pl	1	1225	18-Sep	/	/	/	/	X	X	Border sleepers/braces splitting	Needs Repair PCL			
														Decking plastic rust / peeling	Monitor	
			2	1140	25-Sep	/	/	/	/	X	X	Smoking sign loose in footing	Needs Repair PCL			
116	WANNIASSA PLGR 266	Lansell Circ											Swing seat damaged/mounts/links worn	Monitor		
			1	1340	18-Sep	/	/	/	/	/		X	Swing mounts worn	Monitor		
			2	1005	25-Sep	/	/	/	/	/		X	Border fence panels damaged	Monitor		
117	WANNIASSA PLGR 269	Sainsbury St	1	1305	18-Sep	/	/	/	/	X	X	Border logs splitting	Monitor			
														Holes in shade sail	Monitor	
			2	1035	25-Sep	/	/	/	/	X	X	Burn marks on tic tac toe	Monitor			
															Bench seat slats damaged	Needs Repair PCL
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN													
119	WANNIASSA PLGR 276	Steinfeld Circ	1	1235	18-Sep	/	/	/	/	X	X	Border Sleepers splitting	Monitor			
														Bench seat slats splitting	Monitor	
			2	1130	25-Sep	/	/	/	/	X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ			
															Decks worn x 2	Needs Repair - LAZ
															Bridge slats splitting	Monitor
												Bridge/Chain net links worn/plastic	Monitor			
												Bearings / wheels damaged on fly fox trolley	Needs Repair J&E			
			1	1310	18-Sep	/	/	/	/	X	X	Border logs splitting	Monitor			



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection								Sep-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
120	WANNIASSA PLGR 268	Sullivan Cres												Bridge/chain links worn	Monitor	
			2	1025	25-Sep	/	/	/	/	X	X			Handle plastic worn on flying fox	Monitor	
															Swing seats/mounts worn/splitting	Monitor
0:00	WANNIASSA PLGR 277	Watkins St	1	1245	18-Sep	/	/	/	/	X	X			Border sleepers damaged	Needs Repair - PCL	
														Swing mounts worn	Monitor	
			2	1110	25-Sep	/	/	/	/	X	X			Bridge timber splitting	Monitor	
															Park bench missing / damaged timber	Needs Repair - PCL
													Decking worn/lichen growing	Monitor		
122	WANNIASSA PLGR 274	Wheeler Cres	1	1230	18-Sep	/	/	/	/	X	X			Decking worn / rusting	Monitor	
															Swing mounts/ links worn	Monitor
			2	1150	25-Sep	/	/	/	/	X	X			Fireman pole damaged	Monitor	
															Roman triangles links worn plastic worn	Monitor
													Chain net links worn	Monitor		
123	WANNIASSA PLGR 272	Whiteman St	1	1250	18-Sep	/	/	/	/	X	X			Swing mounts/s hooks/ chain	Monitor	
			2	1100	25-Sep	/	/	/	/	X	X			Border logs splitting	Monitor	
													Horse head splitting	Monitor		



Name Of Inspector: Domenik Month of Inspection: Sep-19

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
				Level 1or Level 2			Level 1/2	/	x	/	x	/	x	/	x	/	x	/			x	/
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	1330	06-Sep	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban		
																				Awning luvvers mounts rusting	Monitor	
			2	1130	27-Sep	/		/		/		/		/					X	Bridge mounts worn	Monitor	
																					Pommels links/mounts worn/hosing split	Monitor
																					Swing mounts/brackets worn	Monitor
																					2 x tread caps missing on surfer	Monitor
																					Bridge metal slip hazard	Angle / monitor
																					Basketball backboard worn	Monitor
																					Climb chain mounts/links worn/hosing split	Monitor
																					Rubber soft fall worn	Monitor
2	COTTER PLGR 539	CASURINA SANDS	1	1440	06-Sep	/		/		/		/			X		X	Post timber splitting	Monitor			
																			Decking timber splitting	Monitor		
			2	1110	27-Sep	/		/		/		/			X		X	Rope bridge wearing/rope fraying	Monitor			
																		Tree debris in bark	Needs Removal PCL			
3	GREENWAY PLGR 538	Pine Island Rd	1	1540	04-Sep	/		/		/		/			X		X	Border logs splitting	Monitor			
			1	645	09-Sep	/		/		/		/			X		X	Climbing wall worn/rusting	Monitor			
			1	715	18-Sep	/		/		/		/			X		X	Movement in staircase footing	Monitor			
			1	1315	23-Sep	/		/		/		/			X		X	Swing mounts/chains worn	Monitor			
			1			/		/		/		/			X		X	1 x pop rivets missing on deck panel	Repaired by J&E 9/9/19			
																				Decks/bridge worn/rusting	Monitor	
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	1	1115	06-Sep	/		/		/		/			X		X	Fence timber splitting around water tanks	Monitor			
																			Water tanks splitting on openings	Repaired by J&E 12/9/19		
			2		27-Sep	/		/		/		/			X		X	Water tanks decking timber splitting/worn	Monitor			
																				Small slide cracked at entry	Repaired by LAZ 12/9/19	
																				Spider climb net rope frayed	Monitor	
																				Chain cover split on flying fox	Repaired by J&E 12/9/19	
																				Spring kangaroo base loose	Repaired by J&E 6/9/19	
																				Rubber soft fall splitting / low bark	Monitor	
																					Tree roots lifting paths	Needs Repair PCL
																					Handrail missing at top of twin slide	Repaired by J&E 12/9/19
																					Slide welds cracked at exit on large slide	Repaired by LAZ 12/9/19
																					Timber splitting on large spring platform	Monitor
																					Flying fox posts splitting	Monitor
																		Rubber soft fall worn at flying fox	Monitor			
																		Hand water pump not working/plates loose	Being Repaired			
																		Fly fox seat clearance under 400mm	Repaired by LAZ			
																		Flat swing has been removed	Repaired by J&E 12/9/19			



Name Of Inspector

Domenik

Month of Inspection

Sep-19

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Inspectors Signature: D.Radman



Name Of Inspector Domenik Month of Inspection Oct-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection Time	Date of Inspection Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description Hazard	Action Taken- For full details please refer to attached Playground Safety Inspection Report Action			
							/	x	/	x	/	x	/	x	/	x	/	x			/	x	
1	BANKS PLGR 413	Pocket Ave		1	800	01-Oct	/		/		/		/			X	X		Loose slide leg	Monitor			
				2	840	08-Oct	/		/		/		/				X	X		Chain net links/mounts worn	Monitor / Needs Repair LAZ		
				1	1305	15-Oct	/		/		/		/				X	X		Track ride worn links	Monitor		
				1	720	21-Oct	/		/		/		/				X	X		Border concrete cracking / lifting	Needs Repair PCL		
				1	725	28-Oct	/		/		/		/				X	X		Small plastic slide damaged	Monitor		
2	BONYTHON PLGR 535	Burgoyne St																Titer totes arms missing	07/01/2019				
				1	655	01-Oct	/		/		/		/				X		Ropes worn on climb net	Monitor			
				2	1600	08-Oct	/		/		/		/				X		Spinner seat small crack in plastic	Monitor			
				1	1600	15-Oct	/		/		/		/				X		Graffiti on fire truck	Needs Removal PCL			
				1	1400	21-Oct	/		/		/		/				X		Collar pins worn	Monitor			
3	FADDEN PLGR 228	Coyne St																Ropes worn on small single swing	Monitor				
				1	857	01-Oct	/		/		/		/			X	X		Swing mounts worn	Monitor			
				2	940	08-Oct	/		/		/		/				X	X		Cracked welds on slide entry	Monitor		
				1	1345	15-Oct	/		/		/		/				X	X		Worn links bridge/climb chains	Monitor		
				1	805	21-Oct	/		/		/		/				X	X		Timber split on panels	Monitor		
4	GORDON PLGR 278	McGillvray Circ																Border logs splitting	Monitor				
				1	1020	28-Oct	/		/		/		/				X	X		Holes in softfall / splitting	Needs repair - PCL		
																				Footpath lifting	Needs repair - PCL		
																					Slide footing loose	Monitor	
																					Spinning seesaw hanger has worn bolts/handle	Monitor	
																					Hose splitting on chain covers	Monitor	
																					Movement in brackets on web towers	Monitor	
																					Fibreglass on tea cup spinner cracking	Monitor	
																						Swing mounts worn x 2	Needs Repair - J&E
																						Damaged see-saw brackets x 3	Needs Repair - J&E
5	GOWRIE PLGR 328	Jeffries St																	Rope climb net worn 80%	Needs Repair - J&E			
				1	730	01-Oct	/		/		/		/			X	X		Spinner top bearings loose	Monitor			
				2	800	08-Oct	/		/		/		/				X	X		Damaged super nova	Monitor		
				1	1350	11-Oct	/		/		/		/				X	X		Border logs splitting	Monitor		
				1	1245	15-Oct	/		/		/		/				X	X		Damaged super nova	Monitor		
				1	700	18-Oct	/		/		/		/				X	X		Border logs splitting	Monitor		
				1	700	21-Oct	/		/		/		/				X	X		Roman triangles worn links	Needs repair - LAZ		
				1	700	25-Oct	/		/		/		/				X	X		Wire walk cable worn	Monitor		
				1	700	28-Oct	/		/		/		/				X	X		Decking worn on tower	Monitor		
																					Wire bridge mount worn/chain low links worn	Needs repair - LAZ	
																	Cracked welds in tower/rust	Needs repair - LAZ					
																		Rubber Soft fall splitting/holes	Needs repair - PCL				
																		Swing chains/brackets/mounts	Monitor				
																		bench below tea cup playground coming out of footing	Needs repair - PCL				
																		Hole in shade sail	Monitor				
																		Softfall splitting / holes forming	Needs Repair PCL				
																		Timber worn on carousel	Monitor				
																		Spider net worn	Monitor				



Name Of Inspector Domenik Month of Inspection Oct-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection Time	Date of Inspection Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description Hazard	Action Taken- For full details please refer to attached Playground Safety Inspection Report Action		
							/	x	/	x	/	x	/	x	/	x	/	x			/	x
6	GREENWAY PLGR 242	Anketell St		1	1035	28-Oct	/		/		/		/		/			X				
				1	1110	01-Oct	/		/		/		/		X		X			Border sleepers missing and rotten	Needs Repair - PCL	
				1	700	04-Oct	/		/		/		/		X		X					
				2	1335	08-Oct	/		/		/		/		X		X				Swing brackets/mounts worn	Needs Repair - J&E
				1	1310	11-Oct	/		/		/		/		X		X				Digger bucket has a hole	Needs Repair - LAZ
				1	1510	15-Oct	/		/		/		/		X		X				Worn ropes on bridge	Monitor
				1	750	18-Oct	/		/		/		/		X		X					
				1	1555	21-Oct	/		/		/		/		X		X				Tyre swing mounts worn/crossbar movement in sleeve/s hooks	Monitor
				1	725	25-Oct	/		/		/		/		X		X				Log steps/posts splitting on tower	Monitor
				1	1400	28-Oct	/		/		/		/		X		X				Tower fort movement in footing	Monitor
7	GREENWAY PLGR 240	De Little Circ PLAR 286		1	1040	01-Oct	/		/		/		/		X				Spider net worn	Monitor		
				2	1305	08-Oct	/		/		/		/		X		X			Handle rubber split on Spring Carousel	Monitor	
				1	1445	15-Oct	/		/		/		/		X		X			Graffiti on post	Remove - PCL	
				1	1440	21-Oct	/		/		/		/		X		X			Spring boat loose footings	Monitor	
				1	1430	28-Oct	/		/		/		/		X		X			Holes in softfall	Needs repair - PCL	
8	GREENWAY PLGR 417	Eileen Good St		1	1130	01-Oct	/		/		/		X		X				Swing seat/bracket/links worn	Monitor		
				2	1355	08-Oct	/		/		/		/		X		X			Bark low	Needs Top up - PCL	
				1	1520	15-Oct	/		/		/		/		X		X			Border logs splitting	Monitor	
				1	1605	21-Oct	/		/		/		/		X		X			Baby seat worn	Monitor	
				1	1350	28-Oct	/		/		/		/		X		X			Fort/seesaw timber splitting	Monitor	
9	GREENWAY PLGR 240	Florence Taylor St PLAR 288		1	1100	01-Oct	/		/		/		X		X				Decking worn	Monitor		
				2	1325	08-Oct	/		/		/		/		X		X			Bark low	Needs Top up - PCL	
				1	1459	15-Oct	/		/		/		/		X		X			Concrete border lifting	Monitor	
				1	1545	21-Oct	/		/		/		/		X		X			Crack in slide plastic	Monitor	
				1	1420	28-Oct	/		/		/		/		X		X					
124	GREENWAY PLGR	Limburg Way		1	600	01-Oct	/		/		/		/		X				Timber decking splitting	Monitor		
				2	1405	08-Oct	/		/		/		/		X		X			Climb wall timber splitting	Monitor	
				1	1525	15-Oct	/		/		/		/		X		X			Swing seat brackets worn	Monitor	
				1	1620	21-Oct	/		/		/		/		X		X					
				1	1340	28-Oct	/		/		/		/		X		X					
10	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807		1	1050	01-Oct	/		/		/		X		X				Bark low	Needs Top up - PCL		
				2	1315	08-Oct	/		/		/		/		X		X			Decks rusted/plastic worn	Monitor	
				1	1450	15-Oct	/		/		/		/		X		X			Bridge plastic worn	Monitor	
				1	1436	21-Oct	/		/		/		/		X		X			Swing seat/brackets/mounts/s-hooks worn	Monitor	
				1	1440	28-Oct	/		/		/		/		X		X				Stair footing loose	Monitor
11	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET																			
			1	1020	01-Oct	/		/		/		/		X		X			Bearings/guide rollers worn on fly fox	Monitor		



Name Of Inspector Domenik Month of Inspection Oct-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
							/	x	/	x	/	x	/	x	/	x	/	x			/
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		2	1215	08-Oct	/		/		/				X	X			Swing mounts/brackets worn	Monitor	
				1	1630	15-Oct	/		/		/					X	X			Concrete border lifting	Monitor
				1	1520	21-Oct	/		/		/					X	X			Bridge slats splitting	Monitor
				1	1103	28-Oct	/		/		/					X	X			Movement in see saw base	Monitor
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	1015	01-Oct	/		/		/				X	X			Damaged concrete border	Monitor	
				2	1200	08-Oct	/		/		/					X	X			Damaged park seat	Needs repair - PCL
				1	1640	15-Oct	/		/		/					X	X			baby swing damaged	Monitor
				1	1515	21-Oct	/		/		/					X	X			Plastic Rock on climb wall cracking	Monitor
				1	1040	28-Oct	/		/		/					X	X			Movement in base of carousel	Needs repair - J&E
14	KAMBAH PLGR 305	Springbett St		1	1030	01-Oct	/		/		/				X	X			Twin S/S slide has crack in surface	Monitor	
				1	730	04-Oct	/		/		/					X	X			Swing seat/brackets/links/mounts worn	Monitor
				2	1230	08-Oct	/		/		/					X	X			Super nova damaged	Monitor
				1	1245	11-Oct	/		/		/					X	X			Hosing split on carousel	Monitor (taped)
				1	1600	15-Oct	/		/		/					X	X			Mount worn on large fly fox	Monitor
				1	825	18-Oct	/		/		/					X	X			Border logs splitting	Monitor
				1	1525	21-Oct	/		/		/					X	X			Sml fly fox movement in bolt	Monitor
				1	800	25-Oct	/		/		/					X	X			Tic Tac Toe damaged (taped)	Needs Repair J&E
				1	1120	28-Oct	/		/		/					X	X			Damage panel on quad hoops	Monitor
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	925	01-Oct	/		/		/				X	X			Low branches at swings & fly fox/grass in bark	Cut back/remove - PCL	
				2	1055	08-Oct	/		/		/					X	X			Burn marks at liberty swing seat	Monitor
				1	1430	15-Oct	/		/		/					X	X			Bark low/ washed out	Needs repair - PCL
				1	1446	21-Oct	/		/		/					X	X			Bark low	Needs Top up - PCL
				1	930	28-Oct	/		/		/					X	X			Burn mark seesaw	Monitor
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	930	01-Oct	/		/		/				X	X			Swing mounts	Monitor	
				2	1105	08-Oct	/		/		/					X	X			Timber swing posts splitting/ missing swings	?
				1	1435	15-Oct	/		/		/					X	X			Worn decks/ bridge	Monitor
				1	1450	21-Oct	/		/		/					X	X			Damaged rock wall	Monitor
				1	1015	28-Oct	/		/		/					X	X			Rope worn on carousel	Monitor
17	MACARTHUR PLGR 327	Bayly Pl		1	845	01-Oct	/		/		/				X	X			Swing seat / brackets worn	Monitor	
				2	924	08-Oct	/		/		/					X	X			Rope worn on climbing net/carousel	Monitor
				1	1332	15-Oct	/		/		/					X	X			Movement in base towards post of carousel	Needs repair - J&E
				1	750	21-Oct	/		/		/					X	X			Gravel washed into bark	Needs removal PCL
				1	1000	28-Oct	/		/		/					X	X			Low bark	Needs Top up - PCL
18	THEODORE PLGR 263	Chippindall Circ		1	820	01-Oct	/		/		/				X	X			Softfall patches lifting under birds nest swing	Needs Repair PCL	
				2	900	08-Oct	/		/		/					X	X			Swing mounts/brackets worn	Monitor
				1	1317	15-Oct	/		/		/					X	X			Carousel seat worn/rusting	Monitor
				1	730	21-Oct	/		/		/					X	X			Worn/damaged deck/bridge	Monitor
																		Loose handle/footings on spring animal x 2	Monitor		



Name Of Inspector: Domenik
Month of Inspection: Oct-19

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action
	PLGR 205		1	748	28-Oct	/		/		/		/		/			X	Holes in shade sail	Monitor
																		Low bark	Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	830	01-Oct	/		/		/		/			X	X	Weld cracking at slide entry	Needs Repair - LAZ	
			2	911	08-Oct	/		/		/		/			X	X	Decking plastic worn/surface rust	Monitor	
			1	1322	15-Oct	/		/		/		/			X	X	Swing/Chain bridge links/mounts worn	Monitor	
			1	735	21-Oct	/		/		/		/			X	X	Movement in frog footing	Monitor	
			1	756	28-Oct	/		/		/		/			X	X	Border concrete cracking	Needs Repair - PCL	
20	WANNIASSA PLGR 271	Sangster Pl	1	915	01-Oct	/		/		/		/			X	X	Swing mounts brackets worn	Monitor	
			2	1015	08-Oct	/		/		/		/			X	X	Decking worn	Monitor	
			1	1420	15-Oct	/		/		/		/			X	X	Hole in chain wire fence	Needs Repair - LAZ	
			1	835	21-Oct	/		/		/		/			X	X	Park bench missing arm rest	Needs Repair - PCL	
			1	1045	28-Oct	/		/		/		/			X	X	Holes and splitting in softfall	Needs repair - PCL	

Inspectors Signature: D.Radman



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection								Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report						
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition				Equipment in safe and satisfactory condition					
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action			
1	BANKS PLGR 213	Menzies Court	2	910	09-Oct	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																			Decking plastic worn/surface rust	Monitor	
			1	1110	31-Oct	/		/		/		/				X		X			
																				Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	2	900	09-Oct	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																			Swing seat brackets worn	Monitor	
			1	1100	31-Oct	/		/		/		/				X		X	Decking worn	Monitor	
																				Dints in slide bed	Monitor
																		Border concrete cracking	Needs Repair - PCL		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	2	1305	01-Oct	/		/		/		/					X	Posts handrails split/rotting	Monitor		
																			4 x Post damaged/split on fort	Monitor	
			1	1003	31-Oct	/		/		/		/		/				X	Chain net links and mounts worn	Monitor	
																				Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	2	1200	01-Oct	/		/		/		/			X		X	Border logs splitting	Monitor		
																				Swing seat/brackets damaged /worn	Monitor
			1	940	31-Oct	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																				Slide has crack at entry/movement	Monitor
																		Obscene graffiti on equipment	Needs Removal PCL		
7	BONYTHON PLGR 586	Morice Pl	2	1245	01-Oct	/		/		/		/					X	Loose bolt on chain climb	Repaired by J&E 1/10/19		
																				Swing seat brackets worn	Monitor
			1	950	31-Oct	/		/		/		/		/				X	Worn / missing rope on net	Monitor	
																					Worn links/mounts on pommel/ climb chain

Name Of Inspector		Domenik		Month of Inspection								Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
8	CALWELL PLGR 322	Beckett St	2	1105	09-Oct	/	/	/	/	/	/		X	Decking plastic worn	Monitor		
															Swing mounts worn	Monitor	
			1	700	31-Oct	/	/	/	/	/	/	/		X	Bent monkey bars	Monitor	
																Slide weld cracking at top	Needs Repair - LAZ
																Chain walk hand rail bent	Needs Repair - LAZ
																Bent deck poles	Needs Repair - LAZ
																Low tree branches	Needs Removal PCL
9	CALWELL PLGR 321	Casey Cres	2	1200	09-Oct	/	/	/	/	/	/		X	Swing mounts worn	Monitor		
															Decking plastic worn/decks rusting	Monitor	
			1	720	31-Oct	/	/	/	/	/	/	/		X	Chain net links worn/coating on chains	Monitor	
																See saw timber splitting	Monitor
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	2	1140	09-Oct	/	/	/	/	/		X	X	Decking plastic worn	Monitor		
															Swing mounts/seat/links worn	Monitor	
			1	714	31-Oct	/	/	/	/	/	/		X	X	Low branches	Needs cut back back-PCL	
																Side leg bent	Monitor
11	CALWELL PLGR 319	Samuel Cl	2	1215	09-Oct	/	/	/	/	/		X	X	Border logs splitting	Monitor		
															Swing mounts worn	Monitor	
			1	730	31-Oct	/	/	/	/	/	/		X	X	Bent monkey bars	Monitor	
																Park bench missing timber	Needs Repair - PCL
12	CALWELL PLGR 644	Shopping Centre	2	1530	01-Oct	/	/	/	/	/	/		X	Swing mounts/seat/S hooks worn	Monitor		
															Bark low	Top up bark PCL	
			1	740	31-Oct	/	/	/	/	/	/		X		Carousel missing pop rivets	Repaired by J&E 1/10/19	
													Carousel movement in bearing	Monitor			
13	CALWELL PLGR 320	Were St	2	1225	09-Oct	/	/	/	/	/		X	X	Border logs splitting	Monitor		
															Swing links/mounts worn	Monitor	
			1	735	31-Oct	/	/	/	/	/	/		X	X	Tire worn on tyre swing	Monitor	
14	CHISHOLM PLGR 234	Alston St	2	815	10-Oct	/	/	/	/	/	/		X				
															Swing mounts worn	Monitor	
			1	1635	25-Oct	/	/	/	/	/	/		X		Damaged tic tac toe	Monitor	

Name Of Inspector		Domenik		Month of Inspection							Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
15	CHISHOLM PLGR 233	Dalyell St											Baby seat chain cover worn	Monitor		
														Fly fox handle plastic worn	Monitor	
			2	830	10-Oct	/	/	/	/	/		X	Timber decking splitting	Needs repair - J&E		
														Tyre swing mounts worn	Monitor	
			1	1640	25-Oct	/	/	/	/	/		X	Fly fox links worn	Monitor		
														Chain net mounts worn	Monitor	
														Fly fox nylon guides worn	Needs Repair - J&E	
												Bench seat damaged	Needs Repair PCL			
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	2	745	10-Oct	/	/	/	/	/		X	Timber decking splitting	Monitor		
														Track ride not gliding with ease	Needs Repair - J&E	
			1	1610	25-Oct		/	/	/	/		X	Swing seat damaged/brackets/links worn	Monitor		
														Post loose in footing	Monitor	
												Uneven paving around playground	Needs Repair PCL			
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	2	755	10-Oct	/	/	/	/	/		X	Timber decking splitting	Monitor		
														Slide damaged at exit	Monitor	
			1	1620	25-Oct		/	/	/	/		X	Log steps splitting	Monitor		
														Damaged park bench	Needs Repair - PCL	
														Tyre /s hooks wearing on tire swing	Monitor	
												Graffiti on slide	Remove - PCL			
18	CHISHOLM PLGR 235	Kirkcaldie Circ	2	645	10-Oct	/	/	/	/	/		X	Swing mounts/links worn	Monitor		
														Decking plastic worn/rusting	Monitor	
			1	1650	25-Oct		/	/	/	/		X	Climb net mounts/plastic worn	Monitor		
														Plastic at slide exit damaged	Needs Repair J&E	
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	2	805	10-Oct	/	/	/	/	/		X	Decking plastic worn	Monitor		
														Tyre swing mounts worn	Monitor	
			1	1630	25-Oct		/	/	/	/		X	Climb net links worn	Monitor		
														Damaged park bench	Monitor	
															Plastic panel damaged	Monitor
															Concrete border damaged	Needs repair - J&E
												Bent/damaged deck poles	Needs repair - LAZ			
20	CHISHOLM PLGR 236	Proctor St	2	705	10-Oct	/	/	/	/	/		X	Swing mounts/links/seat worn	Monitor		
														Low bark	Needs top up - PCL	
			1	1655	25-Oct		/	/	/	/		X	Dints in slide	Monitor		
												Fly fox handle plastic worn	Monitor			

Name Of Inspector		Domenik		Month of Inspection						Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	2	1250	10-Oct	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor		
													Border timber damaged	Needs Repair PCL	
			1	1455	25-Oct	/	/	/	/	X	X	Movement in carousel base	Monitor		
													Decking timber splitting	Monitor	
													Chain net links / mounts worn	Monitor	
													Lichen growing on decks	Monitor	
											Bolt missing on deck	Repaired by J&E 10/10/19			
29	FADDEN PLGR 509	Nicklin Cres	2	1330	10-Oct	/	/	/	/	X	X	Rocks missing in border wall	Needs Repair - PCL		
													Rope bridge mount broken/rope worn	Needs Repair PCL	
			1	1445	25-Oct	/	/	/	/	X	X	Climbing nets rope worn	Monitor		
													Panel/ roof panels cracked on fort	Monitor	
											Tower posts splitting	Monitor			
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	2	1240	10-Oct	/	/	/	/	X	X	Swing mounts/ links worn	Monitor		
			1	1500	25-Oct	/	/	/	/	X	X	Border logs worn	Monitor		
													Dent in parallel bars/swing post	Monitor	
GILMORE	GILMORE	Heagney Cres	2	1400	09-Oct	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor		
													Rubber frog damaged	Monitor	
			1	1545	25-Oct	/	/	/	/	X	X				
														Low bark	Needs Top up - PCL
GILMORE	GILMORE	Hogue Pl	2	1405	09-Oct	/	/	/	/	X	X	Fence damaged	Monitor		
													Spinner seats worn/ rusting	Monitor	
			1	1523	25-Oct	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL		
														Bark low	Top up bark PCL
GILMORE	GILMORE	Rosman Circ	2	1413	09-Oct	/	/	/	/	/	X	Bridge timber splitting	Monitor		
														Concrete at bench lifting	Needs Repair PCL
			1	1530	25-Oct	/	/	/	/	/	X	Damaged bolt caps	Needs Repair - J&E		
GORDON	GORDON	Iredale Pl	2	1030	09-Oct	/	/	/	/	/	X	Swing seat brackets worn	Monitor		
														Chain net/ladder links worn/plastic	Monitor
			1	1145	31-Oct	/	/	/	/	/	X	Damaged post caps x 4	Monitor		
														Slide damaged	Monitor

Name Of Inspector		Domenik			Month of Inspection							Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN												
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET												
52	ISABELLA PLAINS PLGR 280	Findon Pl	2	1420	01-Oct	/	/	/	/		X	X	Ropes worn on web	Monitor	
													Decks/Posts splitting/rotten	Monitor	
			1	1520	24-Oct	/	/	/	/		X	X	Swing mounts/seat worn	Monitor	
														Decking poles bent	Needs Repair J&E
														Concrete border lifting	Needs Repair PCL
												Gaps were slide joins	Monitor		
												Swing timber splitting	Monitor		
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	2	1320	01-Oct	/	/	/	/			X	Swing mounts worn	Monitor	
			1	1534	24-Oct	/	/	/	/			X	Plastic slide cracked	Monitor	
														Movement in swing posts	Monitor
														Frog plastic worn around handle	Monitor
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	2	1355	01-Oct	/	/	/	/		X	X	Border path concrete cracking	Monitor	
													Slide surface worn	Monitor	
			1	1526	24-Oct	/	/	/	/		X	X	Chain net links	Monitor	
														Spring animal missing	Needs repair - J&E
55	KAMBAH PLGR 312	Allchin Circuit No 1	2	1705	15-Oct	/	/	/	/			X	Slide leg loose in footing	Monitor	
													Low bark	Top - PCL	
			1			/	/	/	/			X	Spring animal loose in footing	Monitor	
												Angle bar missing at climbing net damaged	Needs repair - LAZ		
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	2	1726	15-Oct	/	/	/	/		X	X	Border logs splitting	Monitor	
													Swing mounts/brackets worn	Monitor	
			1	1500	31-Oct	/	/	/	/		X	X	Concrete lifting quad hoop game	Monitor	
														Chain net links / mounts worn	Monitor
												Slide surface worn	Monitor		
			2	835	15-Oct	/	/	/	/		X	X	Border logs damaged	Needs Repair PCL	
													Swing mounts worn/loose due to timber shrinking	Monitor	

Name Of Inspector		Domenik		Month of Inspection							Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
57	KAMBAH PLGR 313	Attiwell Circ	1		/	/	/	/	X	X	Bench seat frame bent	Monitor		
												Swing timber damage/splitting	Monitor	
												Asphalt cracking / lifting	Needs Repair PCL	
												See-saw footrest damaged	Monitor	
58	KAMBAH PLGR 314	Barritt St	2	1645	15-Oct	/	/	/	/	/	X	2 x Decking plastic worn > 60%	Needs Repair - LAZ	
													Bridge plastic worn/ rusted	Monitor
			1	1455	21-Oct	/	/	/	/	/	X	Welds cracked on chain net	Needs Repair - LAZ	
													Fort panel movement	Monitor
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN											
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN											
61	KAMBAH PLGR 301	Boustead Circ	2	905	26-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Damaged plastic on stairs	Monitor
			1			/	/	/	/	X	X	Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	2	1215	12-Oct	/	/	/	/	X	X	Timber decking splitting	Monitor	
													Swing posts splitting and rotten	Monitor
			1	1445	31-Oct	/	/	/	/	X	X	Movement in ladder plate to decking	Monitor	
													Timber border lifting/damaged	Monitor
													Swing mounts/brackets worn/small movement	Monitor
											Bark washed out	Needs Repair - PCL		
63	KAMBAH PLGR 317	Bullock Circ	2	850	26-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Rubber on stairs splitting	Monitor
			1			/	/	/	/	X	X	Worn rubber on deck	Needs Repair LAZ	
													Climb chain/bridge links worn	Monitor
													Bridge slats split	Needs Repair - J&E
											Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 200	Coghill Cl	2	1020	12-Oct	/	/	/	/	X	X	Swing mounts worn	Monitor	
													Border logs splitting	Monitor
			1	1405	01-Nov	/	/	/	/	X	X	Carousel loose - movement in bearing	Monitor	

Name Of Inspector		Domenik		Month of Inspection				Oct-19				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	2	951	26-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor
			1			/	/	/	/	X	X	Swing mounts worn	Monitor
						/	/	/	/			Decking plastic worn	Monitor
												Low bark	Needs Top up - PCL
												flying fox handle/mount/links worn	Monitor
												Bridge timber splitting	Monitor
												Bridge/climbing net links worn	Monitor
66	KAMBAH PLGR 304	Dale Circ	2	1050	26-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor
						/	/	/	/			Decks rusty/ plastic peeling	Needs Repair LAZ
			1			/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor
												Swing brackets/mounts worn	Monitor
67	KAMBAH PLGR 291	Deuchar Cl	2	1030	12-Oct	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor
						/	/	/	/			Border sleepers splitting	Monitor
			1	1410	01-Nov	/	/	/	/	X	X	Swing mounts worn	Monitor
												Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	2	1655	15-Oct	/	/	/	/	X	X	Border logs splitting	Monitor
						/	/	/	/			Decking plastic worn	Monitor
			1			/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ
												Swing mounts worn	Monitor
												Bark low	Needs top up - PCL
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	2	1325	12-Oct	/	/	/	/	X	/	Rocks missing on rock wall	Needs Repair PCL
						/	/	/	/	X	/		
			1	1525	31-Oct	/	/	/	/			Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs Pl	2	1230	12-Oct	/	/	/	/	/	X	Knots and crosses cracking	Monitor
						/	/	/	/			Bolt caps brittle on tower	Monitor
			1	1550	31-Oct	/	/	/	/	/	X		
71	KAMBAH	Horton Cl	2	1040	12-Oct	/	/	/	/	X	X	Chain net links worn	Monitor
						/	/	/	/			Decking plastic worn/rusting	Needs Repair LAZ
			1	1415	01-Nov	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL

Name Of Inspector		Domenik		Month of Inspection						Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
71	PLGR 289	Horton Ct										Parallel slide bar bent	Monitor	
													Wearing swing brackets	Monitor
													Tyre swing tyre worn	Needs Repair J&E
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	2	1310	12-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			1	1530	31-Oct	/	/	/	/	X	X	Bridge slats splitting	Needs Repair J&E	
													Bridge/ chain net links worn	Monitor
73	KAMBAH PLGR 307	Humble Court	2	1154	12-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			1	1440	01-Nov	/	/	/	/	X	X	Swing mounts/brackets worn	Monitor	
													Slide dented	Monitor
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	2	800	26-Oct	/	/	/	/	/	X	Swing mounts/brackets worn	Monitor	
													Deck/bridge plastic worn	Monitor
			1			/	/	/	/	/	X	X	Handle loose on turtle	Monitor
75	KAMBAH PLGR 286	Lascelles Circ	2	1247	12-Oct	/	/	/	/	X	X	Border Sleepers splitting	Monitor	
													See saw Top centre plate cracked	Needs Repair - LAZ
			1	1540	31-Oct	/	/	/	/	X	X	Low branches	Cut back - PCL	
													Bridge slats splitting/links worn/movement	Monitor
76	KAMBAH PLGR 325	Learmonth Dr										Chain net links worn	Monitor	
			2	913	26-Oct	/	/	/	/	X	X	Fort Timber panels worn/split	Monitor	
													Climb net ropes worn	Monitor
			1			/	/	/	/	X	X	Timber posts splitting	Monitor	
													Rock wall missing rocks	Needs Repair J&E
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)										Damaged bolt caps on equipment	Monitor	
													Spring motorcycle panels worn	Monitor
			2	1110	12-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Decking plastic worn	Monitor
			1	1420	01-Nov	/	/	/	/	X	X	Burn marks on post / slide	Monitor	
											Fly fox handle broken off	Needs Repair J&E		
											Bridge/Climb net links worn	Monitor		
											Bridge slats splitting/movement worn timber	Monitor		

Name Of Inspector		Domenik		Month of Inspection								Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	2	1125	12-Oct	/	/	/	/	/	/	X	Monitor all links in hosing	Monitor			
														Damaged rubber chain hose	Monitor		
			1	1425	01-Nov	/	/	/	/	/	/	/	X	Bench seat slat damaged	Needs Repair PCL		
79	KAMBAH PLGR 314	Mannheim St	2	1205	12-Oct	/	/	/	/	/	X	X	Border logs splitting	Monitor			
														Bridge slats splitting	Monitor		
			1	1555	31-Oct	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
															Welds cracked at slide entry	Needs Repair - LAZ	
													Bridge links worn	Monitor			
80	KAMBAH PLGR 285	Marconi Cres	2	1255	12-Oct	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor			
															Gravel washed/weeds into bark	Needs Removal - PCL	
			1	1535	31-Oct	/	/	/	/	/	/	/	X	Deck edge wear	Monitor		
													Spring bear loose in footing	Monitor			
81	KAMBAH PLGR 308	Maxworthy St	2	1145	12-Oct	/	/	/	/	/	/	X	Swing mounts worn	Monitor			
															Bark low	Needs Top up - PCL	
			1	1435	01-Nov	/	/	/	/	/	/	/	X				
													Damaged spinner seats x 2	Needs Repair - J&E			
82	KAMBAH PLGR 292	McKillop Pl	2	1010	26-Oct	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															2 x decks plastic worn	Needs Repair - LAZ	
			1			/	/	/	/	/	/	X	X	Swing seat/brackets worn	Monitor		
																Bridge/decks rusting	Monitor
													Flat swing seat damaged	Monitor			
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	2	930	26-Oct	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															Slide has small dents	Monitor	
			1			/	/	/	/	/	/	X	X	Split rubber on stairs	Monitor		
													Graffiti on panel	Needs Removal PCL			
84	KAMBAH PLGR 302	Pinkerton Circ	2	1100	26-Oct	/	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL			
															Decking plastic worn/surface rust	Monitor	
			1			/	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor		
																Low tree branches	Needs removal- PCL
																Exposed tree roots in bark	Needs removal- PCL
													Bark low	Needs Top up - PCL			
			2	1340	12-Oct									New playground under construction	Fenced off		

Name Of Inspector		Domenik		Month of Inspection						Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
85	KAMBAH PLGR 306	Primmer Court	1	1520	31-Oct											
86	KAMBAH PLGR 303	Rounsevell St	2	922	26-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Swing mounts worn	Monitor	
			1			/	/	/	/		X	X	Slide metal rusting/ dented	Monitor		
														spring animal footing loose	Needs Repair J&E	
												Lap seat worn	Monitor			
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN													
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN													
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN													
90	KAMBAH PLGR 290	Toole Pl	2	1040	26-Oct	/	/	/	/		X	X	Swing posts splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			1			/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor		
															Bridge links worn	Monitor
															Climb net links/mounts worn	Monitor
															Slide loose at entry bracket	Monitor
															Star pickets in bark	Needs Removal PCL
												Border sleepers splitting	Monitor			
91	KAMBAH PLGR 202	Vanzetti Cres	2	1135	12-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Decking worn/rusting	Monitor	
			1	1430	01-Nov	/	/	/	/		X	X	Movement in stair footing	Monitor		
												Bridge plastic worn/rusting	Monitor			

Name Of Inspector		Domenik		Month of Inspection						Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
												Swing mounts/brackets worn	Monitor		
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN												
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	2	1440	08-Oct	/	/	/	/		X	X	Decking worn	Monitor	
			1	1520	25-Oct	/	/	/	/		X	X	Chain net links/mounts worn	Monitor	
														Bent deck poles	Monitor
														Border damaged/rotted	Needs Repair - PCL
												Worn timber on spring horse	Monitor		
												Bark low and footings exposed	Needs Top up - PCL		
94	MONASH PLGR 252	Alabaster St	2	1056	04-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor	
			1	1132	25-Oct	/	/	/	/		X	X	Swing mounts/ links worn	Monitor	
														Bite marks in swing seat	Monitor
														Damaged spiral ladder	Monitor
														Damaged tic tac toe	Monitor
												Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	2	1017	04-Oct	/	/	/	/			X	Posts splitting and rotten	Monitor	
														Swing mounts/links/brackets worn	Monitor
			1	1145	25-Oct	/	/	/	/			X	Bridge mounts/chain worn	Needs Repair LAZ	
														Bridge timber splitting	Monitor
												Fibreglass damaged/cracking/worn on slides	Monitor		
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	2	1030	04-Oct	/	/	/	/		X	X	Steering wheel bracket worn	Monitor	
			1	1140	25-Oct	/	/	/	/		X	X	Border timber splitting/missing	Needs Repair - PCL	
														Dirt washed into bark	Needs repair - PCL
												Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	2	1140	04-Oct	/	/	/	/			X	Swing mounts/ links worn	Monitor	
														Concrete stump at bench	Needs Removal - PCL
			1	1125	25-Oct	/	/	/	/			X	Low hanging branches	Needs Removal - PCL	
98	MONASH PLGR 250	Hallstrom Circ	2	955	04-Oct	/	/	/	/		X	X	Swing brackets/mounts/links worn	Monitor	
														Concrete border lifting	Needs Repair PCL
			1	1150	25-Oct	/	/	/	/		X	X	Damaged bolt caps on spring toy	Needs Repair J&E	

Name Of Inspector		Domenik		Month of Inspection							Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	2	1200	04-Oct	/	/	/	/		X	X	Movement in swing crossbar	Monitor		
														Bridge links/mounts worn/movement	Monitor	
			1	1100	25-Oct	/	/	/	/		X	X	Swing mounts worn	Monitor		
															Bent bar/cracked welds on bridge	Needs Repair - LAZ
															Bark low	Needs Top up - PCL
													Bridge slats splitting / lichen	Monitor		
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	2	1006	04-Oct	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor		
														Triangles worn plastic	Monitor	
			1	1155	25-Oct	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
													Spring animal crack in foot rest/head loose	Monitor		
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin Pl)	2	930	04-Oct	/	/	/	/	/		X				
															Horse head splitting	Monitor
			1	900	31-Oct	/	/	/	/	/		X	Damaged tyre swing	Monitor		
102	OXLEY PLGR 255	Newman Morris Circ	2	920	04-Oct	/	/	/	/		X	X	Swing mounts worn	Monitor		
															Bite marks in swing seat	Monitor
			1	915	31-Oct	/	/	/	/		X	X	Bark washing out	Needs repair PCL		
													Border concrete damaged	Needs Repair PCL		
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	2	1240	04-Oct	/	/	/	/		X	X	Border sleepers damaged	Needs Repair J&E		
															Deck plastic worn	Monitor
			1	846	31-Oct	/	/	/	/		X	X	Carousel rusting/loose in footing	Monitor		
															Spring frog handle loose	Monitor
													Pod mounts worn (eyelet)	Needs repair - LAZ		
104	RICHARDSON PLGR 258	Chauncy Cres	2	1335	04-Oct	/	/	/	/	/		X	Decking plastic worn	Monitor		
															Swing mounts worn	Monitor
			1	807	31-Oct	/	/	/	/	/		X	Cuts on slide (smoothed)	Monitor		
105	RICHARDSON PLGR 259	Clift Cres	2	1255	04-Oct	/	/	/	/	/		X	Obscene graffiti / damage on new concrete path	Needs Removal PCL		
															Worn swing chains/mounts/movement in post	Monitor
			1	830	31-Oct	/	/	/	/	/		X				
																Bark low / dirt in bark
													Bolt caps damaged on spring animal	Needs Repair J&E		
			2	1320	04-Oct	/	/	/	/	/		X	Decking plastic worn/surface rust	Monitor		
														Climb net mounts worn	Needs Repair LAZ	

Name Of Inspector		Domenik			Month of Inspection					Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
106	RICHARDSON PLGR 257	Vidal St	1	813	31-Oct	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor		
													Climb net links worn	Monitor	
														Climb net bar bent	Monitor
														Tyre swing links worn	Monitor
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN												
108	THEODORE PLGR 265	Dyett Circ	2	1505	01-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			1	1445	24-Oct	/	/	/	/	X	X	Decking timber splitting	Monitor		
												Chain net links worn	Monitor		
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN												
110	THEODORE PLGR 261	Louis Loder St	2	1517	01-Oct	/	/	/	/	X	X	Border logs splitting	Monitor		
													Decking timber splitting	Monitor	
			1	1450	24-Oct	/	/	/	/	X	X	Slide fibreglass cracking/worn	Monitor		
														Chain net links worn	Monitor
												Bark low	Needs Top up - PCL		
111	THEODORE PLGR 264	Scantleberry St	2	1445	01-Oct	/	/	/	/	X	X	Border concrete broken/lifting	Needs Repair - PCL		
													Border logs splitting	Monitor	
			1	1440	24-Oct	/	/	/	/	X	X	Trees growing in bark	Needs Removal - PCL		
														Slide damaged at top	Monitor
														Spring animal timber worn	Monitor
														Decking timber/panel splitting	Monitor
												Chain net links worn	Monitor		
112	WANNIASSA PLGR 270	Billson Pl	2	955	12-Oct	/	/	/	/	/	X				
														Decking plastic worn	Monitor
			1	1518	29-Oct	/	/	/	/	/	X		Bridge plastic worn	Needs Repair LAZ	
														Damaged tic tac toe	Monitor
												Worn rubber on sp ke spinner	Needs Repair J&E		
													Decking timber worn	Monitor	

Name Of Inspector		Domenik		Month of Inspection								Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
113	WANNIASSA PLGR 267	Bussau Cl	1	1545	29-Oct	/	/	/	/		X	X	Chain net links worn/plastic peeling	Monitor			
														Damaged/rotting borders	Monitor		
															Concrete path lifting	Needs Repair PCL	
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	2	1005	12-Oct	/	/	/	/	/		X	Decking plastic worn x 1	Needs Repair - LAZ			
															Swing mounts/brackets worn	Monitor	
			1	1500	29-Oct	/	/	/	/	/			X				
115	WANNIASSA PLGR 275	Hervey Pl	2	1445	10-Oct	/	/	/	/		X	X	Border sleepers/braces splitting	Needs Repair PCL			
															Decking plastic rust / peeling	Monitor	
			1	1415	29-Oct	/	/	/	/			X	X	Smoking sign loose in footing	Needs Repair PCL		
116	WANNIASSA PLGR 266	Lansell Circ	2	900	12-Oct	/	/	/	/	/		X	Swing mounts worn	Monitor			
															Movement in spring animal	Monitor	
			1	1600	29-Oct	/	/	/	/	/			X	Border fence panels damaged	Monitor		
117	WANNIASSA PLGR 269	Sainsbury St	2	945	12-Oct	/	/	/	/		X	X	Border logs splitting	Monitor			
															Holes in shade sail	Monitor	
			1	1525	29-Oct	/	/	/	/			X	X				
																Burn marks on tic tac toe	Monitor
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN														
119	WANNIASSA PLGR 276	Steinfeld Circ	2	1510	10-Oct	/	/	/	/		X	X	Border Sleepers splitting	Monitor			
															Bench seat slats splitting	Monitor	
			1	1430	29-Oct	/	/	/	/			X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ		
																Decks worn x 2	Needs Repair - LAZ
																Bridge slats splitting	Monitor
120	WANNIASSA	Sullivan Cree													Bridge/Chain net links worn/plastic	Monitor	
			2	930	12-Oct	/	/	/	/		X	X	Bearings / wheels damaged on fly fox trolley	Needs Repair J&E			
																Border logs splitting	Monitor
														Bridge/chain links worn	Monitor		

Name Of Inspector		Domenik		Month of Inspection								Oct-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
120	PLGR 268	Sumivan Cres	1	1535	29-Oct	/	/	/	/		X	X	Handle plastic worn on flying fox	Monitor	
													Swing seats/mounts worn/splitting	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St	2	1535	10-Oct	/	/	/	/		X	X	Border sleepers damaged	Needs Repair - PCL	
													Swing mounts worn	Monitor	
			1	1445	29-Oct	/	/	/	/		X	X	Bridge timber splitting	Monitor	
													Park bench missing / damaged timber	Needs Repair - PCL	
													Decking worn/lichen growing	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres	2	1430	10-Oct	/	/	/	/		X	X	Decking worn / rusting	Monitor	
													Swing mounts/ links worn	Monitor	
			1	1400	29-Oct	/	/	/	/		X	X	Fireman pole damaged	Monitor	
													Roman triangles links worn plastic worn	Monitor	
													Chain net links worn	Monitor	
123	WANNIASSA PLGR 272	Whiteman St	2	1600	10-Oct	/	/	/	/		X	X	Swing mounts/s hooks/ chains worn	Monitor	
			1	1458	29-Oct	/	/	/	/		X	X	Border logs splitting	Monitor	
													Horse head splitting	Monitor	



Name Of Inspector: Domenik Month of Inspection: Oct-19

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
						/	x	/	x	/	x	/	x	/	x	/	x			/	x	Hazard	Action
1	COTTER PLGR 620	COTTER PICNIC GROUND	2	1120	27-Oct	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban			
																				Awning ladders mounts rusting	Monitor		
			1	915	01-Nov	/		/		/		/		/					X	Bridge mounts worn	Monitor		
																					Pommels links/mounts worn/hosing split	Monitor	
																					Swing mounts/brackets worn	Monitor	
																						2 x tread caps missing on surfer	Monitor
																						Bridge metal slip hazard	Angle / monitor
																						Basketball backboard worn	Monitor
																						Climb chain mounts/links worn/hosing split	Monitor
																						Rubber soft fall worn	Monitor
2	COTTER PLGR 539	CASURINA SANDS	2	1100	27-Oct	/		/		/		/		/				X	Post timber splitting	Monitor			
																				Decking timber splitting	Monitor		
			1	900	01-Nov	/		/		/		/		/					X	Rope bridge wearing	Monitor		
3	GREENWAY PLGR 538	Pine Island Rd	1	635	01-Oct	/		/		/		/			X	X			Border logs splitting	Monitor			
			2	1545	08-Oct	/		/		/		/			X	X			Climbing wall worn/rusting	Monitor			
			1	1540	15-Oct	/		/		/		/			X	X			Movement in staircase footing	Monitor			
			1	1420	21-Oct	/		/		/		/			X	X				Swing mounts/chains worn	Monitor		
			1	1330	28-Oct	/		/		/		/			X	X				Pop rivet missing on deck	Needs Repair J&E		
																					Decks/bridge worn/rusting	Monitor	
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	2	1158	27-Oct	/		/		/		/			X	X			Fence timber splitting around water tanks	Monitor			
																				Timber splitting on large spring platform	Monitor		
			1	1000	01-Nov	/		/		/		/				X	X			Water tanks decking timber splitting/worn	Monitor		
																					Flying fox posts splitting	Monitor	
																					Spider climb net rope frayed	Monitor	
																					Hand water pump not working/plates loose	Removed until further notice PCL	
																					Tree roots lifting paths	Needs Repair PCL	
																					Rubber soft fall splitting / low bark	Needs Repair PCL	



Name Of Inspector

Domenik

Month of Inspection

Oct-19

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Inspectors Signature: D.Radman



Location Theodore Chippindal Cct

Time 900

Date 08/10/2019

Name Domenik Radman

Weather Sunny

Date Next Assessment

ITEM TO BE ASSESSED For potential hazards	✓ x	ISSUE What is the Hazard	RISK L M H VH	REVIEW		
				What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS						
1.01 Good visibility for supervision, surrounds in good condition, no graffiti	/					
1.02 Bubbler and water features clean and fully operational	/					
1.03 Access ramps, pathways, entrances free of slipping & tripping hazards	/					
1.04 Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/					
1.05 Paths around playground clear of hazards cracks, trips, vegetation	/					
1.06 Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/					
1.07 Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	L	Monitor		
1.08 Gates closing & locking devices operational, no finger entrapments (>12mm)	/					
1.09 Access, entrance & ancillary items free of protrusions/sharp edges	/					
SURFACING						
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings						
2.01	/					
2.02 Rubbish that may be hygiene issue removed	/					
2.03 Broken glass, rocks, foreign objects likely to cause injury removed	/					
2.04 Surface in good condition, no trip points	/					
2.05 Drainage operational, no contamination from runoff	/					
LOOSE FILL MATERIAL						
2.06 Check depth min 300mm-400mm, top up or rake as required	X	Low bark	M	Top up bark		PCL
2.07 Loose-fill containment edging / barrier secure, free of protrusions	/					
2.08 No material deterioration or contamination by clay or other matter	/					
SYNTHETIC MATERIAL						
2.09 Fouling of surface or chewing gum, foreign objects, rocks	/					
2.10 Joints, wear layer, impact attenuation layer or sub-base failure	/					
EQUIPMENT						
Platforms, Structures and frames						
3.01 Foundation and structures free of movement, rot or corrosion	/					
3.02 No water penetration into structure or fittings, bulging, corrosion	/					
3.03 Handrails, guardrails, barriers, decks, platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor		
3.04 Physical damage or missing parts, bolts, present and secure, vandalism	/					
3.05 Check end caps, bolts, screws, tube ends	/					
3.06 No cracked or damaged plastic or wood panels, no graffiti	/					
3.07 No protruding screws, nails, bolts, sharp edges, splintering or cracks	/					
3.08 Remove loose items brought into playground - ropes, rocks, sticks	/					
3.09 Equipment free from moss, mould, unhygienic matter - slip potential	/					
Chains, Ropes, Cables, Nets and Tyres						
3.10 Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/					
3.11 No fraying of ropes or cable (or ends) - Replace or remove	/					
3.12 Wear in chains & connectors <40%	/					
3.13 No entrapment hazards, no corrosion, no sharp edges	/					
Swings						
3.14 Check for squeaking bushes - lubricate/replace	/					
3.15 Swing action smooth & quiet, seat has no damage or vandalism	/					
3.16 Wear in chains & connectors <40%	X	Swing mounts/brackets worn	L	Monitor		
3.17 Check seat & pivot connections for tightness, s-hooks for closure	/					
3.18 Impact attenuating edge intact, no cracking or exposed metal components	/					
3.19 Drain holes in tyres clear, no exposed metal wire	/					
3.20 Seat clearance from ground min 400mm	/					
Slides						
3.21 No damage or foreign objects on slide bed/sides - exit wear area	/					
3.22 Structure slide & supports - stability, looseness, corrosion, splinters	/					
3.23 Runout section height <350mm (or 200mm up to 1500mm sliding section)	/					
3.24 No entrapments, sliding smooth, overlap of joints downwards	/					
Carousels (rotating equipment)						
3.25 Speed limited to 5m/s	/					
3.26 Smooth & quiet rotation (both directions), platform level & stable	/					
3.27 Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	L	Monitor		
3.28 Underside clear of protrusions & sharp edges	/					
Runways (flying foxes)						
3.29 Trolley motion smooth, no loose wire strands, speed limited to 7m/s	/					
3.30 End stops haven't moved, they bring trolley to a controlled stop	/					
3.31 No loose/missing bolts, rot/corrosion (particularly at ground level)	/					
3.32 Is cable secure, platform stable, seat/grip condition, clearance 400mm	/					
Seesaws & rocking equipment (Spring Animals)						
3.33 No looseness in movement or damage, missing bolts/handles	X	2 x spring animal movement in handle/footing	L	Monitor		
3.34 No rot or corrosion, foundation movement, splintered timber	/					
Sandpits						
3.35 No ponding water, drainage issues or health hazards	/					
3.36 Sand pit edges and supports intact & secure	/					
3.37 Sand raked to remove foreign objects, fouling, glass	/					

RISK LEVEL - SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely) - Once every 100yrs
 2 Unlikely (Conceivable) - Once every 30 yrs
 3 Possible (Could occur) - Once every 10 yrs
 4 Likely (Almost certain) (On an annual basis)

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 4-5 Serious injury, possible long term absence from school
 6-7 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 360:200 Risk Management.

NOTES

Empty space for notes.



Name Of Inspector Domenik Month of Inspection Nov-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection Time	Date of Inspection Date	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description Hazard	Action Taken- For full details please refer to attached Playground Safety Inspection Report Action				
							/	x	/	x	/	x	/	x	/	x	/	x			/	x		
1	BANKS PLGR 413	Pocket Ave		1	945	06-Nov	/		/		/		/				X	X	Loose slide leg	Monitor				
				1	1345	11-Nov	/		/		/		/				X	X	Chain net links/mounts worn	Monitor / Needs Repair LAZ				
				1	920	18-Nov	/		/		/		/				X	X	Track ride worn links	Monitor				
				2	835	25-Nov	/		/		/		/				X	X	Border concrete cracking / lifting	Needs Repair PCL				
				1			/		/		/		/				X	X	Small plastic slide damaged	Monitor				
2	BONYTHON PLGR 535	Burgoyne St					/		/		/		/					Titer toters arms missing	Removed until further notice - PCL					
				1	1000	05-Nov	/		/		/		/					X	Ropes worn on climb net	Monitor				
				1	830	11-Nov	/		/		/		/					X	Spinner centre plastic damaged	Repaired by J&E 6/11/19				
				1	730	19-Nov	/		/		/		/						X	Graffiti on fire truck	Needs Removal PCL			
				2	1530	25-Nov	/		/		/		/						X	Collar pins worn	Monitor			
3	FADDEN PLGR 228	Coyne St		1			/		/		/		/					X	Ropes worn on small single swing	Monitor				
				1	1310	06-Nov	/		/		/		/				X	X	Swing mounts worn	Monitor				
				1	1217	11-Nov	/		/		/		/				X	X	Cracked welds on slide entry	Monitor				
				1	858	19-Nov	/		/		/		/				X	X	Worn links bridge/climb chains	Monitor				
				2	955	25-Nov	/		/		/		/				X	X	Timber split on panels	Monitor				
4	GORDON PLGR 278	McGilvray Circ					/		/		/		/					X	Border logs splitting	Monitor				
				1			/		/		/		/							X	Holes in softfall / splitting	Needs repair - PCL		
				1			/		/		/		/								X	Footpath lifting	Needs repair - PCL	
				1			/		/		/		/									X	Slide footing loose	Monitor
				1			/		/		/		/									X	Spinning seesaw hanger has worn bolts/handle	Monitor
				1			/		/		/		/									X	Hose splitting on chain covers	Monitor
				1			/		/		/		/									X	Movement in brackets on web towers	Monitor
				1	700	01-Nov	/		/		/		/									X	Fibreglass on tea cup spinner cracking	Monitor
				1	920	06-Nov	/		/		/		/									X	Swing mounts worn x 2	Needs Repair - J&E
				1	700	08-Nov	/		/		/		/									X	Damaged see-saw brackets x 3	Needs Repair - J&E
				1	1410	11-Nov	/		/		/		/									X	Rope climb net worn 80%	Needs Repair - J&E
				1	715	15-Nov	/		/		/		/									X	Spinner top bearings loose	Monitor
				1	900	18-Nov	/		/		/		/									X	Damaged super nova	Monitor
1	700	22-Nov	/		/		/		/									X	Border logs splitting	Monitor				
2	800	25-Nov	/		/		/		/									X	Roman triangles worn links	Needs repair - LAZ				
1	700	29-Nov	/		/		/		/									X	Wire walk cable worn	Monitor				
5	GOWRIE PLGR 328	Jeffries St					/		/		/		/						X	Decking worn on tower	Monitor			
				1	1400	06-Nov	/		/		/		/								X	Wire bridge mount worn/chain low links worn	Needs repair - LAZ	
				1	1200	11-Nov	/		/		/		/								X	Cracked welds in tower/rust	Needs repair - LAZ	
				1	845	19-Nov	/		/		/		/									X	Rubber Soft fall splitting/holes	Needs repair - PCL
				2	1030	25-Nov	/		/		/		/									X	Swing chains/brackets/mounts	Monitor
			/		/		/		/										X	bench below tea cup playground coming out of footing	Needs repair - PCL			
			/		/		/		/										X	Hole in shade sail	Monitor			
			/		/		/		/										X	Softfall splitting / holes forming	Needs Repair PCL			
			/		/		/		/										X	Timber worn on carousel	Monitor			
			/		/		/		/										X	Spider net worn	Monitor			



Name Of Inspector Domenik Month of Inspection Nov-19

	Suburb	Street	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
				Level 1 or Level 2			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/			x	/	x
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	1055	11-Nov	/		/		/				X	X			Swing mounts/brackets worn	Monitor			
				1	1110	19-Nov	/		/		/		/			X	X			Concrete border lifting	Monitor		
				2	1240	25-Nov	/		/		/		/			X	X			Bridge slats splitting	Monitor		
				1			/		/		/		/			X	X			Movement in see saw base	Monitor		
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	1225	04-Nov	/		/		/				X	X			Damaged concrete border	Monitor			
				1	1105	11-Nov	/		/		/		/			X	X			Damaged park seat	Needs repair - PCL		
				1	1100	19-Nov	/		/		/		/			X	X			baby swing damaged	Monitor		
				2	1228	25-Nov	/		/		/		/			X	X			Plastic Rock on climb wall cracking	Monitor		
				1			/		/		/		/			X	X			Movement in base of carousel	Needs repair - J&E		
14	KAMBAH PLGR 305	Springbett St		1	810	01-Nov	/		/		/				X	X			Twin S/S slide has crack in surface	Monitor			
				1	1245	04-Nov	/		/		/		/			X	X			Swing seat/brackets/links/mounts worn	Monitor		
				1	840	08-Nov	/		/		/		/			X	X			Super nova damaged	Monitor		
				1	1035	11-Nov	/		/		/		/			X	X			Hosing split on carousel	Monitor (taped)		
				1	900	15-Nov	/		/		/		/			X	X			Mount worn on large fly fox	Monitor		
				1	1120	19-Nov	/		/		/		/			X	X			Border logs splitting	Monitor		
				1	837	22-Nov	/		/		/		/			X	X			Sml fly fox movement in bolt	Monitor		
				2	1250	25-Nov	/		/		/		/			X	X			Tic Tac Toe damaged (taped)	Needs Repair J&E		
				1	830	29-Nov	/		/		/		/			X	X			Damage panel on quad hoops	Monitor		
																					Low branches at swings & fly fox/grass in bark	Cut back/remove - PCL	
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	1200	04-Nov	/		/		/				X	X			Burn marks at liberty swing seat	Monitor			
				1	1120	11-Nov	/		/		/		/			X	X			Bark low/ washed out	Needs repair - PCL		
				1	1037	19-Nov	/		/		/		/			X	X			Bark low	Needs Top up - PCL		
				2	1105	25-Nov	/		/		/		/			X	X			Burn mark seesaw	Monitor		
				1			/		/		/		/			X	X			Swing mounts	Monitor		
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	1210	04-Nov	/		/		/					X				Timber swing posts splitting/ missing swings	?		
				1	1115	11-Nov	/		/		/		/				X				Worn decks/ bridge	Monitor	
				1	1045	19-Nov	/		/		/		/				X				Damaged rock wall	Monitor	
				2	1130	25-Nov	/		/		/		/				X				Rope worn on carousel	Monitor	
				1			/		/		/		/				X				Swing seat / brackets worn	Monitor	
17	MACARTHUR PLGR 327	Bayly Pl		1	1225	06-Nov	/		/		/				X						Bark low	Needs Repair PCL	
				1	1230	11-Nov	/		/		/		/				X					Worn swing links/brackets	Monitor
				1	940	19-Nov	/		/		/		/				X					Rope worn on climbing net/carousel	Monitor
				2	935	25-Nov	/		/		/		/				X					Movement in base towards post of carousel	Needs repair - J&E
				1			/		/		/		/				X					Gravel washed into bark	Needs removal PCL
18	THEODORE PLGR 263	Chippindall Circ		1	1030	06-Nov	/		/		/					X					Low bark	Needs Top up - PCL	
				1	1305	11-Nov	/		/		/		/				X					Softfall patches lifting under birds nest swing	Needs Repair PCL
				1	940	18-Nov	/		/		/		/				X					Swing mounts/bushes worn	Monitor
				2	955	25-Nov	/		/		/		/				X					Carousel seat worn/rusting	Monitor
																				Worn/damaged deck/bridge	Monitor		
																					Loose handle/footings on spring animal x 2	Monitor	



Name Of Inspector

Domenik

Month of Inspection

Nov-19

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
	PLGR 205		1			/		/		/		/		/			X	2 x flat swings damaged	Repaired by J&E 6/11/19
																		Holes in shade sail	Monitor
																		Low bark	Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres	1	1200	06-Nov	/		/		/		/			X	X		Weld cracking at slide entry	Needs Repair - LAZ
			1	1250	11-Nov	/		/		/		/			X	X		Decking plastic worn/surface rust	Monitor
			1	950	18-Nov	/		/		/		/			X	X		Swing/Chain bridge links/mounts worn	Monitor
			2	915	25-Nov	/		/		/		/			X	X		Movement in frog footing	Monitor
			1			/		/		/		/			X	X		Border concrete cracking	Needs Repair - PCL
20	WANNIASSA PLGR 271	Sangster Pl	1	1100	04-Nov	/		/		/		/			X	X		Swing mounts brackets worn	Monitor
			1	1140	11-Nov	/		/		/		/			X	X		Decking worn	Monitor
			1	1020	19-Nov	/		/		/		/			X	X		Hole in chain wire fence	Needs Repair - LAZ
			2		25-Nov	/		/		/		/			X	X		Park bench missing arm rest	Needs Repair - PCL
			1			/		/		/		/			X	X		Holes and splitting in softfall	Needs repair - PCL

Inspectors Signature: D.Radman

PCL

LAZ

J&E

Name Of Inspector		Domenik		Month of Inspection								Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report						
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with sofffall		Sofffall free of litter glass/sharp objects		Sofffall raked and free of trip hazards		Border secure and in good condition				Equipment in safe and satisfactory condition					
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action			
1	BANKS PLGR 213	Menzies Court	1	1505	11-Nov	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																			Decking plastic worn/surface rust	Monitor	
			1	900	26-Nov	/		/		/		/				X		X			
																				Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	1	1510	11-Nov	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																			Swing seat brackets worn	Monitor	
			1	846	26-Nov	/		/		/		/				X		X	Decking worn	Monitor	
																				Dints in slide bed	Monitor
																		Border concrete cracking	Needs Repair - PCL		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	730	13-Nov	/		/		/		/					X	Posts handrails split/rotting	Monitor		
																			4 x Post damaged/split on fort	Monitor	
			1	645	21-Nov	/		/		/		/						X	Chain net links and mounts worn	Monitor	
																				Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	820	13-Nov	/		/		/		/			X		X	Border logs splitting	Monitor		
																				Swing seat/brackets damaged /worn	Repaired by J&E 13/11/19
			1	705	21-Nov	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																				Slide has crack at entry/movement	Monitor
7	BONYTHON PLGR 586	Morice Pl	1	808	13-Nov	/		/		/		/					X				
																				Swing seat brackets worn	Monitor
			1	655	21-Nov	/		/		/		/						X	Worn / missing rope on net	Monitor	
																					Worn links/mounts on pommel/ climb chain

Name Of Inspector		Domenik		Month of Inspection							Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
8	CALWELL PLGR 322	Beckett St	1	730	12-Nov	/	/	/	/	/	/	X	Decking plastic worn	Monitor		
														Swing mounts worn	Monitor	
			1	1240	21-Nov	/	/	/	/	/	/	/	X	Bent monkey bars	Monitor	
															Slide weld cracking at top	Needs Repair - LAZ
															Chain walk hand rail bent	Needs Repair - LAZ
															Bent deck poles	Needs Repair - LAZ
															Low tree branches	Needs Removal PCL
9	CALWELL PLGR 321	Casey Cres	1	820	12-Nov	/	/	/	/	/	/	X	Swing mounts worn	Monitor		
														Decking plastic worn/decks rusting	Monitor	
			1	1213	21-Nov	/	/	/	/	/	/	X	Chain net links worn/coating on chains	Monitor		
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)											See saw timber splitting	Monitor		
			1	740	12-Nov	/	/	/	/		X	X	Decking plastic worn	Monitor		
															Swing mounts/seat/links worn	Monitor
			1	1235	21-Nov	/	/	/	/		X	X	Low branches	Needs cut back back-PCL		
												Side leg bent	Monitor			
11	CALWELL PLGR 319	Samuel Cl	1	800	12-Nov	/	/	/	/		X	X	Border logs splitting	Monitor		
														Swing mounts worn	Monitor	
			1	1218	21-Nov	/	/	/	/		X	X	Bent monkey bars	Monitor		
												Park bench missing timber	Needs Repair - PCL			
12	CALWELL PLGR 644	Shopping Centre	1	745	12-Nov	/	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor		
														Bark low	Top up bark PCL	
			1	1225	21-Nov	/	/	/	/	/	/	X		Carousel movement in bearing	Monitor	
13	CALWELL PLGR 320	Were St	1	755	12-Nov	/	/	/	/		X	X	Border logs splitting	Monitor		
														Swing links/mounts worn	Monitor	
			1	1222	21-Nov	/	/	/	/		X	X	Tire worn on tyre swing	Monitor		
14	CHISHOLM PLGR 234	Alston St	1	1016	12-Nov	/	/	/	/	/	/	X		Swing mounts worn	Monitor	
			1	1140	21-Nov	/	/	/	/	/	/	X		Damaged tic tac toe	Monitor	

Name Of Inspector		Domenik		Month of Inspection							Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
												Baby seat chain cover worn	Monitor		
												Fly fox handle plastic worn	Monitor		
15	CHISHOLM PLGR 233	Dalyell St	1	1022	12-Nov	/	/	/	/	/	X	Timber decking splitting	Needs repair - J&E		
													Tyre swing mounts worn	Monitor	
			1	1145	21-Nov	/	/	/	/	/	/	X	Fly fox links worn	Monitor	
														Chain net mounts worn	Monitor
														Fly fox nylon guides worn	Needs Repair - J&E
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	1	940	12-Nov	/	/	/	/	/	X	Timber decking splitting	Monitor		
													Track ride not gliding with ease	Needs Repair - J&E	
			1	1110	21-Nov		/	/	/	/	/	X	Swing seat damaged/brackets/links worn	Monitor	
														Post loose in footing	Monitor
											Uneven paving around playground	Needs Repair PCL			
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	1	1000	12-Nov	/	/	/	/	/	X	Timber decking splitting	Monitor		
													Slide damaged at exit	Monitor	
			1	1120	21-Nov		/	/	/	/	/	X	Log steps splitting	Monitor	
														Damaged park bench	Needs Repair - PCL
														Tyre /s hooks wearing on tire swing	Monitor
											Graffiti on slide	Remove - PCL			
18	CHISHOLM PLGR 235	Kirkcaldie Circ	1	1030	12-Nov	/	/	/	/	/	X	Swing mounts/links worn	Monitor		
													Decking plastic worn/rusting	Monitor	
			1	1150	21-Nov		/	/	/	/	/	X	Climb net mounts/plastic worn	Monitor	
														Plastic at slide exit damaged	Needs Repair J&E
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	1	1005	12-Nov	/	/	/	/	/	X	Decking plastic worn	Monitor		
														Tyre swing mounts worn	Monitor
			1	1130	21-Nov		/	/	/	/	/	X	Climb net links worn	Monitor	
														Damaged park bench	Monitor
														Plastic panel damaged	Monitor
														Concrete border damaged	Needs repair - J&E
											Bent/damaged deck poles	Needs repair - LAZ			
20	CHISHOLM PLGR 236	Proctor St	1	1035	12-Nov	/	/	/	/	/	X	Swing mounts/links/seat worn	Monitor		
														Low bark	Needs top up - PCL
			1	955	21-Nov		/	/	/	/	/	X	Dints in slide	Monitor	
												Fly fox handle plastic worn	Monitor		

Name Of Inspector	Domenik		Month of Inspection						Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	1110	12-Nov	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor	
													Border timber damaged	Needs Repair PCL
			1	1620	21-Nov	/	/	/	/	X	X	Movement in carousel base	Monitor	
													Decking timber splitting	Monitor
													Chain net links / mounts worn	Monitor
													Lichen growing on decks	Monitor
29	FADDEN PLGR 509	Nicklin Cres	1	730	07-Nov	/	/	/	/	X	X	Rocks missing in border wall	Needs Repair - PCL	
													Rope bridge mount broken/rope worn	Needs Repair PCL
			1	1630	21-Nov	/	/	/	/	X	X	Climbing nets rope worn	Monitor	
													Panel/ roof panels cracked on fort	Monitor
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	1050	12-Nov	/	/	/	/	X	X	Swing mounts/ links worn	Monitor	
													Damaged baby swing	Monitor
			1	1610	21-Nov	/	/	/	/	X	X	Border logs worn	Monitor	
31	GILMORE PLGR 238	Hogue Pl										Dent in parallel bars/swing post	Monitor	
			1	840	12-Nov	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor	
													Rubber frog damaged	Monitor
			1	1040	21-Nov	/	/	/	/	X	X	Low bark	Needs Top up - PCL	
32	GILMORE PLGR 239	Rosman Circ	1	855	12-Nov	/	/	/	/	X	X	Fence damaged	Monitor	
													Spinner seats worn/ rusting	Monitor
			1	1050	21-Nov	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL	
33	GORDON PLGR 215	Iredale Pl										Bark low	Top up bark PCL	
			1	905	12-Nov	/	/	/	/	/	X	Bridge timber splitting	Monitor	
													Concrete at bench lifting	Needs Repair PCL
33	GORDON PLGR 215	Iredale Pl	1	1100	21-Nov	/	/	/	/	/	X	3 x damaged bolt caps on fort	Repaired by J&E - 12/11/19	
			1	1435	07-Nov	/	/	/	/	/	X	Swing seat brackets worn	Monitor	
33	GORDON PLGR 215	Iredale Pl										Chain net/ladder links worn/plastic	Monitor	
			1	1030	26-Nov	/	/	/	/	/	X	Damaged post caps x 4	Monitor	
												Slide damaged	Monitor	

Name Of Inspector		Domenik			Month of Inspection				Nov-19				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN												
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET												
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	1200	08-Nov	/	/	/	/		X	X	Ropes worn on web	Monitor	
													Decks/Posts splitting/rotten	Monitor	
			1	1425	20-Nov	/	/	/	/		X	X	Swing mounts/seat worn	Monitor	
														Decking poles bent	Repaired by J&E 8/11/19
														Concrete border lifting	Needs Repair PCL
												Gaps were slide joins	Monitor		
													Swing timber splitting	Monitor	
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	1140	08-Nov	/	/	/	/	/		X	Swing mounts worn	Monitor	
			1	1410	20-Nov	/	/	/	/	/		X	Plastic slide cracked	Monitor	
														Movement in swing posts	Monitor
														Frog plastic worn around handle	Monitor
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	1145	08-Nov	/	/	/	/		X	X	Border path concrete cracking	Monitor	
													Slide surface worn	Monitor	
			1	1417	20-Nov	/	/	/	/		X	X	Chain net links	Monitor	
														Spring animal missing	Needs repair - J&E
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	1240	19-Nov	/	/	/	/	/		X	Slide leg loose in footing	Monitor	
													Low bark	Top - PCL	
			1	1400	27-Nov	/	/	/	/	/		X	Spring animal loose in footing	Monitor	
												Angle bar missing at climbing net damaged	Needs repair - LAZ		
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	1445	14-Nov	/	/	/	/		X	X	Border logs splitting	Monitor	
													Swing mounts/brackets worn	Monitor	
			1	1345	26-Nov	/	/	/	/		X	X	Concrete lifting quad hoop game	Monitor	
														Chain net links / mounts worn	Monitor
												Slide surface worn	Monitor		
												Border logs damaged	Needs Repair PCL		
												Swing mounts worn/loose due to timber shrinking	Monitor		

Name Of Inspector		Domenik		Month of Inspection							Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
57	KAMBAH PLGR 313	Attiwell Circ	1	1420	27-Nov	/	/	/	/	X	X	Bench seat frame bent	Monitor		
													Swing timber damage/splitting	Monitor	
														Asphalt cracking / lifting	Needs Repair PCL
														See-saw footrest damaged	Monitor
58	KAMBAH PLGR 314	Barritt St	1	1220	19-Nov	/	/	/	/	/	X				
														Bridge plastic worn/ rusted	Monitor
			1	1330	27-Nov	/	/	/	/	/	X		Welds cracked on chain net	Needs Repair - LAZ	
												Fort panel movement	Monitor		
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	1040	15-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Damaged plastic on stairs	Monitor	
			1	1115	27-Nov	/	/	/	/	X	X		Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	1340	14-Nov	/	/	/	/	X	X	Timber decking splitting	Monitor		
													Swing posts splitting and rotten	Monitor	
			1	1220	26-Nov	/	/	/	/	X	X		Movement in ladder plate to decking	Monitor	
														Timber border lifting/damaged	Monitor
														Swing mounts/brackets worn/small movement	Monitor
											Bark washed out	Needs Repair - PCL			
63	KAMBAH PLGR 317	Bullock Circ	1	1115	15-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Rubber on stairs splitting	Monitor	
			1	1215	27-Nov	/	/	/	/	X	X		Worn rubber on deck	Needs Repair LAZ	
														Climb chain/bridge links worn	Monitor
												Bridge slats split	Repaired by J&E 27/11/19		
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 200	Coghill Cl	1	1200	14-Nov	/	/	/	/	X	X	Swing mounts worn	Monitor		
													Border logs splitting	Monitor	
			1	1105	26-Nov	/	/	/	/	X	X	Carousel loose - movement in bearing	Monitor		

Name Of Inspector	Domenik	Month of Inspection										Nov-19	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition			Hazard Description	
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	1020	15-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor		
												Swing mounts worn	Monitor		
			1	1500	26-Nov	/	/	/	/	X	X	Decking plastic worn	Monitor		
												Low bark	Needs Top up - PCL		
												flying fox handle/mount/links worn	Monitor		
												Bridge timber splitting	Monitor		
												Bridge/climbing net links worn	Monitor		
66	KAMBAH PLGR 304	Dale Circ	1	950	15-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor		
												Decks rusty/ plastic peeling	Needs Repair LAZ		
			1	1520	26-Nov	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor		
												Swing brackets/mounts worn	Monitor		
67	KAMBAH PLGR 291	Deuchar Cl	1	1220	14-Nov	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor		
												Border sleepers splitting	Monitor		
			1	1120	26-Nov	/	/	/	/	X	X	Swing mounts worn	Monitor		
												Damaged post collars	Monitor		
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	1230	19-Nov	/	/	/	/	X	X	Border logs splitting	Monitor		
												Decking plastic worn	Monitor		
			1	1345	27-Nov	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ		
												Swing mounts worn	Monitor		
												Bark low	Needs top up - PCL		
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	1415	14-Nov	/	/	/	/	X	/	Rocks missing on rock wall	Needs Repair PCL		
			1	1310	26-Nov	/	/	/	/	X	/				
												Bridge timber splitting	Monitor		
70	KAMBAH PLGR 284	Gibbs Pl	1	1330	14-Nov	/	/	/	/	/	X	Knots and crosses cracking	Monitor		
												Bolt caps brittle/damaged on tower	Monitor		
			1	1210	26-Nov	/	/	/	/	/	X				
71	KAMBAH	Horton Cl	1	1230	14-Nov	/	/	/	/	X	X	Chain net links worn	Monitor		
												Decking plastic worn/rusting	Needs Repair LAZ		
			1	1125	26-Nov	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL		

Name Of Inspector		Domenik		Month of Inspection						Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition					
71	PLGR 289	Horton Cr										Parallel slide bar bent	Monitor	
													Wearing swing brackets	Monitor
													Tyre swing tyre worn	Needs Repair J&E
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	1	1410	14-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Bridge slats splitting	Needs Repair J&E
													Bridge/ chain net links worn	Monitor
73	KAMBAH PLGR 307	Humble Court	1	1310	14-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Swing mounts/brackets worn	Monitor
			1	1150	26-Nov	/	/	/	/	X	X	Slide dented	Monitor	
											Low bark	Needs Repair - PCL		
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	1030	15-Nov	/	/	/	/	/	X	Swing mounts/brackets worn	Monitor	
													Deck/bridge plastic worn	Monitor
			1	1440	26-Nov	/	/	/	/	/	X	Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	Lascelles Circ	1	1350	14-Nov	/	/	/	/	X	X	Border Sleepers splitting	Monitor	
													See saw Top centre plate cracked	Needs Repair - LAZ
			1	1240	26-Nov	/	/	/	/	X	X	Low branches	Cut back - PCL	
													Bridge slats splitting/links worn/movement	Monitor
													Chain net links worn	Monitor
											Decking plastic worn	Monitor		
76	KAMBAH PLGR 325	Learmonth Dr	1	1055	15-Nov	/	/	/	/	X	X	Fort Timber panels worn/split	Monitor	
													Climb net ropes worn	Monitor
			1	1130	27-Nov	/	/	/	/	X	X	Timber posts splitting	Monitor	
													Rock wall missing rocks	Monitor
													Damaged bolt caps on equipment	Monitor
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)											Spring motorcycle panels worn	Monitor
			1	930	07-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Decking plastic worn	Monitor
			1	1130	26-Nov	/	/	/	/	X	X	Bum marks on post / slide	Monitor	
													Fly fox handle broken off	Needs Repair J&E
											Bridge/Climb net links worn	Monitor		
											Bridge slats splitting/movement worn timber	Monitor		

Name Of Inspector		Domenik		Month of Inspection				Nov-19				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report					
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition									
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	1240	14-Nov	/	/	/	/	/	X	Monitor all links in hosing	Monitor					
													Damaged rubber chain hose	Monitor				
			1	1135	26-Nov	/	/	/	/	/	/	X	Bench seat slat damaged	Needs Repair PCL				
79	KAMBAH PLGR 314	Mannheim St	1	1320	14-Nov	/	/	/	/	/	X	X	Border logs splitting	Monitor				
														Bridge slats splitting	Monitor			
			1	1200	26-Nov	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor			
															Welds cracked at slide entry	Needs Repair - LAZ		
													Bridge links worn	Monitor				
80	KAMBAH PLGR 285	Marconi Cres	1	1400	14-Nov	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor				
															Gravel washed/weeds into bark	Needs Removal - PCL		
			1	1245	26-Nov	/	/	/	/	/	/	/	X	Deck edge wear	Monitor			
													Spring bear loose in footing	Monitor				
81	KAMBAH PLGR 308	Maxworthy St	1	1300	14-Nov	/	/	/	/	/	/	X	Swing mounts worn	Monitor				
															Bark low	Needs Top up - PCL		
			1	1145	26-Nov	/	/	/	/	/	/	/	X					
													Damaged spinner seats x 2	Needs Repair - J&E				
82	KAMBAH PLGR 292	McKillop Pl	1	1010	15-Nov	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
			1	1455	26-Nov	/	/	/	/	/	/	X	X	Swing seat/brackets worn	Monitor			
																Bridge/decks rusting	Monitor	
													Flat swing seat damaged	Monitor				
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	1530	13-Nov	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
																Slide has small dents	Monitor	
			1	1445	26-Nov	/	/	/	/	/	/	X	X	Split rubber on stairs	Monitor			
														Graffiti on panel	Needs Removal PCL			
84	KAMBAH PLGR 302	Pinkerton Circ	1	940	15-Nov	/	/	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL			
																Decking plastic worn/surface rust	Monitor	
			1	1530	26-Nov	/	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor			
																	Low tree branches	Needs removal- PCL
																	Exposed tree roots in bark	Needs removal- PCL
														Bark low	Needs Top up - PCL			
														New playground under construction	Fenced off			

Name Of Inspector		Domenik		Month of Inspection				Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report					
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
85	KAMBAH PLGR 306	Primmer Court	1	1330	26-Nov											
86	KAMBAH PLGR 303	Rounsevell St	1	1045	15-Nov	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Swing mounts worn	Monitor	
			1	1145	27-Nov	/	/	/	/		X	X	Slide metal rusting/ dented	Monitor		
														spring animal footing loose	Monitor	
												Lap seat worn	Monitor			
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN													
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN													
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN													
90	KAMBAH PLGR 290	Toole Pl	1	1000	15-Nov	/	/	/	/		X	X	Swing posts splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			1	1510	26-Nov	/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor		
															Bridge links worn	Monitor
															Climb net links/mounts worn	Monitor
															Slide loose at entry bracket	Monitor
												Star pickets in bark	Needs Removal PCL			
												Border sleepers splitting	Monitor			
91	KAMBAH PLGR 202	Vanzetti Cres	1	1250	14-Nov	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Decking worn/rusting	Monitor	
			1	1140	26-Nov	/	/	/	/		X	X	Movement in stair footing	Monitor		
												Bridge plastic worn/rusting	Monitor			

Name Of Inspector		Domenik		Month of Inspection						Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition				
												Swing mounts/brackets worn	Monitor
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN										
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	1220	11-Nov	/	/	/	/	X	X	Decking worn	Monitor
			1	1600	21-Nov	/	/	/	/	X	X	Chain net links/mounts worn	Monitor
												Bent deck poles	Monitor
												Border damaged/rotted	Needs Repair - PCL
												Worn timber on spring horse	Monitor
												Bark low	Needs Top up - PCL
94	MONASH PLGR 252	Alabaster St	1	1150	13-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor
			1	805	21-Nov	/	/	/	/	X	X	Swing mounts/ links worn	Monitor
												Bite marks in swing seat	Monitor
												Damaged spiral ladder	Monitor
												Damaged tic tac toe	Monitor
												Worn/rusting bridge	Monitor
95	MONASH PLGR 248	Charleston St	1	1005	13-Nov	/	/	/	/	/	X	Posts splitting and rotten	Monitor
												Swing mounts/links/brackets worn	Monitor
			1	745	21-Nov	/	/	/	/	/	X	Bridge mounts/chain worn	Needs Repair LAZ
												Bridge timber splitting	Monitor
												Fibreglass damaged/cracking/worn on slides	Monitor
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	1015	13-Nov	/	/	/	/	X	X	Steering wheel bracket worn	Monitor
			1	755	21-Nov	/	/	/	/	X	X	Border timber splitting/missing	Needs Repair - PCL
												Dirt washed into bark	Needs repair - PCL
												Slide surface worn	Monitor
97	MONASH PLGR 247	Cockcroft Ave	1	1200	13-Nov	/	/	/	/	/	X	Swing mounts/ links worn	Monitor
			1	810	21-Nov	/	/	/	/	/	X	Concrete stump at bench	Needs Removal - PCL
												Low hanging branches	Needs Removal - PCL
98	MONASH PLGR 250	Hallstrom Circ	1	930	13-Nov	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor
			1	735	21-Nov	/	/	/	/	X	X	Concrete border lifting	Needs Repair PCL
												1 x Damaged bolt caps on spring toy	Repaired by J&E 13/11/19

Name Of Inspector	Domenik	Month of Inspection	Nov-19										Action Taken- For full details please refer to attached Playground Safety Inspection Report		
			Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition		Hazard Description	
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	1300	13-Nov	/	/	/	/		X	X	Movement in swing crossbar	Monitor	
														Bridge links/mounts worn/movement	Monitor
			1	820	21-Nov	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Bent bar/cracked welds on bridge	Needs Repair - LAZ
														Bark low	Needs Top up - PCL
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	955	13-Nov	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor	
													Triangles worn plastic	Monitor	
			1	740	21-Nov	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor	
														Spring animal crack in foot rest/head loose	Monitor
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin Pl)	1	1300	12-Nov	/	/	/	/	/		X	New timber border lifting	Monitor	
														Horse head splitting	Monitor
			1	725	21-Nov	/	/	/	/	/		X	Damaged tyre swing	Monitor	
102	OXLEY PLGR 255	Newman Morris Circ	1	1250	12-Nov	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Bite marks in swing seat	Monitor
			1	720	21-Nov	/	/	/	/	/		X	X	Bark washing out	Needs repair PCL
														Border concrete damaged	Needs Repair PCL
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	1245	08-Nov	/	/	/	/		X	X	Border sleepers damaged	Needs Repair J&E	
														Deck plastic worn	Monitor
			1	1430	20-Nov	/	/	/	/	/		X	X	Carousel rusting/loose in footing	Monitor
														Spring frog handle loose	Monitor
104	RICHARDSON PLGR 258	Chauncy Cres											Pod mounts worn (eyelet)	Needs repair - LAZ	
			1	1340	08-Nov	/	/	/	/	/		X	Decking plastic worn	Monitor	
			1	1455	20-Nov	/	/	/	/	/		X	Swing mounts worn	Monitor	
105	RICHARDSON PLGR 259	Clift Cres											Cuts on slide (smoothed)	Monitor	
			1	1304	08-Nov	/	/	/	/	/		X	Obscene graffiti / damage on new concrete path	Needs Removal PCL	
														Worn swing chains/mounts/movement in post	Monitor
			1	1435	20-Nov	/	/	/	/	/	/		X	Loose bolt/grub screw on fort	Repaired by J&E 20/11/19
													Bark low / dirt in bark	Top up bark - PCL	
														Bolt caps damaged on spring animal	Repaired by J&E 8/11/19
			1	1328	08-Nov	/	/	/	/	/		X	Decking plastic worn/surface rust	Monitor	
													Climb net mounts worn	Needs Repair LAZ	

Name Of Inspector		Domenik		Month of Inspection						Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
106	RICHARDSON PLGR 257	Vidal St	1	1500	20-Nov	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor		
													Climb net links worn	Monitor	
														Climb net bar bent	Monitor
														Tyre swing links worn	Monitor
														Bark low	Needs top up - PCL
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN												
108	THEODORE PLGR 265	Dyett Circ	1	1415	08-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Decking timber splitting	Monitor	
			1	1205	21-Nov	/	/	/	/	X	X	Chain net links worn	Monitor		
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN												
110	THEODORE PLGR 261	Louis Loder St	1	1425	08-Nov	/	/	/	/	X	X	Border logs splitting	Monitor		
													Decking timber splitting	Monitor	
			1	1210	21-Nov	/	/	/	/	X	X	Slide fibreglass cracking/worn	Monitor		
														Chain net links worn	Monitor
														Bark low	Needs Top up - PCL
111	THEODORE PLGR 264	Scantleberry St	1	1405	08-Nov	/	/	/	/	X	X	Border concrete broken/lifting	Needs Repair - PCL		
													Border logs splitting	Monitor	
			1	1200	21-Nov	/	/	/	/	X	X	Trees growing in bark	Needs Removal - PCL		
														Slide damaged at top	Monitor
														Spring animal timber worn	Monitor
														Decking timber/panel splitting	Monitor
112	WANNIASSA PLGR 270	Billson Pl	1	1045	08-Nov	/	/	/	/	/	X				
														Decking plastic worn	Monitor
			1	1040	22-Nov	/	/	/	/	/	X		Bridge plastic worn	Needs Repair LAZ	
														Damaged tic tac toe	Monitor
												Worn rubber on sp ke spinner	Needs Repair J&E		
													Decking timber worn	Monitor	

Name Of Inspector		Domenik		Month of Inspection								Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
113	WANNIASSA PLGR 267	Bussau Cl	1	1120	22-Nov	/	/	/	/	/	X	X	Chain net links worn/plastic peeling	Monitor			
														Damaged/rotting borders	Monitor		
															Concrete path lifting	Needs Repair PCL	
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	1030	08-Nov	/	/	/	/	/		X	Decking plastic worn x 1	Needs Repair - LAZ			
															Swing mounts/brackets worn	Monitor	
			1	1030	22-Nov	/	/	/	/	/			X	Grab handle loose	Monitor		
115	WANNIASSA PLGR 275	Hervey Pl	1	935	08-Nov	/	/	/	/		X	X	Border sleepers/braces splitting	Needs Repair PCL			
															Decking plastic rust / peeling	Monitor	
			1	945	22-Nov	/	/	/	/			X	X	Smoking sign loose in footing	Needs Repair PCL		
116	WANNIASSA PLGR 266	Lansell Circ											Swing seat damaged/mounts/links worn	Monitor			
			1	1126	08-Nov	/	/	/	/	/		X	Swing mounts worn	Monitor			
			1	1130	22-Nov	/	/	/	/	/		X	Border fence panels damaged	Monitor			
117	WANNIASSA PLGR 269	Sainsbury St	1	1050	08-Nov	/	/	/	/		X	X	Border logs splitting	Monitor			
															Holes in shade sail	Monitor	
			1	1050	22-Nov	/	/	/	/			X	X	Burn marks on tic tac toe	Monitor		
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN														
119	WANNIASSA PLGR 276	Steinfeld Circ	1	945	08-Nov	/	/	/	/		X	X	Border Sleepers splitting	Monitor			
															Bench seat slats splitting	Monitor	
			1	1010	22-Nov	/	/	/	/			X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ		
																Decks worn x 2	Needs Repair - LAZ
																Bridge slats splitting	Monitor
120	WANNIASSA	Sullivan Cree												Bridge/Chain net links worn/plastic	Monitor		
			1	1055	08-Nov	/	/	/	/		X	X	Bearings / wheels damaged on fly fox trolley	Needs Repair J&E			
															Border logs splitting	Monitor	
													Bridge/chain links worn	Monitor			

Name Of Inspector		Domenik		Month of Inspection								Nov-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
120	PLGR 268	Sumivan Cres	1	1110	22-Nov	/	/	/	/	/	X	X	Handle plastic worn on flying fox	Monitor	
													Swing seats/mounts worn/splitting	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St	1	950	08-Nov	/	/	/	/		X	X	Border sleepers damaged	Needs Repair - PCL	
														Swing mounts worn	Monitor
			1	1016	22-Nov	/	/	/	/		X	X	Bridge timber splitting	Monitor	
															Park bench missing / damaged timber
													Decking worn/lichen growing	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres	1	925	08-Nov	/	/	/	/		X	X	Decking worn / rusting	Monitor	
														Swing mounts/ links worn	Monitor
			1	940	22-Nov	/	/	/	/		X	X	Fireman pole damaged	Monitor	
															Roman triangles links worn plastic worn
													Chain net links worn	Monitor	
123	WANNIASSA PLGR 272	Whiteman St	1	1000	08-Nov	/	/	/	/		X	X	Swing mounts/s hooks/ chains worn	Monitor	
			1	1022	22-Nov	/	/	/	/		X	X	Border logs splitting	Monitor	
													Horse head splitting	Monitor	



Name Of Inspector: Domenik Month of Inspection: Nov-19

	Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
						/	x	/	x	/	x	/	x	/	x	/	x			/	x	Hazard
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	1210	07-Nov	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban		
																				Awning ladders mounts rusting	Monitor	
			1	1430	22-Nov	/		/		/		/		/					X	Bridge mounts worn	Monitor	
																					Pommels links/mounts worn/hosing split	Monitor
																					Swing mounts/brackets worn	Monitor
																					2 x tread caps missing on surfer	Monitor
																					Bridge metal slip hazard	Angle / monitor
																					Basketball backboard worn	Monitor
																					Climb chain mounts/links worn/hosing split	Monitor
																					Rubber soft fall worn	Monitor
																		Cracked all access panel on ramp	Monitor			
																		Low bark	Top up bark - PCL			
																		Spring animal worn timber	Monitor			
2	COTTER PLGR 539	CASURINA SANDS	1	1150	07-Nov	/		/		/		/		/				X	Post timber splitting	Monitor		
																				Decking timber splitting	Monitor	
			1	1415	22-Nov	/		/		/		/		/					X	Rope bridge wearing	Monitor	
3	GREENWAY PLGR 538	Pine Island Rd	1	940	05-Nov	/		/		/		/			X	X			Border logs splitting	Monitor		
			1	850	11-Nov	/		/		/		/			X	X			Climbing wall worn/rusting	Monitor		
			1	740	19-Nov	/		/		/		/			X	X			Movement in staircase footing	Monitor		
			2	1520	25-Nov	/		/		/		/				X	X			Swing mounts/chains worn	Monitor	
			1			/		/		/		/				X	X			Pop rivet missing on deck	Repaired by J&E 5/11/19	
																					Decks/bridge worn/rusting	Monitor
																		Bark low	Needs Top up - PCL			
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	1	1310	07-Nov	/		/		/		/			X	X			Fence timber splitting around water tanks	Monitor		
																				Timber splitting on large spring platform	Monitor	
			1	1500	22-Nov	/		/		/		/				X	X			Water tanks decking timber splitting/worn	Monitor	
																					Flying fox posts splitting	Monitor
																					Spider climb net rope frayed	Monitor
																					Hand water pump not working/plates loose	Removed until further notice PCL
																					Tree roots lifting paths	Needs Repair PCL
																					Rubber soft fall splitting / low bark	Needs Repair PCL
																		Timber seating at BBQ missing bolts	Needs Repair PCL			



Name Of Inspector

Domenik

Month of Inspection

Nov-19

Suburb	Street	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					/	x	/	x	/	x	/	x	/	x	/	x		
		Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Inspectors Signature: D.Radman



PLAYGROUND INSPECTIONS REPAIR REQUEST

Work Order Number _____ PLGR No. 263

Suburb Theodore Address Chippindall Circ

Insp Date 06/11/2019 Insp Time 1030 Bark low No

Problem 2 x flat swings damaged - needs Repair J&E

Action Taken Replace 1 x flat swing + 1 x baby swing with new - repaired by J&E 6/11/19

Inspectors Name Domenik Signature D.Radman



Location Theodore Chippindal Cct

Time 855

Date 25/11/2019

Name Domenik Radman

Weather Sunny

Date Next Assessment

ITEM NO	ISSUE What is the Hazard	RISK L M H VH	REVIEW		
			What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS					
1.01	Good visibility for supervision, surrounds in good condition, no graffiti	/			
1.02	Bubblers and water features clean and fully operational	/			
1.03	Access ramps, pathways, entrances free of slipping & tripping hazards	/			
1.04	Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/			
1.05	Paths around playground clear of hazards cracks, trips, vegetation	/			
1.06	Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/			
1.07	Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	L	Monitor
1.08	Gates closing & locking devices operational, no finger entrapments (>12mm)	/			
1.09	Access, entrance & ancillary items free of protrusions/sharp edges	/			
SURFACING					
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings					
2.01	Rubbish that may be hygiene issue removed	/			
2.02	Broken glass, rocks, foreign objects likely to cause injury removed	/			
2.03	Surface in good condition, no trip points	/			
2.04	Drainage operational, no contamination from runoff	/			
LOOSE FILL MATERIAL					
2.06	Check depth min 300mm-400mm, top up or rake as required	X	Low bark	M	Top up bark PCL
2.07	Loose-fill containment edging / barrier secure, free of protrusions	/			
2.08	No material deterioration or contamination by clay or other matter	/			
SYNTHETIC MATERIAL					
2.09	Fouling of surface or chewing gum, foreign objects, rocks	/			
2.10	Joints, wear layer, impact attenuation layer or sub-base failure	/			
EQUIPMENT					
Platforms, Structures and frames					
3.01	Foundation and structures free of movement, rot or corrosion	/			
3.02	No water penetration into structure or fittings, bulging, corrosion	/			
3.03	Handrails, guardrails, barriers, decks, platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor
3.04	Physical damage or missing parts, bolts, present and secure, vandalism	/			
3.05	Check end caps, bolts, screws, tube ends	/			
3.06	No cracked or damaged plastic or wood panels, no graffiti	/			
3.07	No protruding screws, nails, bolts, sharp edges, splintering or cracks	/			
3.08	Remove loose items brought into playground - ropes, rocks, sticks	/			
3.09	Equipment free from moss, mould, unhygienic matter - slip potential	/			
Chains, Ropes, Cables, Nets and Tyres					
3.10	Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/			
3.11	No fraying of ropes or cable (or ends) - Replace or remove	/			
3.12	Wear in chains & connectors <40%	/			
3.13	No entrapment hazards, no corrosion, no sharp edges	/			
Swings					
3.14	Check for squeaking bushes - lubricate/replace	/			
3.15	Swing action smooth & quiet, seat has no damage or vandalism	/			
3.16	Wear in chains & connectors <40%	X	Swing mounts worn	L	Monitor
3.17	Check seat & pivot connections for tightness, s-hooks for closure	/			
3.18	Impact attenuating edge intact, no cracking or exposed metal components	/			
3.19	Drain holes in tyres clear, no exposed metal wire	/			
3.20	Seat clearance from ground min 400mm	/			
Slides					
3.21	No damage or foreign objects on slide bed/sides - exit wear area	/			
3.22	Structure slide & supports - stability, looseness, corrosion, splinters	/			
3.23	Runout section height <350mm (or 200mm up to 1500mm sliding section)	/			
3.24	No entrapments, sliding smooth, overlap of joints downwards	/			
Carousels (rotating equipment)					
3.25	Speed limited to 5m/s	/			
3.26	Smooth & quiet rotation (both directions), platform level & stable	/			
3.27	Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	L	Monitor
3.28	Underside clear of protrusions & sharp edges	/			
Runways (flying foxes)					
3.29	Trolley motion smooth, no loose wire strands, speed limited to 7m/s	/			
3.30	End stops haven't moved, they bring trolley to a controlled stop	/			
3.31	No loose/missing bolts, rot/corrosion (particularly at ground level)	/			
3.32	Is cable secure, platform stable, seat/grip condition, clearance 400mm	/			
Seesaws & rocking equipment (Spring Animals)					
3.33	No looseness in movement or damage, missing bolts/handles	X	2 x spring animal movement in handle/footing	L	Monitor
3.34	No rot or corrosion, foundation movement, splintered timber	/			
Sandpits					
3.35	No ponding water, drainage issues or health hazards	/			
3.36	Sand pit edges and supports intact & secure	/			
3.37	Sand raked to remove foreign objects, fouling, glass	/			

RISK LEVEL - SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely) - Once every 100yrs
 2 Unlikely (Conceivable) - Once every 30 yrs
 3 Possible (Could occur) - Once every 10 yrs
 4 Likely (Almost certain) (On an annual basis)

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 4-5 Serious injury, possible long term absence from school
 6-7 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 360:200 Risk Management.

NOTES

Empty space for notes.



Name Of Inspector

Domenik

Month of Inspection

Dec-19

Name Of Inspector		Domenik			Month of Inspection								Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard		Action				
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	Hazard	Action
1	BANKS PLGR 413	Pocket Ave	2	833	02-Dec	/	/	/	/	/	/	/	X	X	Loose slide leg	Monitor
			1	753	09-Dec	/	/	/	/	/	/	/	X	X	Chain net links/mounts worn	Monitor / Needs Repair LAZ
			1	905	16-Dec	/	/	/	/	/	/	/	X	X	Baby swing safety chain clip damaged	Repaired by J&E 16/12/19
			1	1715	23-Dec	/	/	/	/	/	/	/	X	X	Border concrete cracking / lifting	Needs Repair PCL
			1	715	30-Dec	/	/	/	/	/	/	/	X	X	Small plastic slide damaged	Monitor
																Titer toters arms missing
2	BONYTHON PLGR 535	Burgoyne St	2	1455	02-Dec	/	/	/	/	/	/	/	X	X	Ropes worn on climb net	Monitor
			1	1200	09-Dec	/	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor
			1	1440	16-Dec	/	/	/	/	/	/	/	X	X	Graffiti on fire truck	Needs Removal PCL
			1	1115	23-Dec	/	/	/	/	/	/	/	X	X	Collar pins worn	Monitor
			1	1135	30-Dec	/	/	/	/	/	/	/	X	X	Ropes worn on small single swing	Monitor
													Black rubber mount points melting	Monitor		
3	FADDEN PLGR 228	Coyne St	2	1526	02-Dec	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor	
			1	850	09-Dec	/	/	/	/	/	/	X	X	Cracked welds on slide entry	Monitor	
			1	955	16-Dec	/	/	/	/	/	/	X	X	Worn links bridge/climb chains	Monitor	
			1	1625	23-Dec	/	/	/	/	/	/	X	X	Timber split on panels	Monitor	
			1		30-Dec	/	/	/	/	/	/	X	X	Border logs splitting	Monitor	
															Holes in softfall / splitting	Needs repair - PCL
															Footpath lifting	Needs repair - PCL
															Slide footing loose	Monitor
												Spinning seesaw hanger has worn bolts/handle	Monitor			
												Hose splitting on chain covers	Monitor			
												Movement in brackets on web towers	Monitor			
4	GORDON PLGR 278	McGilvray Circ	2	800	02-Dec	/	/	/	/	/	/	X	X	Fibreglass on tea cup spinner cracking	Monitor	
			1	706	06-Dec	/	/	/	/	/	/	X	X	Swing mounts worn x 2	Needs Repair - J&E	
			1	730	09-Dec	/	/	/	/	/	/	X	X	Damaged see-saw brackets x 3	Needs Repair - J&E	
			1	840	16-Dec	/	/	/	/	/	/	X	X	Rope climb net worn 80%	Needs Repair - J&E	
			1	630	20-Dec	/	/	/	/	/	/	X	X	Spinner top bearings loose	Monitor	
			1	1731	23-Dec	/	/	/	/	/	/	X	X	Damaged super nova	Monitor	
			1	620	27-Dec	/	/	/	/	/	/	X	X	Border logs splitting	Monitor	
			1	630	30-Dec	/	/	/	/	/	/	X	X	Roman triangles worn links	Needs repair - LAZ	
															Wire wa k cable worn	Monitor
															Decking worn on tower	Monitor
															Wire bridge mount worn/chain low links worn	Needs repair - LAZ
															Cracked welds in tower/rust	Needs repair - LAZ
															Rubber Soft fall splitting/holes	Needs repair - PCL
												Swing chains/brackets/mounts	Monitor			
												bench below tea cup playground coming out of footing	Needs repair - PCL			
												Hole in shade sail	Monitor			



Name Of Inspector

Domenik

Month of Inspection

Dec-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
							/	x	/	x	/	x	/	x	/	x	/	x		
11	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET																	
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		2	1218	02-Dec	/	/	/	/	/	/	/	/	X	X	Bearings/guide rollers worn on fly fox	Monitor		
				1	1010	09-Dec	/	/	/	/	/	/	/	/	X	X	Swing mounts/brackets worn	Monitor		
			1	1055	16-Dec	/	/	/	/	/	/	/	/	X	X	Concrete border lifting	Monitor			
			1	1301	23-Dec	/	/	/	/	/	/	/	/	X	X	Bridge slats splitting	Monitor			
			1	911	30-Dec	/	/	/	/	/	/	/	/	X	X	Movement in see saw base	Monitor			
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)	2	1205	02-Dec	/	/	/	/	/	/	/	/	X	X	Damaged concrete border	Monitor			
			1	1005	09-Dec	/	/	/	/	/	/	/	/	X	X	Damaged park seat	Needs repair - PCL			
			1	1050	16-Dec	/	/	/	/	/	/	/	/	X	X	baby swing damaged	Monitor			
			1	1307	23-Dec	/	/	/	/	/	/	/	/	X	X	Plastic Rock on climb wall cracking	Monitor			
			1	905	30-Dec	/	/	/	/	/	/	/	/	X	X	Movement in base of carousel	Needs repair - J&E			
14	KAMBAH PLGR 305	Springbett St	2	1230	02-Dec	/	/	/	/	/	/	/	/	X	X	Twin S/S slide has crack in surface	Monitor			
			1	822	06-Dec	/	/	/	/	/	/	/	/	X	X	Swing seat/brackets/links/mounts worn	Monitor			
			1	1018	09-Dec	/	/	/	/	/	/	/	/	X	X	Super nova damaged	Monitor			
			1	1100	16-Dec	/	/	/	/	/	/	/	/	X	X	Hosing split on carousel	Monitor (taped)			
			1	800	20-Dec	/	/	/	/	/	/	/	/	X	X	Mount worn on large fly fox	Monitor			
			1	1235	23-Dec	/	/	/	/	/	/	/	/	X	X	Border logs splitting	Monitor			
			1	730	27-Dec	/	/	/	/	/	/	/	/	X	X	Sml fly fox movement in bolt	Monitor			
			1	1011	30-Dec	/	/	/	/	/	/	/	/	X	X	Tic Tac Toe damaged (taped)	Needs Repair J&E			
						/	/	/	/	/	/	/	/	X	X	Damage panel on quad hoops	Monitor			
																Low branches at swings & fly fox/grass in bark	Cut back/remove - PCL			
																Bum marks at liberty swing seat	Monitor			
																Bark low/ washed out	Needs repair - PCL			
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)	2	1140	02-Dec	/	/	/	/	/	/	/	/	X	X	Bark low	Needs Top up - PCL			
			1	935	09-Dec	/	/	/	/	/	/	/	/	X	X	Burn mark seesaw	Monitor			
			1	1037	16-Dec	/	/	/	/	/	/	/	/	X	X	Swing mounts	Monitor			
			1	1420	23-Dec	/	/	/	/	/	/	/	/	X	X	Timber swing posts splitting/ missing swings	?			
			1	847	30-Dec	/	/	/	/	/	/	/	/	X	X	Worn decks/ bridge	Monitor			
																Damaged rock wall	Monitor			
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)	2	1150	02-Dec	/	/	/	/	/	/	/	/		X					
			1	941	09-Dec	/	/	/	/	/	/	/	/		X	Rope worn on carousel	Monitor			
			1	1043	16-Dec	/	/	/	/	/	/	/	/		X	Swing seat / brackets worn	Monitor			
			1	1415	23-Dec	/	/	/	/	/	/	/	/		X					
			1	853	30-Dec	/	/	/	/	/	/	/	/		X	Bark low	Needs Repair PCL			
17	MACARTHUR PLGR 327	Bayly PI	2	935	02-Dec	/	/	/	/	/	/	/	/		X	Worn swing links/brackets	Monitor			
			1	835	09-Dec	/	/	/	/	/	/	/	/		X	Rope worn on climbing net/carousel	Monitor			
			1	945	16-Dec	/	/	/	/	/	/	/	/		X	Movement in base towards post of carousel	Needs repair - J&E			
			1	1635	23-Dec	/	/	/	/	/	/	/	/		X	Gravel washed into bark	Needs removal PCL			
			1	742	30-Dec	/	/	/	/	/	/	/	/		X	Low bark	Needs Top up - PCL			
																Softfall patches lifting under birds nest swing	Needs Repair PCL			



CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector: Domenik Month of Inspection: Dec-19

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
							/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x		
18	THEODORE PLGR 263	Chippindall Circ		2	849	02-Dec	/		/		/		/		/		/		/		/		/		X		Swing mounts/bushes worn	Monitor				
				1	815	09-Dec	/		/		/		/		/		/		/		/		/		/		X		Carousel seat worn/rusting	Monitor		
				1	920	16-Dec	/		/		/		/		/		/		/		/		/		/		X		Worn/damaged deck/bridge	Monitor		
				1	1655	23-Dec	/		/		/		/		/		/		/		/		/		/		X		Loose handle/footings on spring animal x 2	Monitor		
				1	727	30-Dec	/		/		/		/		/		/		/		/		/		/		X		Tree branch stuck in shade sail	Needs Removal PCL		
																														Holes in shade sail	Monitor	
																														Low bark	Needs Top up - PCL	
19	THEODORE PLGR 262	Lawrence Wackett Cres		2	910	02-Dec	/		/		/		/		/		/		X		X		X		X		Weld cracking at slide entry	Needs Repair - LAZ				
				1	820	09-Dec	/		/		/		/		/		/		/		X		X		X		X		Decking plastic worn/surface rust	Monitor		
				1	930	16-Dec	/		/		/		/		/		/		/		X		X		X		X		Swing/Chain bridge links/mounts worn	Monitor		
				1	1650	23-Dec	/		/		/		/		/		/		/		X		X		X		X		Movement in frog footing	Monitor		
				1	731	30-Dec	/		/		/		/		/		/		/		X		X		X		X		Border concrete cracking	Needs Repair - PCL		
20	WANNIASSA PLGR 271	Sangster Pl		2	1115	02-Dec	/		/		/		/		/		/		X		X		X		X		Swing mounts brackets worn	Monitor				
				1	925	09-Dec	/		/		/		/		/		/		/		X		X		X		X		Decking worn	Monitor		
				1	1030	16-Dec	/		/		/		/		/		/		/		X		X		X		X		Hole in chain wire fence	Needs Repair - LAZ		
				1	1425	23-Dec	/		/		/		/		/		/		/		X		X		X		X		Park bench missing arm rest	Needs Repair - PCL		
				1	830	30-Dec	/		/		/		/		/		/		/		X		X		X		X		Holes and splitting in softfall	Needs repair - PCL		

Inspectors Signature: D.Radman

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik			Month of Inspection								Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
						/	x	/	x	/	x	/	x	Hazard			Action	
1	BANKS PLGR 213	Menzies Court	2	1420	03-Dec	/		/		/		X	X	Fort panel cracked/stairs damaged	Monitor			
															Decking plastic worn/surface rust	Monitor		
			1	720	19-Dec	/		/		/		X	X					
																Border concrete cracking	Monitor	
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN															
3	BANKS PLGR 212	Wilson Cres	2	1405	03-Dec	/		/		/		X	X	Bench seat slats loose / missing bolts	Needs Repair PCL			
															Swing seat brackets worn	Monitor		
			1	730	19-Dec	/		/		/		X	X	Decking worn	Monitor			
																Dints in slide bed	Monitor	
														Border concrete cracking	Needs Repair - PCL			
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	2	1645	03-Dec	/		/		/			X	Posts handrails split/rotting	Monitor			
															4 x Post damaged/split on fort	Monitor		
			1	1525	16-Dec	/		/		/			X	Chain net links and mounts worn	Monitor			
																Swing mounts worn	Monitor	
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN															
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	2	1702	03-Dec	/		/		/		X	X	Border logs splitting	Monitor			
			1	1500	16-Dec	/		/		/		X	X	Timber decking lifting / splitting	Needs Repair - J&E			
														Slide has crack at entry/movement	Monitor			
7	BONYTHON PLGR 586	Morice Pl	2	1655	03-Dec	/		/		/			X	Swing seat brackets worn	Monitor			
			1	1515	16-Dec	/		/		/			X	Worn / missing rope on net	Monitor			
														Worn links/mounts on pommel/ climb chain	Monitor			
8	CALWELL PLGR 322	Beckett St	2	1205	03-Dec	/		/		/			X	Decking plastic worn	Monitor			
																Swing mounts worn	Monitor	
			1	1030	18-Dec	/		/		/			X	Bent monkey bars	Monitor			
																	Slide weld cracking at top	Needs Repair - LAZ
																	Chain walk hand rail bent	Needs Repair - LAZ
														Bent deck poles	Needs Repair - LAZ			
														Low tree branches	Needs Removal PCL			
			2	1105	03-Dec	/		/		/		X	Swing mounts worn	Monitor				



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection										Dec-19	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition									
9	CALWELL PLGR 321	Casey Cres	1	1145	18-Dec	/	/	/	/	/	/	/	/	X	Decking plastic worn/decks rusting	Monitor	
																Chain net links/coiling on chains worn	Monitor
																	See saw timber splitting
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	2	1154	03-Dec	/	/	/	/				X	X	Decking plastic worn	Monitor	
																Swing mounts/seat/links worn	Monitor
			1	1050	18-Dec	/	/	/	/				X	X	Low branches	Needs cut back back-PCL	
														Side leg bent	Monitor		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection								Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
11	CALWELL PLGR 319	Samuel Cl	2	1120	03-Dec	/	/	/	/	/	X	X	Border logs splitting	Monitor	
														Swing mounts worn	Monitor
			1	1135	18-Dec	/	/	/	/	/	X	X	Bent monkey bars	Monitor	
												Park bench missing timber	Needs Repair - PCL		
12	CALWELL PLGR 644	Shopping Centre	2	1140	03-Dec	/	/	/	/	/		X	Swing mounts/seat/S hooks worn	Monitor	
														Bark low	Top up bark PCL
			1	1115	18-Dec	/	/	/	/	/		X	Carousel movement in bearing	Monitor	
13	CALWELL PLGR 320	Were St	2	1125	03-Dec	/	/	/	/		X	X	Border logs splitting	Monitor	
														Swing links/mounts worn	Monitor
			1	1130	18-Dec	/	/	/	/		X	X	Tire worn on tyre swing	Monitor	
14	CHISHOLM PLGR 234	Alston St	2	815	05-Dec	/	/	/	/	/		X	Swing mounts worn	Monitor	
			1	1255	18-Dec	/	/	/	/	/		X	Damaged tic tac toe	Monitor	
												Baby seat chain cover worn	Monitor		
												Fly fox handle plastic worn	Monitor		
15	CHISHOLM PLGR 233	Dalyell St	2	916	05-Dec	/	/	/	/	/		X	Timber decking splitting	Needs repair - J&E	
														Tyre swing mounts worn	Monitor
			1	1235	18-Dec	/	/	/	/	/		X	Fly fox links worn	Monitor	
												Chain net mounts worn	Monitor		
												Fly fox nylon guides worn	Needs Repair - J&E		
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	2	846	05-Dec	/	/	/	/	/		X	Timber decking splitting	Monitor	
														Track ride not gliding with ease	Needs Repair - J&E
			1	1317	18-Dec	/	/	/	/	/		X	Swing seat damaged/brackets/links worn	Monitor	
												Post loose in footing	Monitor		
												Uneven paving around playground	Needs Repair PCL		
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	2	852	05-Dec	/	/	/	/	/		X	Timber decking splitting	Monitor	
														Slide damaged at exit	Monitor
			1	1313	18-Dec	/	/	/	/	/		X	Log steps splitting	Monitor	
												Damaged park bench	Needs Repair - PCL		
												Tyre /s hooks wearing on tire swing	Monitor		
												Graffiti on slide	Remove - PCL		
18	CHISHOLM PLGR 235	Kirkcaldie Circ	2	800	05-Dec	/	/	/	/	/		X	Swing mounts/links worn	Monitor	
														Decking plastic worn/rusting	Monitor
			1	1405	18-Dec	/	/	/	/	/		X	Climb net mounts/plastic worn	Monitor	
												Plastic at slide exit damaged	Needs Repair J&E		
	CHISHOLM	Meeson St	2	900	05-Dec	/	/	/	/	/		X	Decking plastic worn	Monitor	
														Tyre swing mounts worn	Monitor
			1	1305	18-Dec	/	/	/	/	/		X	Climb net links worn	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector	Domenik	Month of Inspection										Dec-19	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
		Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition								
19	CHISHOLM PLGR 230	Mofflin St (Mofflin St)													Damaged park bench	Monitor	
																Plastic panel damaged	Monitor
																Concrete border damaged	Needs repair - J&E
																Bent/damaged deck poles	Needs repair - LAZ
20	CHISHOLM PLGR 236	Proctor St	2	906	05-Dec	/	/	/	/	/	/		X	Swing mounts/links/seat worn	Monitor		
															Low bark	Needs top up - PCL	
			1	1415	18-Dec		/	/	/	/	/		X	Dints in slide	Monitor		
														Fly fox handle plastic worn	Monitor		



Name Of Inspector	Domenik	Month of Inspection	Dec-19	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
					Level 1 or Level 2												
21	CONDER PLGR 219	Cremorne Pl (Landells Pl)	2	1350	03-Dec	/	/	/	/	/	/	X	X	Border pavers missing/loose	Needs Repair - J&E		
															Posts splitting and rotten in ground	Needs Repair - J&E	
			1	750	19-Dec	/	/	/	/	/	/	/	X	X	Decks/bridge timber split/damaged	Needs Repair - J&E	
																Ropes worn on climb net (fraying)	Monitor
														Deck connection bolts worn/chain	Needs repair - LAZ		
22	CONDER PLGR 222	Dixson Circ	2	1357	03-Dec	/	/	/	/	/	/		X	Bark washed out	Needs Repair - PCL		
															Panels damaged/rusting	Monitor	
			1	740	19-Dec	/	/	/	/	/	/	/		X	Chain net/mounts worn	Monitor	
																Plastic panel/ tic tac damaged	Monitor
														Swing seat/brackets/mounts/chain worn	Monitor		
23	CONDER PLGR 607	James Smith Circ	2	1300	03-Dec	/	/	/	/	/	/		X	Swing/fort posts splitting/rot	Monitor		
															Climb net rope worn	Monitor	
			1	815	19-Dec	/	/	/	/	/	/	/		X	Decking/panels worn on cubby/spring animal/slide	Monitor	
																Bark low	Needs Top up - PCL
24	CONDER PLGR 220	Montfiore Cres	2	1340	03-Dec	/	/	/	/	/	/	X	X	Border logs splitting	Monitor		
																Climb net links/mounts worn	Monitor
			1	755	19-Dec	/	/	/	/	/	/	/	X	X	Bark low	Needs Top up - PCL	
																Bridge rail cracked	Needs repair - LAZ
														Movement in border sleepers	Monitor		
														Plastic panels brittle	Monitor		
25	CONDER PLGR 244	Russell Drysdale Cr (Daly Pl)	2	1333	03-Dec	/	/	/	/	/	/		X	Bridge plastic/ links worn	Monitor		
																Decking worn/rusting	Monitor
			1	804	19-Dec	/	/	/	/	/	/	/		X	Slide mount on deck rusting	Needs repair - LAZ	
														Bark washed out / dirt in bark	Needs repair - PCL		
26	FADDEN PLGR 225	Bertram St (Riordan St)	2	732	05-Dec	/	/	/	/	/	/	X	X	Decking plastic worn	Monitor		
																Chain net links/ mounts worn	Monitor
			1	1515	18-Dec	/	/	/	/	/	/	/	X	X	Tyre swing mounts/ links worn	Monitor	
																Border logs splitting	Monitor
														Border log damaged x 1	Needs Repair PCL		
27	FADDEN PLGR 228	Coyne St	MONDAY RUN														
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	2	713	05-Dec	/	/	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor		
																Border timber damaged	Needs Repair PCL
			1	1442	18-Dec	/	/	/	/	/	/	/	X	X	Movement in carousel base	Monitor	
																Decking timber splitting	Monitor
																Chain net links / mounts worn	Monitor
														Lichen growing on decks	Monitor		
	FADDEN		2	719	05-Dec	/	/	/	/	/	/	X	X	Rocks missing in border wall	Needs Repair - PCL		
														Rope bridge mount broken/rope worn	Needs Repair PCL		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection								Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
29	FADDEN PLGR 509	Nicklin Cres	1	1455	18-Dec	/	/	/	/	X	X	Climbing nets rope worn	Monitor		
													Panel/ roof panels cracked on fort	Monitor	
														Tower posts splitting	Monitor
30	FADDEN PLGR 229	Pamell Pl (Courtice Cl)	2	706	05-Dec	/	/	/	/	X	X	Swing mounts/ links worn	Monitor		
													Damaged baby swing	Monitor	
			1	1436	18-Dec	/	/	/	/	X	X	Border logs worn	Monitor		
	GILMORE	Heagney Cres	2	834	05-Dec	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor		
													Rubber frog damaged	Monitor	
			1	1325	18-Dec	/	/	/	/	X	X	Low bark	Needs Top up - PCL		



Name Of Inspector		Domenik		Month of Inspection								Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
31	GILMORE PLGR 238	Hogue Pl	2	840	05-Dec	/	/	/	/	/	X	X	Fence damaged	Monitor	
														Spinner seats worn/ rusting	Monitor
			1	1335	18-Dec	/	/	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL
													Bark low	Top up bark PCL	
32	GILMORE PLGR 239	Rosman Circ	2	828	05-Dec	/	/	/	/	/	/	X	Bridge timber splitting	Monitor	
														Concrete at bench lifting	Needs Repair PCL
			1	1345	18-Dec	/	/	/	/	/	/	X			
33	GORDON PLGR 215	Iredale Pl	2	1555	03-Dec	/	/	/	/	/	/	X	Swing seat brackets worn	Monitor	
														Chain net/ladder links worn/plastic	Monitor
			1	640	19-Dec	/	/	/	/	/	/	X	X	Damaged post caps x 4	Monitor
															Slide damaged
34	GORDON PLGR 216	Kirkwood Cres	2	1614	03-Dec	/	/	/	/	/	X	X	Swing seat brackets/mounts wearing	Monitor	
														Slide surface dented	Monitor
			1	700	19-Dec	/	/	/	/	/	/	X	X	Dent in swing crossbar/see saw seat	Monitor
													Border sleeper damaged near slide	Needs Repair PCL	
													Tyre swing mounts worn	Monitor	
35	GORDON PLGR 279	Evan Pl	2	1628	03-Dec	/	/	/	/	/	/	X	Chain climb net links wearing	Monitor	
															Bridge/deck plastic worn/rusting in corners
			1	650	19-Dec	/	/	/	/	/	/	X			
36	GORDON PLGR 218	Knoke Ave	2	1427	03-Dec	/	/	/	/	/	/	X	Decking plastic worn	Monitor	
														Missing/loose bolts on deck	Repaired by J&E 3/12/19
			1	711	19-Dec	/	/	/	/	/	/	/	X	Climb net links/mounts/plastic worn	Monitor
													Bench seat slat damaged	Needs Repair PCL	
37	GORDON PLGR 278	McGilvray Circ	MONDAY RUN												
38	GORDON PLGR 217	Poplewell Pl (Tallon Pl)	2	1606	03-Dec	/	/	/	/	/	/	X	Tic tac damaged	Monitor	
															Dents in slide
			1	706	19-Dec	/	/	/	/	/	/	X	Decking worn/surface rust	Monitor	
													Chain net mounts worn	monitor	
39	GORDON PLGR 214	Noel Ryan Gardens	2	1535	03-Dec	/	/	/	/	/	X	X	Fort post splitting	Monitor	
														Slide crack at entry/worn	Removed for Repair J&E
			1	631	19-Dec	/	/	/	/	/	/	X	X	Tree roots in bark	Needs Removal - PCL
															Seesaw seat cracked
													Log steps splitting and rotten	Monitor	
													Concrete border lifting	Monitor	
													Chain bridge links worn	Monitor	
40	GOWRIE PLGR 332	Inwood Pl (Sadlier St)	2	1503	04-Dec	/	/	/	/	/	X	X	Border logs splitting	Monitor	
															Seesaw timber worn
			1	1529	18-Dec	/	/	/	/	/	X	X			



Name Of Inspector	Domenik	Month of Inspection	Dec-19	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
					Level 1or Level 2										
41	GOWRIE PLGR 328	Jeffries St	MONDAY RUN												
	GOWRIE	Howell Pl	2	1437	04-Dec	/	/	/	/	/	/	/	/		
			1	1537	18-Dec	/	/	/	/	/	/	/	/		
42	GOWRIE PLGR 333	Middleton Circ	2	1455	04-Dec	/	/	/	/	/		X	X	Swing mounts/ links worn	Monitor
			1	1533	18-Dec	/	/	/	/	/		X	X	Border concrete cracking	Monitor
43	GOWRIE PLGR 335	Weathers St	2	1515	04-Dec	/	/	/	/	/	/		X	Swing mounts/links worn/rusty	Monitor
			1	1519	18-Dec	/	/	/	/	/	/		X	Slide dented	Monitor
44	GOWRIE PLGR 334	Wray Pl	2	1508	04-Dec	/	/	/	/	/		X	X	Swing posts splitting	Monitor
			1	1524	18-Dec	/	/	/	/	/		X	X	Swing mounts/ links worn	Monitor
														Border sleepers splitting	Monitor
														Concrete border cracked/lifting	Monitor
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN												
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN												
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN												
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN												
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN												
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET												
			2	845	03-Dec	/	/	/	/	/	/	X	X	Ropes worn on web	Monitor



Name Of Inspector	Domenik	Month of Inspection	Dec-19	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
					Level 1 or Level 2													
61	KAMBAH PLGR 301	Boustead Circ	2	1325	05-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															Damaged plastic on stairs	Monitor		
			1	1215	19-Dec	/	/	/	/	/	/	/	X	X	Rusting at bottom of stairs	Monitor		
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	2	1103	06-Dec	/	/	/	/	/	/	X	X	Timber decking splitting	Monitor			
															Swing posts splitting and rotten	Monitor		
			1	1400	23-Dec	/	/	/	/	/	/	/	X	X	Movement in ladder plate to decking	Monitor		
																Timber border lifting/damaged	Monitor	
																Swing mounts/brackets worn/small movement	Monitor	
														Bark washed out	Needs Repair - PCL			
63	KAMBAH PLGR 317	Bullock Circ	2	901	06-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															Rubber on stairs splitting	Monitor		
			1	1105	19-Dec	/	/	/	/	/	/	X	X	Worn rubber on deck	Needs Repair LAZ			
																Climb chain/bridge links worn	Monitor	
64	KAMBAH PLGR 299	Coghill Cl																
			2	1204	06-Dec	/	/	/	/	/	/	X	X	Swing mounts/brackets worn	Monitor			
																Swing mounts worn	Monitor	
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)																
			1	1130	19-Dec	/	/	/	/	/	/	X	X	Border logs splitting	Monitor			
																Carousel loose - movement in bearing	Monitor	
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)																
			2	1257	05-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
																Swing mounts worn	Monitor	
			1	1130	19-Dec	/	/	/	/	/	/	X	X	Decking plastic worn	Monitor			
																	Low bark	Needs Top up - PCL
																	flying fox handle/mount/links worn	Monitor
66	KAMBAH PLGR 304	Dale Circ																
			2	1225	05-Dec	/	/	/	/	/	/	X	X	Bridge timber splitting	Monitor			
																Bridge/climbing net links worn	Monitor	
67	KAMBAH PLGR 291	Deuchar Cl																
			1	1145	19-Dec	/	/	/	/	/	X	X	Border sleepers splitting	Monitor				
																Decks rusty/ plastic peeling	Needs Repair LAZ	
67	KAMBAH PLGR 291	Deuchar Cl																
			2	1208	06-Dec	/	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor				
																Swing brackets/mounts worn	Monitor	
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)																
			2	1208	06-Dec	/	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor				
																	Border sleepers splitting	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)																
			1	1318	19-Dec	/	/	/	/	/	X	X	Swing mounts worn	Monitor				
																	Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)																
			2	938	06-Dec	/	/	/	/	/	X	X	Border logs splitting	Monitor				
																	Decking plastic worn	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)																
			1	1048	19-Dec	/	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ				
																	Swing mounts worn	Monitor
69	KAMBAH	Friend Pl																
			2	1014	06-Dec	/	/	/	/	/	X	X	Bark low	Needs top up - PCL				
																	Rocks missing on rock wall	Needs Repair PCL
69	KAMBAH	Friend Pl																
																	Damaged bolt caps	Monitor



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

	Name Of Inspector	Domenik		Month of Inspection								Dec-19	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
		Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition						
66	PLGR 288	(Crafter PI)	1	1333	23-Dec	/	/	/	/	/	/	X	X		
														Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs PI	2	1114	06-Dec	/	/	/	/	/	/		X	Knots and crosses cracking	Monitor
														Bolt caps brittle/damaged on tower	Monitor
			1	1410	23-Dec	/	/	/	/	/	/		X		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector	Domenik	Month of Inspection	Dec-19	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
					Level 1 or Level 2												
71	KAMBAH PLGR 289	Horton Cl	2	1215	06-Dec	/	/	/	/	/	/	X	X	Chain net links worn	Monitor		
															Decking plastic worn/rusting	Needs Repair LAZ	
			1	1322	19-Dec	/	/	/	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL	
																Parallel slide bar bent	Monitor
																Wearing swing brackets	Monitor
														Tyre swing tyre worn	Needs Repair J&E		
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	2	1033	06-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			1	1342	23-Dec	/	/	/	/	/	/	X	X	Bridge/ chain net links worn	Monitor		
73	KAMBAH PLGR 307	Humble Court	2	1250	06-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			1	1330	19-Dec	/	/	/	/	/	/	X	X	Swing mounts/brackets worn	Monitor		
																Slide dented	Monitor
														Low bark	Needs Repair - PCL		
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	2	1318	05-Dec	/	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
			1	1110	19-Dec	/	/	/	/	/	/		X	Deck/bridge plastic worn	Monitor		
														Handle loose on turtle	Monitor		
75	KAMBAH PLGR 286	Lascelles Circ	2	1050	06-Dec	/	/	/	/	/	/	X	X	Border Sleepers splitting	Monitor		
			1	1352	23-Dec	/	/	/	/	/	/	X	X	See saw Top centre plate cracked	Needs Repair - LAZ		
																	Low branches
														Bridge slats splitting/links worn/movement	Monitor		
														Chain net links worn	Monitor		
														Decking plastic worn	Monitor		
76	KAMBAH PLGR 325	Learmonth Dr	2	1331	05-Dec	/	/	/	/	/	/	X	X	Fort Timber panels worn/split	Monitor		
			1	1210	19-Dec	/	/	/	/	/	/	X	X	Climb net ropes worn	Monitor		
																	Timber posts splitting
														Rock wall missing rocks	Monitor		
														Damaged bolt caps on equipment	Monitor		
														Spring motorcycle panels worn	Monitor		
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	2	1152	06-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			1	1313	19-Dec	/	/	/	/	/	/	X	X	Decking plastic worn	Monitor		
														Burn marks on post / slide	Monitor		
														Fly fox handle broken off	Needs Repair J&E		
														Bridge/Climb net links worn	Monitor		
														Bridge slats splitting/movement worn timber	Monitor		
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	2	1145	06-Dec	/	/	/	/	/	/		X	Monitor all links in hosing	Monitor		
			1	1309	19-Dec	/	/	/	/	/	/		X	Damaged rubber chain hose	Monitor		
														Bench seat slat damaged	Needs Repair PCL		
KAMBAH			2	1315	06-Dec	/	/	/	/	/	/	X	X	Border logs splitting	Monitor		
														Bridge slats splitting	Monitor		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector	Domenik	Month of Inspection										Dec-19	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition					
79	KAMBAH PLGR 314	Mannheim St	1	1340	19-Dec	/	/	/	/	/	X	X	Swing mounts worn	Monitor	
														Welds cracked at slide entry	Needs Repair - LAZ
															Bridge links worn
80	KAMBAH PLGR 285	Marconi Cres	2	1039	06-Dec	/	/	/	/	/		X	Swing brackets/mounts worn	Monitor	
														Gravel washed/weeds into bark	Needs Removal - PCL
			1	1346	23-Dec	/	/	/	/	/		X	Deck edge wear	Monitor	
													Spring bear loose in footing	Monitor	



Name Of Inspector	Domenik	Month of Inspection	Dec-19	Location	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
					Level 1 or Level 2											
81	KAMBAH PLGR 308	Maxworthy St	2	1304	06-Dec	/	/	/	/	/	/	/	X	Swing mounts worn	Monitor	
															Bark low	Needs Top up - PCL
			1	1335	19-Dec	/	/	/	/	/	/	/	/	X	Damaged spinner seats x 2	Needs Repair - J&E
82	KAMBAH PLGR 292	McKillop Pl	2	1248	05-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			1	1135	19-Dec	/	/	/	/	/	/	X	X	Swing seat/brackets worn	Monitor	
															Bridge/decks rusting	Monitor
													Flat swing seat damaged	Monitor		
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	2	1310	05-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor	
															Slide has small dents	Monitor
			1	1120	19-Dec	/	/	/	/	/	/	X	X	Split rubber on stairs	Monitor	
													Graffiti on panel	Needs Removal PCL		
84	KAMBAH PLGR 302	Pinkerton Circ	2	1215	05-Dec	/	/	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL	
															Decking plastic worn/surface rust	Monitor
			1	1150	19-Dec	/	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor	
													Low tree branches	Needs removal- PCL		
													Exposed tree roots in bark	Needs removal- PCL		
													Bark low	Needs Top up - PCL		
85	KAMBAH PLGR 306	Primmer Court	2	1005	06-Dec											
			1	1325	23-Dec	/	/	/	/	/	/	/	/		New playground equipment installed	Has it been certified
86	KAMBAH PLGR 303	Rounsevell St	2	1346	05-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor	
															Swing mounts worn	Monitor
			1	1200	19-Dec	/	/	/	/	/	/	X	X	Slide metal rusting/ dented	Monitor	
													spring animal footing loose	Monitor		
													Lap seat worn	Monitor		
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN													
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN													
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN													
			2	1237	05-Dec	/	/	/	/	/	/	X	X	Swing posts splitting	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection								Dec-19		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition									
90	KAMBAH PLGR 290	Toole Pl													Swing mounts/brackets worn	Monitor	
			1	1140	19-Dec	/	/	/	/			X	X	Swing Mounts have small movement due to worn timber	Monitor		
																Bridge links worn	Monitor
																Climb net links/mounts worn	Monitor
																Slide loose at entry bracket	Monitor
																Star pickets in bark	Needs Removal PCL
																Border sleepers splitting	Monitor



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection							Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
91	KAMBAH PLGR 293	Vanzetti Cres	2	1135	06-Dec	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Decking worn/rusting	Monitor	
			1	1305	19-Dec	/	/	/	/	X	X	Movement in stair footing	Monitor		
													Bridge plastic worn/rusting	Monitor	
												Swing mounts/brackets worn	Monitor		
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN												
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	2	654	05-Dec	/	/	/	/	X	X	Decking worn	Monitor		
													Chain net links/mounts worn	Monitor	
			1	1425	18-Dec	/	/	/	/	X	X	Bent deck poles	Monitor		
													Border damaged/rotted	Needs Repair - PCL	
											Worn timber on spring horse	Monitor			
											Bark low	Needs Top up - PCL			
94	MONASH PLGR 252	Alabaster St	2	1343	04-Dec	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Swing mounts/ links worn	Monitor	
			1	1600	18-Dec	/	/	/	/	X	X	Bite marks in swing seat	Monitor		
													Damaged spiral ladder	Monitor	
											Damaged tic tac toe	Monitor			
											Worn/rusting bridge	Monitor			
95	MONASH PLGR 248	Charleston St	2	1316	04-Dec	/	/	/	/		X	Posts splitting and rotten	Monitor		
													Swing mounts/links/brackets worn	Monitor	
			1	1620	18-Dec	/	/	/	/		X	Bridge mounts/chain worn	Needs Repair LAZ		
													Bridge timber splitting	Monitor	
											Fibreglass damaged/cracking/worn on slides	Monitor			
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	2	1330	04-Dec	/	/	/	/	X	X	Steering wheel bracket worn	Monitor		
													Border timber splitting/missing	Needs Repair - PCL	
												Dirt washed into bark	Needs repair - PCL		
												Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	2	1350	04-Dec	/	/	/	/		X	Swing mounts/ links worn	Monitor		
													Concrete stump at bench	Needs Removal - PCL	
			1	1555	18-Dec	/	/	/	/		X	Low hanging branches	Needs Removal - PCL		
												Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	2	1300	04-Dec	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor		
														Concrete border lifting	Needs Repair PCL
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	2	1416	04-Dec	/	/	/	/	X	X	Movement in swing crossbar	Monitor		
														Bridge links/mounts worn/movement	Monitor
			1	1550	18-Dec	/	/	/	/	X	X	Swing mounts worn	Monitor		
												Bent bar/cracked welds on bridge	Needs Repair - LAZ		
												Bark low	Needs Top up - PCL		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection										Dec-19	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition										
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	2	1300	04-Dec	/	/	/	/	/	/	/	/	X	Bridge slats splitting / lichen	Monitor		
																Decking plastic worn/rusting	Monitor	
			1	1630	18-Dec	/	/	/	/	/	/	/	/	/	X	Triangles worn plastic	Monitor	
																	Swing mounts/brackets worn	Monitor
																	Spring animal crack in foot rest/head loose	Monitor



Name Of Inspector		Domenik		Month of Inspection										Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
101	OXLEY PLGR 256	Cuthbertson Cres (McKibbin Pl)	2	1215	04-Dec	/	/	/	/	/	/	/	X	New timber border lifting	Monitor		
			1	1507	12-Dec	/	/	/	/	/	/	/	X	Horse head splitting Damaged tyre swing	Monitor Monitor		
102	OXLEY PLGR 255	Newman Morris Circ	2	1155	04-Dec	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
			1	1500	12-Dec	/	/	/	/	/	/	X	X	Bite marks in swing seat Bark washing out Border concrete damaged	Monitor Needs repair PCL Needs Repair PCL		
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	2	900	03-Dec	/	/	/	/	/	/	X	X	Border sleepers damaged	Needs Repair J&E		
			1	1225	18-Dec	/	/	/	/	/	/	X	X	Deck plastic worn Carousel rusting/loose in footing Spring frog handle loose Pod mounts worn (eyelet)	Monitor Monitor Monitor Needs repair - LAZ		
104	RICHARDSON PLGR 258	Chauncy Cres	2	942	03-Dec	/	/	/	/	/	/	X	X	Decking plastic worn	Monitor		
			1	1210	18-Dec	/	/	/	/	/	/	X	X	Swing mounts worn Cuts on slide (smoothed)	Monitor Monitor		
105	RICHARDSON PLGR 259	Clift Cres	2	915	03-Dec	/	/	/	/	/	/	X	X	Obscene graffiti / damage on new concrete path	Needs Removal PCL		
			1	1220	18-Dec	/	/	/	/	/	/	X	X	Worn swing chains/mounts/movement in post Bark low / dirt in bark	Monitor Top up bark - PCL		
106	RICHARDSON PLGR 257	Vidal St	2	930	03-Dec	/	/	/	/	/	/	X	X	Decking plastic worn/rusting	Monitor		
			1	1215	18-Dec	/	/	/	/	/	/	X	X	Climb net mounts worn Damaged spring animal foot rest Climb net links worn Climb net bar bent Tyre swing links worn Bark low	Needs Repair LAZ Monitor Monitor Monitor Monitor Needs top up - PCL		
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN														
108	THEODORE PLGR 265	Dyett Circ	2	1030	03-Dec	/	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			1	1155	18-Dec	/	/	/	/	/	/	X	X	Decking timber splitting Chain net links worn	Monitor Monitor		
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN														
110	THEODORE PLGR 261	Louis Loder St	2	1046	03-Dec	/	/	/	/	/	/	X	X	Border logs splitting	Monitor		
			1	1200	18-Dec	/	/	/	/	/	/	X	X	Decking timber splitting Slide fibreglass cracking/worn Chain net links worn	Monitor Monitor Monitor		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection					Dec-19		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equ pment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
										Bark low	Needs Top up - PCL



CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection							Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
111	THEODORE PLGR 264	Scantleberry St	2	1005	03-Dec	/	/	/	/	/	X	X	Border concrete broken/lifting	Needs Repair - PCL			
														Border logs splitting	Monitor		
			1	1150	18-Dec	/	/	/	/	/	X	X	Trees growing in bark	Needs Removal - PCL			
															Slide damaged at top	Monitor	
															Spring animal timber worn	Monitor	
															Decking timber/panel splitting	Monitor	
													Chain net links worn	Monitor			
112	WANNIASSA PLGR 270	Billson Pl	2	1010	05-Dec	/	/	/	/	/		X					
														Decking plastic worn	Monitor		
			1	1510	23-Dec	/	/	/	/	/		X		Bridge plastic worn	Needs Repair LAZ		
													Damaged tic tac toe	Monitor			
													Worn rubber on spike spinner	Needs Repair J&E			
113	WANNIASSA PLGR 267	Bussau Cl	2	935	05-Dec	/	/	/	/	/	X	X	Decking timber worn	Monitor			
														Chain net links worn/plastic peeling	Monitor		
			1	1600	23-Dec	/	/	/	/	/	X	X	Damaged/rotting borders	Monitor			
													Concrete path lifting	Needs Repair PCL			
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	2	1020	05-Dec	/	/	/	/	/		X	Decking plastic worn x 1	Needs Repair - LAZ			
															Swing mounts/brackets worn	Monitor	
			1	1500	23-Dec	/	/	/	/	/		X			Grab handle loose	Monitor	
115	WANNIASSA PLGR 275	Hervey Pl	2	1100	05-Dec	/	/	/	/	/	X	X	Border sleepers/braces splitting	Needs Repair PCL			
															Decking plastic rust / peeling	Monitor	
			1	1435	23-Dec	/	/	/	/	/	X	X	Smoking sign loose in footing	Needs Repair PCL			
													Swing seat damaged/mounts/links worn	Monitor			
116	WANNIASSA PLGR 266	Lansell Circ	2	930	05-Dec	/	/	/	/	/	X	X	Swing mounts worn	Monitor			
															Movement in spring animal	Monitor	
			1	1605	23-Dec	/	/	/	/	/	X	X	Border fence panels damaged	Monitor			
													Missing 1 x fence post cap	Repaired by J&E 23/12/19			
117	WANNIASSA PLGR 269	Sainsbury St	2	955	05-Dec	/	/	/	/	/	X	X	Border logs splitting	Monitor			
															Holes in shade sail	Monitor	
			1	1530	23-Dec	/	/	/	/	/	X	X			Burn marks on tic tac toe	Monitor	
													Bench seat slats damaged	Needs Repair PCL			
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN														
119	WANNIASSA PLGR 276	Steinfeld Circ	2	1055	05-Dec	/	/	/	/	/	X	X	Border Sleepers splitting	Monitor			
															Bench seat slats splitting	Monitor	
			1	1440	23-Dec	/	/	/	/	/	X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ			
																Decks worn x 2	Needs Repair - LAZ
																Bridge slats splitting	Monitor
													Bridge/Chain net links worn/plastic	Monitor			



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection							Dec-19		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition								
120	WANNIASSA PLGR 268	Sullivan Cres	2	940	05-Dec	/	/	/	/			X	X	Bearings / wheels damaged on fly fox trolley	Needs Repair J&E	
															Border logs splitting	Monitor
			1	1540	23-Dec	/	/	/	/			X	X		Bridge/chain links worn	Monitor
																Handle plastic worn on flying fox
														Swing seats/mounts worn/splitting	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Domenik		Month of Inspection								Dec-19		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
0:00	WANNIASSA PLGR 277	Watkins St	2	1040	05-Dec	/	/	/	/	X	X	Border sleepers damaged	Needs Repair - PCL		
													Swing mounts worn	Monitor	
			1	1445	23-Dec	/	/	/	/	X	X	Bridge timber splitting	Monitor		
													Park bench missing / damaged timber	Needs Repair - PCL	
											Decking worn/lichen growing	Monitor			
122	WANNIASSA PLGR 274	Wheeler Cres	2	1120	05-Dec	/	/	/	/	X	X	Decking worn / rusting	Monitor		
													Swing mounts/ links worn	Monitor	
			1	1430	23-Dec	/	/	/	/	X	X	Fireman pole damaged	Monitor		
													Roman triangles links worn plastic worn	Monitor	
											Chain net links worn	Monitor			
123	WANNIASSA PLGR 272	Whiteman St	2	1034	05-Dec	/	/	/	/	X	X	Swing mounts/s hooks/ chains worn	Monitor		
			1	1455	23-Dec	/	/	/	/	X	X	Border logs splitting	Monitor		
											Horse timber splitting/worn	Needs Repair - J&E			



Name Of Inspector

Domenik

Month of Inspection

Dec-19

	Location		Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
	Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x			/

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Inspectors Signature: D.Radman

CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

Address: CHIPPINDALL CIRCUIT, THEODORE UBD: 99 B13

General Report

Type: PUBLIC Hierarchy: LOCAL NEIGHBOURHOOD

Visual Amenity: Fair Landform: Gentle Slope No. of Play Items: 5 Expt'd usage: Medium Appr. size: 12m x 17m

Shade Level: Good Shelter/Shade Description: Shadesail and medium trees south and north

Nearest Public Toilets: None Signage: No Smoking within 10m of playground

No. of Drink fountains: 0 No. of Bins: 0 No. of seats / Capacity for supervision: 1 / 3 Parking: None

Surrounding Land Use: Open Spaces Lighting: None

Comments: New shadesail installed between 2017 and 2018 inspections.



Photo taken: 08/04/2020 PLAR318 from the SE.

Photo taken: 08/04/2020 PLAR318 from the NW.

Playground Areas

Area ID: PLAR318	Current	Contains a medium combination unit, double swing, spin poles and spring rockers.	Equipment Cnt. 5 Av. Cond (/5): 2.3
<u>Year Upgraded:</u> 2000 Estm'd <input checked="" type="checkbox"/>	Age(yrs) <4 4-7 8-12 13+	Cond'n (1:new-5:bad)	Equipment Weighted Risk Score (/25): 4.3
Fall Area Edging: 40m Concrete	2	Area(m2)	Fencing: None
Main Surface Type: TANBARK	2	205	Access Type: Sealed Path
Other Undersurface: None			Estimated Extra Mulch Req. (m3): 11.5
Softfall Depths(mm):	250 - SW support post at steps. 160 - 0.5m north of spin pole.		
			Synthetic Impact OK (est'd)? NA

Inspection History

Date	Type	Results / Summary	
8/04/2020	Full	Completed by Play Spect. Works and associated risk are listed below. Additional information is recorded as part of the data for specific playground items.	DG
20/03/2018	Full	Completed by Play DMC.	DG
1/08/2017	Full	Completed by Play DMC.	DG
14/07/2016	Full	Completed by Play DMC.	DG
5/05/2015	Full	Completed by Play DMC.	DG
27/04/2012	Full	Completed by Play DMC.	DG
25/05/2011	Full	Completed by Play DMC.	DG
23/06/2010	Full	Completed by Play DMC.	DG






CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

Works

Works to address identified issues are listed below. If blank then none recorded in the database for this playground

Equipment and Works Description	Tracking:	Dates	Responsibility	Photo (larger sizes provided elsewhere in main report)
<p>Priority: Medium Level of Risk: 8 - Moderate (D4)</p> <p>Works ID: 8038 Works Type: General Order ID:</p> <p>Mulch is low. Top up mulch (~15m³ req) so after it settles there is at least 200mm in all impact areas, 250mm in heavy use areas.</p>	Approved: <input type="checkbox"/> Started: <input type="checkbox"/> Completed: <input type="checkbox"/> Checked: <input type="checkbox"/>	Last Observed: 8/04/2020	First Identified: 8/04/2020	
<p>PLAR318. Item 2. Swing Frame (double) - Swing (flat seat)</p> <p>Priority: Low Level of Risk: 4 - Low (E4)</p> <p>Works ID: 6070 Works Type: General Order ID:</p> <p>Hammerlocks used on flat swing chains have openings ~11mm. The 8.6mm finger probe passes through openings but 12mm probe doesn't. As such, H-locks should be clamped tighter, covered by rubber hosing, have grommets placed in them or be replaced with H-locks that allow 12mm finger probe to pass or don't allow 8.6mm finger probe to pass (latter is preferred).</p>	Approved: <input type="checkbox"/> Started: <input type="checkbox"/> Completed: <input type="checkbox"/> Checked: <input type="checkbox"/>	Last Observed: 8/04/2020	First Identified: 14/07/2016	
<p>PLAR318. Item 4. Train Rocker (spring)</p> <p>Priority: Low Level of Risk: 1 - Very Low (E1)</p> <p>Works ID: 6588 Works Type: General Order ID:</p> <p>The hand support is loose. Refasten.</p>	Approved: <input type="checkbox"/> Started: <input type="checkbox"/> Completed: <input type="checkbox"/> Checked: <input type="checkbox"/>	Last Observed: 8/04/2020	First Identified: 1/08/2017	
<p>PLAR318. Item 1. Combination Unit (medium) - Panel (tic-tac-toe)</p> <p>Priority: Very Low Level of Risk: 2 - Very Low (E2)</p> <p>Works ID: 5425 Works Type: General Order ID:</p> <p>The tic tac toe components can slide up and down along the vertical rail and could be potential pinch points. These components are relatively lightweight hence the risk is deemed to be very low. Provide spacers between barrels to inhibit components from sliding.</p>	Approved: <input type="checkbox"/> Started: <input type="checkbox"/> Completed: <input type="checkbox"/> Checked: <input type="checkbox"/>	Last Observed: 8/04/2020	First Identified: 5/05/2015	
<p>Priority: Monitor Level of Risk: 2 - Very Low (E2)</p> <p>Works ID: 8500 Works Type: General Order ID:</p> <p>There are small holes in the shadecloth. Monitor. Cover holes or replace cloth upon significant deterioration.</p>	Approved: <input type="checkbox"/> Started: <input type="checkbox"/> Completed: <input type="checkbox"/> Checked: <input type="checkbox"/>	Last Observed: 8/04/2020	First Identified: 8/04/2020	

Regular ongoing maintenance works are generally not listed (eg. raking back displaced mulch, weeding, recoating, cleaning graffiti, etc). Inspections are visual assessments hence do not include structural engineering and materials testing and assessment of the equipment. Conformance to playgrounds Standards such as AS4685 is not mandatory and a non-conformance may be deemed acceptable based on risk assessment. AS4685 is not retrospective so equipment built prior to Oct 2005 that conforms to the superseded AS1924 is generally acceptable. It is the decision of the playground operator as to what works are to be implemented and what Levels of Risk and non-conformances they deem acceptable. This report and the completion of any works listed is not a guarantee that an incident will not occur. Safety in play provision is not absolute and accidents do occur (as they do anywhere) regardless of design. Any costs listed are indicative only due a range of factors.

PLAY SPECT
INSPECTIONS | ADVICE | REPORTING

Report by Play Spect
Ph: (03) 97852293.

Level of Risk Assessment Notes

Risk is generally assessed on likelihood and consequences using the matrix on the right. Other important factors such as benefits of play (eg. play value) are also considered. This matrix is based on the principles of ISO31000 Risk Management (2009) and the RoSPA guide Risk Assessment of Children's Playgrounds (2005). However this matrix conservatively has more High and Extreme levels than typically used.

Injury Type		Little/None	Minor	Moderate	Serious	Permanent
		1	2	3	4	5
Highly unlikely	E (1)	Very Low (1)	Very Low (2)	Low (3)	Low (4)	Moderate (5)
Unlikely	D (2)	Very Low (2)	Low (4)	Moderate (6)	Moderate (8)	High (10)
Possible	C (3)	Low (3)	Moderate (6)	Moderate (9)	High (12)	High (15)
Likely	B (4)	Low (4)	Moderate (8)	High (12)	High (16)	Extreme (20)
Very likely	A (5)	Moderate (5)	High (10)	High (15)	Extreme (20)	Extreme (25)

Equipment listings and attributes for this playground are provided on the following pages.

CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

1 - Combination Unit (medium)

Asset ID: PLST1469
Area ID: PLAR318

Current
Level of Risk: E5 - Moderate

Materials: Metal (powder ctd)

Make: Playspace

Has Markings per Sectn 4, AS? NA

Inspection Date: 8/04/2020

Condition: 2- Good

Model:

Installed by:

Installation Date: 1/01/2000 Est.

Item Components

Asset_ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type	Removed/ Current
1 PLCO5752	Deck (square)	4	Metal (rubber ctd)	1/01/2000	<input checked="" type="checkbox"/>	3		Current
3 PLCO5754	Slide (straight)	1	Steel (stainless)	1/01/2000	<input checked="" type="checkbox"/>	3		Current
4 PLCO5755	Panel (shopfront)	1	Metal (powder ctd)	1/01/2000	<input checked="" type="checkbox"/>	2		Current
5 PLCO5756	Access (stairway)	1	Metal (powder ctd)	1/01/2000	<input checked="" type="checkbox"/>	2		Current
6 PLCO5757	Bridge (clatter)	1	Metal (rubber ctd) Comments: Height=550mm	1/01/2000	<input checked="" type="checkbox"/>	2		Current
7 PLCO5758	Panel (tic-tac-toe)	1	Plastic	1/01/2000	<input checked="" type="checkbox"/>	2		Current



Photo taken: 08/04/2020



Photo taken: 08/04/2020



Photo taken: 08/04/2020



Photo taken: 08/04/2020 Neck probe just not touching the bottom.

Detailed Field Notes

for the Combination Unit (medium)

Inspection Date: 8/04/2020

Comments: Note: Clauses below refer to AS4685(2004) and an update of this was released in April 2014. However, as this item was built prior May 2015, AS4685(2004) is still applicable as AS4685 (2014) is not retrospective, although comments in relation to AS4685(2014) are also provided where relevant.

General Safety Requirements (AS4685.1)

1. Are all free heights of fall <2.5m? (and <2.2m for upper body equip. Or <1.5m for SEC.)	(Cl 2.2.4.1)	<input checked="" type="checkbox"/> Y
2. Is it free of sharp or rough edges or projections that may present a hazard to users?	(Cl 2.2.5)	<input checked="" type="checkbox"/> Y
3. Are shear, pinch and crush points non-existent or inaccessible?		<input type="checkbox"/> N
4. Is it free of head or neck entrapments? Use probes (HT for >600mm high 89-230mm)	(Cl.2.2.7/App D)	<input type="checkbox"/> N

Description/Measurements

Max. deck height=1.3m.
At the small combination unit, the gaps between tic tac toe barrels could be potential pinch points.
Gaps between barrier rails and in vertical handrails are 100-120mm (AS4685 requires gaps <89mm but this is not retrospective, OK under previous Standard which required gaps<125mm). The openings in the top of the barriers at the sides of the slide top could theoretically be potential neck entrapments under AS4685.1 as the neck probe doesn't quite touch the bottom of the openings. However the probe will touch the bottom if rotated just slightly; the openings were OK under the previous Standard to which this item was built and AS4685 is not retrospective; and the risk is low.

5. Is it free of clothing, torso, foot, limb, finger traps?	<input checked="" type="checkbox"/> Y
---	---------------------------------------

CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

Additional Checks (as per part of App.B AS4486.1)

6. Is the item complete with no missing parts?	<input checked="" type="checkbox"/>	
7. Are all joints fastened properly?	<input checked="" type="checkbox"/>	
8. Is the protective paint or coating (where req.) in good cond.? (NA for trtd timber or stainless / galv steel)	<input checked="" type="checkbox"/>	
9. Are all ends of steel sections capped?	<input checked="" type="checkbox"/>	
10. Are all fixed structures stable?	<input checked="" type="checkbox"/>	
11. Are all footings and foundations covered with compacted soil?	<input checked="" type="checkbox"/>	
12. Is equipment free from other significant damage? (cracking, rust, weld cracks, broken members, wear, warping, distortion, non-lubricated, etc)	<input type="checkbox"/>	The slide face is dented. There are warped holes in the decks, cut in the lowest deck and edges of the clatter beams are bent..
13. Was the equipment free from any other significant non-conformances or problems not covered elsewhere in this list or report?	<input checked="" type="checkbox"/>	

Access (Cl. 2.2.3 and 2.2.9 AS4685.1)

14. Are the correct accesses used? (Cl.2.2.9) (ramps<15<steps<45, 60<step ladders<65<rung ladders)	<input checked="" type="checkbox"/>	
15. Are ladder dimensions correct? (Cl.2.2.9.2) >2 rungs. Even spacing<300mm / Width 300-600mm / Rungs or styles (both if near vertical) conform to grip = 16-45mm. >90mm open space to rear of centre of rung or step. Gaps>230mm.	<input type="checkbox"/>	NA
16. Are step dimensions correct? (Cl.2.2.9.3) >2 risers. Even 100-220mm rise / Tread depth>140mm (pref. 225-350) / Width>600mm, >450 SEC. No gap when viewed from above.	<input type="checkbox"/>	200/235/585mm. (Under AS4685, 2014 there is no stairway tread width requirement)
17. Do stairs >2m high have int. landings? (Cl. 2.2.9.3) (height int. <2m. >1m long. Line of stairs offset or >90degrees diff.)	<input type="checkbox"/>	NA
18. Do ramps, stairs, bridges have 2 handrails? (<60mm wide. 2 req. at 800-1000mm and 400-550mm (Cl. 2.2.4.2) or 1 btwn 450-700mm for SEC and stepladders)	<input checked="" type="checkbox"/>	600 and 1000mm. Clatter bridge=350-950mm.
19. Are opening widths < adjoining assembly widths or 800mm?	<input checked="" type="checkbox"/>	
20. Do openings have hand supports? (Cl.2.2.4.8, 9) Conform to grip (16-45mm) and can't be used to climb (>500mm step)	<input checked="" type="checkbox"/>	

Protection Against Falling (Cl.2.2.4 AS4685)

21. Are barriers provided where standing surface is >0.5m above ground? (or rail for 0.5-1.2m decks in SEC)	<input checked="" type="checkbox"/>	
22. Are heights >900mm? (or >700mm for decks 0.5-1.2m high) (SEC, >700mm or guardrail 650-750mm high)	<input checked="" type="checkbox"/>	960mm.

Slides (AS4685.3)

Slides have a starting section (<5deg), sliding section (SS) and run-out section (<5deg)

23. Is there a rail 700-900mm high across opening? (for attachment slides >1m high) (Cl.2.3.4)	<input checked="" type="checkbox"/>	800mm.
24. Is SS angle OK? (Max.<60, Ave<40) (Cl.2.4.1)	<input checked="" type="checkbox"/>	32deg.
25. Is the width adequate? (Cl.2.4.2 and 2.9.1) (SSL>1.5m: >350mm (and <700 for curved). Tunnel dia. >585mm)	<input checked="" type="checkbox"/>	370mm.
26. Is runout length and angle OK? (Cl.2.5) (SSL<1.5m, >300mm. SSL>1.5m, >500mm. SSL>7.5m, >1500mm)	<input checked="" type="checkbox"/>	650mm, 0deg.
27. Is end hght OK? (SSL<1.5m:<200mm. SSL>1.5m:<350mm)	<input checked="" type="checkbox"/>	320mm.
28. Are side heights OK? (Cl.2.3.2 and 2.6) (Starting section: Falling protctn req. if length>200mm from platform SS: FHOF<1.0m,>50mm. FHOF>1.0m,>100mm)	<input checked="" type="checkbox"/>	130mm.

CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

2 - Swing Frame (double)		Asset ID: PLST1470 Area ID: PLAR318	Current Level of Risk: E4 - Low
---------------------------------	--	--	---

Materials: Metal (powder ctd)	Make: Playspace	Has Markings per Sectn 4, AS? NA	Inspection Date: 8/04/2020
Condition: 3- Fair	Model:	Installed by:	Installation Date: 1/01/2000 Est: <input checked="" type="checkbox"/>

<u>Item Components</u>								
Asset_ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type	Removed/ Current
1	PLCO5761 Swing (flat seat)	1	Rubber	1/01/2010	<input checked="" type="checkbox"/>	3		Current
Comments: Height=490mm. Chain/ Hammerlock openings=6/ ~11mm.								
2	PLCO5762 Swing (toddler seat)	1	Rubber	1/01/2020	<input checked="" type="checkbox"/>	1		Current
Comments: Height=410mm. Chain/ S-hook openings=6/ ~6mm.								

Comments: Crossbeam is chipped and peeling. Monitor.



Photo taken: 08/04/2020



Photo taken: 08/04/2020 Upper shackles worn. Monitor.

3 - Rotating Element		Asset ID: PLST1472 Area ID: PLAR318	Current Level of Risk: E3 - Low
-----------------------------	--	--	---

Materials: Metal (powder ctd)	Make: Playspace	Has Markings per Sectn 4, AS? NA	Inspection Date: 8/04/2020
Condition: 2- Good	Model:	Installed by:	Installation Date: 1/01/2000 Est: <input checked="" type="checkbox"/>

<u>Item Components</u>								
Asset_ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type	Removed/ Current
1	PLCO5764 Spin Pole	1	Metal (powder ctd)/Rubber	1/01/2000	<input checked="" type="checkbox"/>	2		Current
Comments: Rubber coating worn.								



Photo taken: 08/04/2020



Photo taken: 08/04/2020 Rubber coating worn on foot pad. Monitor.

CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

4 - Rocker				Asset ID: PLST1473 Area ID: PLAR318		Current Level of Risk: E3 - Low	
Materials: Metal (powder ctd)		Make: Playspace		Has Markings per Sectn 4, AS? NA		Inspection Date: 8/04/2020	
Condition: 2- Good		Model:		Installed by:		Installation Date: 1/01/2000 Est. <input checked="" type="checkbox"/>	
Item Components							
Asset_ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type Removed/Current
1	PLCO5040	Rocker (spring)	1	Metal (powder ctd)	1/01/2000	<input checked="" type="checkbox"/>	2 Train Current
Comments: Coat is faded, loose hand support.							



Photo taken: 08/04/2020

5 - Rocker				Asset ID: PLST1474 Area ID: PLAR318		Current Level of Risk: E3 - Low	
Materials: Metal (powder ctd)		Make: Playspace		Has Markings per Sectn 4, AS? NA		Inspection Date: 8/04/2020	
Condition: 2- Good		Model:		Installed by:		Installation Date: 1/01/2000 Est. <input checked="" type="checkbox"/>	
Item Components							
Asset_ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type Removed/Current
1	PLCO5039	Rocker (spring)	1	Metal (powder ctd)	1/01/2000	<input checked="" type="checkbox"/>	2 Hippopotamus Current
Comments: Coat is faded.							



Photo taken: 08/04/2020

6 - Rocker				Asset ID: PLST1923 Area ID: PLAR318		Removed Level of Risk: E3 - Low	
Materials: Metal (powder ctd)		Make: Playspace		Has Markings per Sectn 4, AS? NA		Inspection Date: 1/08/2017	
Condition: 2- Good		Model:		Installed by:		Installation Date: 1/01/2000 Est. <input type="checkbox"/>	
Item Components							
Asset_ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type Removed/Current
1	PLCO5038	Rocker (spring)	1	Metal (powder ctd)	1/01/2000	<input type="checkbox"/>	2 Dinosaur Current
Comments: Rocker removed between 2017 and 2018 inspections.							

CHIPPINDALL CIRCUIT

Playground Inventory Report

Playground ID: PLGR263

7 - Rotating Element

Asset ID: PLST1471

Removed

Area ID: PLAR318

Level of Risk: E3 - Low

Materials: Metal (powder ctd)

Make: Playspace

Has Markings per Sectn 4, AS? NA

Inspection Date: 27/04/2012

Condition: 2- Good

Model:

Installed by:

Installation Date: 1/01/2000

Est:

Item Components

Asset ID	Component	Count	Materials	Date Installed	Est.	Condition 1-new to 5-Bad	Rocker Type	Removed/ Current
1 PLCO5763	Spin Pole	1	Metal (powder ctd)/Rubber	1/01/2000	<input checked="" type="checkbox"/>	2		Removed
Comments: West spin pole removed between 2012 and 2015 inspections.								

Name Of Inspector

Shane

Month of Inspection

Mar-20

		Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action		
1	BANKS PLGR 413	Pocket Ave	1	10:27	02-Mar	/		/		/		/		X		X	Loose slide leg	Monitor		
			1	10:30	10-Mar	/		/		/		/		X		X	Chain net links/mounts worn	Monitor / Needs Repair LAZ		
			1	11:17	16-Mar	/		/		/		/		X		X				
			2	12:49	23-Mar	/		/		/		/		X		X	Border concrete cracking / lifting	Needs Repair PCL		
			1	10:15	30-Mar	/		/		/		/		X		X	Small plastic slide damaged	Monitor		
																Titer toters arms missing	Removed until further notice - PCL			
2	BONYTHON PLGR 535	Burgoyne St	1	9:37	02-Mar	/		/		/		/				X	Ropes worn on climb net	Monitor		
			1	9:40	10-Mar	/		/		/		/				X	Swing mounts worn	Monitor		
			1	9:48	16-Mar	/		/		/		/				X	Graffiti on fire truck	Needs Removal PCL		
			2	11:55	23-Mar	/		/		/		/				X	Collar pins worn	Monitor		
			1	9:30	30-Mar	/		/		/		/				X	Ropes worn on small single swing	Monitor		
																Black rubber mount points melting	Monitor			
3	FADDEN PLGR 228	Coyne St	1	11:25	02-Mar	/		/		/		/		X		X	Swing mounts worn	Monitor		
			1	11:40	10-Mar	/		/		/		/		X		X	Cracked welds on slide entry	Monitor		
			1	12:18	16-Mar	/		/		/		/		X		X	Worn links bridge/climb chains	Monitor		
			2	1:58	23-Mar	/		/		/		/		X		X	Timber split on panels	Monitor		
			1	11:35	30-Mar	/		/		/		/		X		X	Border logs splitting	Monitor		
																			Holes in softfall / splitting	Needs repair - PCL
																			Footpath lifting	Needs repair - PCL
																			Slide footing loose	Monitor
																			Spinning seesaw hanger has worn bolts/handle	Monitor
																Hose splitting on chain covers	Monitor			
																Movement in brackets on web towers	Monitor			
4	GORDON PLGR 278	McGilvray Circ	1	10:15	02-Mar	/		/		/		/		X		X	Fibreglass on tea cup spinner cracking	Monitor		
			1	8:55	06-Mar	/		/		/		/		X		X	Swing mounts worn x 2	Needs Repair - J&E		
			1	10:15	10-Mar	/		/		/		/		X		X	Damaged see-saw brackets x 3	Needs Repair - J&E		
			1	2:05	13-Mar	/		/		/		/		X		X	Rope climb net worn 80%	Needs Repair - J&E		
			1	11:05	16-Mar	/		/		/		/		X		X	Spinner top bearings loose	Monitor		
			1	9:15	20-Mar	/		/		/		/		X		X	Damaged super nova	Monitor		
			2	12:34	23-Mar	/		/		/		/		X		X	Border logs splitting	Monitor		
			1	9:04	27-Mar	/		/		/		/		X		X	Roman triangles worn links	Needs repair - LAZ		
				10:00	30-Mar	/		/		/		/		X		X	Wire walk cable worn	Monitor		
																			Decking worn on tower	Monitor
																			Wire bridge mount worn/chain low links worn	Needs repair - LAZ
																			Cracked welds in tower/rust	Needs repair - LAZ
																			Rubber Soft fall splitting/holes	Needs repair - PCL
																Swing chains/brackets/mounts	Monitor			
																bench below tea cup playground coming out of footing	Needs repair - PCL			
																Hole in shade sail	Monitor			
5	GOWRIE PLGR 328	Jeffries St	1	11:39	02-Mar	/		/		/		/				X	Softfall splitting / holes forming	Needs Repair PCL		
			1	11:53	10-Mar	/		/		/		/				X	Timber worn on carousel	Monitor		
			1	12:28	16-Mar	/		/		/		/				X	Spider net worn	Monitor		
			2	2:11	23-Mar	/		/		/		/		/			X			

Name Of Inspector **Shane** Month of Inspection **Mar-20**

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
							/	x	/	x	/	x	/	x	/	x						
				Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x		Hazard	Action			
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	7:14	02-Mar	/		/		/		/		X	X		Bearings/guide rollers worn on fly fox	Monitor			
				1	7:12	10-Mar	/		/		/		/		X	X		Swing mounts/brackets worn	Monitor			
				1	7:32	16-Mar	/		/		/		/		X	X		Concrete border lifting	Monitor			
				2	9:19	23-Mar	/		/		/		/		X	X		Bridge slats splitting	Monitor			
				1	7:16	30-Mar	/		/		/		/		X	X		Movement in see saw base	Monitor			
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	6:55	02-Mar	/		/		/		/		X	X		Damaged concrete border	Monitor			
				1	6:57	10-Mar	/		/		/		/		X	X		Damaged park seat	Needs repair - PCL			
				1	7:20	16-Mar	/		/		/		/		X	X		baby swing damaged	Monitor			
				2	9:05	23-Mar	/		/		/		/		X	X		Plastic Rock on climb wall cracking	Monitor			
				1	7:00	30-Mar	/		/		/		/		X	X		Movement in base of carousel	Needs repair - J&E			
14	KAMBAH PLGR 305	Springbett St		1	7:45	02-Mar	/		/		/		/		X	X		Twin S/S slide has crack in surface	Monitor			
				1	7:00	06-Mar	/		/		/		/		X	X		Swing seat/brackets/links/mounts worn	Monitor			
				1	7:43	10-Mar	/		/		/		/		X	X		Super nova damaged	Monitor			
				1	9:00	13-Mar	/		/		/		/		X	X		Hosing split on carousel	Monitor (taped)			
				1	8:05	16-Mar	/		/		/		/		X	X		Mount worn on large fly fox	Monitor			
				1	7:00	20-Mar	/		/		/		/		X	X		Border logs splitting	Monitor			
				2	9:52	23-Mar	/		/		/		/		X	X		Sml fly fox movement in bolt	Monitor			
				1	7:00	27-Mar	/		/		/		/		X	X		Tic Tac Toe damaged (taped)	Needs Repair J&E			
					7:45	30-Mar	/		/		/		/		X	X		Damage panel on quad hoops	Monitor			
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	12:07	02-Mar	/		/		/		/		X	X		Bark low	Needs repair - PCL			
				1	12:20	10-Mar	/		/		/		/		X	X		Burn mark seesaw	Monitor			
				1	12:55	16-Mar	/		/		/		/		X	X		Swing mounts	Monitor			
				2	2:46	23-Mar	/		/		/		/		X	X		Timber swing posts splitting/ missing swings	?			
				1	12:15	30-Mar	/		/		/		/		X	X		Worn decks/ bridge	Monitor			
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)																Damaged rock wall	Monitor			
				1	12:20	02-Mar	/		/		/		/			X						
				1	12:35	10-Mar	/		/		/		/				X			Rope worn on carousel	Monitor	
				1	1:10	16-Mar	/		/		/		/				X			Swing seat / brackets worn	Monitor	
				2	3:02	23-Mar	/		/		/		/				X					
17	MACARTHUR PLGR 327	Bayly PI		1	12:30	30-Mar	/		/		/		/			X			Bark low	Needs Repair PCL		
				1	11:03	02-Mar	/		/		/		/			X				Worn swing links/brackets	Monitor	
				1	11:11	10-Mar	/		/		/		/			X				Rope worn on climbing net/carousel	Monitor	
				1	11:50	16-Mar	/		/		/		/			X				Movement in base towards post of carousel	Needs repair - J&E	
				2	1:34	23-Mar	/		/		/		/			X				Gravel washed into bark	Needs removal PCL	
THEODORE				1	11:06	30-Mar	/		/		/		/			X			Low bark	Needs Top up - PCL		
																					Softfall patches lifting under birds nest swing	Needs Repair PCL
				1	10:37	02-Mar	/		/		/		/				X				Swing mounts/bushes worn	Monitor
				1	10:45	10-Mar	/		/		/		/			X				Carousel seat worn/rusting	Monitor	
				1	11:28	16-Mar	/		/		/		/			X				Worn/damaged deck/bridge	Monitor	



Name Of Inspector **Shane** Month of Inspection **Mar-20**

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
							/	x	/	x	/	x	/	x	/	x	/	x			
18	THEODORE PLGR 263	Chippindall Circ		2	1:05	23-Mar	/		/		/		/		/		X		Loose handle/footings on spring animal x 2	Monitor	
				1	10:15	30-Mar	/		/		/		/		/		X		Tree branch stuck in shade sail	Needs Removal PCL	
																				Holes in shade sail	Monitor
																					Low bark
19	THEODORE PLGR 262	Lawrence Wackett Cres		1	10:47	02-Mar	/		/		/		/		X	X		Weld cracking at slide entry	Needs Repair - LAZ		
				1	10:59	10-Mar	/		/		/		/		X	X			Decking plastic worn/surface rust	Monitor	
				1	11:38	16-Mar	/		/		/		/		X	X			Swing/Chain bridge links/mounts worn	Monitor	
				2	1:18	23-Mar	/		/		/		/		X	X				Movement in frog footing	Monitor
				1	10:37	30-Mar	/		/		/		/		X	X				Border concrete cracking	Needs Repair - PCL
20	WANNIASSA PLGR 271	Sangster Pl		1	11:53	02-Mar	/		/		/		/		X	X			Swing mounts brackets worn	Monitor	
				1	12:10	10-Mar	/		/		/		/		X	X				Decking worn	Monitor
				1	12:45	16-Mar	/		/		/		/		X	X				Hole in chain wire fence	Needs Repair - LAZ
				2	2:35	23-Mar	/		/		/		/		X	X				Park bench missing arm rest	Needs Repair - PCL
				1	12:00	30-Mar	/		/		/		/		X	X				Holes and splitting in softfall	Needs repair - PCL

Inspectors Signature: S.Conroy

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

	Suburb	Street	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
			Level 1or Level 2			Level 1/2	/	x	/	x	/	x	/	x	/	x	/			x	
1	BANKS PLGR 213	Menzies Court	1	12:29	04-Mar	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																			Decking plastic worn/surface rust	Monitor	
			1	9:17	18-Mar	/		/		/		/				X		X			
																				Border concrete cracking	Monitor
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	1	12:40	04-Mar	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																			Swing seat brackets worn	Monitor	
			1	9:27	18-Mar	/		/		/		/				X		X	Decking worn	Monitor	
																				Dints in slide bed	Monitor
																		Border concrete cracking	Needs Repair - PCL		
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	11:09	04-Mar	/		/		/		/		/			X	Posts handrails split/rotting	Monitor		
																			4 x Post damaged/split on fort	Monitor	
			1	7:30	18-Mar	/		/		/		/		/			X	Chain net links and mounts worn	Monitor		
																				Swing mounts worn	Monitor
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	10:46	04-Mar	/		/		/		/			X		X	Border logs splitting	Monitor		
			1	7:00	18-Mar	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																		Slide has crack at entry/movement	Monitor		
7	BONYTHON PLGR 586	Morice Pl	1	10:58	04-Mar	/		/		/		/		/			X				
																				Swing seat brackets worn	Monitor
			1	7:18	18-Mar	/		/		/		/		/				X	Worn / missing rope on net	Monitor	
																					Worn links/mounts on pommel/ climb chain



Name Of Inspector

Shane

Month of Inspection

Mar-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
8	CALWELL PLGR 322	Beckett St	1	1:00	05-Mar	/	/	/	/	/	X	Decking plastic worn	Monitor		
													Swing mounts worn	Monitor	
			1	12:15	18-Mar	/	/	/	/	/	/	X	Bent monkey bars	Monitor	
														Slide weld cracking at top	Needs Repair - LAZ
														Chain walk hand rail bent	Needs Repair - LAZ
														Bent deck poles	Needs Repair - LAZ
												Low tree branches	Needs Removal PCL		
9	CALWELL PLGR 321	Casey Cres	1	1:30	05-Feb	/	/	/	/	/	X	Swing mounts worn	Monitor		
													Decking plastic worn/decks rusting	Monitor	
			1	11:31	18-Mar	/	/	/	/	/	/	X	Chain net links/coating on chains worn	Monitor	
												See saw timber splitting	Monitor		
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	1	1:09	05-Mar	/	/	/	/		X	X	Decking plastic worn	Monitor	
														Swing mounts/seat/links worn	Monitor
			1	12:01	18-Mar	/	/	/	/		X	X	Low branches	Needs cut back back-PCL	
												Side leg bent	Monitor		
11	CALWELL PLGR 319	Samuel Cl	1	1:17	05-Mar	/	/	/	/		X	X	Border logs splitting	Monitor	
														Swing mounts worn	Monitor
			1	11:40	18-Mar	/	/	/	/		X	X	Bent monkey bars	Monitor	
												Park bench missing timber	Needs Repair - PCL		
12	CALWELL PLGR 644	Shopping Centre	1	12:50	05-Mar	/	/	/	/	/		X	Swing mounts/seat/S hooks worn	Monitor	
														Bark low	Top up bark PCL
													Carousel movement in bearing	Monitor	
13	CALWELL PLGR 320	Were St	1	1:24	05-Mar	/	/	/	/		X	X	Border logs splitting	Monitor	
														Swing links/mounts worn	Monitor
			1	11:52	18-Mar	/	/	/	/		X	X	Tire worn on tyre swing	Monitor	
14	CHISHOLM PLGR 234	Alston St	1	11:22	05-Mar	/	/	/	/	/		X			
														Swing mounts worn	Monitor
			1	9:38	19-Mar	/	/	/	/	/	/		X		
													Damaged tic tac toe	Monitor	
													Baby seat chain cover worn	Monitor	



Name Of Inspector		Shane		Month of Inspection							Mar-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
21	CONDER PLGR 219	Ceremonial Pl (Landells Pl)	1	9:51	18-Mar	/	/	/	/	/	X	X	Decks/bridge timber split/damaged	Needs Repair - J&E			
														Ropes worn on climb net (fraying)	Monitor		
															Deck connection bolts worn/chain	Needs repair - LAZ	
22	CONDER PLGR 222	Dixson Circ	1	2:37	05-Mar	/	/	/	/	/		X	Bark washed out	Needs Repair - PCL			
														Panels damaged/rusting	Monitor		
			1	9:39	18-Mar	/	/	/	/	/		X	Chain net/mounts worn	Monitor			
															Plastic panel/ tic tac damaged	Monitor	
23	CONDER PLGR 607	James Smith Circ	1	2:01	05-Mar	/	/	/	/	/		X	Swing/fort posts splitting/rot	Monitor			
															Climb net rope worn	Monitor	
			1	10:33	18-Mar	/	/	/	/	/		X	Decking/panels worn on cubby/spring animal/slide	Monitor			
24	CONDER PLGR 220	Montfiore Cres												Bark low	Needs Top up - PCL		
			1	2:19	05-Mar	/	/	/	/	/	X	X	Border logs splitting	Monitor			
															Climb net links/mounts worn	Monitor	
			1	10:09	18-Mar	/	/	/	/	/	X	X	Bark low	Needs Top up - PCL			
																Bridge rail cracked	Needs repair - LAZ
25	CONDER PLGR 244	Russell Drysdale Cr (Daly Pl)												Movement in border sleepers	Monitor		
			1	2:12	05-Mar	/	/	/	/	/		X	Bridge plastic/ links worn	Monitor			
															Decking worn/rusting	Monitor	
26	FADDEN PLGR 225	Bertram St (Riordan St)	1	10:20	18-Mar	/	/	/	/	/		X	Slide mount on deck rusting	Needs repair - LAZ			
															Bark washed out / dirt in bark	Needs repair - PCL	
			1	7:59	05-Apr	/	/	/	/	/	X	X	Decking plastic worn	Monitor			
																Chain net links/ mounts worn	Monitor
27	FADDEN PLGR 228	Coyne St	1	11:53	19-Mar	/	/	/	/	/	X	X	Tyre swing mounts/ links worn	Monitor			
																Border logs splitting	Monitor
																Border log damaged x 1	Needs Repair PCL
			MONDAY RUN														
			1	8:28	05-Mar	/	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor			
															Border timber damaged	Needs Repair PCL	



Name Of Inspector		Shane		Month of Inspection							Mar-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
													Border sleeper damaged near slide	Needs Repair PCL	
													Tyre swing mounts worn	Monitor	
35	GORDON PLGR 279	Evan Pl	1	11:43	04-Mar	/	/	/	/	/	X		Chain climb net links wearing	Monitor	
			1	8:16	18-Mar	/	/	/	/	/	X		Bridge/deck plastic worn/rusting in corners	Monitor	
36	GORDON PLGR 218	Knoke Ave	1	12:19	04-Mar	/	/	/	/	/	X		Decking plastic worn	Monitor	
			1	9:10	18-Mar	/	/	/	/	/	X		Climb net links/mounts/plastic worn	Monitor	
													Bench seat slat damaged	Needs Repair PCL	
37	GORDON PLGR 278	McGilvray Circ	MONDAY RUN												
38	GORDON PLGR 217	Popplewell Pl (Tallon Pl)	1	12:08	04-Mar	/	/	/	/	/	X		Tic tac damaged	Monitor	
			1	8:50	18-Mar	/	/	/	/	/	X		Dents in slide	Monitor	
													Decking worn/surface rust	Monitor	
													Chain net mounts worn	monitor	
39	GORDON PLGR 214	Noel Ryan Gardens	1	11:18	04-Mar	/	/	/	/	X	X		Fort post splitting	Monitor	
			1	7:48	18-Mar	/	/	/	/	X	X		Slide crack at entry/worn	Removed for Repair J&E	
													Tree roots in bark	Needs Removal - PCL	
													Seesaw seat cracked	Needs Repair LAZ	
													Log steps splitting and rotten	Monitor	
													Concrete border lifting	Monitor	
													Chain bridge links worn	Monitor	
40	GOWRIE PLGR 332	Inwood Pl (Sadlier St)	1	7:21	05-Apr	/	/	/	/	X	X		Border logs splitting	Monitor	
			1	12:18	19-Mar	/	/	/	/	X	X		Seesaw timber worn	Monitor	
41	GOWRIE PLGR 328	Jeffries St	MONDAY RUN												
			1	7:00	04-Mar	/	/	/	/	/	/				
			1	12:35	19-Mar	/	/	/	/	/	/				



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
42	GOWRIE PLGR 333	Middleton Circ	1	7:15	04-Feb	/	/	/	/	X	X	Swing mounts/ links worn	Monitor	
													Border concrete cracking	Monitor
			1	12:25	19-Mar	/	/	/	/	X	X			
43	GOWRIE PLGR 335	Weathers St	1	7:46	04-Mar	/	/	/	/		X	Swing mounts/links worn/rusty	Monitor	
													Slide dented	Monitor
			1	12:03	19-Mar	/	/	/	/	/	X			
44	GOWRIE PLGR 334	Wray Pl	1	7:33	04-Mar	/	/	/	/	X	X	Swing posts splitting	Monitor	
													Swing mounts/ links worn	Monitor
			1	12:12	19-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor	
											Concrete border cracked/lifting	Monitor		
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN											
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN											
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN											
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN											
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN											
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET											



Name Of Inspector

Shane

Month of Inspection

Mar-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	10:16	04-Mar	/	/	/	/	X	X	Ropes worn on web	Monitor		
													Decks/Posts splitting/rotten	Monitor	
			1	1:40	17-Mar	/	/	/	/	X	X	Swing mounts/seat worn	Monitor		
														Concrete border lifting	Needs Repair PCL
														Gaps were slide joints	Monitor
											Swing timber splitting	Monitor			
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	10:38	04-Mar	/	/	/	/	/	X		Swing mounts worn	Monitor	
			1	1:17	17-Mar	/	/	/	/	/	X		Plastic slide cracked	Monitor	
														Movement in swing posts	Monitor
												Frog plastic worn around handle	Monitor		
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	10:29	04-Mar	/	/	/	/	X	X		Border path concrete cracking	Monitor	
														Slide surface worn	Monitor
			1	1:27	17-Mar	/	/	/	/	X	X			Chain net links	Monitor
														Damaged post	Repaired by J&E on 16/3/2020
												Spring animal missing	Needs repair - J&E		
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	2:55	02-Mar	/	/	/	/	/	X		Slide leg loose in footing	Monitor	
														Low bark	Top - PCL
			1	7:00	17-Mar	/	/	/	/	/	X			Spring animal loose in footing	Monitor
												Angle bar missing at climbing net damaged	Needs repair - LAZ		
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	2:35	02-Mar	/	/	/	/	X	X		Border logs splitting	Monitor	
														Swing mounts/brackets worn	Monitor
			1	11:35	17-Mar	/	/	/	/	X	X			Concrete lifting quad hoop game	Monitor
															Chain net links / mounts worn
												Slide surface worn	Monitor		
57	KAMBAH PLGR 313	Attiwell Circ	1	7:33	03-Mar	/	/	/	/	X	X		Border logs damaged	Needs Repair PCL	
														Swing mounts worn/loose due to timber shrinking	Monitor
			1	7:35	17-Mar	/	/	/	/	X	X			Swing timber damage/splitting	Monitor
															Asphalt cracking / lifting
												See-saw footrest damaged	Monitor		
58	KAMBAH PLGR 314	Barritt St	1	7:18	03-Mar	/	/	/	/	/	X		Damaged flat swing	Monitor	
			1	7:27	17-Mar	/	/	/	/	/	X			Bridge plastic worn/ rusted	Monitor
													Welds cracked on chain net	Needs Repair - LAZ	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
										Fort panel movement	Monitor				
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	8:18	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Damaged plastic on stairs	Monitor	
			1	8:20	17-Mar	/	/	/	/	X	X	Rusting at bottom of stairs	Monitor		
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	1:12	02-Mar	/	/	/	/	X	X	Timber decking splitting	Monitor		
													Swing posts splitting and rotten	Monitor	
			1	1:55	16-Mar	/	/	/	/	/	X	X	Movement in ladder plate to decking	Monitor	
														Timber border lifting/damaged	Monitor
												Bark washed out	Needs Repair - PCL		
63	KAMBAH PLGR 317	Bullock Circ	1	7:47	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Rubber on stairs splitting	Monitor	
			1	7:51	17-Mar	/	/	/	/	/	X	X	Worn rubber on deck	Needs Repair LAZ	
														Climb chain/bridge links worn	Monitor
												Smoking sign pulled out	Needs repair J&E		
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 299	Coghill Cl	1	10:56	03-Mar	/	/	/	/	X	X	Swing mounts worn	Monitor		
														Border logs splitting	Monitor
			1	11:07	17-Mar	/	/	/	/	/	X	X	Carousel loose - movement in bearing	Monitor	
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	9:58	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor		
														Swing mounts worn	Monitor
			1	10:00	17-Mar	/	/	/	/	/	X	X	Decking plastic worn	Monitor	
														Low bark	Needs Top up - PCL
															flying fox handle/mount/links worn
												Bridge timber splitting	Monitor		



Name Of Inspector		Shane		Month of Inspection							Mar-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
													Bridge/climbing net links worn	Monitor		
66	KAMBAH PLGR 304	Dale Circ	1	9:02	03-Mar	/	/	/	/			X	X	Border sleepers splitting	Monitor	
															Decks rusty/ plastic peeling	Needs Repair LAZ
			1	9:18	17-Mar	/	/	/	/			X	X	Bridge rusty/ plastic worn	Monitor	
67	KAMBAH PLGR 291	Deuchar Cl												Swing brackets/mounts worn	Monitor	
			1	11:14	03-Mar	/	/	/	/			X	X	Decking plastic worn/surface rust	Monitor	
			1	11:20	17-Mar	/	/	/	/			X	X	Border sleepers splitting	Monitor	
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)												Swing mounts worn	Monitor	
			1	7:00	03-Mar	/	/	/	/			X	X	Border logs splitting	Monitor	
			1	7:14	17-Mar	/	/	/	/			X	X	Decking plastic worn	Monitor	
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)												Bushes worn on see saw	Needs Repair LAZ	
			1	1:59	02-Mar	/	/	/	/			X	X	Swing mounts worn	Monitor	
			1	2:48	16-Mar	/	/	/	/			X	X	Bark low	Needs top up - PCL	
70	KAMBAH PLGR 284	Gibbs Pl												Rocks missing on rock wall	Needs Repair PCL	
			1	12:58	02-Mar	/	/	/	/					Damaged bolt caps	Monitor	
			1	2:05	16-Mar	/	/	/	/							
71	KAMBAH PLGR 289	Horton Cl												Bridge timber splitting	Monitor	
			1	11:07	03-Mar	/	/	/	/			X	X	Knots and crosses cracking	Monitor	
			1	11:14	17-Mar	/	/	/	/			X	X	Bolt caps brittle/damaged on tower	Monitor	
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)												Chain net links worn	Monitor	
			1	1:44	02-Mar	/	/	/	/			X	X	Decking plastic worn/rusting	Needs Repair LAZ	
			1	2:34	16-Mar	/	/	/	/			X	X	Damaged/missing/loose border timber	Needs Repair - PCL	
													Parallel slide bar bent	Monitor		
													Wearing swing brackets	Monitor		
													Tyre swing tyre worn	Needs Repair J&E		
														Border sleepers splitting	Monitor	
														Bridge/ chain net links worn	Monitor	
														Border sleepers splitting	Monitor	
														Swing mounts/brackets worn	Monitor	



Name Of Inspector

Shane

Month of Inspection

Mar-20

73	KAMBAH PLGR 307	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
73	KAMBAH PLGR 307	Humble Court	1	1:35	16-Mar	/	/	/	/	/	X	Slide dented	Monitor		
													Low bark	Needs Repair - PCL	
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	8:02	03-Mar	/	/	/	/	/	X	Swing mounts/brackets worn	Monitor		
													Deck/bridge plastic worn	Monitor	
			1	8:05	17-Mar	/	/	/	/	/	/	X	Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	Lascelles Circ	1	1:22	02-Mar	/	/	/	/	X	X	Border Sleepers splitting	Monitor		
													See saw Top centre plate cracked	Needs Repair - LAZ	
			1	2:15	16-Mar	/	/	/	/	/	X	X	Low branches	Cut back - PCL	
														Bridge slats splitting/links worn/movement	Monitor
											Chain net links worn	Monitor			
											Decking plastic worn	Monitor			
76	KAMBAH PLGR 325	Learmonth Dr	1	8:29	03-Mar	/	/	/	/	X	X	Fort Timber panels worn/split	Monitor		
													Climb net ropes worn	Monitor	
			1	8:33	17-Mar	/	/	/	/	/	X	X	Timber posts splitting	Monitor	
														Rock wall missing rocks	Monitor
														Damaged bolt caps on equipment	Monitor
											Spring motorcycle panels worn	Monitor			
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	1	10:49	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			1	10:58	17-Mar	/	/	/	/	/	X	X	Burn marks on post / slide	Monitor	
														Fly fox handle broken off	Needs Repair J&E
											Bridge/Climb net links worn	Monitor			
											Bridge slats splitting/movement worn timber	Monitor			
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	10:28	03-Mar	/	/	/	/	/	X	Monitor all links in hosing	Monitor		
													Damaged rubber chain hose	Monitor	
			1	10:41	17-Mar	/	/	/	/	/	/	X	Bench seat slat damaged	Needs Repair PCL	
79	KAMBAH PLGR 314	Mannheim St	1	12:46	02-Mar	/	/	/	/	X	X	Border logs splitting	Monitor		
														Bridge slats splitting	Monitor
			1	1:45	16-Mar	/	/	/	/	/	X	X	Swing mounts worn	Monitor	
														Welds cracked at slide entry	Needs Repair - LAZ
											Bridge links worn	Monitor			



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

ID	KAMBAH PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
														Shane		
80	KAMBAH PLGR 285	Marconi Cres	1	1:33	02-Mar	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor		
														Gravel washed/weeds into bark	Needs Removal - PCL	
			1	2:24	16-Mar	/	/	/	/	/	/	/	X	Deck edge wear	Monitor	
															Spring bear loose in footing	Monitor
81	KAMBAH PLGR 308	Maxworthy St	1	10:39	03-Mar	/	/	/	/	/	/	X	Swing mounts worn	Monitor		
														Bark low	Needs Top up - PCL	
			1	10:50	17-Mar	/	/	/	/	/	/	/	X	Damaged spinner seats x 2	Needs Repair - J&E	
82	KAMBAH PLGR 292	McKillop Pl	1	9:30	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor			
			1	9:37	17-Mar	/	/	/	/	/	X	X	Swing seat/brackets worn	Monitor		
													Bridge/decks rusting	Monitor		
														Flat swing seat damaged	Monitor	
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	9:41	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															Slide has small dents	Monitor
			1	9:37	17-Mar	/	/	/	/	/	X	X	Split rubber on stairs	Monitor		
														Graffiti on panel	Needs Removal PCL	
84	KAMBAH PLGR 302	Pinkerton Circ	1	8:49	03-Mar	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL			
															Decking plastic worn/surface rust	Monitor
			1	8:53	17-Mar	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor		
																Low tree branches
														Exposed tree roots in bark	Needs removal- PCL	
														Bark low	Needs Top up - PCL	
85	KAMBAH PLGR 306	Primmer Court	1	2:20	02-Mar	/	/	/	/	/	/	/				
			1	2:58	16-Mar	/	/	/	/	/	/	/	/	New playground equipment installed	Has it been certified	
86	KAMBAH PLGR 303	Rounsevell St	1	8:40	03-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor			
															Swing mounts worn	Monitor
			1	8:42	17-Apr	/	/	/	/	/	X	X	Slide metal rusting/ dented	Monitor		
																spring animal footing loose
														Lap seat worn	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

ID	KAMBAH/PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
														MONDAY RUN		
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN													
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN													
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN													
90	KAMBAH PLGR 290	Toole Pl	1	9:16	03-Mar	/	/	/	/		X	X	Swing posts splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			1	9:27	17-Mar	/	/	/	/	/		X	X	Swing Mounts have small movement due to worn timber	Monitor	
															Bridge links worn	Monitor
															Climb net links/mounts worn	Monitor
															Slide loose at entry bracket	Monitor
91	KAMBAH PLGR 293	Vanzetti Cres											Star pickets in bark	Needs Removal PCL		
														Border sleepers splitting	Monitor	
			1	10:16	03-Mar	/	/	/	/	/		X	X	Border sleepers splitting	Monitor	
															Decking worn/rusting	Monitor
			1	10:30	17-Mar	/	/	/	/	/		X	X	Movement in stair footing	Monitor	
															Bridge plastic worn/rusting	Monitor
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN													
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	8:55	05-Mar	/	/	/	/		X	X	Decking worn	Monitor		
															Chain net links/mounts worn	Monitor
			1	11:14	19-Mar	/	/	/	/	/		X	X	Bent deck poles	Monitor	
															Border damaged/rotted	Needs Repair - PCL
												Worn timber on spring horse	Monitor			



Name Of Inspector		Shane		Month of Inspection							Mar-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
														Bark low	Needs Top up - PCL	
94	MONASH PLGR 252	Alabaster St	1	9:38	04-Mar	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
														Swing mounts/ links worn	Monitor	
			1	2:29	17-Mar	/	/	/	/	/	X	X	Bite marks in swing seat	Monitor		
															Damaged spiral ladder	Monitor
															Damaged tic tac toe	Monitor
													Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	1	9:17	04-Mar	/	/	/	/	/		X	Posts splitting and rotten	Monitor		
														Swing mounts/links/brackets worn	Monitor	
			1	2:11	17-Mar	/	/	/	/	/		X	Bridge mounts/chain worn	Needs Repair LAZ		
															Bridge timber splitting	Monitor
													Fibreglass damaged/cracking/worn on slides	Monitor		
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	9:25	04-Mar	/	/	/	/	/	X	X	Steering wheel bracket worn	Monitor		
															Border timber splitting/missing	Needs Repair - PCL
			1	1:55	17-Mar	/	/	/	/	/	X	X	Dirt washed into bark	Needs repair - PCL		
													Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	9:47	04-Mar	/	/	/	/	/		X	Swing mounts/ links worn	Monitor		
															Concrete stump at bench	Needs Removal - PCL
			1	2:29	17-Mar	/	/	/	/	/		X	Low hanging branches	Needs Removal - PCL		
													Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	1	9:07	04-Mar	/	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor		
															Concrete border lifting	Needs Repair PCL
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	10:02	04-Mar	/	/	/	/	/	X	X	Movement in swing crossbar	Monitor		
															Bridge links/mounts worn/movement	Monitor
			1	2:57	17-Mar	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
															Bent bar/cracked welds on bridge	Needs Repair - LAZ
													Bark low	Needs Top up - PCL		
													Bridge slats splitting / lichen	Monitor		
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	8:55	04-Mar	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor		
															Triangles worn plastic	Monitor
			1	12:45	17-Mar	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
													Spring animal crack in foot rest/head loose	Monitor		
101	OXLEY	Cuthbertson Cres	1	7:22	04-Mar	/	/	/	/	/		X	New timber border lifting	Monitor		
															Horse head splitting	Monitor



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

ID	PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
101	PLGR 256	(McKibbin Pl)	1	12:10	17-Mar	/	/	/	/	/	X	Damaged tyre swing	Monitor
102	OXLEY PLGR 255	Newman Morris Circ	1	7:00	04-Mar	/	/	/	/	X	X	Swing mounts worn	Monitor
												Bite marks in swing seat	Monitor
			1	11:55	17-Mar	/	/	/	/	X	X	Bark washing out	Needs repair PCL
												Border concrete damaged	Needs Repair PCL
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	11:59	05-Mar	/	/	/	/	X	X	Border sleepers damaged	Needs Repair J&E
												Deck plastic worn	Monitor
			1	8:52	19-Mar	/	/	/	/	X	X	Carousel rusting/loose in footing	Monitor
												Spring frog handle loose	Monitor
												Pod mounts worn (eyelet)	Needs repair - LAZ
104	RICHARDSON PLGR 258	Chauncy Cres	1	12:27	05-Mar	/	/	/	/	/	X	Decking plastic worn	Monitor
												Swing mounts worn	Monitor
			1	8:15	19-Mar	/	/	/	/	/	X	Cuts on slide (smoothed)	Monitor
105	RICHARDSON PLGR 259	Clift Cres	1	12:09	05-Mar	/	/	/	/	/	X	Obscene graffiti / damage on new concrete path	Needs Removal PCL
												Worn swing chains/mounts/movement in post	Monitor
			1	8:41	19-Mar	/	/	/	/	/	X	Bark low / dirt in bark	Top up bark - PCL
106	RICHARDSON PLGR 257	Vidal St	1	12:17	05-Feb	/	/	/	/	/	X	Decking plastic worn/rusting	Monitor
												Climb net mounts worn	Needs Repair LAZ
			1	8:29	19-Mar	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor
												Climb net links worn	Monitor
												Climb net bar bent	Monitor
												Tyre swing links worn	Monitor
												Bark low	Needs top up - PCL
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN										
108	THEODORE PLGR 265	Dyett Circ	1	1:44	05-Mar	/	/	/	/	X	X	Border sleepers splitting	Monitor
												Decking timber splitting	Monitor
			1	10:58	18-Mar	/	/	/	/	X	X	Chain net links worn	Monitor



Name Of Inspector

Shane

Month of Inspection

Mar-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
	MONDAY RUN														
109	THEODORE PLGR 262	Lawrence Wackett Cres													
110	THEODORE PLGR 261	Louis Loder St	1	1:51	05-Mar	/	/	/	/	X	X	Border logs splitting	Monitor		
													Decking timber splitting	Monitor	
			1	10:42	18-Mar	/	/	/	/	X	X	Slide fibreglass cracking/worn	Monitor		
													Chain net links worn	Monitor	
111	THEODORE PLGR 264	Scantleberry St										Bark low	Needs Top up - PCL		
			1	1:37	05-Mar	/	/	/	/	X	X	Border concrete broken/lifting	Needs Repair - PCL		
														Border logs splitting	Monitor
			1	11:14	18-Mar	/	/	/	/	X	X	Trees growing in bark	Needs Removal - PCL		
														Slide damaged at top	Monitor
														Spring animal timber worn	Monitor
112	WANNIASSA PLGR 270	Billson Pl										Decking timber/panel splitting	Monitor		
			1	7:53	04-Mar	/	/	/	/	/	X				
														Decking plastic worn	Monitor
			1	2:18	19-Mar	/	/	/	/	/	X	X	Bridge plastic worn	Needs Repair LAZ	
113	WANNIASSA PLGR 267	Bussau Cl										Damaged tic tac toe	Monitor		
														Worn rubber on spike spinner	Needs Repair J&E
			1	2:14	03-Mar	/	/	/	/	X	X	Decking timber worn	Monitor		
														Chain net links worn/plastic peeling	Monitor
			1	12:57	19-Mar	/	/	/	/	X	X	Damaged/rotting borders	Monitor		
														Concrete path lifting	Needs Repair PCL
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)													
			1	8:31	04-Mar	/	/	/	/	/	X	X	Decking plastic worn x 1	Needs Repair - LAZ	
														Swing mounts/brackets worn	Monitor
115	WANNIASSA PLGR 275	Hervey Pl													
			1	2:35	19-Mar	/	/	/	/	/	X	X	Grab handle loose	Monitor	
			1	7:31	04-Mar	/	/	/	/	X	X	Border sleepers/braces splitting	Needs Repair PCL		
														Decking plastic rust / peeling	Monitor
116	WANNIASSA	Tansell Circ	1	1:51	19-Mar	/	/	/	/	X	X	Smoking sign loose in footing	Needs Repair PCL		
														Swing seat damaged/mounts/links worn	Monitor
			1	2:00	03-Mar	/	/	/	/	X	X	Swing mounts worn	Monitor		
												Movement in spring animal	Monitor		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
116	PLGR 266	Lansen Circ	1	12:46	19-Mar	/	/	/	/	X	X	Border fence panels damaged	Monitor	
117	WANNIASSA PLGR 269	Sainsbury St	1	8:05	04-Mar	/	/	/	/	X	X	Border logs splitting	Monitor	
													Holes in shade sail	Monitor
			1	2:53	19-Mar	/	/	/	/	X	X	Burn marks on tic tac toe	Monitor	
													Bench seat slats damaged	Needs Repair PCL
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN											
119	WANNIASSA PLGR 276	Steinfeld Circ	1	2:49	03-Mar	/	/	/	/	X	X	Border Sleepers splitting	Monitor	
													Bench seat slats splitting	Monitor
			1	1:42	19-Mar	/	/	/	/	X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ	
													Decks worn x 2	Needs Repair - LAZ
													Bridge slats splitting	Monitor
													Bridge/Chain net links worn/plastic	Monitor
120	WANNIASSA PLGR 268	Sullivan Cres										Bearings / wheels damaged on fly fox trolley	Needs Repair J&E	
			1	8:21	04-Mar	/	/	/	/	X	X	Border logs splitting	Monitor	
													Bridge/chain links worn	Monitor
			1	2:44	19-Mar	/	/	/	/	X	X	Handle plastic worn on flying fox	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St										Swing seats/mounts worn/splitting	Monitor	
			1	2:36	03-Mar	/	/	/	/	X	X	Border sleepers damaged	Needs Repair - PCL	
													Swing mounts worn	Monitor
			1	1:30	19-Mar	/	/	/	/	X	X	Bridge timber splitting	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres										Park bench missing / damaged timber	Needs Repair - PCL	
			1	7:43	04-Mar	/	/	/	/	X	X	Decking worn/lichen growing	Monitor	
													Swing mounts/ links worn	Monitor
			1	2:08	19-Mar	/	/	/	/	X	X	Fireman pole damaged	Monitor	
123	WANNIASSA PLGR 272	Whiteman St										Roman triangles links worn plastic worn	Monitor	
													Chain net links worn	Monitor
			1	2:24	03-Mar	/	/	/	/	X	X	Swing mounts/s hooks/ chains worn	Monitor	
			1	1:04	19-Mar	/	/	/	/	X	X	Border logs splitting	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Shane		Month of Inspection				Mar-20			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report



Name Of Inspector

Shane

Month of Inspection

Mar-20

	Suburb	Street	Location	Type of Inspection		Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
				Level 1or	Level 2			/	x	/	x	/	x	/	x	/	x	/	x			/	x
1	COTTER PLGR 620	COTTER PICNIC GROUND	2	2:25	04-Mar	/		/		/		/		/		/		X		Checker plate on decking	Patched by Jason - Urban		
																					Awning luvvers mounts rusting	Monitor	
			1	2:15	18-Mar	/		/		/		/		/		/			X		Bridge mounts worn	Monitor	
																					Pommels links/mounts worn/ hosing split	Monitor	
																					Swing mounts/brackets worn	Monitor	
																						2 x tread caps missing on surfer	Monitor
																						Bridge metal slip hazard	Angle / monitor
																						Basketball backboard worn	Monitor
																						Climb chain mounts/links worn/hosing split	Monitor
																						Rubber soft fall worn	Monitor
2	COTTER PLGR 539	CASURINA SANDS	1	2:40	04-Mar	/		/		/		/		/		/		X		Cracked all access panel on ramp	Monitor		
																				Low bark	Top up bark - PCL		
																					Spring animal worn timber	Monitor	
3	GREENWAY PLGR 538	Pine Island Rd	1	9:26	02-Mar	/		/		/		/		/			X	X		Post timber splitting	Monitor		
			1	9:25	10-Mar	/		/		/		/		/			X	X		Decking timber splitting	Monitor		
			1	9:35	16-Mar	/		/		/		/		/			X	X		Rope bridge wearing	Monitor		
			2	11:47	23-Mar	/		/		/		/		/			X	X		Border logs splitting	Monitor		
			1	9:20	30-Mar	/		/		/		/		/			X	X		Climbing wall worn/rusting	Monitor		
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND																		Movement in staircase footing	Monitor		
																				Swing mounts/chains worn	Monitor		
																					Decks/bridge worn/rusting	Monitor	
																						Bark low	Needs Top up - PCL
			1	1:25	04-Mar	/		/		/		/		/			X	X			Fence timber splitting around water tanks	Monitor	
			1	1:05	18-Mar	/		/		/		/		/			X	X			Timber splitting on large spring platform	Monitor	
																					Water tanks decking timber splitting/worn	Monitor	
																			Flying fox posts splitting	Monitor			
																			Spider climb net rope frayed	Monitor			
																			Tree roots lifting paths	Needs Repair PCL			
																			Rubber soft fall splitting	Needs Repair PCL on going problem			
																			Timber seating at BBQ missing bolts	Needs Repair PCL			



CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Mar-20

	Suburb	Street	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Inspectors Signature: s.Conroy



Location Theodore Chippindal Cct

Time 11:37

Date 23/03/2020

Name Shane Conroy

Weather Overcast

Date Next Assessment

ITEM NO	BE ASSESSED For potential hazards	✓ x	ISSUE What is the Hazard	RISK L M H VH	REVIEW		
					What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS							
1.01	Good visibility for supervision, surrounds in good condition, no graffiti	/					
1.02	Bubblers and water features clean and fully operational	/					
1.03	Access ramps, pathways, entrances free of slipping & tripping hazards	/					
1.04	Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/					
1.05	Paths around playground clear of hazards cracks, trips, vegetation	/					
1.06	Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/					
1.07	Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	L	Monitor		
1.08	Gates closing & locking devices operational, no finger entrapments (>12mm)	/					
1.09	Access, entrance & ancillary items free of protrusions/sharp edges	/					
SURFACING							
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings							
2.01	Equipment, forced movement devices, and exposed footings	/					
2.02	Rubbish that may be hygiene issue removed	/					
2.03	Broken glass, rocks, foreign objects likely to cause injury removed	/					
2.04	Surface in good condition, no trip points	/					
2.05	Drainage operational, no contamination from runoff	/					
LOOSE FILL MATERIAL							
2.06	Check depth min 300mm-400mm, top up or rake as required	X	Low bark	M	Top up bark		PCL
2.07	Loose-fill containment edging / barrier secure, free of protrusions	/					
2.08	No material deterioration or contamination by clay or other matter	/					
SYNTHETIC MATERIAL							
2.09	Fouling of surface or chewing gum, foreign objects, rocks	/					
2.10	Joints, wear layer, impact attenuation layer or sub-base failure	/					
EQUIPMENT							
Platforms, Structures and frames							
3.01	Foundation and structures free of movement, rot or corrosion	/					
3.02	No water penetration into structure or fittings, bulging, corrosion	/					
3.03	Handrails, guardrails, barriers, decks, platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor		
3.04	Physical damage or missing parts, bolts, present and secure, vandalism	/					
3.05	Check end caps, bolts, screws, tube ends	/					
3.06	No cracked or damaged plastic or wood panels, no graffiti	/					
3.07	No protruding screws, nails, bolts, sharp edges, splintering or cracks	/					
3.08	Remove loose items brought into playground - ropes, rocks, sticks	/					
3.09	Equipment free from moss, mould, unhygienic matter - slip potential	/					
Chains, Ropes, Cables, Nets and Tyres							
3.10	Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/					
3.11	No fraying of ropes or cable (or ends) - Replace or remove	/					
3.12	Wear in chains & connectors <40%	/					
3.13	No entrapment hazards, no corrosion, no sharp edges	/					
Swings							
3.14	Check for squeaking bushes - lubricate/replace	/					
3.15	Swing action smooth & quiet, seat has no damage or vandalism	/					
3.16	Wear in chains & connectors <40%	X	Swing mounts/bushes worn	L	Monitor		
3.17	Check seat & pivot connections for tightness, s-hooks for closure	/					
3.18	Impact attenuating edge intact, no cracking or exposed metal components	/					
3.19	Drain holes in tyres clear, no exposed metal wire	/					
3.20	Seat clearance from ground min 400mm	/					
Slides							
3.21	No damage or foreign objects on slide bed/sides - exit wear area	/					
3.22	Structure slide & supports - stability, looseness, corrosion, splinters	/					
3.23	Runout section height <350mm (or 200mm up to 1500mm sliding section)	/					
3.24	No entrapments, sliding smooth, overlap of joints downwards	/					
Carousels (rotating equipment)							
3.25	Speed limited to 5m/s	/					
3.26	Smooth & quiet rotation (both directions), platform level & stable	/					
3.27	Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	L	Monitor		
3.28	Underside clear of protrusions & sharp edges	/					
Runways (flying foxes)							
3.29	Trolley motion smooth, no loose wire strands, speed limited to 7m/s	/					
3.30	End stops haven't moved they bring trolley to a controlled stop	/					
3.31	No loose/missing bolts, rot/corrosion (particularly at ground level)	/					
3.32	Cable secure, platform stable, seat/grip condition, clearance 400mm	/					
Seesaws & rocking equipment (Spring Animals)							
3.33	No looseness in movement or damage, missing bolts/handles	X	Loose handle/footings on spring animal x 2	L	Monitor		
3.34	No rot or corrosion, foundation movement, splintered timber	/					
Sandpits							
3.35	No ponding water, drainage issues or health hazards	/					
3.36	Sand pit edges and supports intact & secure	/					
3.37	Sand raked to remove foreign objects, fouling, glass	/					

RISK LEVEL ~ SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely) - Once every 100yrs
 2 Unlikely (Conceivable) - Once every 30 yrs
 3 Possible (Could occur) - Once every 10 yrs
 4 Likely (Almost certain) (On an annual basis)

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 3-5 Serious injury, possible long term absence from school
 -5 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 360:200 Risk Management.

NOTES

Empty space for notes.



Name Of Inspector **Shane** Month of Inspection **Apr-20**

Name Of Inspector		Shane		Month of Inspection												Apr-20				
Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action	
1	BANKS PLGR 413	Pocket Ave	1	10:15	06-Apr	/		/		/		/		X		X		Loose slide leg	Monitor	
			1	10:17	13-Apr	/		/		/		/		X		X		Chain net links/mounts worn	Monitor / Needs Repair LAZ	
			2	11:20	20-Apr	/		/		/		/		X		X				
			1	9:40	28-Apr	/		/		/		/		X		X		Border concrete cracking / lifting	Needs Repair PCL	
			1			/		/		/		/		X		X		Small plastic slide damaged	Monitor	
2	BONYTHON PLGR 535	Burgoyne St	1	9:40	06-Apr	/		/		/		/				X		Ropes worn on climb net	Monitor	
			1	9:33	13-Apr	/		/		/		/				X		Swing mounts worn	Monitor	
			2	10:23	20-Apr	/		/		/		/				X		Graffiti on fire truck	Needs Removal PCL	
			1	10:25	28-Apr	/		/		/		/				X		Collar pins worn	Monitor	
			1			/		/		/		/				X		Ropes worn on small single swing	Monitor	
3	FADDEN PLGR 228	Coyne St	1	11:15	06-Apr	/		/		/		/		X		X		Swing mounts worn	Monitor	
			1	11:00	13-Apr	/		/		/		/		X		X		Cracked welds on slide entry	Monitor	
			2	12:45	20-Apr	/		/		/		/		X		X		Worn links bridge/climb chains	Monitor	
			1	8:20	28-Apr	/		/		/		/		X		X		Timber split on panels	Monitor	
			1			/		/		/		/		X		X		Border logs splitting	Monitor	
																			Holes in softfall / splitting	Needs repair - PCL
																			Footpath lifting	Needs repair - PCL
																			Slide footing loose	Monitor
																			Spinning seesaw hanger has worn bolts/handle	Monitor
																			Hose splitting on chain covers	Monitor
4	GORDON PLGR 278	McGilvray Circ	1	10:05	06-Apr	/		/		/		/		X		X		Fibreglass on tea cup spinner cracking	Monitor	
			1	10:10	10-Apr	/		/		/		/		X		X		Swing mounts worn x 2	Needs Repair - J&E	
			1	9:00	13-Apr	/		/		/		/		X		X		Damaged see-saw brackets x 3	Needs Repair - J&E	
			1	8:55	17-Apr	/		/		/		/		X		X		Rope climb net worn 80%	Needs Repair - J&E	
			2	11:02	20-Apr	/		/		/		/		X		X		Spinner top bearings loose	Monitor	
			1	12:05	24-Apr	/		/		/		/		X		X		Damaged super nova	Monitor	
			1	10:10	28-Apr	/		/		/		/		X		X		Border logs splitting	Monitor	
			1			/		/		/		/		X		X		Roman triangles worn links	Needs repair - LAZ	
						/		/		/		/		X		X		Wire walk cable worn	Monitor	
																			Decking worn on tower	Monitor
																			Wire bridge mount worn/chain low links worn	Needs repair - LAZ
																			Cracked welds in tower/rust	Needs repair - LAZ
																			Rubber Soft fall splitting/holes	Needs repair - PCL
5	GOWRIE PLGR 328	Jeffries St	1	11:25	06-Apr	/		/		/		/				X		Softfall splitting / holes forming	Needs Repair PCL	
			1	11:30	13-Apr	/		/		/		/				X		Timber worn on carousel	Monitor	
			2	12:58	20-Apr	/		/		/		/				X		Spider net worn	Monitor	
			1	7:53	28-Apr	/		/		/		/				X				



Name Of Inspector **Shane** Month of Inspection **Apr-20**

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
							/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x		
				Level 1/2	Time	Date																	Hazard	Action								
18	THEODORE PLGR 263	Chippindall Circ		1	9:18	28-Apr	/		/		/		/		/		/		/		/		X				Loose handle/footings on spring animal x 2	Monitor				
				1			/		/		/		/		/		/		/		/		/		X	Tree branch stuck in shade sail	Needs Removal PCL					
																													Holes in shade sail	Monitor		
																													Low bark	Needs Top up - PCL		
19	THEODORE PLGR 262	Lawrence Wackett Cres		1	10:35	06-Apr	/		/		/		/									X	X	Weld cracking at slide entry	Needs Repair - LAZ							
				1	10:45	13-Apr	/		/		/		/											X	X	Decking plastic worn/surface rust	Monitor					
				2	11:50	20-Apr	/		/		/		/												X	X	Swing/Chain bridge links/mounts worn	Monitor				
				1	9:02	28-Apr	/		/		/		/												X	X	Movement in frog footing	Monitor				
				1			/		/		/		/												X	X	Border concrete cracking	Needs Repair - PCL				
20	WANNIASSA PLGR 271	Sangster Pl		1	11:40	06-Apr	/		/		/		/									X	X	Swing mounts brackets worn	Monitor							
				1	11:50	13-Apr	/		/		/		/											X	X	Decking worn	Monitor					
				2	1:24	20-Apr	/		/		/		/												X	X	Hole in chain wire fence	Needs Repair - LAZ				
				1	7:39	28-Apr	/		/		/		/												X	X	Park bench missing arm rest	Needs Repair - PCL				
				1			/		/		/		/												X	X	Holes and splitting in softfall	Needs repair - PCL				

Inspectors Signature: S.Conroy

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

	Suburb	Street	Type of Inspection	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
			Level 1or Level 2			Level 1/2	/	x	/	x	/	x	/	x	/	x	/			x	
1	BANKS PLGR 213	Menzies Court	1	10:41	15-Apr	/		/		/		/			X		X	Fort panel cracked/stairs damaged	Monitor		
																		Decking plastic worn/surface rust	Monitor		
			2	1:00	24-Apr	/		/		/		/				X		X			
																			Border concrete cracking	Monitor	
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																		
3	BANKS PLGR 212	Wilson Cres	1	10:50	15-Apr	/		/		/		/			X		X	Bench seat slats loose / missing bolts	Needs Repair PCL		
																		Swing seat brackets worn	Monitor		
			2	1:11	24-Apr	/		/		/		/				X		X	Decking worn	Monitor	
																			Dints in slide bed	Monitor	
																	Border concrete cracking	Needs Repair - PCL			
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1	9:05	15-Apr	/		/		/		/		/			X	Posts handrails split/rotting	Monitor		
																		4 x Post damaged/split on fort	Monitor		
			2	10:56	24-Apr	/		/		/		/		/				X	Chain net links and mounts worn	Monitor	
																			Swing mounts worn	Monitor	
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																		
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1	8:35	15-Apr	/		/		/		/			X		X	Border logs splitting	Monitor		
			2	10:35	24-Apr	/		/		/		/				X		X	Timber decking lifting / splitting	Needs Repair - J&E	
																		Slide has crack at entry/movement	Monitor		
7	BONYTHON PLGR 586	Morice Pl	1	8:46	15-Apr	/		/		/		/		/			X				
																				Swing seat brackets worn	Monitor
			2	10:45	24-Apr	/		/		/		/		/				X	Worn / missing rope on net	Monitor	
																		Worn links/mounts on pommel/ climb chain	Monitor		



Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
				/	/	/	/	/	/	/	/	X	X						
8	CALWELL PLGR 322	Beckett St	1	2:50	16-Apr	/	/	/	/	/	/	/	/	X		Decking plastic worn	Monitor		
																	Swing mounts worn	Monitor	
			2	10:20	23-Apr	/	/	/	/	/	/	/	/	/	X		Bent monkey bars	Monitor	
																		Slide weld cracking at top	Needs Repair - LAZ
																		Chain walk hand rail bent	Needs Repair - LAZ
																		Bent deck poles	Needs Repair - LAZ
															Low tree branches	Needs Removal PCL			
9	CALWELL PLGR 321	Casey Cres	1	2:13	16-Apr	/	/	/	/	/	/	/	X		Swing mounts worn	Monitor			
																Decking plastic worn/decks rusting	Monitor		
			2	9:30	23-Apr	/	/	/	/	/	/	/	/	X		Chain net links/coating on chains worn	Monitor		
															See saw timber splitting	Monitor			
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)	1	2:35	16-Apr	/	/	/	/	/	/	X	X		Decking plastic worn	Monitor			
																Swing mounts/seat/links worn	Monitor		
			2	10:05	23-Apr	/	/	/	/	/	/	/	X	X		Low branches	Needs cut back back-PCL		
															Side leg bent	Monitor			
11	CALWELL PLGR 319	Samuel Cl	1	2:18	16-Apr	/	/	/	/	/	/	X	X		Border logs splitting	Monitor			
																Swing mounts worn	Monitor		
			2	9:41	23-Apr	/	/	/	/	/	/	/	X	X		Bent monkey bars	Monitor		
															Park bench missing timber	Needs Repair - PCL			
12	CALWELL PLGR 644	Shopping Centre	1	2:06	16-Apr	/	/	/	/	/	/	/	X		Swing mounts/seat/S hooks worn	Monitor			
																	Bark low	Top up bark PCL	
			2	9:17	23-Apr	/	/	/	/	/	/	/	/	X					
															Carousel movement in bearing	Monitor			
13	CALWELL PLGR 320	Were St	1	2:25	16-Apr	/	/	/	/	/	/	X	X		Border logs splitting/ missing	Monitor			
																Swing links/mounts worn	Monitor		
			2	9:51	23-Apr	/	/	/	/	/	/	/	X	X		Tire worn on tyre swing	Monitor		
14	CHISHOLM PLGR 234	Alston St	1	1:38	16-Apr	/	/	/	/	/	/	/	X						
																Swing mounts worn	Monitor		
			2	2:43	22-Apr	/	/	/	/	/	/	/	/	X					
															Damaged tic tac toe	Monitor			
															Baby seat chain cover worn	Monitor			



Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
										Fly fox handle plastic worn	Monitor				
15	CHISHOLM PLGR 233	Dalyell St	1	1:44	16-Apr	/	/	/	/	/	X	Timber decking splitting	Needs repair - J&E		
													Tyre swing mounts worn	Monitor	
			2	2:49	22-Apr	/	/	/	/	/	/	X	Fly fox links worn	Monitor	
														Chain net mounts worn	Monitor
														Fly fox nylon guides worn	Needs Repair - J&E
16	CHISHOLM PLGR 232	Heagney Cres (Couchman Cr)	1	1:11	16-Apr	/	/	/	/	/	X	Timber decking splitting	Monitor		
													Track ride not gliding with ease	Needs Repair - J&E	
			2	2:14	22-Apr	/	/	/	/	/	/	X	Swing seat damaged/brackets/links worn	Monitor	
														Post loose in footing	Monitor
											Uneven paving around playground	Needs Repair PCL			
17	CHISHOLM PLGR 231	Deamer Cres (Next to bus stop)	1	1:22	16-Apr	/	/	/	/	/	X	Timber decking splitting	Monitor		
													Slide damaged at exit	Monitor	
			2	2:24	22-Apr	/	/	/	/	/	/	X	Log steps splitting	Monitor	
														Damaged park bench	Needs Repair - PCL
											Tyre /s hooks wearing on tire swing	Monitor			
											Graffiti on slide	Remove - PCL			
18	CHISHOLM PLGR 235	Kirkcaldie Circ	1	1:48	16-Apr	/	/	/	/	/	X	Swing mounts/links worn	Monitor		
													Decking plastic worn/rusting	Monitor	
			2	2:55	22-Apr	/	/	/	/	/	/	X	Climb net mounts/plastic worn	Monitor	
											Plastic at slide exit damaged	Needs Repair J&E			
19	CHISHOLM PLGR 230	Meeson St (Mofflin St)	1	1:30	16-Apr	/	/	/	/	/	X	Decking plastic worn	Monitor		
													Tyre swing mounts worn	Monitor	
			2	2:33	22-Apr	/	/	/	/	/	/	X	Climb net links worn	Monitor	
														Damaged park bench	Monitor
														Plastic panel damaged	Monitor
														Concrete border damaged	Needs repair - J&E
20	CHISHOLM PLGR 236	Proctor St	1	1:55	16-Apr	/	/	/	/	/	X	Swing mounts/links/seat worn	Monitor		
														Low bark	Needs top up - PCL
			2	3:01	22-Apr	/	/	/	/	/	/	X	Dints in slide	Monitor	
											Fly fox handle plastic worn	Monitor			
CONDER	Cramona Pl		1	11:37	15-Apr	/	/	/	/	/	X	X	Border pavers missing/loose	Needs Repair - J&E	
														Posts splitting and rotten in ground	Needs Repair - J&E



Name Of Inspector		Shane		Month of Inspection							Apr-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
21	CONDER PLGR 219	Ceremonial Pl (Landells Pl)	2	2:15	23-Apr	/	/	/	/	/	X	X	Decks/bridge timber split/damaged	Needs Repair - J&E		
														Ropes worn on climb net (fraying)	Monitor	
															Deck connection bolts worn/chain	Needs repair - LAZ
22	CONDER PLGR 222	Dixson Circ	1	11:14	15-Apr	/	/	/	/	/		X	Bark washed out	Needs Repair - PCL		
														Panels damaged/rusting	Monitor	
			2	2:45	24-Mar	/	/	/	/	/		X	Chain net/mounts worn	Monitor		
														Plastic panel/ tic tac damaged	Monitor	
23	CONDER PLGR 607	James Smith Circ	1	11:57	15-Apr	/	/	/	/	/		X	Swing/fort posts splitting/rot	Monitor		
														Climb net rope worn	Monitor	
			2	1:43	23-Apr	/	/	/	/	/		X	Decking/panels worn on cubby/spring animal/slide	Monitor		
24	CONDER PLGR 220	Montfiore Cres												Bark low	Needs Top up - PCL	
			1	11:26	15-Apr	/	/	/	/	/		X	X	Border logs splitting	Monitor	
															Climb net links/mounts worn	Monitor
			2	2:29	23-Apr	/	/	/	/	/		X	X	Bark low	Needs Top up - PCL	
															Bridge rail cracked	Needs repair - LAZ
25	CONDER PLGR 244	Russell Drysdale Cr (Daly Pl)												Movement in border sleepers	Monitor	
			1	11:46	15-Apr	/	/	/	/	/		X	Bridge plastic/ links worn	Monitor		
															Decking worn/rusting	Monitor
26	FADDEN PLGR 225	Bertram St (Riordan St)												Slide mount on deck rusting	Needs repair - LAZ	
			1	11:44	16-Apr	/	/	/	/	/	X	X	Bark washed out / dirt in bark	Needs repair - PCL		
															Decking plastic worn	Monitor
			2	12:50	22-Apr	/	/	/	/	/		X	X	Chain net links/ mounts worn	Monitor	
27	FADDEN PLGR 228	Coyne St												Tyre swing mounts/ links worn	Monitor	
															Border logs splitting	Monitor
															Border log damaged x 1	Needs Repair PCL
			MONDAY RUN													
			1	12:11	16-Apr	/	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor		
														Border timber damaged	Needs Repair PCL	



Name Of Inspector

Shane

Month of Inspection

Apr-20

ID	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report													
													Name Of Inspector	Shane	Month of Inspection	Apr-20									
28	FADDEN PLGR 224	2	1:15	22-Apr	/	/	/	/	/	/	X	X	Movement in carousel base	Monitor											
													Decking timber splitting	Monitor											
													Chain net links / mounts worn	Monitor											
													Lichen growing on decks	Monitor											
29	FADDEN PLGR 509	1	11:59	16-Apr	/	/	/	/	/	X	X	X	Rocks missing in border wall	Needs Repair - PCL											
													Rope bridge mount broken/rope worn	Needs Repair PCL											
													2	1:05	22-Apr	/	/	/	/	/	X	X	Climbing nets rope worn	Monitor	
																									Panel/ roof panels cracked on fort
30	FADDEN PLGR 229	2	12:18	16-Apr	/	/	/	/	/	X	X	X	Swing mounts/ links worn	Monitor											
													Damaged baby swing	Monitor											
													2	1:24	22-Apr	/	/	/	/	/	X	X	Border logs worn	Monitor	
																									Dent in parallel bars/swing post
	GILMORE	1	12:48	16-Apr	/	/	/	/	/	X	X	X	Concrete border damaged/lifting	Monitor											
													Rubber frog damaged	Monitor											
													1	1:55	22-Apr	/	/	/	/	/	X	X	Low bark	Needs Top up - PCL	
31	GILMORE PLGR 238	1	1:05	16-Apr	/	/	/	/	/	X	X	X	Fence damaged	Monitor											
													Spinner seats worn/ rusting	Monitor											
													2	2:02	22-Apr	/	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL	
32	GILMORE PLGR 239	1	12:54	16-Apr	/	/	/	/	/	/	/	X	Bridge timber splitting	Monitor											
													Concrete at bench lifting	Needs Repair PCL											
													2	1:48	22-Apr	/	/	/	/	/	/	/	X		
33	GORDON PLGR 215	1	9:32	15-Apr	/	/	/	/	/	/	/	X	Swing seat brackets worn	Monitor											
													Chain net/ladder links worn/plastic	Monitor											
													2	11:18	24-Apr	/	/	/	/	/	/	/	X	Damaged post caps x 4	Monitor
																									Slide damaged
34	GORDON DT GP 216	1	10:10	15-Apr	/	/	/	/	/	/	/	X	X	Swing seat brackets/mounts wearing	Monitor										
														Slide surface dented	Monitor										
														2	11:40	24-Apr	/	/	/	/	/	/	X	X	Dent in swing crosbar/see saw seat



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
42	GOWRIE PLGR 333	Middleton Circ	1	11:07	16-Apr	/	/	/	/	X	X	Swing mounts/ links worn	Monitor	
													Border concrete cracking	Monitor
			2	12:11	22-Apr	/	/	/	/	X	X			
43	GOWRIE PLGR 335	Weathers St	1	11:33	16-Apr	/	/	/	/		X	Swing mounts/links worn/rusty	Monitor	
													Slide dented	Monitor
			2	12:39	22-Apr	/	/	/	/	/	X			
44	GOWRIE PLGR 334	Wray Pl	1	11:22	16-Apr	/	/	/	/	X	X	Swing posts splitting	Monitor	
													Swing mounts/ links worn	Monitor
			2	12:32	22-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor	
												Concrete border cracked/lifting	Monitor	
45	GREENWAY PLGR 242	Anketell St	MONDAY RUN											
46	GREENWAY PLGR 240	De Little Circ PLAR 286	MONDAY RUN											
47	GREENWAY PLGR 417	Eileen Good St	MONDAY RUN											
48	GREENWAY PLGR 240	Florence Taylor St PLAR 288	MONDAY RUN											
49	GREENWAY PLGR 240	Mortimer Lewis Dr PLAR 807	MONDAY RUN											
50	GREENWAY PLGR 538	Pine Island Rd	MONDAY RUN / RURAL SHEET											



Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report					
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	1:10	14-Apr	/	/	/	/	X	X	Ropes worn on web	Monitor			
													Decks/Posts splitting/rotten	Monitor		
			2	7:47	23-Apr	/	/	/	/	/	X	X	Swing mounts/seat worn	Monitor		
														Concrete border lifting	Needs Repair PCL	
														Gaps were slide joints	Monitor	
												Swing timber splitting	Monitor			
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	12:35	14-Apr	/	/	/	/	/	X		Swing mounts worn	Monitor		
			2	7:00	23-Apr	/	/	/	/	/	X		Plastic slide cracked	Monitor		
														Movement in swing posts	Monitor	
														Frog plastic worn around handle	Monitor	
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	12:45	14-Apr	/	/	/	/	X	X		Border path concrete cracking	Monitor		
														Slide surface worn	Monitor	
			2	7:30	24-Apr	/	/	/	/	/	X	X		Chain net links	Monitor	
														Damaged post	Repaired by J&E on 16/3/2020	
												Spring animal missing	Needs repair - J&E			
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	7:00	08-Apr	/	/	/	/	/	X		Slide leg loose in footing	Monitor		
														Low bark	Top - PCL	
			2	8:48	21-Apr	/	/	/	/	/	X	X		Spring animal loose in footing	Monitor	
												Angle bar missing at climbing net damaged	Needs repair - LAZ			
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	2:59	06-Apr	/	/	/	/	X	X		Border logs splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			2	2:55	20-Apr	/	/	/	/	/	X	X		Concrete lifting quad hoop game	Monitor	
															Chain net links / mounts worn	Monitor
															Slide surface worn	Monitor
57	KAMBAH PLGR 313	Attiwell Circ	1	7:45	08-Apr	/	/	/	/	X	X		Border logs damaged	Needs Repair PCL		
														Swing mounts worn/loose due to timber shrinking	Monitor	
			2	9:30	21-Apr	/	/	/	/	/	X	X				
															Swing timber damage/splitting	Monitor
															Asphalt cracking / lifting	Needs Repair PCL
												See-saw footrest damaged	Monitor			
58	KAMBAH PLGR 314	Barritt St	1	7:38	08-Apr	/	/	/	/	/	X		Damaged flat swing	Monitor		
														Bridge plastic worn/ rusted	Monitor	
			2	9:13	21-Apr	/	/	/	/	/	X	X		Welds cracked on chain net	Needs Repair - LAZ	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
										Fort panel movement	Monitor				
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	8:47	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			2	10:22	21-Apr	/	/	/	/	X	X	Damaged plastic on stairs Rusting at bottom of stairs	Monitor Monitor		
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	12:47	06-Apr	/	/	/	/	X	X	Timber decking splitting	Monitor		
													Swing posts splitting and rotten	Monitor	
			2	1:56	21-Apr	/	/	/	/	X	X	Movement in ladder plate to decking	Monitor		
													Timber border lifting/damaged	Monitor	
												Bark washed out	Needs Repair - PCL		
63	KAMBAH PLGR 317	Bullock Circ	1	8:15	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Rubber on stairs splitting	Monitor	
			2	9:59	21-Apr	/	/	/	/	X	X	Worn rubber on deck	Needs Repair LAZ		
													Climb chain/bridge links worn	Monitor	
												Smoking sign pulled out	Repaired by J&E on 8/4/2020		
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 299	Coghill Cl	1	11:18	08-Apr	/	/	/	/	X	X	Swing mounts worn	Monitor		
													Border logs splitting	Monitor	
			2	1:28	21-Apr	/	/	/	/	X	X	Carousel loose - movement in bearing	Monitor		
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	10:23	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Swing mounts worn	Monitor	
			2	12:15	21-Apr	/	/	/	/	X	X	Decking plastic worn	Monitor		
														Low bark	Needs Top up - PCL
														flying fox handle/mount/links worn	Monitor
												Bridge timber splitting	Monitor		



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
										Bridge/climbing net links worn	Monitor			
66	KAMBAH PLGR 304	Dale Circ	1	9:35	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor	
													Decks rusty/ plastic peeling	Needs Repair LAZ
			2	11:16	21-Apr	/	/	/	/	X	X	Bridge rusty/ plastic worn	Monitor	
												Swing brackets/mounts worn	Monitor	
67	KAMBAH PLGR 291	Deuchar Cl	1	11:32	08-Apr	/	/	/	/	X	X	Decking plastic worn/surface rust	Monitor	
													Border sleepers splitting	Monitor
			2	1:44	21-Apr	/	/	/	/	X	X	Swing mounts worn	Monitor	
												Damaged post collars	Monitor	
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	7:26	08-Apr	/	/	/	/	X	X	Border logs splitting	Monitor	
													Decking plastic worn	Monitor
			1	9:00	21-Apr	/	/	/	/	X	X	Bushes worn on see saw	Needs Repair LAZ	
												Swing mounts worn	Monitor	
												Bark low	Needs top up - PCL	
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	2:24	06-Apr	/	/	/	/	X	X	Rocks missing on rock wall	Needs Repair PCL	
													Damaged bolt caps	Monitor
			2	2:48	21-Apr	/	/	/	/	X	X			
												Bridge timber splitting	Monitor	
70	KAMBAH PLGR 284	Gibbs Pl	1	1:05	06-Apr	/	/	/	/		X	X	Knots and crosses cracking	Monitor
														Bolt caps brittle/damaged on tower
			2	2:06	21-Apr	/	/	/	/		X			
71	KAMBAH PLGR 289	Horton Cl	1	11:24	08-Apr	/	/	/	/	X	X	Chain net links worn	Monitor	
													Decking plastic worn/rusting	Needs Repair LAZ
			2	1:34	21-Apr	/	/	/	/	X	X	Damaged/missing/loose border timber	Needs Repair - PCL	
												Parallel slide bar bent	Monitor	
												Wearing swing brackets	Monitor	
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	1	2:16	06-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			2	2:39	21-Apr	/	/	/	/	X	X			
												Bridge/ chain net links worn	Monitor	
			1	12:28	06-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor	
												Swing mounts/brackets worn	Monitor	

KAMBAH

Name Of Inspector

Shane

Month of Inspection

Apr-20

73	KAMBAH PLGR 307	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
73	KAMBAH PLGR 307	Humble Court	2	2:20	20-Apr	/	/	/	/	/	X	Slide dented	Monitor				
													Low bark	Needs Repair - PCL			
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	8:25	08-Apr	/	/	/	/	/	X	Swing mounts/brackets worn	Monitor				
													Deck/bridge plastic worn	Monitor			
			2	10:14	21-Apr	/	/	/	/	/	/	X	Handle loose on turtle	Monitor			
75	KAMBAH PLGR 286	Lascelles Circ	1	1:17	06-Apr	/	/	/	/		X	Border Sleepers splitting	Monitor				
													See saw Top centre plate cracked	Needs Repair - LAZ			
			2	2:17	21-Apr	/	/	/	/	/	X	Low branches	Cut back - PCL				
														Bridge slats splitting/links worn/movement	Monitor		
														Chain net links worn	Monitor		
76	KAMBAH PLGR 325	Learmonth Dr										Decking plastic worn	Monitor				
			1	9:04	08-Apr	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor			
														Climb net ropes worn	Monitor		
			2	10:36	21-Apr	/	/	/	/	/		X	X	Timber posts splitting	Monitor		
															Rock wall missing rocks	Monitor	
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)											Damaged bolt caps on equipment	Monitor			
															Spring motorcycle panels worn	Monitor	
			1	11:10	08-Apr	/	/	/	/	/		X	X	Border sleepers splitting	Monitor		
			2	1:16	21-Apr	/	/	/	/	/		X	X	Bum marks on post / slide	Monitor		
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)											Bridge/Climb net links worn	Monitor			
															Bridge slats splitting/movement worn timber	Monitor	
			1	10:45	08-Apr	/	/	/	/	/	/		X	Monitor all links in hosing	Monitor		
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)											Damaged rubber chain hose	Monitor			
			2	12:45	21-Apr	/	/	/	/	/		X	Bench seat slat damaged	Needs Repair PCL			
79	KAMBAH PLGR 314	Mannheim St															
			1	12:38	06-Apr	/	/	/	/		X	X	Border logs splitting	Monitor			
															Bridge slats splitting	Monitor	
			2	2:35	20-Apr	/	/	/	/	/		X	X	Swing mounts worn	Monitor		
79	KAMBAH PLGR 314	Mannheim St											Welds cracked at slide entry	Needs Repair - LAZ			
															Bridge links worn	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector **Shane** Month of Inspection **Apr-20**

ID	KAMBAH PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground Inspection Criteria										Action Taken- For full details please refer to attached Playground Safety Inspection Report
						Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description				
80	KAMBAH PLGR 285	Marconi Cres	1	1:31	06-Apr	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor		
														Gravel washed/weeds into bark	Needs Removal - PCL	
			2	2:24	21-Apr	/	/	/	/	/	/	X	Deck edge wear	Monitor		
												Spring bear loose in footing	Monitor			
81	KAMBAH PLGR 308	Maxworthy St	1	10:55	08-Apr	/	/	/	/	/	X	Swing mounts worn	Monitor			
													Bark low	Needs Top up - PCL		
			2	12:30	21-Apr	/	/	/	/	/	X	Damaged spinner seats x 2	Needs Repair - J&E			
82	KAMBAH PLGR 292	McKillop Pl	1	9:58	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor			
			2	11:53	21-Apr	/	/	/	/	/	X	X	Swing seat/brackets worn	Monitor		
												Bridge/decks rusting	Monitor			
												Flat swing seat damaged	Monitor			
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	10:07	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor			
														Slide has small dents	Monitor	
			2	12:05	21-Apr	/	/	/	/	/	X	X	Split rubber on stairs	Monitor		
												Graffiti on panel	Needs Removal PCL			
84	KAMBAH PLGR 302	Pinkerton Circ	1	9:25	08-Apr	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL			
														Decking plastic worn/surface rust	Monitor	
			2	10:58	21-Apr	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor		
														Low tree branches	Needs removal- PCL	
												Exposed tree roots in bark	Needs removal- PCL			
												Bark low	Needs Top up - PCL			
85	KAMBAH PLGR 306	Primmer Court	1	2:44	06-Apr	/	/	/	/	/	/					
			2	2:58	21-Apr	/	/	/	/	/	/	/		New playground equipment installed	Has it been certified	
86	KAMBAH PLGR 303	Rounsevell St	1	9:14	08-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor			
														Swing mounts worn	Monitor	
			2	10:48	21-Apr	/	/	/	/	/	X	X	Slide metal rusting/ dented	Monitor		
														spring animal footing loose	Monitor	
												Lap seat worn	Monitor			



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN											
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN											
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN											
90	KAMBAH PLGR 290	Toole Pl	1	9:46	08-Apr	/	/	/	/	X	X	Swing posts splitting	Monitor	
													Swing mounts/brackets worn	Monitor
			2	11:37	21-Apr	/	/	/	/	X	X	Swing Mounts have small movement due to worn timber	Monitor	
													Bridge links worn	Monitor
													Climb net links/mounts worn	Monitor
													Slide loose at entry bracket	Monitor
91	KAMBAH PLGR 293	Vanzetti Cres	1	10:35	08-Apr	/	/	/	/	X	X	Star pickets in bark	Needs Removal PCL	
													Border sleepers splitting	Monitor
			2	12:33	21-Apr	/	/	/	/	X	X	Decking worn/rusting	Monitor	
													Movement in stair footing	Monitor
													Bridge plastic worn/rusting	Monitor
													Swing mounts/brackets worn	Monitor
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN											
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	12:35	16-Apr	/	/	/	/	X	X	Decking worn	Monitor	
													Chain net links/mounts worn	Monitor
			2	1:36	22-Apr	/	/	/	/	X	X	Bent deck poles	Monitor	
													Border damaged/rotted	Needs Repair - PCL
											Worn timber on spring horse	Monitor		



Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
										Bark low	Needs Top up - PCL				
94	MONASH PLGR 252	Alabaster St	1	10:18	16-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Swing mounts/ links worn	Monitor	
			2	11:10	14-Mar	/	/	/	/	/	X	X	Bite marks in swing seat	Monitor	
														Damaged spiral ladder	Monitor
														Damaged tic tac toe	Monitor
											Worn/rusting bridge	Monitor			
95	MONASH PLGR 248	Charleston St	1	9:47	16-Apr	/	/	/	/	/	X	Posts splitting and rotten	Monitor		
													Swing mounts/links/brackets worn	Monitor	
			1	10:40	22-Apr	/	/	/	/	/	X	X	Bridge mounts/chain worn	Needs Repair LAZ	
														Bridge timber splitting	Monitor
											Fibreglass damaged/cracking/worn on slides	Monitor			
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	9:59	16-Apr	/	/	/	/	X	X	Steering wheel bracket worn	Monitor		
														Border timber splitting/missing	Needs Repair - PCL
			2	10:55	22-Apr	/	/	/	/	X	X	X	Dirt washed into bark	Needs repair - PCL	
												Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	10:27	16-Apr	/	/	/	/	/	X	Swing mounts/ links worn	Monitor		
														Concrete stump at bench	Needs Removal - PCL
			2	11:25	22-Apr	/	/	/	/	/	X	X	Low hanging branches	Needs Removal - PCL	
												Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	1	9:30	16-Apr	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor		
														Concrete border lifting	Needs Repair PCL
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	10:47	16-Apr	/	/	/	/	X	X	Movement in swing crossbar	Monitor		
														Bridge links/mounts worn/movement	Monitor
			2	11:43	22-Apr	/	/	/	/	/	X	X	Swing mounts worn	Monitor	
														Bent bar/cracked welds on bridge	Needs Repair - LAZ
												Bark low	Needs Top up - PCL		
												Bridge slats splitting / lichen	Monitor		
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	9:20	16-Apr	/	/	/	/	/	X	Decking plastic worn/rusting	Monitor		
														Triangles worn plastic	Monitor
			2	10:06	22-Apr	/	/	/	/	/	X	X	Swing mounts/brackets worn	Monitor	
												Spring animal crack in foot rest/head loose	Monitor		
101	OXLEY	Cuthbertson Cres	1	12:00	08-Apr	/	/	/	/	/	X	New timber border lifting	Monitor		
														Horse head splitting	Monitor



Name Of Inspector

Shane

Month of Inspection

Apr-20

ID	PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
101	PLGR 256	(McKibbin Pl)	2	7:18	22-Apr	/	/	/	/	/	X	Damaged tyre swing	Monitor		
102	OXLEY PLGR 255	Newman Morris Circ	1	11:50	08-Apr	/	/	/	/	X	X	Swing mounts worn	Monitor		
													Bite marks in swing seat	Monitor	
			2	7:25	22-Apr	/	/	/	/	X	X	Bark washing out	Needs repair PCL		
											Border concrete damaged	Needs Repair PCL			
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	2:33	14-Apr	/	/	/	/	X	X	Border sleepers damaged	Needs Repair J&E		
													Deck plastic worn	Monitor	
			2	8:07	23-Apr	/	/	/	/	X	X	Carousel rusting/loose in footing	Monitor		
											Spring frog handle loose	Monitor			
												Pod mounts worn (eyelet)	Needs repair - LAZ		
104	RICHARDSON PLGR 258	Chauncy Cres	1	1:50	14-Apr	/	/	/	/	/	X	Decking plastic worn	Monitor		
													Swing mounts worn	Monitor	
			2	8:55	23-Apr	/	/	/	/	/	X	Cuts on slide (smoothed)	Monitor		
											Star picks in bark	Needs removal - PCL			
105	RICHARDSON PLGR 259	Clift Cres	1	2:18	14-Apr	/	/	/	/	/	X	Worn swing chains/mounts/movement in post	Monitor		
			2	8:33	23-Apr	/	/	/	/	/	X	Bark low / dirt in bark	Top up bark - PCL		
106	RICHARDSON PLGR 257	Vidal St	1	2:05	14-Apr	/	/	/	/	/	X	Decking plastic worn/rusting	Monitor		
													Climb net mounts worn	Needs Repair LAZ	
			2	8:46	23-Apr	/	/	/	/	/	X	Damaged spring animal foot rest	Monitor		
														Climb net links worn	Monitor
														Climb net bar bent	Monitor
											Tyre swing links worn	Monitor			
												Bark low	Needs top up - PCL		
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN												
108	THEODORE PLGR 265	Dyett Circ	1	12:23	15-Apr	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Decking timber splitting	Monitor	
			2	1:20	23-Apr	/	/	/	/	X	X	Chain net links worn	Monitor		



Name Of Inspector

Shane

Month of Inspection

Apr-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
	MONDAY RUN													
109	THEODORE PLGR 262	Lawrence Wackett Cres												
110	THEODORE PLGR 261	Louis Loder St	1	12:14	15-Apr	/	/	/	/	X	X	Border logs splitting	Monitor	
													Decking timber splitting	Monitor
			2	1:30	23-Apr	/	/	/	/	X	X	Slide fibreglass cracking/worn	Monitor	
													Chain net links worn	Monitor
											Bark low	Needs Top up - PCL		
111	THEODORE PLGR 264	Scantleberry St	1	12:38	15-Apr	/	/	/	/	X	X	Border concrete broken/lifting	Needs Repair - PCL	
													Border logs splitting	Monitor
			2	1:10	23-Apr	/	/	/	/	X	X	Trees growing in bark	Needs Removal - PCL	
													Slide damaged at top	Monitor
													Spring animal timber worn	Monitor
													Decking timber/panel splitting	Monitor
											Chain net links worn	Monitor		
112	WANNIASSA PLGR 270	Billson Pl	1	7:33	16-Apr	/	/	/	/	/	X			
													Decking plastic worn	Monitor
			2	8:20	22-Apr	/	/	/	/	/	X		Bridge plastic worn	Needs Repair LAZ
														Damaged tic tac toe
												Worn rubber on spike spinner	Needs Repair J&E	
113	WANNIASSA PLGR 267	Bussau Cl	1	8:53	16-Apr	/	/	/	/	X	X	Decking timber worn	Monitor	
													Chain net links worn/plastic peeling	Monitor
			2	9:35	22-Apr	/	/	/	/	X	X	Damaged/rotting borders	Monitor	
														Concrete path lifting
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	8:14	16-Apr	/	/	/	/	/	X	Decking plastic worn x 1	Needs Repair - LAZ	
													Swing mounts/brackets worn	Monitor
			2	8:58	22-Apr	/	/	/	/	/	X			Grab handle loose
115	WANNIASSA PLGR 275	Hervey Pl	1	7:00	16-Apr	/	/	/	/	X	X	Border sleepers/braces splitting	Needs Repair PCL	
													Decking plastic rust / peeling	Monitor
			2	7:50	22-Apr	/	/	/	/	X	X	Smoking sign loose in footing	Needs Repair PCL	
														Swing seat damaged/mounts/links worn
116	WANNIASSA	Tansell Circ	1	9:15	16-Apr	/	/	/	/	X	X	Swing mounts worn	Monitor	
														Movement in spring animal



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
110	PLGR 266	Lansen Circ	2	9:47	22-Apr	/	/	/	/	X	X	Border fence panels damaged	Monitor	
												Damaged baby safety clip	Repaired by J&E on 16/4/2020	
117	WANNIASSA PLGR 269	Sainsbury St	1	7:45	16-Apr	/	/	/	/	X	X	Border logs splitting	Monitor	
													Holes in shade sail	Monitor
			2	8:31	22-Apr	/	/	/	/	X	X	Burn marks on tic tac toe	Monitor	
											Bench seat slats damaged	Needs Repair PCL		
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN											
119	WANNIASSA PLGR 276	Steinfeld Circ	1	8:34	16-Apr	/	/	/	/	X	X	Border Sleepers splitting	Monitor	
													Bench seat slats splitting	Monitor
			2	9:18	22-Apr	/	/	/	/	X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ	
													Decks worn x 2	Needs Repair - LAZ
													Bridge slats splitting	Monitor
										Bridge/Chain net links worn/plastic	Monitor			
											Bearings / wheels damaged on fly fox trolley	Needs Repair J&E		
120	WANNIASSA PLGR 268	Sullivan Cres	1	7:59	16-Apr	/	/	/	/	X	X	Border logs splitting	Monitor	
													Bridge/chain links worn	Monitor
			2	8:51	22-Apr	/	/	/	/	X	X	Handle plastic worn on flying fox	Monitor	
											Swing seats/mounts worn/splitting	Monitor		
0:00	WANNIASSA PLGR 277	Watkins St	1	8:22	16-Apr	/	/	/	/	X	X	Border sleepers damaged	Needs Repair - PCL	
													Swing mounts worn	Monitor
			2	9:10	22/4/1020	/	/	/	/	X	X	Bridge timber splitting	Monitor	
											Park bench missing / damaged timber	Needs Repair - PCL		
											Decking worn/lichen growing	Monitor		
122	WANNIASSA PLGR 274	Wheeler Cres	1	7:16	16-Apr	/	/	/	/	X	X	Decking worn / rusting	Monitor	
													Swing mounts/ links worn	Monitor
			2	8:01	22-Apr	/	/	/	/	X	X	Fireman pole damaged	Monitor	
													Roman triangles links worn plastic worn	Monitor
											Chain net links worn	Monitor		
123	WANNIASSA PLGR 272	Whiteman St	1	8:41	16-Apr	/	/	/	/	X	X	Swing mounts/s hooks/ chains worn	Monitor	
			2	9:25	22-Apr	/	/	/	/	X	X	Border logs splitting	Monitor	



Tuggeranong
Playground Inspection
Report 2019

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Shane		Month of Inspection					Apr-20			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	



Name Of Inspector

Shane

Month of Inspection

Apr-20

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
							/	x	/	x	/	x	/	x	/	x	/	x			/	x	/	x
				Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action				
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	2:00	15-Apr	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban				
																				Awning luvvers mounts rusting	Monitor			
			2	2:20	24-Apr	/		/		/		/		/					X	Bridge mounts worn	Monitor			
																					Pommels links/mounts worn/ hosing split	Monitor		
																					Swing mounts/brackets worn	Monitor		
																						2 x tread caps missing on surfer	Monitor	
																						Bridge metal slip hazard	Angle / monitor	
																						Basketball backboard worn	Monitor	
																						Climb chain mounts/links worn/hosing split	Monitor	
																						Rubber soft fall worn	Monitor	
																			Cracked all access panel on ramp	Monitor				
																			Low bark	Top up bark - PCL				
																			Spring animal worn timber	Monitor				
2	COTTER PLGR 539	CASURINA SANDS	1	2:35	15-Apr	/		/		/		/		/				X	Post timber splitting	Monitor				
																				Decking timber splitting	Monitor			
			2	2:40	24-Apr	/		/		/		/		/					X	Rope bridge wearing	Monitor			
3	GREENWAY PLGR 538	Pine Island Rd	1	9:30	06-Apr	/		/		/		/				X	X	Border logs splitting	Monitor					
			1	9:35	13-Apr	/		/		/		/				X	X	Climbing wall worn/rusting	Monitor					
			2	10:02	20-Apr	/		/		/		/				X	X	Movement in staircase footing	Monitor					
			1	10:40	28-Apr	/		/		/		/				X	X	Swing mounts/chains worn	Monitor					
			1			/		/		/		/				X	X							
																						Decks/bridge worn/rusting	Monitor	
																			Bark low	Needs Top up - PCL				
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	1	1:20	15-Apr	/		/		/		/				X	X	Fence timber splitting around water tanks	Monitor					
																					Timber splitting on large spring platform	Monitor		
			2			/		/		/		/					X	X	Water tanks decking timber splitting/worn	Monitor				
																						Flying fox posts splitting	Monitor	
																						Spider climb net rope frayed	Monitor	
																							Tree roots lifting paths	Needs Repair PCL
																							Rubber soft fall splitting	Needs Repair PCL on going problem
																							Timber seating at BBQ missing bolts	Needs Repair PCL
																				Reserve shut due to Covid-19	15/04/2020			



CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Shane

Month of Inspection

Apr-20

	Suburb	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
						/	x	/	x	/	x	/	x	/	x				
		Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8. Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Inspectors Signature: s.Conroy



PLAYGROUND INSPECTIONS REPAIR REQUEST

Work Order Number _____ PLGR No. 266

Suburb Wanniassa Address Lansell circ

Insp Date 16/04/2020 Insp Time 9:05 Bark low No

Problem Damaged baby safety clip - needs repair J&E

Action Taken Replaced Baby seat

Inspectors Name Shane Signature S.Conroy



Location Theodore Chippindal Cct

Time 10 45

Date 25/05/2020

Name James Gardner

Weather Sunny

Date Next Assessment

ITEM NO	BE ASSESSED For potential hazards	ISSUE What is the Hazard	RISK L M H VH	REVIEW		
				What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS						
1.01	Good visibility for supervision, surrounds in good condition, no graffiti	/				
1.02	Bubblers and water features clean and fully operational	/				
1.03	Access ramps, pathways, entrances free of slipping & tripping hazards	/				
1.04	Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/				
1.05	Paths around playground clear of hazards cracks, trips, vegetation	/				
1.06	Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/				
1.07	Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	L	Monitor	
1.08	Gates closing & locking devices operational, no finger entrapments (>12mm)	/				
1.09	Access, entrance & ancillary items free of protrusions/sharp edges	/				
SURFACING						
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings						
2.01	Play equipment, forced movement devices, and exposed footings	/				
2.02	Rubbish that may be hygiene issue removed	/				
2.03	Broken glass, rocks, foreign objects likely to cause injury removed	/				
2.04	Surface in good condition, no trip points	/				
2.05	Drainage operational, no contamination from runoff	/				
LOOSE FILL MATERIAL						
2.06	Check depth min 300mm-400mm, top up or rake as required	X	Low bark	M	Top up bark	PCL
2.07	Loose-fill containment edging / barrier secure, free of protrusions	/				
2.08	No material deterioration or contamination by clay or other matter	/				
SYNTHETIC MATERIAL						
2.09	Fouling of surface or chewing gum, foreign objects, rocks	/				
2.10	Joints, wear layer, impact attenuation layer or sub-base failure	/				
EQUIPMENT						
Platforms, Structures and frames						
3.01	Foundation and structures free of movement, rot or corrosion	/				
3.02	No water penetration into structure or fittings, bulging, corrosion	/				
3.03	Handrails, guardrails, barriers, decks, platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor	
3.04	Physical damage or missing parts, bolts, present and secure, vandalism	/				
3.05	Check end caps, bolts, screws, tube ends	/				
3.06	No cracked or damaged plastic or wood panels, no graffiti	/				
3.07	No protruding screws, nails, bolts, sharp edges, splintering or cracks	/				
3.08	Remove loose items brought into playground - ropes, rocks, sticks	/				
3.09	Equipment free from moss, mould, unhygienic matter - slip potential	/				
Chains, Ropes, Cables, Nets and Tyres						
3.10	Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/				
3.11	No fraying of ropes or cable (or ends) - Replace or remove	/				
3.12	Wear in chains & connectors <40%	/				
3.13	No entrapment hazards, no corrosion, no sharp edges	/				
Swings						
3.14	Check for squeaking bushes - lubricate/replace	/				
3.15	Swing action smooth & quiet, seat has no damage or vandalism	/				
3.16	Wear in chains & connectors <40%	X	Swing mounts/bushes worn	L	Monitor	
3.17	Check seat & pivot connections for tightness, s-hooks for closure	/				
3.18	Impact attenuating edge intact, no cracking or exposed metal components	/				
3.19	Drain holes in tyres clear, no exposed metal wire	/				
3.20	Seat clearance from ground min 400mm	/				
Slides						
3.21	No damage or foreign objects on slide bed/sides - exit wear area	/				
3.22	Structure slide & supports - stability, looseness, corrosion, splinters	/				
3.23	Runout section height <350mm (or 200mm up to 1500mm sliding section)	/				
3.24	No entrapments, sliding smooth, overlap of joints downwards	/				
Carousels (rotating equipment)						
3.25	Speed limited to 5m/s	/				
3.26	Smooth & quiet rotation (both directions), platform level & stable	/				
3.27	Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	M	Monitor	
3.28	Underside clear of protrusions & sharp edges	/				
Runways (flying foxes)						
3.29	Trolley motion smooth, no loose wire strands, speed limited to 7m/s	/				
3.30	End stops haven't moved they bring trolley to a controlled stop	/				
3.31	No loose/missing bolts, rot/corrosion (particularly at ground level)	/				
3.32	Is cable secure, platform stable, seat/grip condition, clearance 400mm	/				
Seesaws & rocking equipment (Spring Animals)						
3.33	No looseness in movement or damage, missing bolts/handles	X	Movement in handle/footings on spring animal x 2	L	Monitor	
3.34	No rot or corrosion, foundation movement, splintered timber	/				
Sandpits						
3.35	No ponding water, drainage issues or health hazards	/				
3.36	Sand pit edges and supports intact & secure	/				
3.37	Sand raked to remove foreign objects, fouling, glass	/				

RISK LEVEL ~ SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

- Probability or likelihood
 1 Rare (Highly unlikely) - Once every 100yrs
 2 Unlikely (Conceivable) - Once every 30 yrs
 Possible (Could occur - Once every 10 yrs)
 Likely (Almost certain (On an annual basis)
- Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 3- Serious injury, possible long term absence from school
 -5 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 360:200 Risk Management.

NOTES

Empty space for notes.



Location Theodore Chippindal Cct

Time 11 05

Date 17/08/2020

Name James Gardner

Weather Sunny

Date Next Assessment

ITEM TO BE ASSESSED For potential hazards	✓ x	ISSUE What is the Hazard	RISK L M H V H	REVIEW		
				What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS						
1.01 Good visibility for supervision, surrounds in good condition, no graffiti	/					
1.02 Bubbblers and water features clean and fully operational	/					
1.03 Access ramps, pathways, entrances free of slipping & tripping hazards	/					
1.04 Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/					
1.05 Paths around playground clear of hazards, cracks, trips, vegetation	/					
1.06 Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/					
1.07 Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	L	Needs repair		PCL
1.08 Gates, closing & locking devices operational, no finger entrapments (>12mm)	/					
1.09 Access, entrance & ancillary items free of protrusions/sharp edges	/					
SURFACING						
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings						
2.01 Rubbish that may be hygiene issue removed	/					
2.02 Broken glass, rocks, foreign objects likely to cause injury removed	/					
2.03 Surface in good condition, no trip points	/					
2.04 Drainage operational, no contamination from runoff	/					
LOOSE FILL MATERIAL						
2.06 Check depth min 300mm-400mm top up or rake as required	X	Low bark	H	Top up bark		PCL
2.07 Loose-fill containment edging / barrier secure free of protrusions	/					
2.08 No material deterioration or contamination by clay or other matter	/					
SYNTHETIC MATERIAL						
2.09 Fouling of surface or chewing gum, foreign objects, rocks	/					
2.10 Joints, wear layer, impact attenuation layer or sub-base failure	/					
EQUIPMENT						
Platforms, Structures and frames						
3.01 Foundation and structures free of movement rot or corrosion	/					
3.02 No water penetration into structure or fittings bulging corrosion	/					
3.03 Handrails guardrails barriers decks platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor		
3.04 Physical damage or missing parts bolts present and secure vandalism	/					
3.05 Check end caps bolts screws tube ends	/					
3.06 No cracked or damaged plastic or wood panels no graffiti	/					
3.07 No protruding screws nails bolts sharp edges splintering or cracks	/					
3.08 Remove loose items brought into playground - ropes rocks sticks	/					
3.09 Equipment free from moss mould unhygienic matter - slip potential	/					
Chains, Ropes, Cables, Nets and Tyres						
3.10 Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/					
3.11 No fraying of ropes or cable (or ends) - Replace or remove	/					
3.12 Wear in chains & connectors <40%	/					
3.13 No entrapment hazards, no corrosion, no sharp edges	/					
Swings						
3.14 Check for squeaking bushes - lubricate/replace	/					
3.15 Swing action smooth & quiet, seat has no damage or vandalism	/					
3.16 Wear in chains & connectors <40%	X	Swing mounts/bushes worn	L	Monitor		
3.17 Check seat & pivot connections for tightness, s-hooks for closure	/					
3.18 Impact attenuating edge intact, no cracking or exposed metal components	/					
3.19 Drain holes in tyres clear, no exposed metal wire	/					
3.20 Seat clearance from ground min 400mm	/					
Slides						
3.21 No damage or foreign objects on slide bed/sides - exit wear area	/					
3.22 Structure slide & supports - stability looseness corrosion splinters	/					
3.23 Runout section height <350mm (or 200mm up to 1500mm sliding section)	/					
3.24 No entrapments, sliding smooth, overlap of joints downwards	/					
Carousels (rotating equipment)						
3.25 Speed limited to 5m/s	/					
3.26 Smooth & quiet rotation (both directions), platform level & stable	/					
3.27 Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	M	Monitor		
3.28 Underside clear of protrusions & sharp edges	/					
Runways (flying foxes)						
3.29 Trolley motion smooth no loose wire strands speed limited to 7m/s	/					
3.30 End stops haven't moved they bring trolley to a controlled stop	/					
3.31 No loose/missing bolts rot/corrosion (particularly at ground level)	/					
3.32 Is cable secure, platform stable, seat/grip condition, clearance 400mm	/					
Seesaws & rocking equipment (Spring Animals)						
3.33 No looseness in movement or damage, missing bolts/handles	X	Movement in handle/footings on spring animal x 2	L	Monitor		
3.34 No rot or corrosion, foundation movement, splintered timber	/					
Sandpits						
3.35 No ponding water drainage issues or health hazards	/					
3.36 Sand pit edges and supports intact & secure	/					
3.37 Sand raked to remove foreign objects, fouling, glass	/					

RISK LEVEL - SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely - Once every 100yrs)
 2 Unlikely (Conceivable - Once every 30 yrs)
 Possible (Could occur - Once every 10 yrs)
 Likely (Almost certain (On an annual basis))

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 3-4 Serious injury, possible long term absence from school
 5 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 3802:200 Risk Management.

NOTES



Location Theodore Chippindal Cct

Time 10:36

Date 20/07/2020

Name James Gardner

Weather Sunny

Date Next Assessment

ITEM TO BE ASSESSED	✓ x	ISSUE What is the Hazard	RISK L M H V H	REVIEW		
				What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS						
1.01 Good visibility for supervision, surrounds in good condition, no graffiti	/					
1.02 Bubbblers and water features clean and fully operational	/					
1.03 Access ramps, pathways, entrances free of slipping & tripping hazards	/					
1.04 Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/					
1.05 Paths around playground clear of hazards, cracks, trips, vegetation	/					
1.06 Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/					
1.07 Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	L	Monitor		
1.08 Gates, closing & locking devices operational, no finger entrapments (>12mm)	/					
1.09 Access, entrance & ancillary items free of protrusions/sharp edges	/					
SURFACING						
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings						
2.01 Rubbish that may be hygiene issue removed	/					
2.02 Broken glass, rocks, foreign objects likely to cause injury removed	/					
2.03 Surface in good condition, no trip points	/					
2.04 Drainage operational, no contamination from runoff	/					
LOOSE FILL MATERIAL						
2.06 Check depth min 300mm-400mm top up or rake as required	X	Low bark	M	Top up bark		PCL
2.07 Loose-fill containment edging / barrier secure free of protrusions	/					
2.08 No material deterioration or contamination by clay or other matter	/					
SYNTHETIC MATERIAL						
2.09 Fouling of surface or chewing gum, foreign objects, rocks	/					
2.10 Joints, wear layer, impact attenuation layer or sub-base failure	/					
EQUIPMENT						
Platforms, Structures and frames						
3.01 Foundation and structures free of movement rot or corrosion	/					
3.02 No water penetration into structure or fittings bulging corrosion	/					
3.03 Handrails guardrails barriers decks platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor		
3.04 Physical damage or missing parts bolts present and secure vandalism	/					
3.05 Check end caps bolts screws tube ends	/					
3.06 No cracked or damaged plastic or wood panels no graffiti	/					
3.07 No protruding screws nails bolts sharp edges splintering or cracks	/					
3.08 Remove loose items brought into playground - ropes rocks sticks	/					
3.09 Equipment free from moss mould unhygienic matter - slip potential	/					
Chains, Ropes, Cables, Nets and Tyres						
3.10 Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/					
3.11 No fraying of ropes or cable (or ends) - Replace or remove	/					
3.12 Wear in chains & connectors <40%	/					
3.13 No entrapment hazards, no corrosion, no sharp edges	/					
Swings						
3.14 Check for squeaking bushes - lubricate/replace	/					
3.15 Swing action smooth & quiet, seat has no damage or vandalism	/					
3.16 Wear in chains & connectors <40%	X	Swing mounts/bushes worn	L	Monitor		
3.17 Check seat & pivot connections for tightness, s-hooks for closure	/					
3.18 Impact attenuating edge intact, no cracking or exposed metal components	/					
3.19 Drain holes in tyres clear, no exposed metal wire	/					
3.20 Seat clearance from ground min 400mm	/					
Slides						
3.21 No damage or foreign objects on slide bed/sides - exit wear area	/					
3.22 Structure slide & supports - stability looseness corrosion splinters	/					
3.23 Runout section height <350mm (or 200mm up to 1500mm sliding section)	/					
3.24 No entrapments, sliding smooth, overlap of joints downwards	/					
Carousels (rotating equipment)						
3.25 Speed limited to 5m/s	/					
3.26 Smooth & quiet rotation (both directions), platform level & stable	/					
3.27 Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	M	Monitor		
3.28 Underside clear of protrusions & sharp edges	/					
Runways (flying foxes)						
3.29 Trolley motion smooth no loose wire strands speed limited to 7m/s	/					
3.30 End stops haven't moved they bring trolley to a controlled stop	/					
3.31 No loose/missing bolts rot/corrosion (particularly at ground level)	/					
3.32 Is cable secure, platform stable, seat/grip condition, clearance 400mm	/					
Seesaws & rocking equipment (Spring Animals)						
3.33 No looseness in movement or damage, missing bolts/handles	X	Movement in handle/footings on spring animal x 2	L	Monitor		
3.34 No rot or corrosion, foundation movement, splintered timber	/					
Sandpits						
3.35 No ponding water drainage issues or health hazards	/					
3.36 Sand pit edges and supports intact & secure	/					
3.37 Sand raked to remove foreign objects, fouling, glass	/					

NOTES

RISK LEVEL - SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely - Once every 100yrs)
 2 Unlikely (Conceivable - Once every 30 yrs)
 Possible (Could occur - Once every 10 yrs)
 Likely (Almost certain (On an annual basis)

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 3-4 Serious injury, possible long term absence from school
 5 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 3802:200 Risk Management.



PLAYGROUND INSPECTIONS REPAIR REQUEST

Work Order Number _____

PLGR No. 263

Suburb Theodre

Address Chippindall Circ

Insp Date 24/07/2020

Insp Time 11:50

Bark low No

Problem Baby seat direction to be changed - Requested by PCL

Action Taken Changed baby seat direction

Inspectors Name James

Signature J.Gardner

Name Of Inspector

Joseph

Month of Inspection

Oct-20

		Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action	
1	BANKS PLGR 413	Pocket Ave	1	7:18	06-Oct	/		/		/		/		X	X		Loose slide leg	Monitor	
			1	7:35	12-Oct	/		/		/		X	X				Chain net links/mounts worn	Monitor / Needs Repair LAZ	
			2	7:14	19-Oct	/		/		/		X	X				Baby seat damaged	Monitor	
			1	8:32	26-Oct	/		/		/		X	X				Border concrete cracking / lifting	Needs Repair PCL	
			1			/		/		/		X	X				Small plastic slide damaged	Monitor	
																Titer toters arms missing	Removed until further notice - PCL		
2	BONYTHON PLGR 535	Burgoyne St	1	8:00	06-Oct	/		/		/		/			X		Ropes worn on climb net	Monitor	
			1	8:35	12-Oct	/		/		/		/			X		Swing mounts worn	Monitor	
			2	8:05	19-Oct	/		/		/		/				X		Timber worn on fort/equipment	Monitor
			1	9:17	26-Oct	/		/		/		/				X		Collar pins worn	Monitor
			1			/		/		/		/				X		Ropes worn on small single swing	Monitor
																Black rubber mount points melting	Monitor		
3	FADDEN PLGR 228	Coyne St	1	11:28	06-Oct	/		/		/		/		X	X		Swing mounts worn	Monitor	
			1	3:11	12-Oct	/		/		/		/		X	X		Cracked welds on slide entry	Monitor	
			2	12:50	19-Oct	/		/		/		/		X	X		Worn links bridge/climb chains	Monitor	
			1	12:47	26-Oct	/		/		/		/		X	X		Timber split on panels	Monitor	
			1			/		/		/		/		X	X		Border logs splitting	Monitor	
																		Holes in softfall / splitting/low bark	Needs repair - PCL
																		Footpath lifting	Needs repair - PCL
																		Slide footing loose	Monitor
															Spinning seesaw hanger has worn mount/handle	Monitor			
																Hose splitting on chain covers	Monitor		
																Movement in brackets on web towers	Monitor		
4	GORDON PLGR 278	McGilvray Circ	1	6:32	02-Oct	/		/		/		/		X	X		Fibreglass on tea cup spinner cracking	Monitor	
			1	7:46	06-Oct	/		/		/		/		X	X		Border posts removed x 3	Needs repair PCL	
			1	7:04	09-Oct	/		/		/		/		X	X		Damaged see-saw brackets x 3	Needs Repair - J&E	
			1	8:16	12-Oct	/		/		/		/		X	X		Rope climb net worn 80%	Monitor - No Sharps	
			1	7:01	16-Oct	/		/		/		/		X	X		Spinner top bearings loose	Monitor	
			2	7:47	19-Oct	/		/		/		/		X	X		Damaged super nova	Monitor - Siliconed	
			1	2:37	23-Oct	/		/		/		/		X	X		Border logs splitting	Monitor	
			1	9:01	26-Oct	/		/		/		/		X	X		Roman triangles worn links	Needs repair - LAZ - Parawebb	
			1	7:12	30-Oct	/		/		/		/		X	X		Wire walk cable worn	Monitor	
																		Decking worn on tower	Monitor
																		Wire bridge mount worn/chain low links worn	Needs repair - LAZ
																		Cracked welds in tower/rust	Needs repair - LAZ
																		Rubber Soft fall splitting/holes	Needs repair - PCL
															Swing chains/brackets/mounts	Monitor			
															bench below tea cup playground coming out of footing	Needs repair - PCL			
															Hole in shade sail	Monitor			
5	GOWRIE PLGR 328	Jeffries St	1	11:07	06-Oct	/		/		/		/			X		Softfall splitting / holes forming	Needs Repair PCL	
			1	12:20	12-Oct	/		/		/		/			X		Timber worn on carousel	Monitor	
			2	12:19	19-Oct	/		/		/		/			X		Spider net worn	Monitor	
			1	12:25	26-Oct	/		/		/		/				X		Softfall Removed from paths	Needs repair PCL



Name Of Inspector **Joseph** Month of Inspection **Oct-20**

Suburb	Street	Location	Type of Inspection		Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
			Level 1or Level 2	Time		/	x	/	x	/	x	/	x	/	x	/	x		
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)	1	9:56	06-Oct	/		/		/		/		X	X	Bearings/guide rollers worn on fly fox	Monitor		
			1	11:02	12-Oct	/		/		/		/		X	X	Swing mounts/brackets worn	Monitor		
			2	10:38	19-Oct	/		/		/		/		X	X	Concrete border lifting	Monitor		
			1	11:18	26-Oct	/		/		/		/		X	X	Bridge slats splitting	Monitor		
			1			/		/		/		/		X	X	Movement in see saw	Needs repair - LAZ		
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)	1	10:07	06-Oct	/		/		/		/		X	X	Damaged concrete border	Monitor		
			1	11:13	12-Oct	/		/		/		/		X	X	Damaged park seat	Needs repair - PCL		
			2	10:56	19-Oct	/		/		/		/		X	X	baby swing damaged	Monitor		
			1	11:29	26-Oct	/		/		/		/		X	X	Plastic Rocks on climb wall cracking/brittle	Monitor		
			1			/		/		/		/		X	X	Movement in base of carousel	Needs repair - J&E		
14	KAMBAH PLGR 305	Springbett St	1	7:57	02-Oct	/		/		/		/		X	X	flying fox mount worn/Large flying fox cable	Needs welding/ filing and needs tensioning - LAZ		
			1	9:46	06-Oct	/		/		/		/		X	X	Swing seat/brackets/links/mounts worn	Monitor		
			1	8:22	09-Oct	/		/		/		/		X	X	Super nova damaged	Monitor		
			1	10:47	12-Oct	/		/		/		/		X	X	Spinner bearings worn	Monitor		
			1	8:24	16-Oct	/		/		/		/		X	X	Mount worn on large fly fox	Monitor		
			2	10:25	19-Oct	/		/		/		/		X	X	Border logs splitting	Monitor		
			1	3:34	23-Oct	/		/		/		/		X	X	Sml fly fox movement in bolt/pommel worn/hosing	Monitor - Taped		
			1	11:08	26-Oct	/		/		/		/		X	X	Tic Tac Toe damaged - Smashed/brittle (taped)	Needs Repair J&E		
			1	8:27	30-Oct	/		/		/		/		X	X	Damage panel on quad hoops	Monitor		
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)	1	10:28	06-Oct	/		/		/		/		X	X	Low branches at Large flyfox/ Small fly fox grass in bark	Cut back/remove - PCL		
			1	11:36	12-Oct	/		/		/		/		X	X	Burn marks at liberty swing seat	Monitor		
			2	11:33	19-Oct	/		/		/		/		X	X	Bark low/ washed out/weeds in bark - flyfoxs, large swings, carousels	Needs repair - PCL		
			1	11:52	26-Oct	/		/		/		/		X	X	Burn mark seesaw	Monitor		
			1			/		/		/		/		X	X	Swing mounts	Monitor		
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)	1	10:19	06-Oct	/		/		/		/		X	X	Timber swing posts splitting/ missing swings	?		
			1	11:26	12-Oct	/		/		/		/		X	X	Worn decks/ bridge - plastic coating peeling	Needs Repair - LAZ		
			2	11:11	19-Oct	/		/		/		/		X	X	Damaged rock wall	Monitor		
			1	11:43	26-Oct	/		/		/		/		X	X	Rope worn on carousel	Monitor		
17	MACARTHUR PLGR 327	Bayly Pl	1	11:43	06-Oct	/		/		/		/		X	X	Swing seat / brackets worn	Monitor		
			1	3:30	12-Oct	/		/		/		/		X	X	Bark low	Needs Repair PCL		
			2	1:06	19-Oct	/		/		/		/		X	X	Worn swing links/brackets	Monitor		
			1	1:10	26-Oct	/		/		/		/		X	X	Rope worn on climbing net/carousel	Monitor		
			1			/		/		/		/		X	X	Movement in base towards post of carousel	Needs repair - J&E		
THEODORE			1	7:00	06-Oct	/		/		/		/		X	X	Gravel washed into bark	Needs removal PCL		
			1	7:17	12-Oct	/		/		/		/		X	X	Low bark	Needs Top up - PCL		
			2	6:50	19-Oct	/		/		/		/		X	X	Swing mounts/bushes worn	Monitor		
			1			/		/		/		/		X	X	Carousel seat worn/rusting	Monitor		
			2			/		/		/		/		X	X	Worn/damaged deck/bridge	Monitor		



Name Of Inspector **Joseph** Month of Inspection **Oct-20**

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
							/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x		
				Level 1/2	Time	Date																	Hazard	Action								
18	THEODORE PLGR 263	Chippindall Circ		1	8:17	26-Oct	/		/		/		/		/		/		/		/		X		Loose handle/footings on spring animal x 2	Monitor						
				1			/		/		/		/		/		/		/		/		/		X	Tree branch stuck in shade sail	Needs Removal PCL					
																												Holes in shade sail	Monitor			
																												Low bark	Needs Top up - PCL			
19	THEODORE PLGR 262	Lawrence Wackett Cres		1	6:51	06-Oct	/		/		/		/									X	X	Weld cracking at slide entry	Needs Repair - LAZ							
				1	7:07	12-Oct	/		/		/		/		/									X	X	Decking plastic worn/surface rust	Monitor					
				2	6:38	19-Oct	/		/		/		/		/										X	X	Swing/Chain bridge links/mounts worn	Monitor				
				1	8:08	26-Oct	/		/		/		/		/										X	X	Movement in frog footing	Monitor				
				1			/		/		/		/		/										X	X	Border concrete cracking	Needs Repair - PCL				
20	WANNIASSA PLGR 271	Sangster Pl		1	10:39	06-Oct	/		/		/		/									X	X	Swing mounts brackets worn	Monitor							
				1	11:51	12-Oct	/		/		/		/		/									X	X	Decking worn	Monitor					
				2	11:50	19-Oct	/		/		/		/		/										X	X	Hole in chain wire fence	Needs Repair - LAZ				
				1	12:04	26-Oct	/		/		/		/		/										X	X	Park bench missing arm rest	Needs Repair - PCL				
				1			/		/		/		/		/										X	X	Holes and splitting in softfall	Needs repair - PCL				

Inspectors Signature: J.Djerke

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector **Joseph** Month of Inspection **Oct-20**

	Suburb	Street	Type of Inspection		Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
			Level 1	Level 2			/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action		
1	BANKS PLGR 213	Menzies Court	1		1:19	07-Oct	/		/		/		/		/		/		X				X			Fort panel cracked/stairs damaged	Monitor					
																											Decking plastic worn/surface rust	Monitor				
			2		11:29	20-Oct	/		/		/		/		/		X							X								
																												Border concrete cracking	Monitor			
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																													
3	BANKS PLGR 212	Wilson Cres	1		1:31	07-Oct	/		/		/		/		X				X							Bench seat slats loose / missing bolts	Needs Repair PCL					
																												Swing seat brackets worn	Monitor			
			2		11:18	20-Oct	/		/		/		/		X					X							Decking worn	Monitor				
																												Dints in slide bed	Monitor			
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)																									Border concrete cracking	Needs Repair - PCL				
			1		8:20	08-Oct	/		/		/		/		/								X				Posts handrails split/rotting	Monitor				
			2		12:51	20-Oct	/		/		/		/		/									X				4 x Post damaged/split on fort	Monitor			
																												Chain net links and mounts worn	Monitor			
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																													
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1		8:33	08-Oct	/		/		/		/		X				X								Border logs splitting	Needs repair - PCL				
			2		1:25	20-Oct	/		/		/		/		X					X								ber decking lifting / splitting/structure s	Needs Repair - J&E - Rebuild			
																										Slide has crack at entry/movement	Monitor					
																											Swing mounts worn	Monitor				
7	BONYTHON PLGR 586	Morice Pl	1		8:44	08-Oct	/		/		/		/															Swing seat brackets worn	Monitor			
			2		1:03	20-Oct	/		/		/		/		/														Worn / missing rope on net	Monitor		
																											Worn links/mounts on pommel/ climb chain	Monitor				
																											Mount on pommel worn	Needs Repair - LAZ				



Name Of Inspector **Joseph** Month of Inspection **Oct-20**

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground				Softfall				Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
				free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition						
8 CALWELL PLGR 322 Beckett St	1	7:35	08-Oct	/	/	/	/	/	/	X	Decking plastic worn	Monitor		
											Swing mounts worn	Monitor		
	2	8:13	20-Oct	/	/	/	/	/	/	X	Bent monkey bars	Monitor		
											Slide weld cracking at top/side	Needs Repair - LAZ		
											Chain walk hand rail bent	Needs Repair - LAZ		
											Bent deck poles	Needs Repair - LAZ		
											Low tree branches	Needs Removal PCL		
9 CALWELL PLGR 321 Casey Cres	1	7:12	08-Oct	/	/	/	/	/	/	X	Swing mounts worn	Monitor		
											Decking plastic worn/decks rusting	Monitor		
	2	9:10	20-Oct	/	/	/	/	/	/	X	Chain net links/coating on chains worn	Monitor		
10 CALWELL PLGR 323 Mountain Circ (Zox Cct)											See saw timber splitting	Monitor		
	1	7:23	08-Oct	/	/	/	/	/	X	X	Decking plastic worn	Monitor		
	2	8:24	20-Oct	/	/	/	/	/	X	X	Swing mounts/seat/links worn	Monitor		
11 CALWELL PLGR 319 Samuel Cl											Low branches	Needs cut back back-PCL		
											Side leg bent	Monitor		
	1	7:01	08-Oct	/	/	/	/	/	X	X	Border logs splitting	Monitor		
12 CALWELL PLGR 644 Shopping Centre											Swing mounts worn	Monitor		
	2	8:58	20-Oct	/	/	/	/	/	X	X	Bent monkey bars	Monitor		
											Park bench missing timber	Needs Repair - PCL		
13 CALWELL PLGR 320 Were St	1	6:41	08-Oct	/	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor		
											Bark low	Top up bark PCL		
											Carousel movement in bearing	Monitor		
14 CHISHOLM PLGR 234 Alston St	1	6:53	08-Oct	/	/	/	/	/	X	X	Border logs splitting/ missing	Needs Repair - PCL		
											Swing links/mounts worn	Monitor		
	2	8:49	20-Oct	/	/	/	/	/	X	X	Tire worn on tyre swing	Monitor		
14 CHISHOLM PLGR 234 Alston St														
	1	1:25	06-Oct	/	/	/	/	/	/	X	Rope net install satisfactory?	Level 3 ?		
											Swing mounts worn	Monitor		
	2	6:53	27-Oct	/	/	/	/	/	/	X	Damaged tic tac toe	Monitor		
											Baby seat chain cover worn	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Joseph

Month of Inspection

Oct-20

		Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
21	CONDER PLGR 219	Ceremonial Pl (Landells Pl)	2	10:53	20-Oct	/	/	/	/	X	X	Decks/bridge timber split/damaged	Needs Repair - J&E
												Ropes worn on climb net (fraying)	Monitor
												Deck connection bolts worn/chain	Needs repair - LAZ
22	CONDER PLGR 222	Dixson Circ	1	2:16	07-Oct	/	/	/	/	/	X	Bark washed out	Needs Repair - PCL
												Panels damaged/rusting	Monitor
			2	10:08	20-Oct	/	/	/	/	/	X	Chain net/mounts worn	Monitor
												Plastic panel/ tic tac damaged	Monitor
												Swing seat/brackets/mounts/chain worn	Monitor
23	CONDER PLGR 607	James Smith Circ	1	2:28	07-Oct	/	/	/	/	/	X	Swing/fort posts splitting/rot	Monitor
												Climb net rope worn	Monitor
			2	9:55	20-Oct	/	/	/	/	/	X	Decking/panels worn on cubby/spring animal/slide	Monitor
												Bark low	Needs Top up - PCL
												Deck damaged/rotting	Deck patched - J&E 24/07/20
24	CONDER PLGR 220	Montfiore Cres	1	1:54	07-Oct	/	/	/	/	X	X	Border logs splitting	Monitor
												Climb net links/mounts worn	Monitor
			2	10:41	20-Oct	/	/	/	/	X	X	Bark low	Needs Top up - PCL
												Plastic bridge damaged	Needs repair J&E
												Bridge rail cracked	Needs repair - LAZ
												Movement in border sleepers	Monitor
												Plastic panels brittle	Monitor
25	CONDER PLGR 244	Russell Drysdale Cr (Daly Pl)	1	2:05	07-Oct	/	/	/	/	/	X	Bridge plastic/ links worn	Monitor
												Decking worn/rusting	Monitor
			2	10:18	20-Oct	/	/	/	/	/	X	Slide mount on deck rusting	Needs repair - LAZ
												Bark washed out / dirt in bark	Needs repair - PCL
26	FADDEN PLGR 225	Bertram St (Riordan St)	1	12:21	08-Oct	/	/	/	/	X	X		
			2	8:27	27-Oct	/	/	/	/	X	X	re swing mounts/ links/s hooks worn	Monitor
27	FADDEN PLGR 228	Coyne St	MONDAY RUN										
			1	12:07	08-Oct	/	/	/	/	X	X	Swing mounts worn/links worn	Monitor



Name Of Inspector		Joseph		Month of Inspection							Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	2	8:14	27-Oct	/	/	/	/	/	X	X	Movement in carousel base	Monitor			
														Decking timber splitting	Monitor		
															Chain net links / mounts worn	Monitor	
															Lichen growing on decks	Monitor	
29	FADDEN PLGR 509	Nicklin Cres	1	11:57	08-Oct	/	/	/	/	X	X	Rocks missing in border wall	Needs Repair - PCL				
														Rope bridge mount broken/rope worn	Needs Repair PCL		
			2	8:04	27-Oct	/	/	/	/	X	X	Climbing nets rope worn	Monitor				
															Panel/ roof panels cracked on fort	Monitor	
													Tower posts splitting	Monitor			
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	11:40	08-Oct	/	/	/	/	X	X	Swing mounts/ links worn	Monitor				
															Damaged baby swing	Monitor	
			2	7:50	27-Oct	/	/	/	/	X	X	Border logs worn	Monitor				
															Dent in parallel bars/swing post	Monitor	
	GILMORE	Heagney Cres	1	12:09	06-Oct	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor				
															Rubber frog damaged	Monitor	
			2	1:48	19-Oct	/	/	/	/	X	X	Low bark	Needs Top up - PCL				
31	GILMORE PLGR 238	Hogue Pl	1	12:16	06-Oct	/	/	/	/	X	X	Fence damaged	Monitor				
															Spinner seats worn/ rusting	Monitor	
			2	1:55	19-Oct	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL				
													Bark low	Top up bark PCL			
32	GILMORE PLGR 239	Rosman Circ	1	12:00	06-Oct	/	/	/	/	/	X	Bridge timber splitting	Monitor				
															Concrete at bench lifting	Needs Repair PCL	
			2	1:39	19-Oct	/	/	/	/	/	X	Damaged rock wall	Needs Repair PCL				
33	GORDON PLGR 215	Iredale Pl	1	12:36	07-Oct	/	/	/	/	/	X	Swing seat brackets worn	Monitor				
															Chain net/ladder links worn/plastic	Monitor	
			2	12:25	20-Oct	/	/	/	/	/	X	Damaged post caps x 4	Monitor				
																Slide damaged	Monitor
34	GORDON PLGR 216	Kirkwood Cres	1	12:49	07-Oct	/	/	/	/	X	X	Swing seat brackets/mounts wearing	Monitor				
																Slide surface dented	Monitor
			2	12:04	20-Oct	/	/	/	/	X	X	Dent in swing crosbar/see saw seat	Monitor				



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection							Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	8:08	08-Oct	/	/	/	/	/	X	X	Ropes worn on web	Monitor			
														Decks/Posts splitting/rotten	Monitor		
			2	7:37	20-Oct	/	/	/	/	/	X	X					
															Concrete border lifting	Needs Repair PCL	
															Gaps were slide joints	Monitor	
												Swing timber splitting	Monitor				
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	7:56	08-Oct	/	/	/	/	/		X					
														Swing mounts worn	Monitor		
			2	8:00	20-Oct	/	/	/	/	/		X			Plastic slide cracked	Monitor	
															Movement in swing posts	Monitor	
													Frog plastic worn around handle	Monitor			
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	7:46	08-Oct	/	/	/	/	/	X	X	Border path concrete cracking	Monitor			
														Slide surface worn	Monitor		
			2	7:48	20-Oct	/	/	/	/	/	X	X			Chain net links	Monitor	
															Damaged post	Monitor	
													Spring animal missing	Needs repair - J&E			
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	11:18	09-Oct	/	/	/	/	/		X	Slide leg loose in footing	Monitor			
														Low bark	Top - PCL		
			2	11:03	28-Oct	/	/	/	/	/		X			Spring animal loose in footing	Monitor	
													Angle bar missing at climbing net damaged	Needs repair - LAZ			
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	11:33	09-Oct	/	/	/	/	/	X	X	Border logs splitting	Monitor			
															Swing mounts/brackets worn	Monitor	
			2	11:16	28-Oct	/	/	/	/	/	X	X			Concrete lifting quad hoop game	Monitor	
																Chain net links / mounts worn	Monitor
																Slide surface worn	Monitor
57	KAMBAH PLGR 313	Attiwell Circ	1	10:49	09-Oct	/	/	/	/	/	X	X	Border logs damaged	Needs Repair PCL			
															Swing mounts worn/loose due to timber shrinking	Monitor	
			2	10:34	28-Oct	/	/	/	/	/	X	X			Swing timber damage/splitting	Monitor	
																Asphalt cracking / lifting	Needs Repair PCL
													See-saw footrest damaged	Monitor			
58	KAMBAH PLGR 314	Barritt St	1	10:39	09-Oct	/	/	/	/	/		X	Damaged flat swing	Monitor			
															Bridge plastic worn/ rusted	Monitor	
			2	10:24	28-Oct	/	/	/	/	/	/	X			Welds cracked on chain net	Needs Repair - LAZ	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph			Month of Inspection						Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
													Fort panel movement	Monitor		
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN													
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN													
61	KAMBAH PLGR 301	Boustead Circ	1	9:50	09-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor		
			2	9:36	28-Oct	/	/	/	/		X	X	Damaged plastic on stairs Rusting at bottom of stairs	Monitor Monitor		
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	12:45	09-Oct	/	/	/	/		X	X	Timber decking splitting	Monitor		
			2	12:24	28-Oct	/	/	/	/		X	X	Swing posts splitting and rotten Movement in ladder plate to decking	Monitor Monitor		
63	KAMBAH PLGR 317	Bullock Circ	1	10:28	09-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Rubber on stairs splitting	Monitor	
			2	10:13	28-Oct	/	/	/	/		X	X	Worn rubber on deck	Needs Repair LAZ		
														Climb chain/bridge links worn Spring animal spring plate weld c	Monitor Needs Repair LAZ	
64	KAMBAH PLGR 299	Coghill Cl	1	2:15	09-Oct	/	/	/	/		X	X	Swing mounts worn	Monitor		
														Border logs splitting/damage	Needs repair - PCL	
			2	1:58	28-Oct	/	/	/	/		X	X	Carousel loose - movement in bearing	Monitor		
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	9:21	09-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor		
														Swing mounts worn	Monitor	
			2	9:07	28-Oct	/	/	/	/		X	X	Decking plastic worn	Monitor		
															Low bark	Needs Top up - PCL
															flying fox handle/mount/links worn Bridge timber splitting	Monitor Monitor



Name Of Inspector		Joseph		Month of Inspection							Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
													Bridge/climbing net links worn	Monitor	
66	KAMBAH PLGR 304	Dale Circ	1	8:35	09-Oct	/	/	/	/			X	X	Border sleepers splitting	Monitor
															Decks rusty/ plastic peeling
			2	8:33	28-Oct	/	/	/	/			X	X	Bridge rusty/ plastic worn	Monitor
														Swing brackets/mounts worn	Monitor
67	KAMBAH PLGR 291	Deuchar Cl	1	2:31	09-Oct	/	/	/	/			X	X	Decking plastic worn/surface rust	Monitor
															Border sleepers splitting
			2	2:14	28-Oct	/	/	/	/			X	X	Swing mounts worn	Monitor
														Damaged post collars	Monitor
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)	1	11:02	09-Oct	/	/	/	/			X	X	Border logs splitting	Needs Repair PCL
															Decking plastic worn
			2	10:46	28-Oct	/	/	/	/			X	X	Bushes worn on see saw	Needs Repair LAZ
														Swing mounts worn	Monitor
														Bark low	Needs top up - PCL
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)	1	12:03	09-Oct	/	/	/	/			X	X	Rocks missing on rock wall	Needs Repair PCL
															Damaged bolt caps
			2	11:30	28-Oct	/	/	/	/			X	X		
														Bridge timber splitting	Monitor
70	KAMBAH PLGR 284	Gibbs Pl	1	12:55	09-Oct	/	/	/	/				X	Knots and crosses cracking	Monitor
															Bolt caps brittle/damaged on tower
			2	12:37	28-Oct	/	/	/	/				X		
71	KAMBAH PLGR 289	Horton Cl	1	2:23	09-Oct	/	/	/	/			X	X	Chain net links worn	Monitor
															Decking plastic worn/rusting
			2	2:06	28-Oct	/	/	/	/			X	X	Damaged/missing/loose border timber	Needs Repair - PCL
														Parallel slide bar bent	Monitor
														Wearing swing brackets	Monitor
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)	1	12:12	09-Oct	/	/	/	/			X	X	Border sleepers splitting	Monitor
			2	11:50	28-Oct	/	/	/	/			X	X		
														Bridge/ chain net links worn	Monitor
			1	1:23	09-Oct	/	/	/	/			X	X	Border sleepers splitting	Monitor
														Swing mounts/brackets worn	Monitor

Name Of Inspector		Joseph			Month of Inspection							Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
73	KAMBAH PLGR 307	Humble Court	2	1:04	28-Oct	/	/	/	/	/	X	X	Slide dented	Monitor	
														Low bark	Needs Repair - PCL
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	9:34	09-Oct	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor	
														Deck/bridge plastic worn	Monitor
			2	9:20	28-Oct	/	/	/	/	/		X	Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	Lascelles Circ	1	12:31	09-Oct	/	/	/	/		X	X	Border Sleepers splitting	Monitor	
														See saw Top centre plate cracked	Needs Repair - LAZ
			2	12:13	28-Oct	/	/	/	/		X	X	Low branches	Cut back - PCL	
														Bridge slats splitting/links worn/movement	Monitor
												Chain net links worn	Monitor		
												Decking plastic worn	Monitor		
76	KAMBAH PLGR 325	Learmonth Dr	1	10:14	09-Oct	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor	
														Climb net ropes worn	Monitor
			2	10:01	28-Oct	/	/	/	/		X	X	Timber posts splitting	Monitor	
														Rock wall missing rocks	Monitor
														Damaged bolt caps on equipment	Monitor
												Spring motorcycle panels worn	Monitor		
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	1	2:06	09-Oct	/	/	/	/		X	X	Border sleepers splitting	Monitor	
			2	1:49	28-Oct	/	/	/	/		X	X	Burn marks on post / slide	Monitor	
															Bridge/Climb net links worn
												Bridge slats splitting/movement worn timber	Monitor		
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	11:44	09-Oct	/	/	/	/	/		X	Monitor all links in hosing	Monitor	
														Damaged rubber chain hose	Monitor
			2	1:26	28-Oct	/	/	/	/	/		X	Bench seat slat damaged	Needs Repair PCL	
79	KAMBAH PLGR 314	Mannheim St	1	1:09	09-Oct	/	/	/	/		X	X	Border logs splitting	Monitor	
														Bridge slats splitting	Monitor
			2	12:49	28-Oct	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Welds cracked at slide entry	Needs Repair - LAZ
												Bridge links worn	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector **Joseph** Month of Inspection **Oct-20**

ID	KAMBAH PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground						Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
						free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition					
80	KAMBAH PLGR 285	Marconi Cres	1	12:22	09-Oct	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor	
														Gravel washed/weeds into bark	Needs Removal - PCL
			2	12:02	28-Oct	/	/	/	/	/	/	/	X	Deck edge wear	Monitor
81	KAMBAH PLGR 308	Maxworthy St											Spring bear loose in footing	Monitor	
			1	1:55	09-Oct	/	/	/	/	/	/	X	Swing mounts worn	Monitor	
			2	1:37	28-Oct	/	/	/	/	/	/	X	Bark low	Needs Top up - PCL	
82	KAMBAH PLGR 292	McKillop Pl											Damaged spinner seats x2	Monitor - Siliconed holes	
			1	9:10	09-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			2	8:56	28-Oct	/	/	/	/	X	X	Swing seat/brackets worn	Monitor		
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)											Bridge/decks rusting	Needs repair - LAZ	
			1	9:42	09-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			2	9:28	28-Oct	/	/	/	/	X	X	Slide has small dents	Monitor		
84	KAMBAH PLGR 302	Pinkerton Circ											Split rubber on stairs	Monitor	
			1	8:58	09-Oct	/	/	/	/	X	X	Graffiti on panel	Needs Removal PCL		
			2	8:43	28-Oct	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL		
85	KAMBAH PLGR 306	Primmer Court											Decking plastic worn/surface rust	Monitor	
			1	11:49	09-Oct	/	/	/	/	/	/			Swing mounts/links/brackets worn	Monitor
			2	11:41	28-Oct	/	/	/	/	/	/			Low tree branches	Needs removal- PCL
86	KAMBAH PLGR 303	Rounsevell St											Exposed tree roots in bark	Needs removal- PCL	
			1	10:01	09-Oct	/	/	/	/	X	X	Bark low	Needs Top up - PCL		
			2	9:47	28-Oct	/	/	/	/	X	X	New playground equipment installed	Has it been certified		
86	KAMBAH PLGR 303	Rounsevell St													
			1	10:01	09-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor		
			2	9:47	28-Oct	/	/	/	/	X	X	Swing mounts worn	Monitor		
86	KAMBAH PLGR 303	Rounsevell St											Slide metal rusting/ dented	Monitor	
														spring animal footing loose	Monitor
														Lap seat worn	Monitor



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector Joseph Month of Inspection Oct-20

ID	PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
														MONDAY RUN	
87	KAMBAH PLGR 305	Springbett St													
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)													
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)													
90	KAMBAH PLGR 290	Toole Pl	1	8:48	09-Oct	/	/	/	/	X	X	Swing posts splitting	Monitor		
													Swing mounts/brackets worn	Monitor	
			2	8:23	28-Oct	/	/	/	/	/	X	X	Swing Mounts have small movement due to worn timber	Monitor	
														Bridge links worn	Monitor
														Climb net links/mounts worn	Monitor
														Slide loose at entry bracket	Monitor
91	KAMBAH PLGR 293	Vanzetti Cres										Seesaw centre plate bolt/mount	Needs repair - LAZ		
													Border sleepers splitting	Monitor	
			1	1:35	09-Oct	/	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			2	1:17	28-Oct	/	/	/	/	/	X	X	Movement in stair footing	Monitor	
														Bridge plastic worn/rusting	Monitor
														Swing mounts/brackets worn	Monitor
92	MACARTHUR PLGR 327	Bayly Pl													
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	11:50	10-Jun	/	/	/	/	X	X	Decking worn	Monitor		
													Chain net links/mounts worn	Monitor	
			2	1:17	21-Sep	/	/	/	/	/	X	X	Bent deck poles	Monitor	
														Border damaged/rotted	Needs Repair - PCL
											Worn timber on spring horse	Monitor			



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection							Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
														Bark low	Needs Top up - PCL		
94	MONASH PLGR 252	Alabaster St	1	10:08	08-Oct	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
														Swing mounts/ links worn	Monitor		
			2	9:36	27-Oct	/	/	/	/	/	X	X	Bite marks in swing seat	Monitor			
															Damaged spiral ladder	Monitor	
																Damaged tic tac toe	Monitor
														Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	1	9:44	08-Oct	/	/	/	/	/		X	Posts splitting and rotten	Monitor			
														Swing mounts/links/brackets worn	Monitor		
			2	10:00	27-Oct	/	/	/	/	/		X	Bridge mounts/chain worn	Needs Repair LAZ			
															Bridge timber splitting	Monitor	
													Fibreglass damaged/cracking/worn on slides	Monitor			
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	9:56	08-Oct	/	/	/	/	/	X	X	Steering wheel bracket worn	Monitor			
															Border timber splitting/missing	Needs Repair - PCL	
			2	9:48	27-Oct	/	/	/	/	/	X	X	Dirt washed into bark	Needs repair - PCL			
														Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	10:34	08-Oct	/	/	/	/	/		X	Swing mounts/ links worn	Monitor			
															Concrete stump at bench	Needs Removal - PCL	
			2	9:23	27-Oct	/	/	/	/	/		X	Low hanging branches	Needs Removal - PCL			
														Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	1	9:19	08-Oct	/	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor			
																Concrete border lifting	Needs Repair PCL
			2	10:18	27-Oct	/	/	/	/	/	X	X					
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	10:23	08-Oct	/	/	/	/	/	X	X	Movement in swing crossbar	Monitor			
															Bridge links/mounts worn/movement	Monitor	
			2	10:32	27-Oct	/	/	/	/	/	X	X	Swing mounts worn	Monitor			
																Bent bar/cracked welds on bridge	Needs Repair - LAZ
																	Bark low
														Bridge slats splitting / lichen	Monitor		
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	9:29	08-Oct	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor			
																Triangles worn plastic	Monitor
			2	10:10	27-Oct	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor			
														Spring animal crack in foot rest/head loose	Monitor		
101	OXLEY	Cuthbertson Cres	1	9:01	08-Oct	/	/	/	/	/		X					
														Horse head splitting	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Joseph

Month of Inspection

Oct-20

ID	PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
101	PLGR 256	(McKibbin Pl)	2	1:41	20-Oct	/	/	/	/	/	X	Damaged tyre swing	Monitor		
102	OXLEY PLGR 255	Newman Morris Circ	1	9:10	08-Oct	/	/	/	/	X	X	Swing mounts worn	Monitor		
													Bite marks in swing seat	Monitor	
			2	2:00	20-Oct	/	/	/	/	X	X	Bark washing out	Needs repair PCL		
											Border concrete damaged	Needs Repair PCL			
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	1:48	06-Oct	/	/	/	/	X	X	Border sleepers	Needs Repair PCL		
													Deck plastic worn	Monitor	
			2	6:36	20-Oct	/	/	/	/	X	X	Carousel rusting/loose in footing	Monitor		
													Spring frog handle loose	Monitor	
											Pod mounts worn (eyelet)	Needs repair - LAZ			
104	RICHARDSON PLGR 258	Chauncy Cres	1	2:16	06-Oct	/	/	/	/	/	X	Decking plastic worn	Monitor		
													Swing mounts worn	Monitor	
			2	7:03	20-Oct	/	/	/	/	/	X	Cuts on slide (smoothed)	Monitor		
											Star picks in bark	Needs removal - PCL			
105	RICHARDSON PLGR 259	Clift Cres	1	2:00	06-Oct	/	/	/	/	/	X	Worn swing chains/mounts/movement in post	Monitor		
			2	6:42	20-Oct	/	/	/	/	/	X	Bark low / dirt in bark	Top up bark - PCL		
106	RICHARDSON PLGR 257	Vidal St	1	2:08	06-Oct	/	/	/	/	/	X	Decking plastic worn/rusting	Monitor		
													Climb net mounts worn	Needs Repair LAZ	
			2	6:58	20-Oct	/	/	/	/	/	X	Damaged spring animal foot rest	Needs Repair LAZ		
														Climb net links worn	Monitor
														Climb net bar bent/deck poles	Monitor
											Tyre swing links worn	Monitor			
											Bark low/tree debris stacked next to	Needs top up/removal - PCL			
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN												
108	THEODORE PLGR 265	Dyett Circ	1	2:49	07-Oct	/	/	/	/	X	X	Border sleepers splitting	Monitor		
													Decking timber splitting	Monitor	
			2	9:00	20-Oct	/	/	/	/	X	X	Chain net links worn	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Joseph

Month of Inspection

Oct-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
	MONDAY RUN													
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN											
110	THEODORE PLGR 261	Louis Loder St	1	2:41	07-Oct	/	/	/	/	X	X	Border logs splitting	Monitor	
			2	9:38	20-Oct	/	/	/	/	X	X	Decking timber splitting Slide fibreglass cracking/worn	Monitor Monitor	
111	THEODORE PLGR 264	Scantleberry St	1	3:01	07-Oct	/	/	/	/	X	X	Border logs splitting	Monitor	
			2	9:22	20-Oct	/	/	/	/	X	X	Slide damaged at top Spring animal timber worn Decking timber/panel splitting	Monitor Monitor Monitor	
112	WANNIASSA PLGR 270	Billson Pl	1	2:12	08-Oct	/	/	/	/	/	X			
			2	1:14	27-Oct	/	/	/	/	/	X	X	Decking plastic worn Bridge plastic worn Damaged tic tac toe Worn rubber on spike spinner	Monitor Needs Repair LAZ Monitor Needs Repair J&E
113	WANNIASSA PLGR 267	Bussau Cl	1	12:52	08-Oct	/	/	/	/	X	X	Decking timber worn Chain net links worn/plastic peeling	Monitor Monitor	
			2	11:53	27-Oct	/	/	/	/	X	X			
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	2:01	08-Oct	/	/	/	/	/	X	Decking plastic worn x 1 Swing mounts/brackets worn	Needs Repair - LAZ Monitor	
			2	1:03	27-Oct	/	/	/	/	/	X			
													Movement in grab handle	Monitor
115	WANNIASSA PLGR 275	Hervey Pl	1	1:33	08-Oct	/	/	/	/	X	X	Border sleepers/braces splitting Decking plastic rust / peeling	Needs Repair PCL Monitor	
			2	12:38	27-Oct	/	/	/	/	X	X	Smoking sign loose in footing Swing seat damaged/mounts/links worn	Needs Repair PCL Monitor	
116	WANNIASSA	Tansell Circ	1	12:42	08-Oct	/	/	/	/	X	X	Swing mounts worn Movement in spring animal	Monitor Monitor	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph			Month of Inspection							Oct-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition									
110	PLGR 266	Lansen Circ	2	11:43	27-Oct	/	/	/	/	/	/	X	X	Border fence panels damaged	Monitor			
117	WANNIASSA PLGR 269	Sainsbury St	1	2:25	08-Oct	/	/	/	/	/	/	X	X	Border logs splitting	Monitor			
															Holes in shade sail	Monitor		
			2	1:29	27-Oct	/	/	/	/	/	/	/	X	X	Burn marks on tic tac toe	Monitor		
																Bench seat slats damaged	Needs Repair PCL	
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN															
119	WANNIASSA PLGR 276	Steinfeld Circ	1	1:24	08-Oct	/	/	/	/	/	/	X	X	Border Sleepers splitting	Monitor			
															Bench seat slats splitting	Monitor		
			2	12:29	27-Oct	/	/	/	/	/	/	/	X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ		
																Decks worn x 2	Needs Repair - LAZ	
																Bridge slats splitting	Monitor	
																Bridge/Chain net links worn/plastic	Monitor	
120	WANNIASSA PLGR 268	Sullivan Cres	1	2:39	08-Oct	/	/	/	/	/	/	X	X	Bearings / wheels damaged on fly fox trolley	Needs Repair J&E			
																Border logs splitting	Monitor	
			2	1:43	27-Oct	/	/	/	/	/	/	/	X	X	Bridge/chain links worn	Monitor		
																Handle plastic worn on flying fox	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St														Swing seats/mounts worn/splitting	Monitor	
			1	1:12	08-Oct	/	/	/	/	/	/	X	X	Border sleepers damaged	Needs Repair - PCL			
			2	12:13	27-Oct	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor			
																Bridge timber splitting	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres															Park bench missing / damaged timber	Needs Repair - PCL
			1	1:45	08-Oct	/	/	/	/	/	/	X	X	Decking worn/lichen growing	Monitor			
																	Decking worn / rusting	Monitor
			2	12:49	27-Oct	/	/	/	/	/	/	X	X	Swing mounts/ links worn	Monitor			
123	WANNIASSA PLGR 272	Whiteman St															Fireman pole damaged	Monitor
																	Roman triangles links worn plastic worn	Monitor
			1	1:00	08-Oct	/	/	/	/	/	/	X	X	Chain net links worn	Monitor			
			2	12:01	27-Oct	/	/	/	/	/	/	X	X	Swing mounts/s hooks/ chains worn	Monitor			
															Border logs splitting	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection				Oct-20			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report



Name Of Inspector

Joseph

Month of Inspection

Oct-20

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
							/	x	/	x	/	x	/	x	/	x				/	x		
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	11:11	07-Oct	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban			
																				Awning luvvers mounts rusting	Monitor		
			2	7:09	28-Oct	/		/		/		/		/					X	Pommels links/mounts worn/ hosing split	Monitor		
																					Swing mounts/brackets worn	Monitor	
																					2 x tread caps missing on surfer	Monitor	
																						Bridge metal slip hazard	Angle / monitor
																						Basketball backboard worn	Monitor
																						Climb chain mounts/links worn/hosing split	Monitor
																						Rubber soft fall worn	Monitor
																						Cracked all access panel on ramp	Monitor
2	COTTER PLGR 539	CASURINA SANDS	1	10:44	07-Oct	/		/		/		/		/				X	Spring animal worn timber	Monitor			
																				Post timber splitting	Monitor		
			2	6:41	28-Oct	/		/		/		/		/					X	Decking timber splitting	Monitor		
																			Rope bridge wearing	Monitor			
3	GREENWAY PLGR 538	Pine Island Rd	1	8:10	06-Oct	/		/		/		/				X	X		Border logs splitting	Monitor			
			1	8:47	12-Oct	/		/		/		/				X	X		Climbing wall worn/rusting	Monitor			
			2	8:18	19-Oct	/		/		/		/				X	X		Movement in staircase footing	Monitor			
			1	9:30	26-Oct	/		/		/		/				X	X			Swing mounts/chains worn	Monitor		
			1			/		/		/		/				X	X			Staircase edges cracking	Needs repair - LAZ		
																					Decks/bridge worn/rusting	Needs repair - LAZ	
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND	1	11:48	07-Oct	/		/		/		/				X	X		Fence timber splitting around water tanks	Monitor			
																				Timber splitting on large spring platform	Monitor		
			2	7:45	28-Oct	/		/		/		/					X	X		Water tanks decking timber splitting/worn	Monitor		
																					Flying fox posts splitting	Monitor	
																					Spider climb net rope frayed	Monitor	
																					Water tanks damaged - Siliconed	Monitor	
																						Tree roots lifting paths	Needs Repair PCL
																						Rubber soft fall splitting	Needs Repair PCL on going problem
																						Slide beds damaged	Monitor
																						Timber bridges splitting/damaged/lifting/	Needs repair - PCL
																			Flat seat swing mounts worn	Swing mounts x2/x2 s hooks - J&			
																			Swing links/seats/brackets worn	Monitor			
																				Side of small slides has cracked welds	Needs repair - LAZ		



Name Of Inspector

Joseph

Month of Inspection

Oct-20

	Suburb	Street	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						/	x	/	x	/	x	/	x	/	x	/	x		
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action
																		Flying fox cable detached	Needs repair - LAZ

Inspectors Signature: J.Djerke

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8.
Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.

Name Of Inspector

Joseph

Month of Inspection

Nov-20

Name Of Inspector		Joseph		Month of Inspection		Nov-20														
Location		Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Suburb	Street	Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action		
1	BANKS PLGR 413	Pocket Ave	1	2:03	02-Nov	/		/		/		/		X	X		Loose slide leg	Monitor		
			1	8:11	09-Nov	/		/		/		/		X	X		Chain net links/mounts worn	Monitor / Needs Repair LAZ		
			2	7:45	16-Nov	/		/		/		/		X	X		Baby seat damaged	Monitor		
			1	7:57	23-Nov	/		/		/		/		X	X		Border concrete cracking / lifting	Needs Repair PCL		
			2			/		/		/		/		X	X		Small plastic slide damaged	Monitor		
																Titer toters arms missing	Removed until further notice - PCL			
2	BONYTHON PLGR 535	Burgoyne St	1	12:59	02-Nov	/		/		/		/			X		Ropes worn on climb net	Monitor		
			1	9:08	09-Nov	/		/		/		/			X		Swing mounts worn	Monitor		
			2	8:49	16-Nov	/		/		/		/			X		Timber worn on fort/equipment	Monitor		
			1	8:42	23-Nov	/		/		/		/			X		Collar pins worn	Monitor		
			2			/		/		/		/			X		Ropes worn on small single swing	Monitor		
																Black rubber mount points melting	Monitor			
3	FADDEN PLGR 228	Coyne St	1	3:13	02-Nov	/		/		/		/		X	X		Swing mounts worn	Monitor		
			1	7:08	09-Nov	/		/		/		/		X	X		Cracked welds on slide entry	Monitor		
			2	6:42	16-Nov	/		/		/		/		X	X		Worn links bridge/climb chains	Monitor		
			1	6:57	23-Nov	/		/		/		/		X	X		Timber split on panels	Monitor		
			2			/		/		/		/		X	X		Border logs splitting	Monitor		
																			Holes in softfall / splitting/low bark	Needs repair - PCL
																			Footpath lifting	Needs repair - PCL
																			Slide footing loose	Monitor
																Spinning seesaw hanger has worn mount/handle	Monitor			
																	Hose splitting on chain covers	Monitor		
																	Movement in brackets on web towers	Monitor		
4	GORDON PLGR 278	McGilvray Circ	1	1:47	02-Nov	/		/		/		/		X	X		Fibreglass on tea cup spinner cracking	Monitor		
			1	7:09	06-Nov	/		/		/		/		X	X		Border posts removed x 3	Needs repair PCL		
			1	8:51	09-Nov	/		/		/		/		X	X		Damaged see-saw brackets x 3	Needs Repair - J&E		
			1	8:25	13-Nov	/		/		/		/		X	X		Rope climb net worn 80%	Monitor - No Sharps		
			2	8:22	16-Nov	/		/		/		/		X	X		Spinner top bearings loose	Monitor		
			1	7:03	20-Nov	/		/		/		/		X	X		Damaged super nova	Monitor - Siliconed		
			1	8:26	23-Nov	/		/		/		/		X	X		Border logs splitting	Monitor		
			1	7:11	27-Nov	/		/		/		/		X	X		Roman triangles worn links	Needs repair - LAZ - Parawebb		
			2		30-Nov	/		/		/		/		X	X		Wire walk cable worn	Monitor		
																			Decking worn on tower	Monitor
																			Wire bridge mount worn/chain low links worn	Needs repair - LAZ
																			Cracked welds in tower/rust	Needs repair - LAZ
																Rubber Soft fall splitting/holes	Needs repair - PCL			
																Swing chains/brackets/mounts	Monitor			
																bench below tea cup playground coming out of footing	Needs repair - PCL			
																Hole in shade sail	Monitor			
5	GOWRIE PLGR 328	Jeffries St	1	3:26	02-Nov	/		/		/		/			X		Softfall splitting / holes forming	Needs Repair PCL		
			1	6:42	09-Nov	/		/		/		/			X		Timber worn on carousel	Monitor		
			2	6:21	16-Nov	/		/		/		/			X		Spider net worn	Monitor		
			1	6:38	23-Nov	/		/		/		/				X		Softfall Removed from paths	Needs repair PCL	

Name Of Inspector

Joseph

Month of Inspection

Nov-20

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
							/	x	/	x	/	x	/	x	/	x	/	x		
				Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action
12	KAMBAH PLGR 300	Boddington Cres (South) (behind IGA)		1	10:11	02-Nov	/		/		/		/		X		X		Bearings/guide rollers worn on fly fox	Monitor
				1	11:44	09-Nov	/		/		/		/		X		X		Swing mounts/brackets worn	Monitor
				2	11:16	16-Nov	/		/		/		/		X		X		Concrete border lifting	Monitor
				1	10:58	23-Nov	/		/		/		/		X		X		Bridge slats splitting	Monitor
				2			/		/		/		/		X		X		Movement in see saw	Needs repair - LAZ
13	KAMBAH PLGR 582	Boddington Cres (North) (behind pre-school)		1	10:02	02-Nov	/		/		/		/		X		X		Slide plastic worn	Monitor
				1	11:55	09-Nov	/		/		/		/		X		X		Damaged concrete border	Monitor
				2	11:35	16-Nov	/		/		/		/		X		X		Damaged park seat	Needs repair - PCL
				1	11:41	23-Nov	/		/		/		/		X		X		baby swing damaged	Monitor
				2			/		/		/		/		X		X		Plastic Rocks on climb wall cracking/brittle	Monitor
14	KAMBAH PLGR 305	Springbett St		1	10:34	02-Nov	/		/		/		/		X		X		Movement in base of carousel	Needs repair - J&E
				1	10:27	06-Nov	/		/		/		/		X		X		flying fox mount worn/Large flying fox cable	Needs welding/ filing and needs tensioning - LAZ
				1	11:31	09-Nov	/		/		/		/		X		X		Swing seat/brackets/links/mounts worn	Monitor
				1	7:44	13-Nov	/		/		/		/		X		X		Super nova damaged	Monitor
				2	11:02	16-Nov	/		/		/		/		X		X		Spinner bearings worn	Monitor
				1	7:57	20-Nov	/		/		/		/		X		X		Mount worn on large fly fox	Monitor
				1	10:48	23-Nov	/		/		/		/		X		X		Border logs splitting	Monitor
				1	8:33	27-Nov	/		/		/		/		X		X		Sml fly fox movement in bolt/pommel worn/hosing	Monitor - Taped
				2		30-Nov	/		/		/		/		X		X		Tic Tac Toe damaged - Smashed/brittle (taped)	Needs Repair J&E
							/		/		/		/		X		X		Damage panel on quad hoops	Monitor
15	KAMBAH PLGR 295	Summerland Kingsmill St (South)		1	10:55	02-Nov	/		/		/		/		X		X		Low branches at Large flyfox/ Small fly fox grass in bark	Cut back/remove - PCL
				1	12:27	09-Nov	/		/		/		/		X		X		Burn marks at liberty swing seat	Monitor
				2	12:11	16-Nov	/		/		/		/		X		X		Burn low/ washed out/weeds in bark - small fly fox, large swings, carousels	Needs repair - PCL
				1	12:05	23-Nov	/		/		/		/		X		X		Burn mark seesaw	Monitor
				2			/		/		/		/		X		X		Swing mounts	Monitor
16	KAMBAH PLGR 580	Summerland Kingsmill St (North)		1	10:46	02-Nov	/		/		/		/		X		X		Timber swing posts splitting/ missing swings	?
				1	12:17	09-Nov	/		/		/		/		X		X		Worn decks/ bridge - plastic coating peeling	Needs Repair - LAZ
				2	12:00	16-Nov	/		/		/		/		X		X		Damaged rock wall	Monitor
				1	11:55	23-Nov	/		/		/		/		X		X		Rope worn on carousel	Monitor
17	MACARTHUR PLGR 327	Bayly Pl		2			/		/		/		/		X		X		Swing seat / brackets worn	Monitor
				1	2:50	02-Nov	/		/		/		/		X		X		Bark low at swings	Needs Repair PCL
				1	7:25	09-Nov	/		/		/		/		X		X		Worn swing links/brackets	Monitor
				2	6:59	16-Nov	/		/		/		/		X		X		Rope worn on climbing net/carousel	Monitor
				1	7:14	23-Nov	/		/		/		/		X		X		Movement in base towards post of carousel	Needs repair - J&E
			/		/		/		/		X		X		Gravel washed into bark	Needs removal PCL				
			/		/		/		/		X		X		Low bark	Needs Top up - PCL				
THEODORE				1	2:18	02-Nov	/		/		/		/		X		X		Swing mounts/bushes worn	Monitor
				1	7:52	09-Nov	/		/		/		/		X		X		Carousel seat worn/rusting	Monitor
				2	7:27	16-Nov	/		/		/		/		X		X		Worn/damaged deck/bridge	Monitor



Name Of Inspector **Joseph** Month of Inspection **Nov-20**

	Suburb	Street	Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
							/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x			/	x	
				Level 1/2	Time	Date	Hazard																												Action
18	THEODORE PLGR 263	Chippindall Circ		1	7:40	23-Nov	Loose handle/footings on spring animal x 2																												Monitor
				2			Tree branch stuck in shade sail																												Needs Removal PCL
							Holes in shade sail																												Monitor
							Low bark																												Needs Top up - PCL
19	THEODORE PLGR 262	Lawrence Wackett Cres		1	2:29	02-Nov	Weld cracking at slide entry																												Needs Repair - LAZ
				1	7:43	09-Nov	Decking plastic worn/surface rust																												Monitor
				2	7:16	16-Nov	Swing/Chain bridge links/mounts worn																												Monitor
				1	7:31	23-Nov	Movement in frog footing																												Monitor
				2			Border concrete cracking																												Needs Repair - PCL
20	WANNIASSA PLGR 271	Sangster Pl		1	11:07	02-Nov	Swing mounts brackets worn																												Monitor
				1	12:41	09-Nov	Decking worn																												Monitor
				2	12:25	16-Nov	Hole in chain wire fence																												Needs Repair - LAZ
				1	12:17	23-Nov	Park bench missing arm rest																												Needs Repair - PCL
				1			Holes and splitting in softfall																												Needs repair - PCL

Inspectors Signature: J.Djerke

PCL LAZ J&E



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector **Joseph** Month of Inspection **Nov-20**

	Suburb	Street	Type of Inspection		Time of Inspection	Date of Inspection	Playground free of drainage problems				Footings covered with softfall				Softfall free of litter glass/sharp objects				Softfall raked and free of trip hazards				Border secure and in good condition				Equipment in safe and satisfactory condition				Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
			Level 1	Level 2			/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action		
1	BANKS PLGR 213	Menzies Court	1		11:42	03-Nov	/		/		/		/		/		/		X		X					Fort panel cracked/stairs damaged	Monitor					
																											Decking plastic worn/surface rust	Monitor				
			1		9:03	18-Nov	/		/		/		/		/		X		X													
																												Border concrete cracking	Monitor			
2	BANKS PLGR 413	Pocket Ave	MONDAY RUN																													
3	BANKS PLGR 212	Wilson Cres	1		12:05	03-Nov	/		/		/		/		X		X									Bench seat slats loose / missing bolts	Needs Repair PCL					
			1		8:52	18-Nov	/		/		/		/		X		X										Swing seat brackets worn	Monitor				
																												Decking worn	Monitor			
																									Dints in slide bed	Monitor						
																									Border concrete cracking	Needs Repair - PCL						
4	BONYTHON PLGR 245	Hussey Cove (Hocking Pl)	1		9:57	03-Nov	/		/		/		/				X									Posts handrails split/rotting	Monitor					
			1		2:26	17-Nov	/		/		/		/		/				X								4 x Post damaged/split on fort	Monitor				
																												Chain net links and mounts worn	Monitor			
																										Swing mounts worn	Monitor					
5	BONYTHON PLGR 535	Burgoyne St	MONDAY RUN																													
6	BONYTHON PLGR 243	Marquet Retreat / Bottrill St	1		9:38	03-Nov	/		/		/		/		X		X										Border logs splitting	Needs repair - PCL				
			1		2:04	17-Nov	/		/		/		/		X		X											ber decking lifting / splitting/structure s	Needs Repair - J&E - Rebuild			
																													Slide has crack at entry/movement	Monitor		
																										Swing mounts worn	Monitor					
7	BONYTHON PLGR 586	Morice Pl	1		9:48	03-Nov	/		/		/		/				X										Swing seat brackets worn	Monitor				
			1		2:16	17-Nov	/		/		/		/		/				X									Worn / missing rope on net	Monitor			
																													Worn links/mounts on pommel/ climb chain	Monitor		
																										Mount on pommel worn	Needs Repair - LAZ					



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Joseph

Month of Inspection

Nov-20

Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
8	CALWELL PLGR 322	Beckett St	1	8:03	03-Nov	/	/	/	/	/	X	Decking plastic worn	Monitor		
													Swing mounts worn	Monitor	
			1	11:34	17-Nov	/	/	/	/	/	/	X	Bent monkey bars	Monitor	
														Slide weld cracking at top/side	Needs Repair - LAZ
														Chain walk hand rail bent	Needs Repair - LAZ
														Bent deck poles	Needs Repair - LAZ
														Low tree branches	Needs Removal PCL
9	CALWELL PLGR 321	Casey Cres	1	7:42	03-Nov	/	/	/	/	/	X	Swing mounts worn	Monitor		
													Decking plastic worn/decks rusting	Monitor	
			1	11:53	17-Nov	/	/	/	/	/	/	X	Chain net links/coating on chains worn	Monitor	
10	CALWELL PLGR 323	Mountain Circ (Zox Cct)										See saw timber splitting	Monitor		
			1	7:52	03-Nov	/	/	/	/	X	X	Decking plastic worn	Monitor		
														Swing mounts/seat/links worn	Monitor
			1	11:43	17-Nov	/	/	/	/	X	X	Low branches	Needs cut back back-PCL		
11	CALWELL PLGR 319	Samuel Cl										Side leg bent	Monitor		
			1	7:31	03-Nov	/	/	/	/	X	X	Border logs splitting	Monitor		
														Swing mounts worn	Monitor
12	CALWELL PLGR 644	Shopping Centre	1	12:01	17-Nov	/	/	/	/	X	X	Bent monkey bars	Monitor		
														Park bench missing timber	Needs Repair - PCL
			1	7:13	03-Nov	/	/	/	/	/	/	X	Swing mounts/seat/S hooks worn	Monitor	
13	CALWELL PLGR 320	Were St											Bark low	Top up bark PCL	
			1	12:26	17-Nov	/	/	/	/	/	/	X	Carousel movement in bearing	Monitor	
			1	7:24	03-Nov	/	/	/	/	/	X	X	Border logs splitting/ missing	Needs Repair - PCL	
14	CHISHOLM PLGR 234	Alston St											Swing links/mounts worn	Monitor	
			1	12:17	17-Nov	/	/	/	/	X	X	Tire worn on tyre swing	Monitor		
			1	6:44	04-Nov	/	/	/	/	/	/	X	Rope net install satisfactory?	Level 3 ?	
												Swing mounts worn	Monitor		
													Damaged tic tac toe	Monitor	
													Baby seat chain cover worn	Monitor	



Name Of Inspector		Joseph		Month of Inspection							Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report			
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition								
28	FADDEN PLGR 224	McPhail Pl (Bow Pl)	1	12:57	16-Nov	/	/	/	/	/	X	X	Movement in carousel base	Monitor			
														Decking timber splitting	Monitor		
															Chain net links / mounts worn	Monitor	
															Lichen growing on decks	Monitor	
29	FADDEN PLGR 509	Nicklin Cres	1	8:43	04-Nov	/	/	/	/	/	X	X	Rocks missing in border wall	Needs Repair - PCL			
														Rope bridge mount broken/rope worn	Needs Repair PCL		
			1	1:10	16-Nov	/	/	/	/	/	X	X	Climbing nets rope worn	Monitor			
															Panel/ roof panels cracked on fort	Monitor	
30	FADDEN PLGR 229	Parnell Pl (Courtice Cl)	1	8:32	04-Nov	/	/	/	/	/	X	X	Swing mounts/ links worn	Monitor			
														Damaged baby swing	Monitor		
			1	1:19	16-Nov	/	/	/	/	/	X	X	Border logs worn	Monitor			
															Dent in parallel bars/swing post	Monitor	
	GILMORE	Heagney Cres	1	7:50	04-Nov	/	/	/	/	/	X	X	Concrete border damaged/lifting	Monitor			
															Rubber frog damaged	Monitor	
			1	6:36	17-Nov	/	/	/	/	/	X	X	Low bark	Needs Top up - PCL			
31	GILMORE PLGR 238	Hogue Pl	1	7:42	04-Nov	/	/	/	/	/	X	X	Fence damaged	Monitor			
															Spinner seats worn/ rusting	Monitor	
			1	6:27	17-Nov	/	/	/	/	/	X	X	Obscene Graffiti etched in bench seat	Needs Removal PCL			
32	GILMORE PLGR 239	Rosman Circ	1	8:01	04-Nov	/	/	/	/	/	/	X	Bridge timber splitting	Monitor			
															Concrete at bench lifting	Needs Repair PCL	
			1	6:46	17-Nov	/	/	/	/	/	/	X	Damaged rock wall	Needs Repair PCL			
33	GORDON PLGR 215	Iredale Pl	1	10:51	03-Nov	/	/	/	/	/	/	X	Swing seat brackets worn	Monitor			
															Chain net/ladder links worn/plastic	Monitor	
			1	9:52	18-Nov	/	/	/	/	/	/	X	Damaged post caps x 4	Monitor			
																Slide damaged	Monitor
34	GORDON DT GR 216	Kirkwood Cres	1	11:11	03-Nov	/	/	/	/	/	X	X	Swing seat brackets/mounts wearing	Monitor			
																Slide surface dented	Monitor
			1	9:33	18-Nov	/	/	/	/	/	X	X	Dent in swing crosbar/see saw seat	Monitor			



Name Of Inspector		Joseph		Month of Inspection							Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
52	ISABELLA PLAINS PLGR 280	Findon Pl	1	10:09	3:11	/	/	/	/	/	X	X	Ropes worn on web	Monitor		
														Decks/Posts splitting/rotten	Monitor	
			1	11:01	17-Nov	/	/	/	/	/	X	X				
															Concrete border lifting	Needs Repair PCL
															Gaps were slide joints	Monitor
												Swing timber splitting	Monitor			
53	ISABELLA PLAINS PLGR 281	Keverstone Circ	1	10:28	03-Nov	/	/	/	/	/		X				
														Swing mounts worn	Monitor	
			1	11:20	17-Nov	/	/	/	/	/		X			Plastic slide cracked	Monitor
															Movement in swing posts	Monitor
													Frog plastic worn around handle	Monitor		
54	ISABELLA PLAINS PLGR 282	Yabtree Pl	1	10:19	03-Nov	/	/	/	/	/	X	X	Border path concrete cracking	Monitor		
														Slide surface worn	Monitor	
			1	11:11	17-Nov	/	/	/	/	/	X	X	Chain net links	Monitor		
															Damaged post	Monitor
													Spring animal missing	Needs repair - J&E		
55	KAMBAH PLGR 312	Allchin Circuit No 1	1	2:11	05-Nov	/	/	/	/	/		X	Slide leg loose in footing	Monitor		
														Low bark	Top - PCL	
			1	12:03	20-Nov	/	/	/	/	/		X			Spring animal loose in footing	Monitor
													Angle bar missing at climbing net damaged	Needs repair - LAZ		
56	KAMBAH PLGR 311	Ammon Pl (Rundle Pl)	1	9:13	05-Nov	/	/	/	/	/	X	X	Border logs splitting	Monitor		
														Swing mounts/brackets worn	Monitor	
			1	12:14	20-Nov	/	/	/	/	/	X	X			Concrete lifting quad hoop game	Monitor
															Chain net links / mounts worn	Monitor
													Slide surface worn	Monitor		
57	KAMBAH PLGR 313	Attiwell Circ	1	1:44	05-Nov	/	/	/	/	/	X	X	Border logs damaged	Needs Repair PCL		
														Swing mounts worn/loose due to timber shrinking	Monitor	
			1	11:40	20-Nov	/	/	/	/	/	X	X			Swing timber damage/splitting	Monitor
															Asphalt cracking / lifting	Needs Repair PCL
													See-saw footrest damaged	Monitor		
58	KAMBAH PLGR 314	Barritt St	1	1:35	05-Nov	/	/	/	/	/		X	Damaged flat swing	Monitor		
														Bridge plastic worn/ rusted	Monitor	
			1	11:31	20-Nov	/	/	/	/	/		X			Welds cracked on chain net	Needs Repair - LAZ



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph			Month of Inspection						Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
													Fort panel movement	Monitor	
59	KAMBAH PLGR 300	Boddington Cres (South)	MONDAY RUN												
60	KAMBAH PLGR 582	Boddington Cres (North)	MONDAY RUN												
61	KAMBAH PLGR 301	Boustead Circ	1	12:52	05-Nov	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Damaged plastic on stairs	Monitor
			1	10:46	20-Nov	/	/	/	/		X	X	Rusting at bottom of stairs	Monitor	
62	KAMBAH PLGR 298	Brimage Pl (McCulloch Pl)	1	7:58	05-Nov	/	/	/	/		X	X	Timber decking splitting	Monitor	
														Swing posts splitting and rotten	Monitor
			1	1:17	20-Nov	/	/	/	/		X	X	Movement in ladder plate to decking	Monitor	
63	KAMBAH PLGR 317	Bullock Circ	1	1:25	05-Nov	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Rubber on stairs splitting	Monitor
			1	11:21	20-Nov	/	/	/	/		X	X	Worn rubber on deck	Needs Repair LAZ	
														Climb chain/bridge links worn	Monitor
												Spring animal spring plate weld c	Needs Repair LAZ		
												Swing mounts/brackets worn	Monitor		
64	KAMBAH PLGR 299	Coghill Cl	1	6:45	05-Nov	/	/	/	/		X	X	Swing mounts worn	Monitor	
														Border logs splitting/damage	Needs repair - PCL
			1	2:32	20-Nov	/	/	/	/		X	X	Carousel loose - movement in bearing	Monitor	
65	KAMBAH PLGR 294	Crouch Pl (Ortloff Pl)	1	12:23	05-Nov	/	/	/	/		X	X	Border sleepers splitting	Monitor	
														Swing mounts worn	Monitor
			1	10:21	20-Nov	/	/	/	/		X	X	Decking plastic worn	Monitor	
															Low bark
												Low bark	Needs Top up - PCL		
												Low bark	Needs Top up - PCL		
													flying fox handle/mount/links worn	Monitor	
													Bridge timber splitting	Monitor	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection							Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
													Bridge/climbing net links worn	Monitor		
66	KAMBAH PLGR 304	Dale Circ	1	11:50	05-Nov	/	/	/	/			X	X	Border sleepers splitting	Monitor	
															Decks rusty/ plastic peeling	Needs Repair LAZ
			1	9:52	20-Nov	/	/	/	/			X	X	Bridge rusty/ plastic worn	Monitor	
67	KAMBAH PLGR 291	Deuchar Cl												Swing brackets/mounts worn	Monitor	
			1	6:34	05-Nov	/	/	/	/			X	X	Decking plastic worn/surface rust	Monitor	
			1	2:47	20-Nov	/	/	/	/			X	X	Border sleepers splitting	Monitor	
68	KAMBAH PLGR 315	Faithfull Circ (Kambah Pool Rd)												Swing mounts worn	Monitor	
			1	1:55	05-Nov	/	/	/	/			X	X	Border logs splitting	Needs Repair PCL	
			1	11:50	20-Nov	/	/	/	/			X	X	Decking plastic worn	Monitor	
69	KAMBAH PLGR 288	Friend Pl (Crafter Pl)												Bushes worn on see saw	Needs Repair LAZ	
			1	8:48	05-Nov	/	/	/	/			X	X	Swing mounts worn	Monitor	
			1	12:26	20-Nov	/	/	/	/			X	X	Bark low	Needs top up - PCL	
70	KAMBAH PLGR 284	Gibbs Pl												Rocks missing on rock wall	Needs Repair PCL	
			1	7:46	05-Nov	/	/	/	/					Damaged bolt caps	Monitor	
			1	1:26	20-Nov	/	/	/	/					Bridge timber splitting	Monitor	
71	KAMBAH PLGR 289	Horton Cl												Knobs and crosses cracking	Monitor	
			1	6:40	05-Nov	/	/	/	/			X	X	Bolt caps brittle/damaged on tower	Monitor	
			1	2:40	20-Nov	/	/	/	/			X	X	Chain net links worn	Monitor	
72	KAMBAH PLGR 287	Haskett St (Shearer Pl)												Decking plastic worn/rusting	Needs Repair LAZ	
			1	8:27	05-Nov	/	/	/	/			X	X	Damaged/missing/loose border timber	Needs Repair - PCL	
			1	12:47	20-Nov	/	/	/	/			X	X	Parallel slide bar bent	Monitor	
													Wearing swing brackets	Monitor		
														Border sleepers splitting	Monitor	
														Bridge/ chain net links worn	Monitor	
														Border sleepers splitting	Monitor	
														Swing mounts/brackets worn	Monitor	



Name Of Inspector		Joseph		Month of Inspection								Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
73	KAMBAH PLGR 307	Humble Court	1	1:48	20-Nov	/	/	/	/	/	X	X	Slide dented	Monitor		
														Low bark	Needs Repair - PCL	
74	KAMBAH PLGR 318	Karney St (Hiles Pl)	1	12:37	05-Nov	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
														Deck/bridge plastic worn	Monitor	
			1	10:32	20-Nov	/	/	/	/	/		X		Handle loose on turtle	Monitor	
75	KAMBAH PLGR 286	Lascelles Circ	1	8:07	05-Nov	/	/	/	/		X	X	Border Sleepers splitting	Monitor		
														See saw Top centre plate cracked	Needs Repair - LAZ	
			1	1:05	20-Nov	/	/	/	/		X	X	Low branches	Cut back - PCL		
														Bridge slats splitting/links worn/movement	Monitor	
												Chain net links worn	Monitor			
												Decking plastic worn	Monitor			
76	KAMBAH PLGR 325	Learmonth Dr	1	1:13	05-Nov	/	/	/	/		X	X	Fort Timber panels worn/split	Monitor		
														Climb net ropes worn	Monitor	
			1	11:11	20-Nov	/	/	/	/		X	X	Timber posts splitting	Monitor		
															Rock wall missing rocks	Monitor
															Damaged bolt caps on equipment	Monitor
												Spring motorcycle panels worn	Monitor			
77	KAMBAH PLGR 309	Livingstone Ave (Symers St)	1	6:54	05-Nov	/	/	/	/		X	X	Border sleepers splitting	Monitor		
			1	2:25	20-Nov	/	/	/	/		X	X	Bum marks on post / slide	Monitor		
															Bridge/Climb net links worn	Monitor
												Bridge slats splitting/movement worn timber	Monitor			
78	KAMBAH PLGR 313	Livingstone Ave (Fimister Cct)	1	7:07	05-Dec	/	/	/	/	/		X	Monitor all links in hosing	Monitor		
														Damaged rubber chain hose	Monitor	
			1	2:07	20-Nov	/	/	/	/		/		X	Bench seat slat damaged	Needs Repair PCL	
79	KAMBAH PLGR 314	Mannheim St	1	7:37	05-Nov	/	/	/	/		X	X	Border logs splitting	Monitor		
															Bridge slats splitting	Monitor
			1	1:36	20-Nov	/	/	/	/		X	X	Swing mounts worn	Monitor		
															Welds cracked at slide entry	Needs Repair - LAZ
												Bridge links worn	Monitor			



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector **Joseph** Month of Inspection **Nov-20**

ID	KAMBAH PLGR	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Month of Inspection										Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
						Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition						
80	KAMBAH PLGR 285	Marconi Cres	1	8:19	05-Nov	/	/	/	/	/	/	/	X	Swing brackets/mounts worn	Monitor		
														Gravel washed/weeds into bark	Needs Removal - PCL		
			1	12:57	20-Nov	/	/	/	/	/	/	/	X	Deck edge wear	Monitor		
															Spring bear loose in footing	Monitor	
81	KAMBAH PLGR 308	Maxworthy St	1	7:03	05-Nov	/	/	/	/	/	/	X	Swing mounts worn	Monitor			
														Bark low	Needs Top up - PCL		
			1	2:16	20-Nov	/	/	/	/	/	/	/	X	Damaged spinner seats x2	Monitor - Siliconed holes		
82	KAMBAH PLGR 292	McKillop Pl	1	12:11	05-Nov	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
														Swing seat/brackets worn	Monitor		
			1	10:12	20-Nov	/	/	/	/	/	/	X	X	Bridge/decks rusting	Needs repair - LAZ		
												Flat swing seat damaged	Monitor				
83	KAMBAH PLGR 296	MacLeod Pl (Paech Pl)	1	12:44	05-Nov	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
														Slide has small dents	Monitor		
			1	10:39	20-Nov	/	/	/	/	/	/	X	X	Split rubber on stairs	Monitor		
												Graffiti on panel	Needs Removal PCL				
84	KAMBAH PLGR 302	Pinkerton Circ	1	12:00	05-Nov	/	/	/	/	/	X	X	Border timber splitting/damaged	Needs Repair - PCL			
														Decking plastic worn/surface rust	Monitor		
			1	10:01	20-Nov	/	/	/	/	/	/	X	X	Swing mounts/links/brackets worn	Monitor		
															Low tree branches	Needs removal- PCL	
												Exposed tree roots in bark	Needs removal- PCL				
												Bark low	Needs Top up - PCL				
85	KAMBAH PLGR 306	Primmer Court	1	9:00	05-Nov	/	/	/	/	/	/	/					
			1	12:38	20-Nov	/	/	/	/	/	/	/	/	New playground equipment installed	Has it been certified		
86	KAMBAH PLGR 303	Rounsevell St	1	1:02	05-Nov	/	/	/	/	/	X	X	Border sleepers splitting	Monitor			
														Swing mounts worn	Monitor		
			1	11:01	20-Nov	/	/	/	/	/	/	X	X	Slide metal rusting/ dented	Monitor		
															spring animal footing loose	Monitor	
												Lap seat worn	Monitor				



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Joseph

Month of Inspection

Nov-20

ID	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
													Monday	Tuesday
87	KAMBAH PLGR 305	Springbett St	MONDAY RUN											
88	KAMBAH PLGR 295	Summerland Kingsmill St (South)	MONDAY RUN											
89	KAMBAH PLGR 580	Summerland Kingsmill St (North)	MONDAY RUN											
90	KAMBAH PLGR 290	Toole Pl	1	11:41	05-Nov	/	/	/	/	X	X	Swing posts splitting	Monitor	
													Swing mounts/brackets worn	Monitor
			1	9:43	20-Nov	/	/	/	/	X	X	Swing Mounts have small movement due to worn timber	Monitor	
													Bridge links worn	Monitor
													Climb net links/mounts worn	Monitor
													Slide loose at entry bracket	Monitor
										Seesaw centre plate bolt/mount	Needs repair - LAZ			
										Border sleepers splitting	Monitor			
91	KAMBAH PLGR 293	Vanzetti Cres	1	7:16	05-Nov	/	/	/	/	X	X	Border sleepers splitting	Monitor	
			1	2:00	20-Nov	/	/	/	/	X	X	Movement in stair footing	Monitor	
													Bridge plastic worn/rusting	Monitor
										Swing mounts/brackets worn	Monitor			
92	MACARTHUR PLGR 327	Bayly Pl	MONDAY RUN											
93	MACARTHUR PLGR 326	Merriman Cres (Hardie Cl)	1	8:11	04-Nov	/	/	/	/	X	X	Decking worn	Monitor	
													Chain net links/mounts worn	Monitor
			1	2:20	16-Nov	/	/	/	/	X	X	Bent deck poles	Monitor	
													Border damaged/rotted	Needs Repair - PCL
										Worn timber on spring horse	Monitor			



Name Of Inspector		Joseph		Month of Inspection							Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
														Bark low	Needs Top up - PCL	
94	MONASH PLGR 252	Alabaster St	1	10:27	04-Nov	/	/	/	/	/	X	X	Border sleepers splitting	Monitor		
														Swing mounts/ links worn	Monitor	
			1	10:23	17-Nov	/	/	/	/	/	X	X	Bite marks in swing seat	Monitor		
															Damaged spiral ladder	Monitor
															Damaged tic tac toe	Monitor
													Worn/rusting bridge	Monitor		
95	MONASH PLGR 248	Charleston St	1	10:55	04-Nov	/	/	/	/	/		X	Posts splitting and rotten	Monitor - inspect PCL / J&E		
														Swing mounts/links/brackets worn	Monitor	
			1	10:00	17-Nov	/	/	/	/	/		X	Bridge mounts/chain worn	Needs Repair LAZ		
															Bridge timber splitting	Monitor
													Fibreglass damaged/cracking/worn on slides	Monitor		
96	MONASH PLGR 251	Clive Steele Ave (Harkness St)	1	10:39	04-Nov	/	/	/	/	/	X	X	Steering wheel bracket worn	Monitor		
														Border timber splitting/missing	Needs Repair - PCL	
			1	10:11	17-Nov	/	/	/	/	/	X	X	Dirt washed into bark	Needs repair - PCL		
													Slide surface worn	Monitor		
97	MONASH PLGR 247	Cockcroft Ave	1	10:00	04-Nov	/	/	/	/	/		X	Swing mounts/ links worn	Monitor		
															Concrete stump at bench	Needs Removal - PCL
			1	10:47	17-Nov	/	/	/	/	/		X	Low hanging branches	Needs Removal - PCL		
													Tree sapplings growing in bark	Needs Removal - PCL		
98	MONASH PLGR 250	Hallstrom Circ	1	11:12	04-Nov	/	/	/	/	/	X	X	Swing brackets/mounts/links worn	Monitor		
															Concrete border lifting	Needs Repair PCL
99	MONASH PLGR 254	Sturdee Cres/ Victor Pl	1	10:14	04-Nov	/	/	/	/	/	X	X	Movement in swing crossbar	Monitor		
															Bridge links/mounts worn/movement	Monitor
			1	10:37	17-Nov	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
															Bent bar/cracked welds on bridge	Needs Repair - LAZ
													Bark low	Needs Top up - PCL		
													Bridge slats splitting / lichen	Monitor		
100	MONASH PLGR 249	William Hudson Cres (Thompson Pl)	1	11:05	04-Nov	/	/	/	/	/		X	Decking plastic worn/rusting	Monitor		
															Triangles worn plastic	Monitor
			1	9:48	17-Nov	/	/	/	/	/		X	Swing mounts/brackets worn	Monitor		
													Spring animal crack in foot rest/head loose	Monitor		
101	OXLEY	Cuthbertson Cres	1	11:31	04-Nov	/	/	/	/	/		X	Horse head splitting	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection							Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition							
101	PLGR 256	(McKibbin Pl)	1	9:30	17-Nov	/	/	/	/	/	/	X	Damaged tyre swing	Monitor		
102	OXLEY PLGR 255	Newman Morris Circ	1	11:39	04-Nov	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
														Bite marks in swing seat	Monitor	
			1	9:18	17-Nov	/	/	/	/	X	X	Bark washing out	Needs repair PCL			
													Border concrete damaged	Needs Repair PCL		
103	RICHARDSON PLGR 501	Casson St (Kennewell Pl)	1	6:40	03-Nov	/	/	/	/	X	X		Border sleepers	Needs Repair PCL		
														Deck plastic worn	Monitor	
			1	1:48	17-Nov	/	/	/	/	X	X		Carousel rusting/loose in footing	Monitor		
													Spring frog handle loose	Monitor		
													Pod mounts worn (eyelet)	Needs repair - LAZ		
104	RICHARDSON PLGR 258	Chauncy Cres	1	7:04	03-Nov	/	/	/	/	/	X		Decking plastic worn	Monitor		
														Swing mounts worn	Monitor	
			1	1:05	17-Nov	/	/	/	/	/	X		Cuts on slide (smoothed)	Monitor		
													Star picks in bark	Needs removal - PCL		
105	RICHARDSON PLGR 259	Clift Cres	1	6:45	03-Nov	/	/	/	/	/	X					
			1	1:36	17-Nov	/	/	/	/	/	X					
106	RICHARDSON PLGR 257	Vidal St	1	6:54	03-Nov	/	/	/	/	/	X		Decking plastic worn/rusting	Monitor		
														Climb net mounts worn	Needs Repair LAZ	
			1	1:14	17-Nov	/	/	/	/	/	X		Damaged spring animal foot rest	Needs Repair LAZ		
															Climb net links worn	Monitor
															Climb net bar bent/deck poles	Monitor
													Tyre swing links worn	Monitor		
													Bark low/tree debris stacked next to p	Needs top up/removal - PCL		
107	THEODORE PLGR 263	Chippindall Circ	MONDAY RUN													
108	THEODORE PLGR 265	Dyett Circ	1	2:20	03-Nov	/	/	/	/	X	X		Border sleepers splitting	Monitor		
														Decking timber splitting	Monitor	
			1	12:43	17-Nov	/	/	/	/	X	X		Chain net links worn	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector

Joseph

Month of Inspection

Nov-20

ID	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report		
													MONDAY RUN	
109	THEODORE PLGR 262	Lawrence Wackett Cres	MONDAY RUN											
110	THEODORE PLGR 261	Louis Loder St	1	2:13	03-Nov	/	/	/	/	X	X	Border logs splitting	Monitor	
			1	12:36	17-Nov	/	/	/	/	X	X	Decking timber splitting	Monitor	
													Slide fibreglass cracking/worn	Monitor
111	THEODORE PLGR 264	Scantleberry St	1	2:31	03-Nov	/	/	/	/	X	X	Border logs splitting	Monitor	
			1	12:56	17-Nov	/	/	/	/	X	X	Slide damaged at top	Monitor	
													Spring animal timber worn	Monitor
													Decking timber/panel splitting	Monitor
112	WANNIASSA PLGR 270	Billson Pl	1	1:16	04-Nov	/	/	/	/	/	X	Decking plastic worn	Monitor	
			1	8:44	17-Nov	/	/	/	/	/	X	Bridge plastic worn	Needs Repair LAZ	
													Damaged tic tac toe	Monitor
113	WANNIASSA PLGR 267	Bussau Cl	1	12:02	04-Nov	/	/	/	/	X	X	Worn rubber on spike spinner	Needs Repair J&E	
			1	7:34	17-Nov	/	/	/	/	X	X	Decking timber worn	Monitor	
													Chain net links worn/plastic peeling	Monitor
114	WANNIASSA PLGR 273	Halfrey Cct (Styles Pl)	1	1:05	04-Nov	/	/	/	/	/	X	Decking plastic worn x 1	Needs Repair - LAZ	
			1	8:34	17-Nov	/	/	/	/	/	X	Swing mounts/brackets worn	Monitor	
													Movement in grab handle	Monitor
115	WANNIASSA PLGR 275	Hervey Pl	1	12:40	04-Nov	/	/	/	/	X	X	Border sleepers/braces splitting	Needs Repair PCL	
			1	8:13	17-Nov	/	/	/	/	X	X	Decking plastic rust / peeling	Monitor	
													Smoking sign loose in footing	Needs Repair PCL
116	WANNIASSA	Tansell Circ	1	11:53	04-Nov	/	/	/	/	X	X	Swing seat damaged/mounts/links worn	Monitor	
													Swing mounts worn	Monitor
												Movement in spring animal	Monitor	



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection							Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition									
116	PLGR 266	Lansen Circ	1	7:26	17-Nov	/	/	/	/	/	/	X	X	Border fence panels damaged	Monitor			
117	WANNIASSA PLGR 269	Sainsbury St	1	1:40	04-Nov	/	/	/	/	/	/	X	X	Border logs splitting	Monitor			
															Holes in shade sail	Monitor		
			1	8:54	17-Nov	/	/	/	/	/	/	/	X	X	Burn marks on tic tac toe	Monitor		
																Bench seat slats damaged	Needs Repair PCL	
118	WANNIASSA PLGR 271	Sangster Pl	MONDAY RUN															
119	WANNIASSA PLGR 276	Steinfeld Circ	1	12:31	04-Nov	/	/	/	/	/	/	X	X	Border Sleepers splitting	Monitor			
															Bench seat slats splitting	Monitor		
			1	8:03	17-Nov	/	/	/	/	/	/	/	X	X	Cracked welds on bridge hand rail	Needs Repair - LAZ		
																Decks worn x 2	Needs Repair - LAZ	
																Bridge slats splitting	Monitor	
																Bridge/Chain net links worn/plastic	Monitor	
120	WANNIASSA PLGR 268	Sullivan Cres	1	1:53	04-Nov	/	/	/	/	/	/	X	X	Bearings / wheels damaged on fly fox trolley	Needs Repair J&E			
																Border logs splitting	Monitor	
			1	9:05	17-Nov	/	/	/	/	/	/	/	X	X	Bridge/chain links worn	Monitor		
																Handle plastic worn on flying fox	Monitor	
0:00	WANNIASSA PLGR 277	Watkins St	1	12:20	04-Nov	/	/	/	/	/	/	X	X	Swing seats/mounts worn/splitting	Monitor			
																Border sleepers damaged	Needs Repair - PCL	
			1	7:52	17-Nov	/	/	/	/	/	/	/	X	X	Swing mounts worn	Monitor		
																Bridge timber splitting	Monitor	
122	WANNIASSA PLGR 274	Wheeler Cres														Park bench missing / damaged timber	Needs Repair - PCL	
			1	12:52	04-Nov	/	/	/	/	/	/	/	X	X	Decking worn/lichen growing	Monitor		
																	Decking worn / rusting	Monitor
			1	8:22	17-Nov	/	/	/	/	/	/	/	X	X	Swing mounts/ links worn	Monitor		
123	WANNIASSA PLGR 272	Whiteman St														Fireman pole damaged	Monitor	
																	Roman triangles links worn plastic worn	Monitor
			1	12:09	04-Nov	/	/	/	/	/	/	/	X	X	Chain net links worn	Monitor		
																	Swing mounts/s hooks/ chains worn	Monitor
															Border logs splitting	Monitor		



Tuggeranong
Playground Inspection
Report 2020

CHIEF MINISTER, TREASURY AND ECONOMIC DEVELOPMENT DIRECTORATE

Name Of Inspector		Joseph		Month of Inspection				Nov-20		Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report
Location	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems	Footings covered with softfall	Softfall free of litter glass/sharp objects	Softfall raked and free of trip hazards	Border secure and in good condition	Equipment in safe and satisfactory condition		



Name Of Inspector

Joseph

Month of Inspection

Nov-20

	Suburb	Street	Location	Type of Inspection Level 1 or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report				
							/	x	/	x	/	x	/	x	/	x				/	x		
1	COTTER PLGR 620	COTTER PICNIC GROUND	1	12:49	06-Nov	/		/		/		/		/				X	Checker plate on decking	Patched by Jason - Urban			
																				Awning luvvers mounts rusting	Monitor		
			1	11:25	18-Nov	/		/		/		/		/					X				
																					Pommels links/mounts worn/ hosing split	Monitor	
																					Swing mounts/brackets worn	Monitor	
																					2 x tread caps missing on surfer	Monitor	
																					Bridge metal slip hazard	Angle / monitor	
																					Basketball backboard worn	Monitor	
																					Climb chain mounts/links worn/hosing split	Monitor	
																					Rubber soft fall worn	Monitor	
2	COTTER PLGR 539	CASURINA SANDS	1	1:07	06-Nov	/		/		/		/		/				X	Spring animal worn timber	Monitor			
																				Post timber splitting	Monitor		
			1	11:38	18-Nov	/		/		/		/		/					X	Decking timber splitting	Monitor		
3	GREENWAY PLGR 538	Pine Island Rd																	Rope bridge wearing	Monitor			
			1	12:46	02-Nov	/		/		/		/		/		X	X	Border logs splitting	Monitor				
			1	9:20	09-Nov	/		/		/		/		/		X	X	Climbing wall worn/rusting	Monitor				
			2	9:03	16-Nov	/		/		/		/		/		X	X	Movement in staircase footing	Monitor				
			1	8:52	23-Nov	/		/		/		/		/		X	X	Swing mounts/chains worn	Monitor				
			1			/		/		/		/		/		X	X	Staircase edges cracking	Needs repair - LAZ				
4	TINBINBILLA NATURE RESERVE PLGR 537	NATURE DISCOVERY PLAYGROUND																	Decks/bridge worn/rusting	Needs repair - LAZ			
																				Bark low/roots in bark	Needs Top up/removal - PCL		
			1	12:07	06-Nov	/		/		/		/		/		X	X	Fence timber splitting around water tanks	Monitor				
																					Timber splitting on large spring platform	Monitor	
			1	10:47	18-Nov	/		/		/		/		/		X	X	Water tanks decking timber splitting/worn	Monitor				
																					Flying fox posts splitting	Monitor	
																					Spider climb net rope frayed	Monitor	
																					Water tanks damaged - Siliconed	Monitor	
																						Tree roots lifting paths	Needs Repair PCL
																						Rubber soft fall splitting	Needs Repair PCL on going problem
																			Slide beds damaged	Monitor			
																			Timber bridges splitting/damaged/lifting/r	Needs repair - PCL			
																			Flat seat swing mounts worn	Swing mounts x2/x2 s hooks - J&			
																			Swing links/seats/brackets worn	Monitor			
																				Side of small slides has cracked welds	Needs repair - LAZ		



Name Of Inspector

Joseph

Month of Inspection

Nov-20

	Suburb	Street	Type of Inspection Level 1or Level 2	Time of Inspection	Date of Inspection	Playground free of drainage problems		Footings covered with softfall		Softfall free of litter glass/sharp objects		Softfall raked and free of trip hazards		Border secure and in good condition		Equipment in safe and satisfactory condition	Hazard Description	Action Taken- For full details please refer to attached Playground Safety Inspection Report	
						/	x	/	x	/	x	/	x	/	x				/
			Level 1/2	Time	Date	/	x	/	x	/	x	/	x	/	x	/	x	Hazard	Action
																		Flying fox cable detached	Needs repair - LAZ

Inspectors Signature: J.Djerke

All inspection and repairs conducted in accordance with AS/NZS 4486:1:1997, AS/NZS 4422:1996 and AS 4685-2004 Page 8. Any item attracting an X to any of the above criteria must be noted on the attached reporting sheet.



Location Theodore Chippindal Cct

Time 12:38

Date

30/11/2020

Name Joseph Djerke

Weather Overcast

Date Next Assessment

ITEM TO BE ASSESSED For potential hazards	✓ x	ISSUE What is the Hazard	RISK L M H V H	REVIEW		
				What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS						
1.01 Good visibility for supervision, surrounds in good condition, no graffiti	/					
1.02 Bubbblers and water features clean and fully operational	/					
1.03 Access ramps, pathways, entrances free of slipping & tripping hazards	/					
1.04 Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/					
1.05 Paths around playground clear of hazards, cracks, trips, vegetation	/					
1.06 Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/					
1.07 Tables, Chairs, Rubbish bin & other ancillary items - secure	X	Shade sail has holes	M	Needs repair		PCL
1.08 Gates, closing & locking devices operational, no finger entrapments (>12mm)	/					
1.09 Access, entrance & ancillary items free of protrusions/sharp edges	/					
SURFACING						
Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings						
2.01 Rubbish that may be hygiene issue removed	/					
2.02 Broken glass, rocks, foreign objects likely to cause injury removed	/					
2.03 Surface in good condition, no trip points	/					
2.04 Drainage operational, no contamination from runoff	/					
LOOSE FILL MATERIAL						
2.06 Check depth min 300mm-400mm top up or rake as required	X	Low bark	H	Top up bark		PCL
2.07 Loose-fill containment edging / barrier secure free of protrusions	/					
2.08 No material deterioration or contamination by clay or other matter	/					
SYNTHETIC MATERIAL						
2.09 Fouling of surface or chewing gum, foreign objects, rocks	/					
2.10 Joints, wear layer, impact attenuation layer or sub-base failure	/					
EQUIPMENT						
Platforms, Structures and frames						
3.01 Foundation and structures free of movement rot or corrosion	/					
3.02 No water penetration into structure or fittings bulging corrosion	/					
3.03 Handrails guardrails barriers decks platforms and bolts present & secure	X	Worn/damaged deck/bridge	L	Monitor		
3.04 Physical damage or missing parts bolts present and secure vandalism	/					
3.05 Check end caps bolts screws tube ends	/					
3.06 No cracked or damaged plastic or wood panels no graffiti	/					
3.07 No protruding screws nails bolts sharp edges splintering or cracks	/					
3.08 Remove loose items brought into playground - ropes rocks sticks	/					
3.09 Equipment free from moss mould unhygienic matter - slip potential	/					
Chains, Ropes, Cables, Nets and Tyres						
3.10 Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	/					
3.11 No fraying of ropes or cable (or ends) - Replace or remove	/					
3.12 Wear in chains & connectors <40%	/					
3.13 No entrapment hazards, no corrosion, no sharp edges	/					
Swings						
3.14 Check for squeaking bushes - lubricate/replace	/					
3.15 Swing action smooth & quiet, seat has no damage or vandalism	/					
3.16 Wear in chains & connectors <40%	X	Swing mounts/bushes worn	L	Monitor		
3.17 Check seat & pivot connections for tightness, s-hooks for closure	/					
3.18 Impact attenuating edge intact, no cracking or exposed metal components	/					
3.19 Drain holes in tyres clear, no exposed metal wire	/					
3.20 Seat clearance from ground min 400mm	/					
Slides						
3.21 No damage or foreign objects on slide bed/sides - exit wear area	/					
3.22 Structure slide & supports - stability looseness corrosion splinters	/					
3.23 Runout section height <350mm (or 200mm up to 1500mm sliding section)	/					
3.24 No entrapments, sliding smooth, overlap of joints downwards	/					
Carousels (rotating equipment)						
3.25 Speed limited to 5m/s	/					
3.26 Smooth & quiet rotation (both directions), platform level & stable	/					
3.27 Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	X	Carousel seat worn/rusting	M	Monitor		
3.28 Underside clear of protrusions & sharp edges	/					
Runways (flying foxes)						
3.29 Trolley motion smooth no loose wire strands speed limited to 7m/s	/					
3.30 End stops haven't moved they bring trolley to a controlled stop	/					
3.31 No loose/missing bolts rot/corrosion (particularly at ground level)	/					
3.32 Is cable secure, platform stable, seat/grip condition, clearance 400mm	/					
Seesaws & rocking equipment (Spring Animals)						
3.33 No looseness in movement or damage, missing bolts/handles	X	Movement in handle/footings on spring animal x 2	L	Monitor		
3.34 No rot or corrosion, foundation movement, splintered timber	/					
Sandpits						
3.35 No ponding water drainage issues or health hazards	/					
3.36 Sand pit edges and supports intact & secure	/					
3.37 Sand raked to remove foreign objects, fouling, glass	/					

RISK LEVEL - SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely - Once every 100yrs)
 2 Unlikely (Conceivable - Once every 30 yrs)
 Possible (Could occur - Once every 10 yrs)
 Likely (Almost certain (On an annual basis)

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 3-4 Serious injury, possible long term absence from school
 5 Very high, potentially fatal or major disability

*The risk level of a hazard is dependent on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 3802:200 Risk Management.

NOTES



Location Theodore Lawrence Wackett Cres

Time

12 59

Date

30/11/2020

Name Joseph Djerke

Weather Overcast

Date Next Assessment

ITEM TO BE ASSESSED For potential hazards	✓ x	ISSUE What is the Hazard	RISK L M H VH	REVIEW		
				What action	When	By Whom
ACCESS ENTRANCE & ANCILLARY ITEMS						
1.01 Good visibility for supervision, surrounds in good condition, no graffiti	/					
1.02 Bubbler and water features clean and fully operational	/					
1.03 Access ramps, pathways, entrances free of slipping & tripping hazards	/					
1.04 Vegetation cut back 2m & free of weeds, litter, glass, syringes etc	/					
1.05 Paths around playground clear of hazards cracks, trips, vegetation	/					
1.06 Seating, tables, fencing, barriers, rubbish bins, bicycle rack - good condition	/					
1.07 Tables, Chairs, Rubbish bin & other ancillary items - secure	/					
1.08 Gates closing & locking devices operational, no finger entrapments (>12mm)	/					
1.09 Access, entrance & ancillary items free of protrusions/sharp edges	/					
SURFACING						
2.01 Pay particular attention to surfacing subject to high use, beneath high equipment, forced movement devices, and exposed footings	/					
2.02 Rubbish that may be hygiene issue removed	/					
2.03 Broken glass, rocks, foreign objects likely to cause injury removed	X	Broken glass on equipment / in bark	H	Removed 30/11/20 - J&E		
2.04 Surface in good condition, no trip points	/					
2.05 Drainage operational, no contamination from runoff	/					
LOOSE FILL MATERIAL						
2.06 Check depth min 300mm-400mm, top up or rake as required	/					
2.07 Loose-fill containment edging / barrier secure, free of protrusions	X	Boarder concrete cracking	M	Needs Repair		PCL
2.08 No material deterioration or contamination by clay or other matter	/					
SYNTHETIC MATERIAL						
2.09 Fouling of surface or chewing gum, foreign objects, rocks	/					
2.10 Joints, wear layer, impact attenuation layer or sub-base failure	/					
EQUIPMENT						
Platforms, Structures and frames						
3.01 Foundation and structures free of movement, rot or corrosion	/					
3.02 No water penetration into structure or fittings, bulging, corrosion	/					
3.03 Handrails, guardrails, barriers, decks, platforms and bolts present & secure	X	Decks plastic worn/surface rust	L	Monitor		
3.04 Physical damage or missing parts, bolts, present and secure, vandalism	X	Movement in chain bridge rails	L	Monitor		
3.05 Check end caps, bolts, screws, tube ends	/					
3.06 No cracked or damaged plastic or wood panels, no graffiti	/					
3.07 No protruding screws, nails, bolts, sharp edges, splintering or cracks	/					
3.08 Remove loose items brought into playground - ropes, rocks, sticks	/					
3.09 Equipment free from moss, mould, unhygienic matter - slip potential	/					
Chains, Ropes, Cables, Nets and Tyres						
3.10 Chains, ropes & nets in good repair, no mods, sharps, cuts, wire strands	X	Chain bridge links/mounts worn	L	Monitor		
3.11 No fraying of ropes or cable (or ends) - Replace or remove	/					
3.12 Wear in chains & connectors <40%	/					
3.13 No entrapment hazards, no corrosion, no sharp edges	/					
Swings						
3.14 Check for squeaking bushes - lubricate/replace	/					
3.15 Swing action smooth & quiet, seat has no damage or vandalism	/					
3.16 Wear in chains & connectors <40%	X	Swing links/mounts worn	L	Monitor		
3.17 Check seat & pivot connections for tightness, s-hooks for closure	/					
3.18 Impact attenuating edge intact, no cracking or exposed metal components	/					
3.19 Drain holes in tyres clear, no exposed metal wire	/					
3.20 Seat clearance from ground min 400mm	/					
Slides						
3.21 No damage or foreign objects on slide bed/sides - exit wear area	/					
3.22 Structure slide & supports - stability, looseness, corrosion, splinters	X	Welds cracking at slide entry	H	Needs repair		LAZ
3.23 Runout section height <350mm (or 200mm up to 1500mm sliding section)	/					
3.24 No entrapments, sliding smooth, overlap of joints downwards	/					
Carousels (rotating equipment)						
3.25 Speed limited to 5m/s	/					
3.26 Smooth & quiet rotation (both directions), platform level & stable	/					
3.27 Covers, seats, pedals, ropes secure, no entrapment, protrusions or sharps	/					
3.28 Underside clear of protrusions & sharp edges	/					
Runways (flying foxes)						
3.29 Trolley motion smooth, no loose wire strands, speed limited to 7m/s	/					
3.30 End stops haven't moved they bring trolley to a controlled stop	/					
3.31 No loose/missing bolts, rot/corrosion (particularly at ground level)	X	Worn links/mounts	L	Monitor		
3.32 Is cable secure, platform stable, seat/grip condition, clearance 400mm	/					
Seesaws & rocking equipment (Spring Animals)						
3.33 No looseness in movement or damage, missing bolts/handles	/					
3.34 No rot or corrosion, foundation movement, splintered timber	X	Spring frog damaged plastic	L	Monitor		
Sandpits						
3.35 No ponding water, drainage issues or health hazards	/					
3.36 Sand pit edges and supports intact & secure	/					
3.37 Sand raked to remove foreign objects, fouling, glass	/					

NOTES

RISK LEVEL ~ SCORING MATRIX *
 [PROBABILITY or LIKELIHOOD] x [CONSEQUENCE or SEVERITY] = LEVEL OF RISK

Probability or likelihood
 1 Rare (Highly unlikely - Once every 100yrs)
 2 Unlikely (Conceivable - Once every 20 yrs)
 Possible (Could occur - Once every 10 yrs)
 Likely (Almost certain (On an annual basis)

Consequences or severity
 0-1 Little or No injury
 1-2 Minor injury requiring some first aid
 2-3 Moderate injury causing absence from school
 3- Serious injury, possible long term absence from school
 4-5 Very high, potentially fatal or major disability

*The risk level of a hazard is dependant on factors including the likelihood of an occurrence and its potential for causing injury or death. The qualitative ratings are found in AS/NZS 360:200 Risk Management.