

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Brief Description
WO98971	PREP	10/06/2025 2:25 PM	71 NORRISS ST, CHISHOLM > Damage to path or other
WO98973	ASSESS	10/06/2025 2:31 PM	Laneway adjacent 71 Norris street, Chisholm, displaced paths, multiple coldmix repairs to make safe

Work Order Supporting Information

WO98971 : Laneway adjacent 71 Norris's street, Chisholm, damaged path, 6.24m2

Last updated by Michael Rootsey10/06/2025 2:24:15 PM

, WR138536 : CSRM Case Number : 00540405

Requester Contact Name: Paula Ludvigson

Phone Number:

Initial enquiry info only. See CSRM for additional correspondence.

Defect location info may be incorrect (address validation limitations).

What is the damage?

Cracked, broken or uneven

What is the material?

Concrete

Could it cause a trip, fall or injury?

Yes

Is it causing traffic or cyclists to swerve?

No

More Information

Uplifted footpath in lane way between Norriss St & Wedgewood Cres. CP have marked it with yellow paint. See Paula in claims team for more details.

Last updated by TCCS Asset Integrations6/06/2025 9:55:42 AM

WO98973 : Laneway adjacent 71 Norriss street, Chisholm, displaced paths, multiple coldmix repairs to make safe

Last updated by Michael Rootsey10/06/2025 2:29:10 PM

Work Order Priority	Work Order Priority Notation	Work Order Actual Finish Date	Work Order Source	Work Order Work Group	Work Order Type
3	Low to Medium Risk (42 days)		Public Enquiry	Concrete - RM	CM - Corrective
1	Very High to Extreme Risk (3 days)	13/06/2025 1:24 PM	Public Enquiry	Concrete - RM	CM - Corrective

Work Order Failure Code	Work Order Cause Code	Work Order Remedy Code	Asset Id	Asset Name
CCK, CCK-02, Concrete - Cracked or displaced, Horizontal displacement (>35mm)	ENV, ENV-02, Environmental, Vegetation	Panel replacement	COPA27623	NORRISS STREET LANEWAY CONCRETE FOOTPATH
CCK, CCK-02, Concrete - Cracked or displaced, Horizontal displacement (>35mm)	MAT, MAT-01, Material, Improper Material	Coldmix	COPA27623	NORRISS STREET LANEWAY CONCRETE FOOTPATH

Asset Category	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb	Work Order Defect Location
Pathways	Concrete - RM	Community Path	Concrete	CHISHOLM	73 Norriss St, Chisholm ACT 2905, Australia
Pathways	Concrete - RM	Community Path	Concrete	CHISHOLM	73 Norriss St, Chisholm ACT 2905, Australia

Asset Id	Asset Name	Asset Status	Asset Category	Work Request ID	Work Request Status	Work Request Status Date
COPA27623	NORRISS STREET LANEWAY CONCRETE FOOTPATH	Active	Pathways	WR138536	INPRG	10/06/2025 2:25 PM

Work Request Created Date	Risk Level	Work Request Brief Description	Asset Suburb	Work Request Defect Location	Work Request Inspection Date
06/06/2025 9:55 AM		71 NORRISS ST, CHISHOLM > Damage to path or other	CHISHOLM	71 NORRISS ST, CHISHOLM ACT 2905	10/06/2025 2:23 PM

Work Request Supporting Information	Work Order ID
<p>WR138536 : CSRM Case Number : 00540405 Requester Contact Name: Paula Ludvigson Phone Number:</p> <p>Initial enquiry info only. See CSRM for additional correspondence. Defect location info may be incorrect (address validation limitations).</p> <p>What is the damage? Cracked, broken or uneven</p> <p>What is the material? Concrete</p> <p>Could it cause a trip, fall or injury? Yes</p> <p>Is it causing traffic or cyclists to swerve? No</p> <p>More Information Uplifted footpath in lane way between Norriss St & Wedgewood Cres. CP have marked it with yellow paint. See Paula in claims team for more details.</p> <p>***Last updated by TCCS Asset Integrations***6/06/2025 9:55:42 AM</p>	<p>WO98971</p>