

FREEDOM OF INFORMATION COVERSHEET

The following information is provided pursuant to section 28 of the *Freedom of Information Act 2016*.

FOI reference: 23-116

Information to be published	Status
1. Access application	Published
2. Decision notice	Published
3. Schedule	Published
4. Documents	Published
5. Additional information identified	Not Applicable
6. Fees	Not Applicable
7. Processing time (in working days)	25 days
8. Decision made by Ombudsman	Not applicable
9. Additional information identified by Ombudsman	Not applicable
10. Decision made by ACAT	Not applicable

11. Additional information identified by ACAT

Not applicable



Freedom of Information - Access Application to Transport Canberra and City Services - Submission confirmation


Your submission has been successful. Please keep a copy of this receipt for your records. Date and time Reference code 08 Oct 2023 8:20:43 PM 4DFVBCRZ GPO Box 158 Transport Canberra and City Services (TCCS) Phone: 02 6207 2987 Canberra ACT 2601 Email: TCCS.FOI@act.gov.au Applicant details Title Given name Family name Preferred name Preferred method of contact Phone Post Contact phone number Contact email address **Contact postal address** Address line 1 Address line 2 Suburb Postcode State Preferred method to receive information * Email Post Same as contact email address Information request Who are you making the request on behalf of? Myself What type of information are you requesting access to? * Other information

What information are you requesting access to under the Act? *

Please provide information for the last five (5) years from the 13th of August 2023 (thus to 13 August 2018) related to all public works, accidents, reports of injury, ambulance requests, 'fix my street' requests, repair works, notifications of issues, quotations or things of a similar nature etc relating to the corner of Flinders Way and Franklin Street in Manuka.

Attach a description or additional details about the information you are requesting access to (optional)
Cnr Franklin St and Flinders Way.JPG
Do you have a similar or identical request currently under review by another ACT Government Directorate?
Yes No
Are you enquiring as
A member of the public
Do you wish to apply for a waiver of fees associated with processing your application?
Yes No
Provide a statement about how the release of information is in the public interest (optional)
Would you like to provide any additional information? (optional)

Attach additional documents to support your application (optional)







Freedom of Information Request - Reference 23-116

I refer to your application for access to government information received by Transport Canberra and City Services (TCCS) on 9 October 2023 in which you sought access to the following government information:

"Please provide information for the last five (5) years from the 13th of August 2023 (thus to 13 August 2018) related to all public works, accidents, reports of injury, ambulance requests, 'fix my street' requests, repair works, notifications of issues, quotations or things of a similar nature etc relating to the corner of Flinders Way and Franklin Street in Manuka."

I thank you for providing the following views on the public interest:

"I believe this corner is dangerous as I was injured there."

Timeframes

A decision is due on your access application by 20 November 2023.

Authority

I am an Information Officer appointed by the Director-General under section 18 of the Act to deal with access applications made under Part 5 of the FOI Act.

Decision on access

In accordance with the FOI Act, a search of TCCS records has been completed and relevant information within our data management systems has been identified. Consistent with the FOI Act, this data has been collated into six records.

In reviewing the information within these records, and applying the public interest test under section 17 of the FOI Act, I have decided to provide you with:

- Partial access to 4 records; and
- Full access to 2 records.

Reasons for my decision are detailed further below in the statement of reasons.

No information relating to ambulance requests were identified to be held by TCCS. In accordance with section 57 of the FOI Act, a copy of the application was provided to the Justice and Community Services Directorate (JACS) to determine if they would hold relevant information. JACS have advised that ambulance records are health records and are therefore not able to be requested under FOI. It is my understanding that JACS have contacted you directly in relation to this part of your application.

Statement of Reasons

In making my decision on disclosing government information, I must identify all relevant factors in schedule 1 and 2 of the FOI Act and determine, on balance, where the public interest lies. In reaching my access decision, I have taken the following into account:

Schedule 1:

No relevant factors identified.

Schedule 2:

Factors favouring disclosure in the public interest (Schedule 2.1)

- Section 2.1(a)(i) promote open discussion of public affairs and enhance the government's accountability;
- Section 2.1(a)(viii) reveal the reason for a government decision and any background or contextual information that informed the decision; and
- Schedule 2.1(a)(xiii) contribute to the administration of justice generally, including procedural fairness.

Factors favouring non-disclosure (Schedule 2.2)

• Section 2.2(a)(ii) - prejudice the protection of an individual's right to privacy or any other right under the *Human Rights Act 2016*.

In reviewing the relevant records, personal information relating to third parties has been identified. I find that factor 2.2(a)(ii) is relevant to this information and I must consider if the disclosure is likely to prejudice the protection of an individual's right to privacy under the *Human Rights Act 2004*. I have found that this information is not readily available to the public and has not otherwise been disclosed by TCCS. I find that the protection of an individual's right to privacy under the *Human Rights Act 2004* carries significant weight. In this instance, I have found the disclosure of personal information to be, on balance, contrary to the public interest.

I find that the factors favouring disclosure can be met with the deletion of information that is contrary to the public interest. A schedule of the relevant records is enclosed at <u>Attachment A</u> and a copy of the relevant records with deletions applied to information contrary to the public interest is enclosed at Attachment B.

Charges

In accordance with <u>Freedom of Information (Fees) Determination 2018</u>, a fee of \$0.35 per page of information disclosed, except for the first 50 pages, may be applied to an access application. I have decided not to apply a fee to your application as the total number of pages marginally exceeds the fee-free threshold.

Online publishing - disclosure log

Under section 28 of the Act, TCCS maintains an online record of access applications called a disclosure log. A copy of your application, my decision and records disclosed to you will be published on the TCCS Disclosure Log within 3 – 10 business days. Your personal information will be deleted from these copies prior to publication.

Ombudsman review

My decision on your access request is a reviewable decision as identified in Schedule 3 of the Act. You have the right to seek an Ombudsman review of this outcome under section 73 of the Act within 20 working days from the day that my decision is published in TCCS' disclosure log, or a longer period allowed by the Ombudsman.

If you wish to request a review of my decision, you may write to the Ombudsman at:

The ACT Ombudsman GPO Box 442 CANBERRA ACT 2601

Via email: actfoi@ombudsman.gov.au

ACT Civil and Administrative Tribunal (ACAT) review

Under section 84 of the Act, if a decision is made under section 82 on an Ombudsman review, you may apply to the ACAT for review of the Ombudsman decision.

Further information may be obtained from ACAT at:

ACT Civil and Administrative Tribunal Level 4, 1 Moore Street GPO Box 370 CANBERRA CITY ACT 2601

Telephone: (02) 6207 1740 www.acat.act.gov.au

If you have any queries concerning the directorate's processing of your request, or would like further information, please contact the TCCS FOI team on (02) 6207 2987 or email to tccs.foi@act.gov.au.

Yours sincerely

Cherie Hughes
Information Officer

14 November 2023

ATTACHMENT A - ACCESS APPLICATION SCHEDULE, FREEDOM OF INFORMATION

Reference Number: 23-116

Please be aware that under the *Freedom of Information Act 2016*, some of the information provided to you will be released to the public through the ACT Government's Open Access Scheme. The Open Access release status column of the table below indicates what documents are intended for release online through open access.

Personal information or business affairs information will not be made available under this policy. If you think the content of your request would contain such information, please inform the contact officer immediately.

Information about what is published on open access is available online at: https://www.cityservices.act.gov.au/about-us/freedom of information/disclosure-log

Factors favouring non-disclosure:

Schedule 2.2(a)(ii) - prejudice the protection of an individual's right to privacy or any other right under the Human Rights Act 2016.

Reference number	Page number	Description	Date	Status	Reason for non-release or deferral	Open Access release status
1	1 - 25	CRM search results	Multiple	Partial access	Schedule 2.2(a)(ii)	Not to be published on the TCCS Disclosure Log
2	26 – 27	IAMS defects search results	Multiple	Full access	Not applicable	as the application relates to personal
3	28 – 38	IAMS search results	Multiple	Partial access	Schedule 2.2(a)(ii)	information.
4	39 – 49	Salesforce search results	Multiple	Partial access	Schedule 2.2(a)(ii)	
5	50 – 76	Work Orders_Franklin street and Flinders way	Multiple	Partial access	Schedule 2.2(a)(ii)	
6	77 – 82	Work Requests_Franklin street and Flinders way	Multiple	Full access	Not applicable	

Total number of documents: 6

REFERENCE	DATE	DATE LAST						CATECORY	CATEGORY	CATEGOR		FOLLO	COMMENT
NUMBER	CREATED	UPDATED	STATUS	QUEUE	SUBJECT	DESCRIPTION	ADDRESS	_	LEVEL 3	Y_LEVEL_ 4	ASSIGNED		CATEGORY
NOIVIBER	CREATED	OPDATED	31A103		FixMyStreet Submission: Footpath &	Footpath & Cycle path Damage to path or others Damage footpath kind of materials?* Concrete What is the issue?* Cracked, broken or uneven Could it cause a trip, fall or injury?*	6 Franklin Street, Griffith ACT 2603,	LEVEL_Z	LEVEL_5	4	ASSIGNED	W_OF	Request for
180830-001208	30/08/2018	30/08/2018	Escalated	1	footpath;	Any additional information?	Australia	Footpaths	Damage				Service
						The posties that deliver in the Manuka Business precinct are reporting that vehicles are more often than not, speeding through the pedestrian crossing at 1 Captain Cook Crescent and not giving way to pedestrians. The posties have reported that numerous times, vehicles have failed to give way to them as they are attempting to cross to the to the other side of the street via the pedestrian crossing							
181030-000022	20/10/2019	20/10/2019	Escalated	Municipal	Road Safety : Fix My Street Report Submission	Is there an opportunity to install speed humps/pedestrian crossing lights at these crossings on both sides of Captain Cook Crescent?	1 Franklin Street, Griffith ACT 2603, Australia	Road Safety				Voc	Request for Service
161030-000022	30/10/2018	30/10/2018	Lscalated	ACT Roads	Man hole cover falling through outside Endeavor house along Franklin street, Manuka. Danger to	Man hole cover falling through outside Endeavor house along Franklin street, Manuka.		noau salety			Dean	Yes	Request for
180926-001026	26/09/2018	13/11/2018	Resolved	1	· ·		Franklin Street	Pot Holes	Road		Dean Newm	nan	nan No

Page 1 of 25

CRM search results

		г	F	Τ	T	In	T			1			
						Can you identify any nearby notable landmarks?:							
						Under cover car park on initial entrance level							
						On public or private land?:							
						Public							
						Type of vehicle?:							
						Car							
						Where is the issue?:							
						Public park							
						Vehicle make							
						Daewoo							
						Vehicle model							
						Tacuma							
						Vehicle color							
						Navy blue							
						Vehicle registration plate							
						YKY 57S							
						Have you seen this vehicle before?:							
						No							
						How long has it been there?:							
						Longer than 10 Days							
						Any vandalism?:							
					FixMyStreet	No							
				City	Submission: Abandoned	Verify Email Address:	Franklin Street &,	Abandoned					Request for
181223-000253	23/12/2018	24/12/2018	Resolved	Rangers	vehicle		Flinders Way	Vehicles				No	Service
						Voucher parking 2 spaces for vehicles however							
						regularly can fit 3 cars. Perhaps check if should be							
						3 spaces? I suppose if only 2 spaces and 3 cars							
						parked just need a voucher displayed for 3rd car.	7 Franklin St,						
				Municinal	Roads : Fix My Street	Just don t want to be booked for not parking within	1						Request for
190111-002121	11/01/2010	14/01/2019	Resolved	1	-	space? Eg double parking?	Australia	Roads					Service
130111-002121	11/01/2013	14/01/2013			Investigation into	Space: Eg double parking:	Australia	Rodds	 				Request for
190211-002532	11/02/2010	11/02/2019		1			Franklin Street		1				Service
120711-007227	11/02/2019	11/02/2019	ivesolven	Rangers	damage to tree	Elindors Way Manuka	Franklin Street &,		 			INU	SEI VICE
						Flinders Way Manuka	1						
				N (1	Doods . Fiv Mr. Charact	5 min parking outside Coles	Flinders Way,			,	امطمئا		Danuart for
					Roads : Fix My Street	Middle spot	Griffith ACT 2603,	<u>.</u>			Nicholas		Request for
190301-001758	1/03/2019	1/03/2019	Escalated	Services	Report Submission	Large pothole	Australia	Roads	-		ourandos	Yes	Service
					Block of the control of		Enville 6:						.
			L		Blocked storm water	L	Franklin Street, and				Margaret		Request for
190227-000086	27/02/2019	4/04/2019	Escalated	Services	drain. needs clearing	Blocked storm water drain. needs clearing.	Flinders Griffith	Stormwater		Į.	Perkovic		Service
						Can you identify any nearby notable landmarks?:							
						Priceline							
						What is the issue?:							
						New tree on street verge/nature strip							
					FixMyStreet	Please provide more information							
					Submission: Trees &	Tree has died and needs to be replaced.	13 Franklin St,						
					shrubs > New tree	Verify Email Address	Griffith ACT 2603,	Grass, tree		۱	isa		
190121-002757	21/01/2019	8/08/2019	Resolved	FMS Trees	planting		Australia	& shrubs	Planting	l.	lederis		
130121 002/3/			1		ı·		<u> </u>	ī					

Page 2 of 25

	1	1	1	_	T	T	1	1	1		1	1	
190808-002157	8/08/2019	14/08/2019	Resolved		FixMyStreet Submission: Roads, parking & vehicles > Roads & traffic >	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Shell Driveway on Finders Way What is the issue?: Potholes What type of pothole are you reporting?: New Where is the pothole?: Other	7 Franklin St, Griffith ACT 2603, Australia	Roads, parking & vehicles	Road & traffic	Potholes			Request for Service
	0,00,101	2 1, 00, 2020			Streetlight out -								
190827-000163	27/08/2019	5/09/2019	Resolved	Streetlight	NeatStreets Ref:	Pole number N338608 out. Reported on 05/08/2029 but the job has not been done.	8 Franklin Street, Griffith	Street Lights	Streetlights	Single bulb out			
					Submission: Roads,	Roads, parking & vehicles Parking & vehicles What is being requested?* Request new parking signage Why do you believe this change is required?* Customer would like a handicapped spot placed out	3 Franklin St, Griffith ACT 2603,	Roads, parking &	Parking &	Request new parking	Greg		Request for
191022-000459	22/10/2019	22/10/2019	Resolved	Services	Parking & vehicles;	the front of the workplace. (endeavour house)	Australia	vehicles	vehicles	signage	Newham		Service
101126 002522	26/11/2010	27/11/2010	Ecclated	Municipal	parking & vehicles > Roads & traffic > Road	What is the issue?: Road condition & safety What would you like to report?: Faded linemarking Please provide more information Faded corner marking Is it posing a safety hazard?: Yes Could it cause a trip, fall or injury?: No Is it causing traffic or cyclists to swerve?:	18-20 Franklin St, Griffith ACT 2603,	Roads, parking &	Road &	Road condition		Voc	Request for
191126-002533	26/11/2019	27/11/2019	Escalated	Services	condition & safety	No	Australia	vehicles	traffic	& safety		Yes	Service
					Submission: Cycle &	What is the issue?: Damage to path or other What is the damage?: Cracked, broken or uneven What is the material?: Concrete Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?: Yes	Manuka Shops Franklin St, Griffith	Cycle &	On road	Damage to path or			Request for
191126-002535	26/11/2019	28/11/2019	Resolved	1	1	Please provide more information:	ACT 2603, Australia	1 '	cycle lanes	other			Service

Page 3 of 25

200108-002203	8/01/2020	15/01/2020	Resolved	FixMyStreet Submission: Roads, parking & vehicles > Roads & traffic >	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Entrance to Coles underground carpark What is the issue?: Potholes What type of pothole are you reporting?: Recurring Where is the pothole?: Road Verify Email Address: xxxxxx@iinet.net.au		Roads, parking & vehicles	Road &	Potholes		Request for Service
		31/01/2020		FixMyStreet	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Adjacent Manuka court What is the issue?: Request replacement parking signage Is the sign:: Broken / damaged What did the sign say? 73. No stop & load zone signs twisted around. Not enforcable Does it affect the flow for traffic or cyclists?: No	Shops, 8 Franklin St,		Parking & vehicles	Request replacem ent parking signage	Yes	Request for Service
191126-002527	26/11/2019	5/02/2020	Resolved	FixMyStreet Submission: Parks & public spaces > Signs > Request cleaning, repair or maintenance	What is the issue?: Request cleaning, repair or maintenance What are you requesting?: Repair What needs to be cleaned, repaired or maintained? Damaged sign Could it cause a trip, fall or injury?: No Is it blocking an access?: No	18-20 Franklin St, Griffith ACT 2603, Australia	Parks & public spaces	Signs	Request cleaning, repair or maintena nce	Yes	Request for Service

Page 4 of 25

			I	<u> </u>			Γ		1	1		
				Municipal	FixMyStreet Submission: Roads, parking & vehicles > Parking & vehicles > Request new parking	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Endeavour House, Cnr Franklin Street and Captain Cook Crescent What is the issue?: Request new parking signage Why do you believe this change is required? Dementia Australia supports clients with Dementia. Can the Commercial Loading Zone be changed to a General Loading Zone to allow dropoffs in a non-metered parking space? Most of our clients have mobility issues and will need extra time allowed. Phone Number:	ENDEAVOUR HOUSE 1 FRANKLIN STREET, GRIFFITH	parking &	Parking &	Request new parking		
200204-001679	4/02/2020	18/02/2020	Escalated	Services	signage	xxxxl@xxxxxxx.org.au	ACT 2603	vehicles	vehicles	signage	Yes	Complaint
200325-000594	25/03/2020	21/04/2020	Resolved		FixMyStreet Submission: Roads, parking & vehicles > Roads & traffic >	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: in the intersection, right hand lane when heading south What is the issue?: Potholes What type of pothole are you reporting?: New Where is the pothole?: Road Phone Number: Verify Email Address: 2116102532020@accesscanberra.act.gov.au.invalid			Road & traffic	Potholes		Request for Service
200323-000594	23/03/2020	Z1/U4/ZUZU	vezoivea	- FUL HUIES		What is the issue?:	GNIFFIITI ACT 2003	verificies	uanic	rotificies		SEI VILE
					FixMyStreet	Multiple bulbs out Pole number (if known) undefined Please provide more information There are no lights working at all on Franklin St from National Circuit to at least Dominion Circuit. It is totally dark going to the carpark.						
190712-000422	12/07/2019	22/04/2020		_	Submission: Streetlights > Multiple bulbs out	Verify Email Address: xxxxxxx@outlook.com	Franklin St, Griffith ACT 2603, Australia		Streetlights	Multiple bulbs out		
130/12-000422	12/0//2019	22/04/2020	ricadived	اع	rividitiple buibs out	AAAAAA@OUUIOOK.COIII	ACT 2003, Australia	Ligiits	Pricerilgins	טעוטא טענ		

Page 5 of 25

					Can you provide any additional information about the location of the job to help us find the issue (i.e. intersections, buildings, landmarks, features)?: On the corner of Canberra Ave and Captin Cook Cres. What is the issue?: Request mowing or maintenance What is the issue?: Overgrown grass Is it blocking access or line of sight?: No Could it cause a trip, fall or injury?: Yes	,						
200521-002437	21/05/2020	22/05/2020	Escalated	 FixMyStreet Submission: Grass, trees & shrubs > Grass	Please provide more information The grass is overgrowing at an exponential rate. I dont believe the ACT government is currently conducting a frequent moving on the government own land. Please conduct asap as it could cause accident. Verify Email Address: xxxx@au.xxxxxxxxxx.com	ENDEAVOUR HOUSE 1 FRANKLIN ST, GRIFFITH ACT 2603	Grass, tree & shrubs	Grass & weeds	Request mowing or maintena nce	Greg Newham	Yes	Request for Service
				FixMyStreet	Can you provide any additional information about the location of the job to help us find the issue (i.e. intersections, buildings, landmarks, features)?: Endeavour House - the paid parking along Captain Cook Crescent What is the issue?: Request new parking signage Why do you believe this change is required? Dementia Australia is moving to Griffith next month and we will be holding support programs fo clients with Dementia. Can one of the metered carparks on Captain Cook Crescent at Endeavour House be designated as a Disabled Parking space? Phone Number:	,	Roads,	Parking &	Request	Pauline		
200204-001734	4/02/2020	15/07/2020	Forwarded to SME	signage	Verify Email Address:	ACT 2603	parking & vehicles	vehicles	parking signage	Bennett	Yes	Request for Service

Page 6 of 25

200717-002270	17/07/2020	11/08/2020	Resolved	Municipal Services		Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: On Franklin St between Capt Cook Cres & Flinders Way there are no pedestrian crossings whatsoever What is the issue?: Road condition & safety What would you like to report?: Request new pedestrian crossing Please provide more information Dementia Australia are relocating into Endeavour House, cnr Franklin and Captain Cook Cres. Parking primarily will be at the Coles Manuka Secure Carparking, however along Franklin Street there are no pedestrian crossings whatsoever. Is it posing a safety hazard?: Yes Could it cause a trip, fall or injury?: Yes Phone Number: Verify Email Address: xxxxx@xxxxxxxxxxxxxxxxxxxxxxxxxxxxx		Roads, parking & vehicles	Road & traffic	Road condition & safety		Yes	Request for Service
						Parks & public spaces Toilets							
						What is being requested?* Request cleaning, repair or maintenance							
						What is the issue?*				Request			
						Repair				cleaning,			
					FixMyStreet	What needs to be cleaned, repaired or maintained?	SHOPS 14 FRANKLIN	Parks &		repair or			
					Submission: Parks &		ST, GRIFFITH ACT	public		maintena	Margaret		Request for
200820-001047	20/08/2020	20/08/2020	Resolved	Services	public spaces; Toilets;	Hand dryer stick on in disabled toilet.	2603	spaces	Toilets	nce	Perkovic		Service

Page 7 of 25

							<u> </u>					
					FixMyStreet Submission: Roads, parking & vehicles > Roads & traffic > Road	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Franklin Street, Griffith adjacent COLES EXPRESS SHELL SERVICE STATION What is the issue?: Road signs What are you requesting?: Replacement of existing signage Please provide more information Sign post with NO STOPPING left arrow and PAY PARKING right arrow not securely fixed in ground. Signs are bent and rotated away from road side, both zones unenforceable, leading to dangerous parking in NO STOPPING zone. Urgent. ACT PARKING OPS. Is it posing a safety hazard?: Yes Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?:	ENDEAVOUR HOUSE 7 FRANKLIN ST, GRIFFITH ACT	parking &	Road &	Road		Request for
200810-001678	10/08/2020	9/09/2020	Resolved	l		No	2603		traffic	signs		Service
				ACT Roads	FixMyStreet Submission: Roads, parking & vehicles > Roads & traffic >	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: At the entrance of the Coles Manuka car park. What is the issue?: Potholes What type of pothole are you reporting?: New Where is the pothole?: Road Verify Email Address:		parking &	Road &			Request for
200827-000622	27/08/2020	11/09/2020	Resolved	- Pot Holes	Potholes	xxxxxxx@gmail.com	2603	vehicles	traffic	Potholes		Service
					FixMyStreet Submission: Roads,	Roads, parking & vehicles Roads & traffic What is being requested?* Potholes What type of pothole are you reporting?* New pothole Where is the issue?* Road Please provide more information CAR PARK ENTRANCE TO COLES MANUKA ON FRANKLIN STREET, LARGE POT HOLES. MANY	FRANKLIN STREET	Roads, parking &	Road &			Request for
200903-001351	3/09/2020	11/09/2020	Resolved	- Pot Holes	Roads & traffic;	THANKS	GRIFFITH	vehicles	traffic	Potholes		Service

Page 8 of 25

							T	ı		-			
				Action Not		FixMyStreet Submission: Water; Stormwater &		•	Water &	Stormwater			Request for
201028-0019	92 28/	10/2020	4/11/2020	Required	ACT Roads		Yes	2603	Sewerage	& sewerage			Service
201202-0029	908 2/	/12/2020	3/12/2020			FixMyStreet Submission: Streetlights > Multiple bulbs out	What is the issue?: Multiple bulbs out Pole number (if known) 220128 Please provide more information multiple bulbs out on canberra avenue near manuka oval Verify Email Address: 252222122020@accesscanberra.act.gov.au.invalid	•	Street Lights	Streetlights	Multiple bulbs out		
210119-0013	373 19/0	01/2021	21/01/2021	Action Not Required		FixMyStreet Submission: Parks & public spaces > Signs >	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: located outside shell service station - stop sign damage What is the issue?: Request cleaning, repair or maintenance What are you requesting?: Repair What needs to be cleaned, repaired or maintained? Stop sign damaged Could it cause a trip, fall or injury?: No Is it blocking an access?:	1-17 FRANKLIN ST, GRIFFITH ACT 2603	I.	Signs	Request cleaning, repair or maintena nce		Request for Service

			1	ı		Danda madina Quahida	I	I	ı	1	ı	I	
						Roads, parking & vehicles							
						Roads & traffic							
						What is being requested?*							
						Potholes							
						What type of pothole are you reporting?*							
						New pothole							
						Where is the issue?*							
					FixMyStreet	Other							
					Submission: Roads,	Please provide more information		Roads,					
					parking & vehicles;	DRIVE WAY ENTRANCE TO COLES MANUKA.	FRANKLIN STREET	parking &	Road &				Request for
210317-000956	17/03/2021	20/04/2021	Resolved	ACT Roads	Roads & traffic;	FRANKLIN STREET GRIFFITH.MANY THANKS.	GRIFFITH	vehicles	traffic	Potholes			Service
						Can you provide any additional information about							
						the location of the job to help us find the issue (i.e.,							
						intersections, buildings, landmarks, features)?:							
						Obvious when you enter the car park							
						What is the issue?:							
						Potholes							
						What type of pothole are you reporting?:							
						New	Opposite						
					FixMyStreet	Where is the pothole?:	ENDEAVOUR						
					Submission: Roads,	Intersection	HOUSE 7 FRANKLIN						
					parking & vehicles >		ST, GRIFFITH ACT	Roads,					
					Roads & traffic >	Verify Email Address:	2603 at entrance to	parking &	Road &				Request for
210406-000433	6/04/2021	20/04/2021	Resolved	ACT Roads	Potholes	xxxx@xxxxxx.com.au	Star Car Wash	vehicles	traffic	Potholes			Service
						Footpath & Cycle path							
						Damage to path or others							
						Damage footpath							
						kind of materials?*							
						Pavers							
						What is the issue?*							
						Uplifting due to tree root							
					FixMyStreet	Could it cause a trip, fall or injury?*							
					Submission: Footpath &	No							
					Cycle path; Damage to	Any additional information?	1-15 Flinders Way,						
				Municipal	path or others; Damage	The trees outside the Coles in Manuka are lifting	Griffith ACT 2603,				Ryan		Request for
180831-000666	31/08/2018	4/09/2018	Escalated	Services	footpath;	the pavers and will cause a fall very soon.	Australia	Footpaths	Damage		Bacon		Service

Page 10 of 25

		1	T	1	Т	Т	Ι	т т	<u> </u>			
						Good afternoon,						
						Please arrange for the following existing Loading		1				
						Zones in Manuka / Griffith to be converted to 24		1				
						hour loading zones.		1				
						- Franklin Street adjacent Capitol Theatre Centre		1				
						- Franklin Street adjacent TAB		1				
						- Flinders Way adjacent Gelatissimo (the road		1				
						markings for this loading zone do not match the		1				
						position of the left arrow sign, please consider		1				
						correcting this)		1				
						It is reasonable for these zones to be converted to		1				
						24 hours as all other parking restrictions in the		1				
						Manuka precinct are either enforceable after-hours		1				
						OR the restrictions change after hours. The		1				
						conversion of these zones will make the zones more consistent across Manuka and will better		1				
						facilitate deliveries to/from businesses in the area.		1				
						As the team leader for LPR parking enforcement, I		1				
						have observed a need for more after-hours loading	The Terrace Shon 4	1				
						zones in the area.	Flinders Way,	1				
				Municipal		Many thanks	Manuka ACT 2603,	1		Margaret		Request for
180924-002025	24/09/2018	25/09/2018			Report Submission	,	Australia	Roads		Perkovic	Yes	Service
						Low colling that the two collectivity would be also as						
					Troop & Chrube : Fix My	I am asking that the trees be trimmed back, on Flinders way, between Murray Way and Franklin St	7/10 Elindors Way	1				
					Street Report	as the leaves and flowers both block gutters and		Grass, tree				
181011-001818	11/10/2018	15/10/2018	Resolved	l	Submission	also sit on awnings.	Australia	& shrubs			Yes	
101011 001010	11/10/2010	13/10/2010	resorred	11110 11000	Customer would like to	and the diff attributes	, tastrana	G 5111 U 25			163	
					see the speed bumps			1				
					put back into place			1				
					along Flinders Way.			1				
					Since they have been			1				
					removed the cars are					1		
					,	Customer would like to see the speed bumps put						
					-	back into place along Flinders Way. Since they have						
					could be a speed van	been removed the cars are flying past at over						
				l		80km. Perhaps there could be a speed van put in						
	00/11/20:-	07/44/22:-				place in the mean time, there are a lot of children	len i vi	[Colleen		Request for
181126-000826	26/11/2018	27/11/2018	Escalated	Services	lot of	in the area.	Flinders Way	Roads		Exposito		Service

Page 11 of 25

	ī	ı	1	1	Ī	los servicios de la companya de la c	I	1	, , , , , , , , , , , , , , , , , , , 		1	
						Can you identify any nearby notable landmarks?:			1			
						Under cover car park on initial entrance level						
						On public or private land?:						
						Public						
						Type of vehicle?:						
						Car						
						Where is the issue?:						
						Public park						
						Vehicle make			1			
						Daewoo			1			
						Vehicle model			1			
						Tacuma						
						Vehicle color			1			
						Navy blue			1			
						Vehicle registration plate						
						YKY 57S			1			
						Have you seen this vehicle before?:						
						No			1			
						How long has it been there?:			1			
						Longer than 10 Days			1			
						Any vandalism?:			1			
					FixMyStreet	No			1			
				City	Submission: Abandoned	Verify Email Address:	Franklin Street &,	Abandoned				Request for
181223-000253	23/12/2018	24/12/2018	Resolved	Rangers	vehicle	xxxxxxx@hotmail.com	Flinders Way	Vehicles			No	Service
									1			
					has called				1			
					requesting repair of a							
					pot hole located next to							
					the pedestrian crossing							
					at 17 Flinders Way in				1			
					Griffith. states	has called requesting repair of a pot hole						
						located next to the pedestrian crossing at 17						
					1.	Flinders Way in Griffith. states that often cars						
					, ,	are parked over the top of this pot hole which may			1			Request for
181212-001843	12/12/2018	15/01/2019	Resolved	- Pot Holes		make it hard to see.	17 Flinders Way	Pot Holes	Road		Yes	Service
					Put in a 50 kilometre							
					speed limit and							
					reinstate the speed		Flinders Way,					
					· ·	Put in a 50 kilometre speed limit and reinstate the	Griffith ACT 2603,	Traffic &		Margaret		Request for
190218-001019	118/02/2019	18/02/2019	Escalated	Services	removed	speed bumps which were removed.	Australia	Road Signs		Perkovic	Yes	Service
	10/02/2013						I . I	1	1 1			
	10/02/2013					Flinders Way Manuka	Franklin Street &,					
	10,02,2013					5 min parking outside Coles	Flinders Way,					
190301-001758		1/03/2019			Roads : Fix My Street	•	•	Roads		Nicholas Lourandos		Request for Service

Page 12 of 25

	T	1			1	Ta	T	1	ı	ı		ī	
						Can you identify any nearby notable landmarks?:							
						Griffith Oval							
						Is the tree blocking a road?:							
						No							
						How tall is the tree?:							
						As tall as a house							
						Is it causing an obstruction?:							
						_							
						No							
						Please describe the issue or upload a photo in the							
						next section so we can assess your request							
						Several large Elm trees situated next to the							
						stormwater drain nearest the Griffith playing fields							
						have snapped and sheered off in the very high							
						winds falling across the cycle and walk way. The							
					FixMyStreet	tree debris is extensive.	Flinders Way, Red						
					Submission: Trees &	Verify Email Address:	Hill ACT 2603,	Grass, tree					
190212-002893	12/02/2019	4/03/2019	Resolved	FMS Trees	shrubs > Fallen tree	xxxxxxx@gmail.com	Australia	& shrubs	Obstruction	Fallen			
130212 002033	12/02/2013	1,03,2013	110011100	11110 11000	Sin above raneir cree	And and a second	rastrana	G 5111 G 55	0.0001.001	- uncii			
						Can you provide any additional information about							
						the location of the job to help us find the issue (i.e.,							
						intersections, buildings, landmarks, features)?:							
						Outside Coles - the middle 5 minute parking space	1						
						pothole 30 cm wide and 15 cm deep							
						What is the issue?:							
						Recurring							
						Where is the issue?:							
						Road							
						Please provide more information							
					FixMyStreet	It s deep and could puncture a tyre							
				ACT Roads	Submission: Potholes >						Dean		Request for
190408-000903	8/04/2019	11/04/2019	Resolved	- Pot Holes			Flinders Way	Pot Holes	Road		Newman		Service
	3,0.,2020	==, 0 :, = 0 = 0		1		RE: Noise levels after 10pm at Manuka Terrace	,						
						Charter Hall (Manuka Terrace) has approved private							
						contractors after hours construction of a small shop							
						above Coles from 11pm to 7am in order to abate							
						•							
						noise for customers at Coles during the day. The							
						noise levels however greatly exceed legal noise							
						thresholds for a residential area after 10pm. The							
						permit to construct a privately held store at the							
						cost of residents living in the complex is a violation.							
						Charter Hall management needs to stop							
						construction activity immediately or risk further							
						legal action.	18 Flinders Way,						
				Municipal	Other : Fix My Street		Griffith ACT 2603,						Request for
190502-000728	2/05/2019	2/05/2019	Escalated		· ·	Regards	Australia	Other				Yes	Service
	, ,			†	Nature Strips : Fix My		17 Flinders Way,				†		
				Municipal	Street Report		Griffith ACT 2603,	Naturestrip			Margaret		Request for
190329-000860	29/03/2019	14/05/2019	Resolved	1	· ·	Please clean the footpaths outside M Centre.	Australia	s			Perkovic	Yes	Service
	, , ,	, ,, .–-	1	ı	ı		ı	1	ı		1		

Page 13 of 25

190628-001243	28/06/2019	2/07/2019	Forwarded to SME	Municipal Services	Snap Send Solve - General Request - 743223	Adshell bus shelter outside Coles, at Franklin St. Griffith has been smashed. Fyshwick cleaning team has removed the broken glass on the floor. Still there is hanging broken glass that needs immediate attention. Sent via Snap Send Solve Fri 28/06/2019 10:43 AM	18, Flinders Way, Griffith, 2603, ACT	Bus Stops				Yes	Request for Service
190730-001689	30/07/2019	30/07/2019			FixMyStreet Submission: Roads, parking & vehicles > Roads & traffic > Road condition & safety	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Outside oliver brown and mee's sushi What is the issue?: Road condition & safety What would you like to report?: Other Please provide more information Kerb and gutter damaged and dangerous Is it posing a safety hazard?: Yes Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?: No Verify Email Address: xxxxxx@xxxx.com	Shops, 11 Flinders Way, Griffith ACT 2603, Australia		Road & traffic	Road condition & safety		Yes	Request for Service
190812-000957	12/08/2019	12/08/2019		Municipal Services	FixMyStreet Submission: Roads, parking & vehicles > Parking & vehicles > Request new parking signage	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Adjacent to Manuka steakhouse What is the issue?: Request new parking signage Why do you believe this change is required? Confusing signage. SIGNS pointing left conflict ONE says five minute PARKING OTHER says 2p all other times when this should be pointing to the right. Means that can t enforce IN this area	Flinders Way, Griffith ACT 2603, Australia	Roads, parking & vehicles	Parking & vehicles	Request new parking signage	Greg Newham		Request for Service

Page 14 of 25

190822-001663	22/08/2019	22/08/2019	Municipal	FixMyStreet Submission: Roads,	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: 5 min parking zone adjacent the Steakhouse next to Manuka Terrace What is the issue?: Request replacement parking signage Is the sign:: Other Please provide more information Officer 73. A 2 hr parking all other times has appeared on top of existing 5min all times sign. These are contradictory to each other and Parking Operations is unable to enforce against this sign arrangement. There isnt a closing sign for the 2hr. What did the sign say? Left hand arrow on a 2 HR all other times Does it affect the flow for traffic or cyclists?: No	19 Flinders Way, Griffith ACT 2603, Australia	Roads, parking & vehicles	Parking & vehicles	Request replacem ent parking signage	Greg Newham		Request for Service
190910-001327	10/09/2019	11/09/2019	Municipal	FixMyStreet	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: On Flinders Way, adjacent Gelatissimo, McDonald s, Manuka. What is the issue?: Road signs What are you requesting?: Replacement of existing signage Please provide more information The recently installed "2P ALL OTHER TIMES" alongside the existing Loading Zone signs both contain left arrows. This renders the 2 hour zone unenforceable by Parking Operations staff, allowing vehicles to park continuously outside of hours. Is it posing a safety hazard?: No Could it cause a trip, fall or injury?: No Is it causing traffic or cyclists to swerve?:	18 Flinders Way, Griffith ACT 2603, Australia	1.	Road & traffic	Road		Yes	Request for Service

Page 15 of 25

		ı		T	Γ	Lug	1	F	T	Ţ	1	
						What is the issue?:						
						Pruning						
						Is the tree/shrub growing from private or public						
						land?:						
						Public						
						What needs to be pruned?:						
						Tree						
						Why does the tree need pruning?:						
						Removal of low branches						
						Is it blocking a road or laneway?:						
						No						
						Is it causing traffic or cyclists to swerve?:						
						No						
						Could it cause a trip, fall or injury?:						
						Yes						
					Fiv MuCtroot							
					I	Was this caused by a recent storm?:						
					Submission: Grass,	No	Flinders Way,		T 0			
101010 001707	10/10/0010	/ /			trees & shrubs > Trees	Please provide more information		Grass, tree				
191010-001787	10/10/2019	14/10/2019	Resolved	FMS Trees	& shrubs > Pruning	Street trees need low branches cut	Australia	& shrubs	shrubs	Pruning		
						Can you provide any additional information about						
						the location of the job to help us find the issue (i.e.,						
						intersections, buildings, landmarks, features)?:						
						2 x sign poles on Flinders Way. Adj Manuka Steak						
						House and Adj McDonald s						
						What is the issue?:						
						Road signs						
						What are you requesting?:						
						Replacement of existing signage						
						Please provide more information						
						The 2 sign poles are not securely fixed in the						
						ground. RIGHT arrow 5 minute sign adj Manuka						
						Steak House and DOUBLE arrow no stopping sign						
						adj McDonald s both regularly spun away from						
						road, unenforceable restrictions and causing						
						dangerous parking.						
						Is it posing a safety hazard?:						
					FixMyStreet	Yes						
					l '	Could it cause a trip, fall or injury?:						
					parking & vehicles >	No	18 Flinders Way,	Roads,				
					I -	Is it causing traffic or cyclists to swerve?:	Griffith ACT 2603,		Road &	Road		Request for
100010 001359	10/00/2010	25/11/2010	Posobiod		Roads & traffic > Road		•		1			-
190910-001358	10/09/2019	25/11/2019	resolved	ACT KONOS	วเลเเว	No	Australia	vehicles	traffic	signs		Service

Page 16 of 25

							<u> </u>						
						Can you provide any additional information about							
						the location of the job to help us find the issue (i.e.,							
						intersections, buildings, landmarks, features)?:							
						Public park pathways opposite Amaya and the Griffith Oval							
						What is the issue?:							
						Report safety concern							
						What are you reporting?:							
						Other							
						Please provide more information							
						Dogs on Lead signage is required on the public							
					FixMyStreet	path and cycle ways.							
					Submission: Parks &			Parks &		Report			
				Municipal	public spaces > Signs >	Verify Email Address:		public		safety			Request for
200128-000065	28/01/2020	30/01/2020	Resolved	Services	Report safety concern	xxxxxx@gmail.com	Flinders Way	spaces	Signs	concern		Yes	Service
						Mens and Womens toilets water at the Griffth							
						Shops are not running. I have tried to contact the							
						City Services Depot for Griffith however was not							
					Water not running in	able to speak to anyone as the number kept cutting					Greg		Request for
200313-001051	13/03/2020	21/05/2020	Resolved	Services	Public Toilets	out.	15 Flinders Way	Roads			Newham		Service
						Can you provide any additional information about							
						the location of the job to help us find the issue (i.e.,							
						intersections, buildings, landmarks, features)?:							
						Telstra site corner of Flinders Way and Murray							
						Cres							
						What is the issue?:							
						Graffiti & vandalism							
						Describe what has been vandalised							
						New bollards around the Telstra station site have							
						been vandalised. One pulled out and removed,							
						another pulled up and left on an angle. Is it posing a safety hazard?:							
						Yes							
					FixMyStreet	If the vandalism is graffiti, is it offensive,							
					1	threatening, racist or obscene?:							
					public spaces > Fencing	1		Parks &					
				Municipal	& bollards > Graffiti &	Verify Email Address:	2 FLINDERS WAY,	public	Fencing &	Graffiti &	Nicholas		Request for
200531-000144	31/05/2020	31/05/2020	Escalated	Services	vandalism	xxxxxx@xxxxxx.com.au	GRIFFITH ACT 2603	spaces	Bollards	vandalism	Lourandos		Service

Page 17 of 25

This car is frequently driven through Manuka with				
extremely loud music and a heart thumping base.				
You can hear it approaching a block away.				
I own a business in Manuka and this car disturbs				
the peace and isn't appreciated by residents,				
shoppers and business owners.				
The driver usually drives through the streets in one				
direction and then the other so I was able to				
photograph it today.				
Can anything be done about it please?				
SHOPS 1 FLINDERS				
Municipal Best regards, WAY, GRIFFITH ACT	Gre	_		
200904-000979 4/09/2020 7/09/2020 Resolved Services Noise nuisance 2603 Other	New	wham	Yes	Complaint
Roads, parking & vehicles				
Parking & vehicles				
What is being requested?*				
Request new parking signage				
Why do you believe this change is required?*				
The area is confusing and people are parking on the				
red bricks. Getting infringements. Could some				
bollards or no parking signs be placed so that				
FixMyStreet people stop parking there. Would also like to Rec	lequest			
Submission: Roads, request that the 2 5minute parking spots out the Roads, new	ew			
Forwarded Municipal parking & vehicles; front of the restaurant could be changed to reflect 25 FLINDERS WAY, parking & parking	arking			Request for
200820-000482 20/08/2020 8/09/2020 to SME Services Parking & vehicles; that they are waiting bays. GRIFFITH ACT 2603 vehicles vehicles sign	ignage		Yes	Service
Cycle & footpaths				
Shared paths				
Blocking the path				
What is causing the obstruction?*				
Other				
Could it cause a trip fall or injury?*				
No No				
is it causing traffic or cyclists to swerve?*				
FixMyStreet No				
TCCS AMIS Submission: Cycle & Please provide more information				
Place Mgt footpaths; Shared works for Parks Construction in VIC and				
	locking			
	he path			

Page 18 of 25

					Really bad pole holes in							
						Really bad pole holes in car park.						
201029-000792	29/10/2020	12/11/2020	Resolved	FMS Trees	· ·		Flinders Way		shrubs	branch		
				I		people use the walking track around there and		Grass, tree	Tree &	fallen		
						lean. Could this please be inspected as many				Remove		
					1	There is a very large tree behind the storage sheds at the CSG Flinders oval that is on a very dangerous						
						Please provide more information						
						No						
						Could it cause a trip, fall or injury? *						
						No						
						footpath? *						
						Is it causing an obstruction to a driveway or						
						No						
						Is it causing traffic or cyclists to swerve? *						
						Is the tree blocking a road? * No						
						No						
						Has it caused damage to private property? *						
						No						
						Was this caused by a recent storm? *						
						Public						
						Is it located on private or public land? *						
						Remove fallen branch						
						Trees & shrubs						
201003-000128	3/ 10/ 2020	15/10/2020	riogiess	Planning	maintenance;	Trees, Grass & shrubs	סאוררווח	Ø SIII UDS	weeus	nce	+	
201009-000128	0/10/2020	15/10/2020		_	1		FLINDERS WAY, GRIFFITH	Grass, tree & shrubs	weeds	maintena		
					1	Please provide more information	ELINIDEDS WAY			or		
					Grass & shrubs; Grass &					mowing		
						Could it cause a trip, fall or injury?*				Request		
					,	No						
						Is it blocking access or line of sight?						
						Overgrown grass						
						What is the issue? *						
						Request mowing or maintenance						
						Trees, Grass & shrubs Grass & Weeds						

Page 19 of 25

	T		T.	ī	T	I- 0 0 1 1	ı	1	1	1		
						Trees, Grass & shrubs						
						Grass & Weeds						
						Request mowing or maintenance						
						What is the issue? *						
						Area missed						
						Is it blocking access or line of sight?						
						No						
					FixMyStreet	Could it cause a trip, fall or injury?*						
					Submission: Trees,	No				Request		
				TCCS AMIS	Grass & shrubs; Grass &	Please provide more information				mowing		
				Place Mgt	Weeds; Request	Area near creek has been missed. No follow up with				or		
			In	Operation	mowing or	whipper snippper.		Grass, tree	Grass &	maintena		
201130-002551	30/11/2020	15/12/2020	Progress	S	maintenance;	OPPOSITE BLOCK OF APARTMENTS	Flinders Way	& shrubs	weeds	nce		
							-					
						Can you provide any additional information about						
						the location of the job to help us find the issue (i.e.,						
						intersections, buildings, landmarks, features)?:						
						Entry and exit of drive-thru						
						What is the issue?:						
						Damage to path or other						
						What is the damage?:						
						Cracked, broken or uneven						
						What is the material?:						
						Concrete						
						Could it cause a trip, fall or injury?:						
						Yes						
						Is it causing traffic or cyclists to swerve?:						
						Yes						
						Please provide more information:						ļ
						The pedestrian crossing markings on the maccas						
						drive-thru is faded and cracked and cannot fully be						ļ
						seen. Needed to repaint however will need to						
						communicate to maccas for a good time to						
					1	complete. Very dangerous.						
					footpaths > Shared	complete. Very dangerous.				Damage		
			Action Not		paths > Damage to path	Verify Email Address:	18 FLINDERS WAY,	Cycle &	Shared	to path or		Request for
201123-002023	23/11/2020	17/12/2020	1	ACT Roads	l	James@xxxxxx.com.au	GRIFFITH ACT 2603	1	paths	other		Service

Page 20 of 25

		In	TCCS AMIS Place Mgt		Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: The 2 cm lip of the concrete drive through driveway at McDonalds which exits at Flinders Way. What is the issue?: Report safety concern What are you reporting?: Other Please provide more information Yesterday at about 1540 while walking from where she had parked her car to Coles Manuka, my 70 year old wife tripped on the 2cm concrete lip to the drive through driveway at McDonalds where it exits into Flinders way, damaging her nose and lip. Phone Number:		Cycle &	Fencing &	Report		
	12/01/2021	Action Not	S	FixMyStreet Submission: Roads, parking & vehicles > Parking & vehicles > Request new parking	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Flinders Way from Manuka roundabout towards Grammar School What is the issue?: Request new parking signage Why do you believe this change is required? All day parking on Flinders Way in Griffith is a traffic hazard. The road from Manuka up the Grammar School is not wide enough to accommodate parked cars and two passing vehicles. Vehicles cross on to the other side of the road to avoid parked cars. Verify Email Address: xxxxxxxx@gmail.com	Manuka	Roads, parking & vehicles	Parking & vehicles	Request new parking signage		Request for Service

Page 21 of 25

	1		1	1	I	Cycle O feetwaths		1	1	1	T	1
						Cycle & footpaths						
						Shared paths						
						Damage to path or other						
						What is the issue? *						
						Cracked, broken or uneven						
						What is the material? *						
						Brick or concrete pavers						
						Could it cause a trip, fall or injury?*						
						Yes						
						Is it causing traffic or cyclists to swerve?*						
						No						
						Please provide more information						
						xxxxxx has tripped over on the lifted red pavement						
						and fallen over on the 26/11/2020 (10.00am) just						
						down the stairs after walking out of						
						Commonwealth Bank in Manuka (Flinders Way) -						
						directly before the pedestrian crossing. There were						
						people who watched and were concearned.						
					1	Advised that he now has a fractured right shoulder						
						and pain on the left sie of his ribs. Went to the				Damage		
			In			· ·	15 flinders way	Cycle &	Shared	to path or		
201029-001847	29/10/2020	18/03/2021					-	I -	paths	other		
						-			1	+	 	
						Cycle & footpaths						
						1 '						
						Shared paths						
						Shared paths Damage to path or other						
						Shared paths Damage to path or other What is the issue? *						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? *						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?*						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?*						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving outside Coles Rebekah						
						Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving outside Coles Rebekah Photos in link below -						
					FixMyStreet	Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving outside Coles Rebekah Photos in link below - https://services.snapsendsolve.com/reports/view/						
					FixMyStreet Submission: Cycle &	Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving outside Coles Rebekah Photos in link below - https://services.snapsendsolve.com/reports/view/ 1299100?signature=eyJhbGciOiJIUzl1NilsInR5cCl6lk				Dames		
					FixMyStreet Submission: Cycle & footpaths; Shared	Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving outside Coles Rebekah Photos in link below - https://services.snapsendsolve.com/reports/view/ 1299100?signature=eyJhbGciOiJIUzI1NilsInR5cCI6Ik pXVCJ9.eyJyZXBvcnRJZCI6MTI5OTEwMCwiaWF0Ijox		Cords 9	Chart	Damage		
201110-000665		18/03/2021			FixMyStreet Submission: Cycle & footpaths; Shared paths; Damage to path	Shared paths Damage to path or other What is the issue? * Cracked, broken or uneven What is the material? * Brick or concrete pavers Could it cause a trip, fall or injury?* Yes Is it causing traffic or cyclists to swerve?* Yes Please provide more information Snap Send Solve - Pavement - Damaged - 1299100 Incident Type: Pavement - Damaged Notes: I just twisted my ankle on this broken paving outside Coles Rebekah Photos in link below - https://services.snapsendsolve.com/reports/view/ 1299100?signature=eyJhbGciOiJIUzI1NilsInR5cCl6lk pXVCJ9.eyJyZXBvcnRJZCl6MTI5OTEwMCwiaWF0ljox NjA0OTU1Njk4fQ.YFA-		1 -	Shared paths	Damage to path or other		

Page 22 of 25 CRM search results

	T	ı	1	T	Т		I	1	1	ı	ı	T	
					FixMyStreet Submission: Cycle & footpaths > Shared	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Trees located outside Wok Me, Manuka Steak House and near crossing What is the issue?: Damage to path or other What is the damage?: Uplifting due to tree root What is the material?: Brick or concrete pavers Could it cause a trip, fall or injury?: Yes Is it causing traffic or cyclists to swerve?: Yes Please provide more information: Pavers around trees have lifted and are a trip hazard				Damage			
			I .		paths > Damage to path		18 FLINDERS WAY,	-	Shared	to path or			
201110-001150	10/11/2020	12/04/2021	Progress	Concrete	or other	xxxxg@xxxxxxl.com.au	GRIFFITH ACT 2603	footpaths	paths	other			
						the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Behind Amaya apartments/public walkway-latitude -35.325771089205425 & Longitude 149.13268406857364 What is the issue?: Pruning Is the tree/shrub growing from private or public land?: Public What needs to be pruned?: Tree Why does the tree need pruning?: Dead wood Is it blocking a road or laneway?: No Is it causing traffic or cyclists to swerve?: No Could it cause a trip, fall or injury?: No Was this caused by a recent storm?:							
						Please provide more information							
					Eivh Austroot	Native large gum tree has a limb to be removed							
					1	due to die back. This is next to the Amaya building complex. The Amya would residence request the							
						mulch of the dead tree limb to be left on site under	12 FLINDERS WAY,	Grass, tree	Tree &				
200927-000031	27/09/2020	4/05/2021	Resolved				GRIFFITH ACT 2603		shrubs	Pruning			

Page 23 of 25 CRM search results

footpaths	Please describe the issue Major trip hazard, as surface isn t flat which imposes a major tripping hazard and accessibility issues.	·	Accessibili ty issues	Garry George	equest for ervice
	example. Full replanting of its Prunus will help revitalize this classic boulevard. Can this be done? Verify Email Address:	Grass, tree	New planting		

Page 24 of 25

			1	1		T	т	1	1	1	1	
						What is the issue?:						
						Pruning						
						Is the tree/shrub growing from private or public						
						land?:						
						Public						
						What needs to be pruned?:						
						Tree						
						Why does the tree need pruning?:						
						Broken branches						
						Is it blocking a road or laneway?:						
						No						
						Is it causing traffic or cyclists to swerve?:						
						No						
						Could it cause a trip, fall or injury?:						
						No						
						Was this caused by a recent storm?:						
						No						
						Please provide more information						
						Because these famous & glorious prunis trees						
						have not been regularly pruned, the branches were						
						overloaded with Summer fruit resulting in broken						
						and splintered branches, crippling these trees.						
					FixMyStreet	These trees need urgent attention.						
					Submission: Grass,							
					trees & shrubs > Trees	Verify Email Address:	12 FLINDERS WAY,	Grass, tree	Tree &			
210424-000472	24/04/2021	6/07/2021	Resolved	FMS Trees	& shrubs > Pruning	xxxxxx@icloud.com	GRIFFITH ACT 2603	& shrubs	shrubs	Pruning		

Page 25 of 25

DEFECT_I					DATE_INSPEC	DATE_REPAIRE			ACTION_DESCRIP		WO_NUMBE
D	STATUS	DESCRIPTION	ACTIVITY_TYPE	DEFECT_TYPE	TED	D	LOCATION	ACTION	TION	SPECIAL_INSTRUCTIONS	R
84417		SWDP-2 Tie Clean from downpipe @ boundry (front). Tree roots have blocked up the storm water out the front of Priceline		Tie Clean to Remove Blockage(SWDP-2)	14/02/2019	11/04/2019	18-20 Franklin Street, Griffith	Tie Clean to Remove Blockage(SWDP-2)		SWDP-2 Tie Clean from downpipe @ boundry (front)	ACT/8682
86173	COMPLETED	Displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Ke rb + Gutt./Con. Is	Paver - Displaced (relay)	16/05/2019	30/07/2019	MANUKA, ALONG FURNEAUX AND FRANKLIN STREET	Paver - Relay		unven pavers in unit and around trees, tripng hazards	
86352	COMPLETED	Displaced pavers at 2 locations	Path/Pram Cross./Veh. Cross./Driveways/Ke rb + Gutt./Con. Is	Paver - Displaced (relay)	31/05/2019	30/07/2019	Flinders Way, Manuka, near corner Franklin St and Pedestrian crossing from Coles	Paver - Relay	at 2 locations in	Relay pavers at 2 locations at which coldmix has been used to make safe.	
86523	COMPLETED	Displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Ke		14/06/2019	30/07/2019	8 Franklin Street, Manuka. Paver border row	Paver - Relay		Relay/Replace pavers. Make safe Image M2	
86524	COMPLETED	Displaced concrete border	Path/Pram Cross./Veh. Cross./Driveways/Ke rb + Gutt./Con. Is	Paver - Displaced (relay)	14/06/2019	30/07/2019	10-12 Franklin Street, Manuka, concrete tree planter	Paver - Relay	Displaced tree	Replace, relay concrete tree border. Make safe. Image M3	
86525	COMPLETED	Displaced pavers	Path/Pram Cross./Veh. Cross./Driveways/Ke rb + Gutt./Con. Is	Paver - Displaced (relay)	14/06/2019	30/07/2019	10-12 Franklin Street, Manuka near bin and sign	Paver - Relay		Relay/replace pavers. Make safe. Image M4	

Page 1 of 2 IAMS defects search results

DEFECT_I		DESCRIPTION	ACTIVITY_TYPE		DATE_INSPEC TED	DATE_REPAIRE			ACTION_DESCRIP	SPECIAL_INSTRUCTIONS	WO_NUMBE
			Path/Pram								
			Cross./Veh.				22 Franklin Street,				
			Cross./Driveways/Ke	Paver - Displaced			Manuka, road side of				
86526	COMPLETED	Displaced pavers	rb + Gutt./Con. Is	(relay)	14/06/2019	30/07/2019	garden wall at crossing	Paver - Relay	Displaced Pavers	Relay pavers. Make safe.	
			Path/Pram							Coldmix repair to make	
			Cross./Veh.							safe adjacent to driveway	
			Cross./Driveways/Ke	Concrete Driveway -			9 Franklin Street,	Concrete Dway - repair	Displaced	at the "Shell Service	
89625	COMPLETED	displaced driveway	rb + Gutt./Con. Is	Damaged	28/11/2019	5/12/2019	Griffith	with coldmix	driveway	station"	

Page 2 of 2

ENQUIRY_	CREATED	COMPLETE						
_		DATE	CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
1059772	24/08/2018	10/10/2018 8:25:03 AM	Community Paths	Complete	ICS FORMS	21 Flinders Way, Griffith ACT 2603, Australia	Asset unable to be matched	Pavers, refer to, 29/08/2018, MR
1060166	4/09/2018		Community Paths	No Action Necessary	ICS FORMS	1-15 Flinders Way, Griffith ACT 2603, Australia	Pavers Uplifting due to tree root. The trees outside the Coles in Manuka are lifting the pavers and will cause a fall very soon.	No trip hazard found.Both sides of the road.
							Please arrange for the following existing Loading Zones in Manuka / Griffith to be converted to 24 hour loading zones. - Franklin Street adjacent Capitol Theatre Centre - Franklin Street adjacent TAB - Flinders Way adjacent Gelatissimo (the road markings for this loading zone do not match the position of the left arrow sign, please consider correcting this) it is reasonable for these zones to be converted to 24 hours as all other parking restrictions in the Manuka precinct are either enforceable afterhours OR the restrictions change after hours. The conversion of these zones will make the zones more consistent across Manuka and will better facilitate deliveries to/from businesses in the area. As the team leader for LPR parking enforcement, I have observed a need for more after-hours loading zones in the area.	inspected today, high demand for parking in manuka precinct, will need to consult MBA if there are any immediate issues, senior management are not supportive of this request - MNW - Will erect 2P all other times in 3 locations only.
1061265	25/09/2018		Road Pavement Traffic Control Device	Closed \ MNW	ICS FORMS	4 Flinders Way, Manuka Flinders Way GRIFFITH	Customer would like to see the speed bumps put back into place along Flinders Way. Since they have been removed the cars are flying past at over 80km. Perhaps there could be a speed van put in place in the mean time, there are a lot of children in the area.	MA enquiry received 1/02/2019 and was sent to RM. No contact details provide.
1068323	18/02/2019		Road Pavement	Received	ICS FORMS	Flinders way, Griffith	Put in a 50 kilometre speed limit and reinstate the speed bumps which were removed.	

Page 1 of 11 IAMS search results

ENQUIRY_	CREATED	COMPLETE						
		DATE	CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
1069002	1/03/2019		Road Pavement		ICS FORMS	Franklin Street &, Flinders Way, Griffith	Flinders Way Manuka 5 min parking outside Coles	
1070554		08/04/2019 10:31:35 AM	Pedestrian Paving	Complete	ICS FORMS	17 Flinders Way, Griffith	Please clean the footpaths outside M Centre.	Sent back to Fix My Street 05042019
		30/07/2019				Along Franklin Street between Furneaux Street and Flinders		Relates to ministerial request ref no#S2019-1340, Refer to Garry
1072531		1:51:41 PM	Pedestrian Paving	Complete	ICS FORMS	Way Manuka	Member of the public has reported trip hazard in unit paving around trees	George, 07/05/2019, MR
1075785		28/08/2019 11:24:43 AM	Kerb	Defect Raised	ICS FORMS	Flinders way, Griffith	Kerb and gutter damaged and dangerous	
1076292	12/08/2019		Street, Warn, Haz, Park, Other	Received	ICS FORMS	Flinders way, Griffith	Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)?: Adjacent to Manuka steakhouse What is the issue?: Request new parking signage Why do you believe this change is required? Confusing signage. SIGNS pointing left conflict ONE says five minute PARKING OTHER says 2p all other times when this should be pointing to the right. Means that can't enforce IN this area	

Page 2 of 11 IAMS search results

ENQUIRY_	CREATED	COMPLETE						
			CLASS	ΣΤΔΤΙΙς	SOURCE	LOCATION	DESCRIPTION	ACTION
	DATE	DATE		STATUS	SOURCE			sent POPS email to confirm
		14/10/2019	Street, Warn, Haz,				Does it affect the flow for traffic or cyclists?:	location, possibly case of wrong sign
1076747		11:05:29 AM		Complete	ICS FORMS	19 Flinders Way, Griffith	No	installation.
1077617			Street, Warn, Haz, Park, Other	Complete	ICS FORMS		The recently installed "2P ALL OTHER TIMES" alongside the existing Loading Zone signs both contain left arrows. This renders the 2 hour zone unenforceable by Parking Operations staff, allowing vehicles to park continuously outside of hours.	emailed POPS to confirm location, possiblity of wrong installtion of left and right arrow.
1086644	18/05/2020		Default Value - Please change	Complete	ICS FORMS	flinders way	Signage	MNW - Remove Bus Zone and Erect R5-41/15 No Parking Pick up Set down during morning and afternoon SCHOOL DAYS

Page 3 of 11 IAMS search results

ENQUIRY_	CREATED	COMPLETE						
_			CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
							Roads, parking & vehicles	
							Parking & vehicles	
							What is being requested?*	
							Request new parking signage	
							Why do you believe this change is required?*	
							The area is confusing and people are parking on the red bricks. Getting	we don't have signs for 'waiting
							infringements. Could some bollards or no parking signs be placed so that	bays' 5min parking is for quick turn
							people stop parking there. Would also like to request that the 2 5minute	around, parking on median is illegal
			Street, Warn, Haz,	_		25 FLINDERS WAY, GRIFFITH	parking spots out the front of the restaurant could be changed to reflect	and enforcable, no signs or bollards
1089523	20/08/2020	12:57:58 PM	Park, Other	Complete	ICS FORMS	ACT 2603	that they are waiting bays.	are warranted in the area - NFA
							Damage footpath	
							kind of materials?*	
							Concrete	
							What is the issue?*	
				No Astisus			Cracked, broken or uneven	
4000000	20/00/2040		Community Daths	No Action	100 500140	C Fue aldie Charact Cuiffith	Could it cause a trip, fall or injury?*	Netformed
1060006	30/08/2018		Community Paths	Necessary	ICS FORMS	6 Franklin Street, Griffith	Yes	Not found
							There are still or possibly new cracked tiles on Franklin St from the Subway	
							along to Gelatissimo. Can Access please repair these. Please advise if these	
				No Action		6-30 Franklin St, Griffith ACT	are not on government land and we will organise our own repairs. Thank	
1060165	4/09/2018		Community Paths			2603, Australia	1	The cracked tiles are on leased land.
1000102	4/03/2018		Community Faths	ivecessary	ICO LOKINO	2003, Australia	you.	THE CLACKED LITES ATE OIL TEASED IAILU.

Page 4 of 11 IAMS search results

ENQUIRY	CREATED	COMPLETE						
_			CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
							Good afternoon	
							I'd like to request a review of the existing loading zone on Manuka Circle,	
							Griffith adjacent the Capitol Theatre Centre.	
							This loading zone creates considerable issues for our parking enforcement	
							units due to the layout of the area. The section of Manuka Circle to which	
							this loading zone applies is less than 4 metres wide. As such, most vehicles	
							occupying this loading zone are not able to leave sufficient space for other	
							vehicles to pass. It is extremely common to see vehicles mounting the	
							gutter and occupying the footpath to accommodate the flow of traffic.	
							This creates a scenario where it is considered improper for an enforcement	
							officer to issue an infringement to said vehicles. Parking officers are not	
							authorised to give drivers permission to park illegally.	
							Please consider converting the loading zone to a pick-up set-down zone.	
							These zones are in very short supply in the Manuka precinct.	
				Classed \			Many thanks	
1061264	25/09/2018		Road Pavement	Closed \ Cancelled	ICS FORMS	6 Franklin St, Griffith	Many thanks	same request as 1061265
1001204	23/03/2018		Road Favernerit	Caricelleu	ICS I ORIVIS	o rrankiiri 3t, driintii		same request as 1001205
							The posties that deliver in the Manuka Business precinct are reporting that	
							vehicles are more often than not, speeding through the pedestrian crossing	
							at 1 Captain Cook Crescent and not giving way to pedestrians.	
							The posties have reported that numerous times, vehicles have failed to	
							give way to them as they are attempting to cross to the to the other side of	
							the street via the pedestrian crossing	
			Traffic Control	<u>.</u>			Is there an opportunity to install speed humps/pedestrian crossing lights at	
1062843	30/10/2018		Device	Received	ICS FORMS	1 Franklin Street, Griffith	these crossings on both sides of Captain Cook Crescent?	
1063496	15/11/2018		Community Paths	Received	ICS FORMS	44 Franklin Street, Griffith	Brick or concrete pavers uplifting due to tree root	
1003430	13/11/2010		Community Fatils	RECEIVEU	ICS I OINIVIS	TT ITAIIMIII JUEEL, OIIIIMI	Brick of concrete pavers upiliting due to tree root	
		11/04/2019					SWDP-2 Tie Clean from downpipe @ boundry (front). Tree roots have	
1067781			Stormwater	Complete	ICS FORMS	18-20 Franklin Street, Griffith	blocked up the storm water out the front of Priceline	tie clean
						Franklin Street, and Flinders		
1068847	27/02/2019		Stormwater	Received	ICS FORMS	Griffith	Blocked storm water drain. needs clearing.	
							Flinders Way Manuka	
							5 min parking outside Coles	
						Franklin Street &, Flinders Way,	Middle spot	
1069002	1/03/2019		Road Pavement	Received	ICS FORMS	Griffith	Large pothole	

Page 5 of 11 IAMS search results

ENQUIRY		COMPLETE						
ID	DATE	DATE	CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
		17/03/2019	Street, Warn, Haz,				A blackspot program sign needs to be moved to the new street light pole.	Sign will be retained in irs current location.
1069632	15/03/2019	10:46:20 PM	Park, Other	Complete	ICS FORMS	Franklin street, FORREST	As it can no longer be seen on the old street light pole.	Comp - Gare - 20/3/19
		30/07/2019				Along Franklin Street between Furneaux Street and Flinders		Relates to ministerial request ref
1072531			Pedestrian Paving	Complete	ICS FORMS	Way Manuka	Member of the public has reported trip hazard in unit paving around trees	no#S2019-1340, Refer to Garry George, 07/05/2019, MR
							Damage to path or other	
1077470	9/09/2019		Shrub Bed	Received	ICS FORMS	Franklin Street, Griffith	Uplifting due to tree root	

Page 6 of 11 IAMS search results

ID DATE DATE CLASS STATUS SOURCE LOCATION DESCRIPTION Good Morning	
Good Morning	
Good Morning	
Good Morning	
In response to your recen	enquiry
proposing parking for disa	
spaces in the area.	Jc,
The overall road environn	ent and
high traffic volume for thi	precinct
requires the disability bay	to be
planned accordingly.	
The parking area you have	
requested fails to meet the	current
design standards for on st	eet
disability parking spaces.	
To consider these location	
existing infrastructure wo	
to be re designed to meet	
above mentioned standar	
Refer below link to all disa	
Roads, parking & vehicles parking spaces in the area	
Parking & vehicles	/
What is being requested?* https://actgov.maps.arcg	
Request new parking signage s/webappviewer/index.ht	
Why do you believe this change is required?* 47039aae14051933b7ad2	7918/90P
25/10/2019 Customer would like a handicapped spot placed out the front 25/10/2019 9:16:30 AM Road Pavement Complete ICS FORMS 3 Franklin St, Griffith (endeavour house)	

Page 7 of 11

ENQUIRY_	CREATED	COMPLETE						
_	DATE		CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
	D/ (12	DATE	CL7 100	3771103	SOURCE	EGG/(IIGIV	DESCRIPTION	Action
							I spend a lot of time at the Manuka rank on Franklin	
							Street, because it's the busiest rank south of the Lake, when Parliament is	
							not sitting. As you're probably aware, it's constantly congested with non-	
							Taxis. Partly because people don't realise the Loading Zone becomes a Taxi	
							Rank after 6pm. Mainly because of the Westpac ATM, the chemist, and the	
							pub.	
							I presume that as the Capitol Theatre site is redeveloped, you'll review the	
							parking arrangements on Franklin Street.	
							In the interim, I suggest moving the Taxi Rank to the other side of the	
							street. The Queanbeyan bus stop can be moved to outside the TAB.	
							The redundant bus stop outside Manuka Plaza can be the new Loading	
							Zone.	
							The overflow Taxi Zones on Flinders Way are unneeded. Make them 5	
							minute zones and make what is now the Taxi Rank also a five minute zone.	
							The Uber drivers will stop there regardless.	
							If you can do these things then I can stop yelling at people for parking in a	
			Street, Warn, Haz,				busy Taxi Zone.	
1079725	4/11/2019		Park, Other	Received	ICS FORMS	Franklin Street, Manuka	Please consider.	
	, , ===				-	,		
							What is the issue?:	
							Road condition & safety	
							What would you like to report?:	
							Faded linemarking	
							Please provide more information	
							Faded corner marking	
							Is it posing a safety hazard?:	
							Yes	
							Could it cause a trip, fall or injury?:	
							No	Refer to Kristijan Ivancic / Brad
							Is it causing traffic or cyclists to swerve?:	Tarlington as a request to re-instate
1080765	27/11/2019		Linemarking	Received	ICS FORMS	Franklin Street, Griffith	No	Linemarking, 28/11/2019, MR

Page 8 of 11 IAMS search results

ENQUIRY_	CREATED	COMPLETE						
ID	DATE	DATE	CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
								has been advised by email - line
								managers have rejected her
								proposal due to the area it is in and
							Dementia Australia is moving to Griffith next month and we will be holding	
		04/03/2020	Street, Warn, Haz,				support programs for clients with Dementia. Can one of the metered carparks on Captain Cook Crescent at Endeavour House be designated as a	lita criteria for disability parking,
1083016				Complete	ICS FORMS			signage is indicated.

Page 9 of 11

ENQUIRY	CREATED	COMPLETE						
	DATE	DATE	CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
								Good Morning
								116
								I have discussed your concerns with my managers and at this time we
								have to deny your request on the
								basis of the land use area, traffic
								volume and demand for parking.
								, , , , , , , , , , , , , , , , , , ,
								Notwithstanding the above, I have
								provided some further information
								regarding Disability/Mobility
							Can you provide any additional information about the location of the job to	
								assistance.
							Endeavour House, Cnr Franklin Street and Captain Cook Crescent	
								Below link to the Mobility permit
								for Access Canberra and screen shot of conditions.
							Why do you believe this change is required? Dementia Australia supports clients with Dementia. Can the Commercial	of conditions.
							Loading Zone be changed to a General Loading Zone to allow drop-offs in a	https://www.accesscapherra.act.go
		27/02/2020	Street, Warn, Haz,					v.au/app/answers/detail/a_id/1677
1083048	6/02/2020			Complete	ICS FORMS			/~/parking-permits#!tabs-2

Page 10 of 11

ENQUIRY_	CREATED	COMPLETE						
_	DATE	DATE	CLASS	STATUS	SOURCE	LOCATION	DESCRIPTION	ACTION
וט	DATE	DAIL	CLASS	314103	JOURCE	LOCATION	DESCRIF HOR	ACTION
							Can you provide any additional information about the location of the job to	
							help us find the issue (i.e., intersections, buildings, landmarks, features)?:	
							On the corner of Canberra Ave and Captin Cook Cres.	
							What is the issue?:	
							Request mowing or maintenance	
							What is the issue?:	
							Overgrown grass	
							Is it blocking access or line of sight?:	
							No	
							Could it cause a trip, fall or injury?:	
							Yes	
							Please provide more information	
							The grass is overgrowing at an exponential rate. I dont' believe the ACT	
						ENDEAVOUR HOUSE 1	government is currently conducting a frequent moving on the government	
1086887	22/05/2020		Urban Open Space	Received	ICS FORMS	FRANKLIN ST, GRIFFITH	own land. Please conduct asap as it could cause accident.	
	. ,					,	· ·	
							Can you provide any additional information about the location of the job to	
							help us find the issue (i.e., intersections, buildings, landmarks, features)?:	
							On Franklin St between Capt Cook Cres & Flinders Way there are no	
							pedestrian crossings whatsoever	
							What is the issue?:	
							Road condition & safety	
							What would you like to report?:	
							Request new pedestrian crossing	
							Please provide more information	
							Dementia Australia are relocating into Endeavour House, cnr Franklin and	
							Captain Cook Cres. Parking primarily will be at the Coles Manuka Secure	
							Carparking, however along Franklin Street there are no pedestrian	* Closed - Reponse sent to the
							crossings whatsoever.	customer via Access Canberra - 11
							Is it posing a safety hazard?:	Auguest 2020 -
							Yes	https://www.accesscanberra.act.go
							Could it cause a trip, fall or injury?:	v.au/cgi-
							Yes	bin/accesscanberra.cfg/php/custom
							Is it causing traffic or cyclists to swerve?:	/fnt/upd.php?p_refno=200717-
						ENDEAVOUR HOUSE 1	Yes	002270&p_ctrl=NmFkMDUyYjJjYjFm
		11/08/2020				FRANKLIN ST, GRIFFITH ACT	Verify Email Address:	ZWM5ZDA0ODhmZDhkN2ZjZmQ5N
1088746	23/07/2020		Road Pavement	Complete	ICS FORMS	2603	xxxxxx@xxxxxxx.org.au	zcwOTc0MWM0Yg%3D%3D
1000/40	23/0//2020	J.JI.ZO FIVI	Indau Faveillelli	Complete	ICO FORIVIO	2003	AAAAAA@AAAAAA.UIg.au	2CWOTCOIVIVVIVIOTE/03D/03D

Page 11 of 11

Date/Time	Case				Assetic Work	AC Case	
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
21/09/2021		GRIFFITH, SHOPS 1 FLINDERS WAY - Fix My Street > Cycle & footpaths > Fencing & bollards > Report safety concern	Other More Information	SHOPS 1 FLINDERS WAY, GRIFFITH ACT 2603		325197	WR88229 has been cancelled in Assetic by Bunnarith Seng. Cancelled reason: Work Request has been cancelled.Enquiry has been investigated and closed via Salesforce, please see case number 00117382 for details.
18/11/2021		Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	What is the material? Unknown/other What is the damage? Cracked, broken or uneven More Information Uneven / missing tiles on pavement adjacent to Manuka Terrace Shopping Complex on Flinders Way Is it causing traffic or cyclists to swerve? Yes Could it cause a trip, fall or injury? Yes	18 FLINDERS WAY, GRIFFITH ACT 2603	WR34825	367857	Workrequest WO46336 is in progress. WorkOrder Corrective Maintenance has been raised in Assetic with a priority of Change (180 days)
18/11/2021	135347	Damage to path or other	res	ACT 2603	WR34825	36/85/	(180 days)
23/11/2021		Access to taxi services in Manuka after closing the taxi rank for pedestrian access	My mother (88 years of age) was catching a taxi today in the new taxi 'rank' after closing the old rank to allow for pedestrian only access. Because of the depth of the gutter and no clear low access (deep gutter) she fell as she opened the door of the taxi. Luckily she held onto the door which prevented her falling onto the pavement and possibly having a major injury (falling backwards which may have resulted in a head injury). I would not hesitate to sue the ACT Government for not thinking things through and providing a safe taxi rank after closing the other rank to make way for pedestrian access only. It astounds me that this was not considered as part of the 'planning' in the closure of the street. Taxi services as it is are not great but luckily the taxi driver exited his taxi to help her to her feet. As a rule taxi drivers are not that nice - heaven forbid they would assist with carrying groceries to her doorstep - after all at 88 she must be able to manage heavy bags by herself. I digress. I will monitor if anything is done about updating/upgrading the taxi rank to make it more purposeful for passenger access and I hope that there is a change. As I have said, I will not hesitate if there is an incident where my mother is hurt to take action.		WR92684	371222	
24/11/2021		Fix My Street > Water > Stormwater > Water leak / flooding	What would you like to report? Flooding Is it posing a safety hazard? Yes Is it causing traffic or cyclists to swerve? Yes Could it cause a trip, fall or injury? Yes Can you identify the source of the issue? Blocked stormwater drain overflowing onto footpath	SHOPS 7 FLINDERS WAY, GRIFFITH ACT 2603		371665	WR35228 has been rejected in Assetic by Graeme Roughton. Rejection reason: Work already completed. Contacted the resident

Page 1 of 11 Salesforce search results

Date/Time	Case				Assetic Work	AC Case	
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
			More Information				
			Street sign knocked over				
			Is it posing a safety hazard?				
			Yes				
			Is it causing traffic or cyclists to swerve?				
			No				
		E' M Charle Bank	Could it cause a trip, fall or injury?				WR41848 has been closed in
		Fix My Street > Roads,	No	10 FUNDEDS WAY CRIFFITH			Assetic by Henry Botha.
10/01/2022			What would you like to report?	18 FLINDERS WAY, GRIFFITH	WD44040		Comments: Linked Work Order
19/01/2022	155051	traffic > Road signs	Replacement of existing signage	ACT 2603	WR41848	409463	has been assessed.
			AC: 00472405. Lodged 10/04/2022. Currently registered. Please forward to Parking				
			Operations				
			Is it causing traffic or cyclists to swerve? No				
			Where is the vehicle located? Major road				
			Type of vehicle? Car				
			Is the vehicle on private or public land? Public				
		Fix My Street > Roads,	How long do you think it has been there? 1-3 weeks				
		parking & vehicles > Parking	Has the vehicle been vandalised? No				
		& vehicles > Report	, ,	SHOPS 3 FLINDERS WAY,			
11/04/2022	183791	abandoned vehicle	Can you provide any additional details about the vehicle? Ford Escape, Grey in colour	GRIFFITH ACT 2603		472405	
			What is the material?				
			Concrete				
			What is the damage?				
			Cracked, broken or uneven				
			More Information				
			I fell on uneven footpath causing bruising & soft tissue injuries requiring medical attention				
		Eiv My Stroot > Cyclo 9	Is it causing traffic or cyclists to swerve?	Footpath hotween Crent			
		Fix My Street > Cycle & footpaths > Shared paths >	No Could it cause a trip, fall or injury?	Footpath between Grant Crescent and Flinders Way			
10/05/2022		'	Yes	Griffith	WR51373	489368	
10/03/2022	137377	Damage to path of other		oriniui .	MIN312/2	403308	
		Pavement at Manuka	Customer request pavement at 18 Flinders Way Griffith at Manuka Terrace Shopping				
16/06/2022				18 Flinders Way Griffith	WR54030		

Page 2 of 11 Salesforce search results

ase				Assetic Work	AC Case	
	Subject	ACTCCS Description	Incident Address		Number	Assetic Status Comments
l	Fix My Street > Cycle & footpaths > Shared paths >	Unknown/other What is the damage? Cracked, broken or uneven More Information Some of the public benches around Manuka centre have bee repaired and repainted but some have not and are dilapidated. Please could the remaining ones be restored and repainted. Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury?	SHOPS 1 FLINDERS WAY,			WR56106 has been rejected in Assetic by PeterJ Sullivan.
	Fix My Street > Roads, parking & vehicles > Roads &	More Information Very dangerous intersection at Canberra Avenue & Flinders Way in Manuka. Many T-bone accidents involving cars turning right from Manuka Oval side across Canberra Avenue into Flinders Way towards Shell. Needs no right hand turn, lights or roundabout. Is it posing a safety hazard? Yes Is it causing traffic or cyclists to swerve?	SHOPS 1 FLINDERS WAY,			WR60641 has been cancelled in Assetic by Bunnarith Seng. Cancelled reason: Work Request has been cancelled. This enquiry appear to have been dealt with. however, if the customer believe this is not the case, please contact
	Fix My Street > Water >	What would you like to report? Water leak Is it posing a safety hazard? No Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No Can you identify the source of the issue?	GRIFFITH ACT 2603			WR68683 has been cancelled in Assetic by Josh Buckingham. Cancelled reason: Work Request has been cancelled.CSRM Case Number: 00244400 Requester Contact Name: Phone Number: Initial enquiry info only.
	· .	·	l '			See CSRM for additional correspondence
	210426	Fix My Street > Cycle & footpaths > Shared paths > 210426 Damage to path or other Fix My Street > Roads, parking & vehicles > Roads & traffic > Road condition & 222694 safety Fix My Street > Water > Stormwater > Water leak /	What is the material? Unknown/other What is the damage? Cracked, broken or uneven More Information Some of the public benches around Manuka centre have bee repaired and repainted but some have not and are dilapidated. Please could the remaining ones be restored and repainted. Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No More Information Very dangerous intersection at Canberra Avenue & Flinders Way in Manuka. Many T-bone accidents involving cars turning right from Manuka Oval side across Canberra Avenue into Flinders Way towards Shell. Needs no right hand turn, lights or roundabout. Is it posing a safety hazard? Yes Is it causing traffic or cyclists to swerve? Yes Is it causing traffic or cyclists to swerve? Yes Unknown/other What would you like to report? Water leak Is it posing a safety hazard? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Can you identify the source of the issue? Stormwater > Water leak/	What is the material? Unknown/other What is the damage? Cracked, broken or uneven More Information Some of the public benches around Manuka centre have bee repaired and repainted but some have not and are dilapidated. Please could the remaining ones be restored and repainted. Fix My Street > Cycle & footpaths > Shared paths > 210426 Damage to path or other More Information Very dangerous intersection at Canberra Avenue & Flinders Way in Manuka. Many T-bone accidents involving cars turning right from Manuka Oval side across Canberra Avenue into Flinders Way towards Shall. Needs no right hand turn, lights or roundabout. Is it causing traffic or cyclists to swerve? Yes Is it causing traffic or cyclists to swerve? Yes Is it causing traffic or cyclists to swerve? Yes ShOPS 1 FLINDERS WAY, GRIFFITH ACT 2603 SHOPS 1 FLINDERS WAY, GRIFFITH ACT 2603 What are you requesting? Other What would you like to report? Water leak Is it posing a safety hazard? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or i	What is the material? Unknown/other What is the damage? Cracked, broken or uneven More Information Some of the public benches around Manuka centre have bee repaired and repainted but some have not and are dilapidated. Please could the remaining ones be restored and repainted. Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No More Information Very dangerous intersection at Canberra Avenue & Flinders Way in Manuka. Many T-bone accidents involving cars turning right from Manuka Oval side across Canberra Avenue into Flinders Way towards Shell. Needs no right hand turn, lights or roundabout. Is it posing a safety hazard? Yes Is it Causing traffic or cyclists to swerve? Yes Unkar are you requesting? What are you requesting? What would you like to report? Water leak Is it posing a safety hazard? No Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Shorts FLINDERS WAY, SHOPS I FLINDERS WAY,	What is the material? Unknown/other What is the damage? Cracked, broken or uneven More Information Some of the public benches around Manuka centre have bee repaired and repainted but some have not and are dilapidated. Please could the remaining ones be restored and repainted. Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No More Information Very dangerous intersection at Canberra Avenue & Flinders Way in Manuka. Many T-bone accidents involving cars turning right from Manuka Oval side across Canberra Avenue into Flinders Way towards Shell. Needs no right hand turn, lights or roundabout. Is it posing a safety hazard? Yes Is it causing traffic or cyclists to swerve? What would you like to report? Water leak Is it posing a safety hazard? No Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No SHOPS 1 FLINDERS WAY, GRIFFITH ACT 2603 S63820 What would you like to report? Water leak Is it posing a safety hazard? No Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No Could it cause a trip, fall or injury? No SHOPS 1 FLINDERS WAY,

Page 3 of 11 Salesforce search results

	Case				Assetic Work		
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
			What needs to be cleaned, repaired or maintained? Several flood warning signs around Griffith Oval have faded so as to become illegible and				
			have also been obscured by graffiti. In the event of a major flood people could miss the				
			warnings and suffer injury as a consequence. Repair or replacement.				
			What are you requesting?				
			Repair				
		Fix My Street > Parks &	Is it blocking an access?				W/P74260 has been rejected in
		public spaces > Signs > Request cleaning, repair or	No Could it cause a trip, fall or injury?	12 FLINDERS WAY, GRIFFITH			WR74369 has been rejected in Assetic by Nathan Hart. Rejection
14/12/2022			Yes	ACT 2603	WR87864		reason: Needs to go to parks
							WR77722 has been cancelled in
							Assetic by Josh Buckingham.
			What needs to be cleaned, repaired or maintained?				Cancelled reason: Work Request
		Fix My Street > Water >	Stormwater at crossing is blocked and lifting manhole cover off What are you requesting?				has been cancelled.CSRM Case Number : 00274669 Requester
		•	Cleaning				Contact Name: Anonymous Phone
		cleaning, repair or	Is it blocking an access?	SHOPS 5 FLINDERS WAY,			Number: Initial enquiry info only.
30/01/2023	274669	maintenance	No	GRIFFITH ACT 2603		656153	See CSRM for additional
			What is the material?				
			Unknown/other				
			What is the damage?				
			Cracked, broken or uneven				
			More Information				
			Benches in Manuka need restoration repainting				
		Fix My Street > Cycle &	Is it causing traffic or cyclists to swerve? No				
		footpaths > Shared paths >	Could it cause a trip, fall or injury?	SHOPS 1 FLINDERS WAY,			
10/03/2023		•	No	GRIFFITH ACT 2603	WR80780	673440	
							W/D02100 bas base same lied in
		Fix My Street > Roads,	Why do you believe this change is required?				WR82180 has been cancelled in Assetic by Bishal Gautam.
		•	The parking signs outside Coles on Flinders Way have been changed from 15 minutes to 5				Cancelled reason: Work Request
			minutes. Five minutes is not enough time to go to a shop or the Post Office or even to get a	SHOPS 1 FLINDERS WAY,			has been cancelled.Have
24/03/2023	303304	parking signage	cup of takeaway coffee. Five minutes is just an excuse for revenue rai	GRIFFITH ACT 2603		692938	responded via SF-00303304

Page 4 of 11 Salesforce search results

Date/Time	Case				Assetic Work	AC Case	
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
		Fix My Street > Cycle &	What is the material? Brick or concrete pavers What is the damage? Cracked, broken or uneven More Information Tripping issue caused by Bricks raised out side Manuka terrace, Flinders way near coles shopping area to Wok Me. Seems there must be an underling issue as doesn't appear to happen in other paved areas of the Msnuka shops Is it causing traffic or cyclists to swerve? No				
30/04/2023		footpaths > Shared paths > Damage to path or other	Could it cause a trip, fall or injury? Yes	18 FLINDERS WAY, GRIFFITH ACT 2603	WR84034	710445	
8/05/2023		Fix My Street > Water > Stormwater > Request cleaning, repair or maintenance	What needs to be cleaned, repaired or maintained? Stormwater sump outside of Coles Supermarket at pedestrian crossing What are you requesting? Cleaning Is it blocking an access?	SHOPS 1 FLINDERS WAY, GRIFFITH ACT 2603	WR84489		WR84489 has been closed in Assetic by Nigel Murphy. Comments: Linked Work Order has been assessed.
6/05/2023		Fix My Street > Cycle & footpaths > Shared paths >	What is the material? Brick or concrete pavers What is the damage? Cracked, broken or uneven More Information Multiple trip hazards in paving around Coles at Manuka Is it causing traffic or cyclists to swerve? Yes Could it cause a trip, fall or injury?	SHOPS 1 FLINDERS WAY,	WN04463		WR86605 has been closed in Assetic by Garry George. Comments: Linked Work Order
14/06/2023			Yes	GRIFFITH ACT 2603	WR86605	740019	has been assessed.

Page 5 of 11 Salesforce search results

Date/Time	Case				Assetic Work	AC Case	
		Subject	ACTCCS Description	Incident Address		Number	Assetic Status Comments
			What is the material?				
			Brick or concrete pavers				
			What is the damage?				
			Cracked, broken or uneven				
			More Information				
			Lifted tiles. Has already caused an injury. An elderly gentleman has tripped and fallen and it				
			injured with cuts to his head, face and body.				
		Fix My Street > Cycle &	Is it causing traffic or cyclists to swerve? Yes				
		footpaths > Shared paths >	Could it cause a trip, fall or injury?	SHOPS 1 FLINDERS WAY,			
21/07/2023			Yes	GRIFFITH ACT 2603	WR89414	757591	
			Where is the pothole? Road				WR23137 has been closed in
		Fix My Street > Roads,	What type of pothole are you reporting?	franklin street, canberra act			Assetic by Matthew Handley. Comments: Linked Work Order
17/05/2021		traffic > Potholes	Unfinished repair	2603	WR23137	226317	WO39403 has been assessed.
			·				
			Why do you believe this change is required We are requesting the painting of a zebra pattern on the footpath at the entrance to the car park beneath Coles in Franklin Street Manuka				WR23140 has been cancelled in Assetic by Neil Pincombe. Cancelled reason: Work Request
			What are you requesting? New path				has been cancelled.An Officer from TMS has visited the site and
			More Information				whilst it is a well used
			The exit from the car park has a zebra crossing painted on the footpath. we would like the markings on the footpath at the entrance to the car park to make it very clear that	ENDEAVOUR HOUSE 7 FRANKLIN ST, GRIFFITH ACT			pedestrian/vehicle access, zebra
17/05/2021		on the footpath at the entrance to the car park	pedestrians have right of way. The road at the entrance keeps getting pot	2603		226333	crossing markings are not used on footpath
, , , , , , ,			, , , , , , , , , , , , , , , , , , , ,			1335	·
			Why do you believe this change is required				
			There is a very dangerous crossing where someone will get hurt				
			What are you requesting?				
			Extension to an existing path				
			More Information				
			When riding along Captain Cook Cr, as it crosses Franklin St, the bike path stops just before				
26/06/2021		ľ.	the intersection. There are cars parked right up to the curb on Franklin St, and cars cannot see those on the path.	ACT 2603	WR25393	250600	
		:	I The state of the		1======		l

Page 6 of 11 Salesforce search results

	Case				Assetic Work		
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
17/01/2022		Roads, parking & vehicles >	More Information Franklin street between flinders way and captain cook crescent Where is the pothole? Road What type of pothole are you reporting? New	ENDEAVOUR HOUSE 3 FRANKLIN ST, GRIFFITH ACT 2603	WR41562		Workrequest WO48295 is in progress. WorkOrder Corrective Maintenance has been raised in Assetic with a priority of Serious (10 days)
19/05/2022		· ·	Removing existing bus stop and provide short term parking arrangement at Franklin Street, Kingston	Franklin Street			
24/05/2022		Fix My Street > Roads, parking & vehicles > Roads &	More Information Snap Send Solve - Report Number: 2302995 Thursday, April 21st 2022, 8:00:46 am AEST Incident Type: Pothole Notes: Large potholes near entrance to Cole?s car park in middle of the Where is the pothole? Road What type of pothole are you reporting?	ENDEAVOUR HOUSE 3 FRANKLIN ST, GRIFFITH ACT	WP52464	500063	
24/05/2022	196836	traffic > Potholes	New	2603	WR52464	500963	
19/07/2022		Fix My Street > Cycle & footpaths > Shared paths >	What is causing the obstruction? Builders/construction equipment or unauthorised signs More Information The footpath and surrounding areas outside the old Capitol Theatre development in Franklin St Manuka have been a disgrace for many months. Of ongoing concern is the area outside the old bakery where the old signs etc still block half the footpath! Is it causing traffic or cyclists to swerve? Yes Could it cause a trip, fall or injury? Yes	SHOPS 6 FRANKLIN ST, GRIFFITH ACT 2603			WR87926 has been rejected in Assetic by Michael Rootsey. Rejection reason: SHOPS 6 FRANKLIN ST, GRIFFITH, Refer to RANGERS, construction sites, Fences / barriers blocking paths
6/08/2022		Fix My Street > Roads, parking & vehicles > Roads &	More Information Corner of Franklin Street and Captain Cook Crescent, next to Coles at Manuka/Griffith. It?s at the pedestrian crossing nearest to Coles Where is the pothole? Intersection What type of pothole are you reporting? New	1-17 FRANKLIN ST, GRIFFITH ACT 2603	WR58288	550508	

Page 7 of 11 Salesforce search results

Date/Time	Case				Assetic Work	AC C250	
		Cubicat	ACTCCC Description	Incident Address			Assetic Status Comments
Opened	Number	Subject	ACTCCS Description	incluent Address	Request ID	Number	Assette Status Comments
			NA/hat is assessed that a hatmostic m2				
			What is causing the obstruction? Other				
			More Information				
			I have previously reported on 19 July last and then 17 August the disgraceful state and				
			dangerous situation with the footpath in Franklin St Manuka, outside the old Capitol				
			Theatre. I?m very disappointed that I?ve had no response and nothing done😡				
			Is it causing traffic or cyclists to swerve?				WR87881 has been closed in
		Fix My Street > Cycle &	Yes				Assetic by Garry George.
		footpaths > Shared paths >	Could it cause a trip, fall or injury?	SHOPS 6 FRANKLIN ST,			Comments: Linked Work Order
21/11/2022		Blocking the path	Yes	GRIFFITH ACT 2603	WR87881	620251	has been assessed.
21/11/2022	254177	blocking the path			W1107001	020231	nas seen assessea.
			More Information				
			Deep pothole at entrance to Coles supermarket underground parking				
			Where is the pothole?				WR73661 has been cancelled in
		Fix My Street > Roads,	Road				Assetic by Frank Cortes. Cancelled
		1 · · · · · · · · · · · · · · · · · · ·	What type of pothole are you reporting?				reason: Work Request has been
5/12/2022	259302	-	Recurring	Franklin Street, Manuka		628883	cancelled.Location not specific
							WR74198 has been cancelled in
			What needs to be cleaned, repaired or maintained?				Assetic by Josh Buckingham.
			storm water is overflowing. near to coles supermarket.				Cancelled reason: Work Request
			What are you requesting?				has been cancelled.CSRM Case
			Repair				Number: 00261254 Requester
		Fix My Street > Water >	Is it blocking an access?				Contact Name:
		Stormwater > Request	No				Phone Number: Initial
		cleaning, repair or	Could it cause a trip, fall or injury?	FRANKLIN ST, GRIFFITH ACT			enquiry info only. See CSRM for
12/12/2022	261254	maintenance	Yes	2603		632198	additional corr
			More Information				
			large pothole. Entrance to Coles car park Manuka.				
			Where is the pothole?	ENDEAVOUR HOUSE 3			WR75353 has been closed in
		Doods portion 0til	Road What type of nothele are you reporting?	ENDEAVOUR HOUSE 3			Assetic by Shane Cox. Comments:
1/01/2022	205070	Roads, parking & vehicles >	What type of pothole are you reporting?	FRANKLIN ST, GRIFFITH ACT	W/D75252	(2075)	Linked Work Order has been
1/01/2023	2058/0	Roads & traffic > Potholes	Recurring	2603	WR75353	039/58	assessed.
			More Information				
			Captain Cook Cres Manuka cnr Franklin Street. large recurring pothole near pedestrian				
			crossing				
			Where is the pothole?				
			Road	ENDEAVOUR HOUSE 1			
		Roads, parking & vehicles >	What type of pothole are you reporting?	FRANKLIN ST, GRIFFITH ACT			
1/01/2023			Recurring	2603	WR75354	639761	
2,01,2023	203072	The state of the s	[0	1	1, 5554	1 333,01	

Page 8 of 11 Salesforce search results

	Case				Assetic Work		
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
			Issue Description				
		Fix My Street > Cycle &	Corner of Flinders & Franklin Sts, Manuka - inaccessible footpath. Footpath was dug up in				
		footpaths > Shared paths >	late Aug-22, remains untouched and cordoned off. What is the delay in fixing and returning	MANUKA PLAZA 2 FRANKLIN			
5/01/2023	267136	Accessibility issues	access to normal?	ST, GRIFFITH ACT 2603	WR75840	641796	
			More Information				
			was getting out of his vehicle parked opposite the coles carpark at 7 Franklin st				
			Manuka and he has fractured his foot on the pothole.				
			Where is the pothole?				WR76688 has been closed in
		Fix My Street > Roads,	Road	ENDEAVOUR HOUSE 7			Assetic by Shane Cox. Comments:
/ /		. •		FRANKLIN ST, GRIFFITH ACT			Linked Work Order has been
16/01/2023	270540	traffic > Potholes	New	2603	WR76688	647386	assessed.
			What is the material?				
			Brick or concrete pavers				
			What is the damage?				
			Uplifting due to tree root Is it causing traffic or cyclists to swerve?				WR77362 has been rejected in
		Fix My Street > Cycle &	Yes				Assetic by Neil Phillips. Rejection
		footpaths > Shared paths >		SHOPS 16 FRANKLIN ST,			reason: Not roadsACT asset -
24/01/2023	273157	Damage to path or other	Yes	GRIFFITH ACT 2603		652484	please send to city presentation
			What is the material?				
			Brick or concrete pavers				
			What is the damage?				
			Cracked, broken or uneven				
			More Information				
			Mary tripped on pavers walking towards Westpac Bank from Coles - Manuka. Paver is on				
			the same side as the Bank, infront of doors that take you to second floor just before bank.				
			Mary sustained injuries from the fall. Please call customer. Is it causing traffic or cyclists to swerve?				WR78476 has been closed in
		Fix My Street > Cycle &	No				Assetic by Garry George.
		footpaths > Shared paths >		SHOPS 14 FRANKLIN ST,			Comments: Linked Work Order
6/02/2023		·	Yes	GRIFFITH ACT 2603	WR78476	662270	has been assessed.

Page 9 of 11 Salesforce search results

/-:							
	Case Number	Subject	ACTCCS Description	Incident Address	Assetic Work Request ID	Number	Assetic Status Comments
Орепец	Number	Jubject	ACTOCS Description	incident Address	Request ib	Number	Assette Status Comments
			What is the material?				
			Concrete What is the damage?				
			Cracked, broken or uneven				
			More Information				
			Re the cut-away section of the traffic island on Franklin St, Manuka adjacent to Captain				
			Cook Crescent, the surface is uplifted compromising the movement of elderly, disabled,				
			those with shopping trollies, e-scooters, prams, bicycles. Pls level sfc.				
		Fig. N. Character Conda 0	Is it causing traffic or cyclists to swerve?				WR83523 has been closed in
		Fix My Street > Cycle & footpaths > Shared paths >	No Could it cause a trip, fall or injury?	1-7 FRANKLIN ST, GRIFFITH			Assetic by Shane Cox. Comments: Linked Work Order has been
18/04/2023			Yes	ACT 2603	WR83523		assessed.
	000.01	- amage to pain or care.				7 00000	
			More Information				
			Turning off Captain Cook Cres to Franklin Street and then into Coles carpark there is a gigantic pothole that is actually unavoidable. Even driving the slowest I can the hole feels				
			like it is about to damage my tyre or rim. It has been there a while.				
			Where is the pothole?				WR84075 has been closed in
		Fix My Street > Roads,	Road	ENDEAVOUR HOUSE 3			Assetic by Matthew Handley.
		-	What type of pothole are you reporting?	FRANKLIN ST, GRIFFITH ACT			Comments: Linked Work Order
1/05/2023	312422	traffic > Potholes	New	2603	WR84075	710663	has been assessed.
			What is the material?				
			Brick or concrete pavers				
			What is the damage?				
			Cracked, broken or uneven More Information				
			Lifted pavers directly outside the front entry to Endeavour House Manuka on Franklin				
			Street. Building is used by people with mobility and cognitive issues to access community				
			services located within the building. Issue likely caused by tree root				Workrequest WO65467 is in
			Is it causing traffic or cyclists to swerve?				progress. WorkOrder Corrective
		Fix My Street > Cycle &	No	ENDEAVOUR HOUSE 3			Maintenance has been raised in
45 (05 (000		footpaths > Shared paths >	Could it cause a trip, fall or injury?	FRANKLIN ST, GRIFFITH ACT	MADOFOCO		Assetic with a priority of Change
15/05/2023	31/203	Damage to path or other	Yes	2603	WR85068	/18/20	(180 days)

Page 10 of 11 Salesforce search results

Date/Time	Case				Assetic Work	AC Case	
Opened	Number	Subject	ACTCCS Description	Incident Address	Request ID	Number	Assetic Status Comments
			What is the material?				
			Brick or concrete pavers				
			What is the damage?				
			Cracked, broken or uneven				
			More Information				
			We have loose bricks outside the entrance to our venue in Manuka Parade, last week an				
			elderly gentleman tripped on the bricks and fell heavily, it is a serious safety hazard.				
			Is it causing traffic or cyclists to swerve?				
		Fix My Street > Cycle &	Yes				
		footpaths > Shared paths >	Could it cause a trip, fall or injury?	SHOPS 6 FRANKLIN ST,			
21/07/2023	334699	Damage to path or other	Yes	GRIFFITH ACT 2603	WR89423	757663	
							WR89500 has been cancelled in
							Assetic by Bunnarith Seng.
		Fix My Street > Roads,	Why do you believe this change is required?				Cancelled reason: Work Request
		parking & vehicles > Parking	The lines in the carpark are rather difficult to see and need to be repainted so that cars				has been cancelled.Closing this
		& vehicles > Request new	know where to park. At the moment, some cars are taking up 2 spaces because it's	1-7 FRANKLIN ST, GRIFFITH			enquiry in Assetic so it can be
22/07/2023	334880	parking signage	impossible to see the lines.	ACT 2603	WR89591	758023	redirected to Road Maintenance

Page 11 of 11 Salesforce search results

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Creator	Work Order Brief Description	Work Order Priority	Work Order Priority Notation	Work Order SLA Date	Work Order TCOMP Date	Work Order COMP Date	Work Order Schedule Start	Work Order Schedule Finish
WO67899	ASSESS	26/04/2023 11:05 AM	Michael Rootsey	1-7 FRANKLIN ST, GRIFFITH > Damage to path or other		2 Urgent (2 days)	28/04/2023 11:05 AM	16/05/2023 10:46 AM		26/04/2023 11:05 AM	28/04/2023 11:05 AM
WO48295	PREP	18/01/2022 8:57 AM	Shane Cox	Roads, parking & vehicles > Roads & traffic > Potholes	i.	3 Serious (10 days)	28/01/2022 8:57 AM	02/02/2022 9:47 AM		18/01/2022 12:00 AM	13/03/2022 12:00 AM
WO46293	PREP	6.57 AIVI	Stiatie Cox	tranic > Potnoies		3 Serious (10 days)	AIVI	02/02/2022 9.47 AWI		AIVI	AIVI
WO63266	ASSESS	04/01/2023 1:41 PM	Tony Newman	Pothole in asphalt at the entrance to the underground carpark to Coles. Please repair.		3 Serious (10 days)	14/01/2023 1:41 PM	23/01/2023 10:11 AM		16/01/2023 12:00 AM	03/02/2023 12:00 AM
WO68131	ASSESS	01/05/2023 1:39 PM	Michael Rootsey	3 Franklin street, Griffith > Roads & traffic > Potholes		3 Serious (10 days)	11/05/2023 1:39 PM	05/05/2023 1:42 PM		01/05/2023 1:39 PM	11/05/2023 1:39 PM
WO68132	ASSESS	01/05/2023 1:41 PM	Michael Rootsey	3 Franklin street, damaged road pavement, coldmix repairs to make safe		3 Serious (10 days)	11/05/2023 1:41 PM	04/05/2023 10:38 AM		01/05/2023 1:41 PM	11/05/2023 1:41 PM
WO58545	ASSESS	15/09/2022 10:58 AM	Tony Newman	Loose and missing flagstone's stones , please remove loose flagstones and place coldmix to make safe.		2 Urgent (2 days)	17/09/2022 10:58 AM	24/09/2022 9:55 AM		23/09/2022 12:00 AM	07/10/2022 12:00 AM
NO64077	ASSESS	23/01/2023 10:39 AM	Michael Rootsey	Damaged road pavement/ kerbs at 10 Franklin Street, multiple coldmix repairs to make safe		3 Serious (10 days)	02/02/2023 10:39 AM	01/02/2023 2:21 PM		23/01/2023 12:00 AM	03/02/2023 12:00 AM
WO43210	ASSESS	30/08/2021 12:36 PM	Matthew Handley	FIX MY STREET		3 Serious (10 days)	09/09/2021 2:36 AM	15/09/2021 8:41 AM	15/09/2021 9:31 AM		17/09/2021 12:00 AM
WO46512	ASSESS	25/11/2021 6:39 AM	Shane Cox	Roads, parking & vehicles > Roads & traffic > Potholes	·	3 Serious (10 days)	04/12/2021 7:39 PM	25/11/2021 11:24 AM	26/11/2021 8:59 AM	25/11/2021 12:00 AM	25/01/2022 12:00 AM
NO47238	ASSESS	13/12/2021 1:17 PM	Shane Cox	Roads, parking & vehicles > Roads & traffic > Potholes	i.	3 Serious (10 days)	23/12/2021 2:17 AM	27/01/2022 8:43 AM		13/12/2021 12:00 AM	22/02/2022 12:00 AM
WO43211	ASSESS	30/08/2021 12:36 PM	Matthew Handley	FIX MY STREET		3 Serious (10 days)	09/09/2021 2:36 AM	02/11/2021 12:29 PM	04/11/2021 9:59 AM	20/10/2021 12:00 AM	05/11/2021 12:00 AM
WO42707	ASSESS	12/08/2021 9:19 AM	Shane Cox	Roads, parking & vehicles > Roads & traffic > Potholes	i.	3 Serious (10 days)	22/08/2021 9:19 AM	12/08/2021 11:16 AM	18/08/2021 9:05 AM	12/08/2021 12:00 AM	12/09/2021 12:00 AM
WO46340	ASSESS	19/11/2021 11:07 AM	Garry George	Pothole @ bus stop Franklin St opposite Shell.		3 Serious (10 days)	29/11/2021 12:07 AM	23/11/2021 2:22 PM	25/11/2021 7:50 AM	19/11/2021 11:07 AM	29/11/2021 11:07 AM

	Work Order	Work Order	Work Order		Work Order	Work Order	Work Order SLA		Work Order COMP		Work Order
Work Order ID WO29194	Status	20/11/2020 11:06 AM	Shane Cox	Work Order Brief Description Roads, parking & vehicles; Roads & traffic; Potholes	Priority		30/11/2020 11:06 AM	Work Order TCOMP Date 26/11/2020 8:36 AM	03/12/2020 10:11 AM	Schedule Start 20/11/2020 12:00 AM	Schedule Finish 20/12/2020 12:00 AM
WO36499	ASSESS	17/03/2021 1:00 PM	Shane Cox	Roads, parking & vehicles; Roads & traffic;			27/03/2021 2:00 AM	09/04/2021 9:10 AM	20/04/2021 9:02 AM	17/03/2021 12:00 AM	
WO11405	ASSESS	11/07/2017 3:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	10/01/2019 4:36 AM		07/07/2020 3:17 PM	11/07/2017 3:36 PM	07/01/2018 2:36 PM
W055408	ASSESS	13/07/2022 3:01 PM	Swadesh Khatri	Cycle & footpaths > Shared paths > Damage to path or other 29 LA PEROUSE ST, GRIFFITH ACT 2603, cracked and lifted footpath causing trip hazard, Breakout and coldmix to make safe		2 High Risk (14 days)	27/07/2022 3:01 PM	19/07/2022 8:39 AM		15/07/2022 12:00 AM	29/07/2022 12:00 AM
WO4014	ASSESS	05/08/2015 2:53 PM	Michael Rootsey	Damaged Kerb and Gutter		Very Low Risk (18 4 months)	03/02/2017 3:53 AM		07/07/2020 11:26 AM	05/08/2015 2:53 PM	01/02/2016 1:53 PM
WO9326	ASSESS	10/11/2016 2:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:36 AM		07/07/2020 2:06 PM	10/11/2016 2:36 PM	09/05/2017 1:36 PM
WO11552	INPRG	11/05/2017 2:47 PM	Michael Rootsey	Damaged Asphalt Driveway and Vehicle crossing		5 Change (180 days)	07/11/2017 3:47 PM			01/04/2021 12:00 AM	30/06/2021 12:00 AM
WO10882	ASSESS	11/05/2017 3:03 PM	Michael Rootsey	Damaged Driveway / Road Pavement		5 Change (180 days)	07/11/2017 4:03 PM		07/07/2020 3:16 PM	11/05/2017 3:03 PM	21/05/2017 2:03 PM
WO12633	ASSESS	15/11/2017 7:21 AM	Michael Rootsey	Displaced Path		Very Low Risk (18 4 months)	16/05/2019 6:21 PM		07/07/2020 4:16 PM	15/11/2017 7:21 AM	25/11/2017 6:21 AM
WO8993	ASSESS	10/11/2016 2:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:36 AM		07/07/2020 2:06 PM	10/11/2016 2:36 PM	09/05/2017 1:36 PM
WO4147	ASSESS	05/08/2015 2:59 PM	Michael Rootsey	Displaced Path		Very Low Risk (18 4 months)	03/02/2017 3:59 AM		07/07/2020 11:26 AM	05/08/2015 2:59 PM	15/08/2015 1:59 PM
WO10228	ASSESS	06/04/2017 3:05 PM	Michael Rootsey	Damaged Kerb and Gutter and Road		Very Low Risk (18 4 months)	06/10/2018 3:05 AM		07/07/2020 2:42 PM	06/04/2017 3:05 PM	03/10/2017 2:05 PM

	Work Order	Work Order	Work Order		Work Order	Work Order	Work Order SLA		Work Order COMP	Work Order	Work Order
Work Order ID	Status	Creation Time	Creator	Work Order Brief Description	Priority	Priority Notation	Date	Work Order TCOMP Date	Date	Schedule Start	Schedule Finish
WO50234	ASSESS	01/03/2022 11:12 AM	Michael Rootsey	Damaged path at 35 Flinders Way, 14.76m2		2 High Risk (14 days)	15/03/2022) 11:12 AM	31/08/2022 3:38 PM		09/05/2022 12:00 AM	30/06/2022 12:00 AM
WO9557	ASSESS	10/11/2016 2:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:36 AM		07/07/2020 2:06 PM	10/11/2016 2:36 PM	09/05/2017 1:36 PM
WO4624	ASSESS	15/01/2016 2:02 PM	Dean Newman	Damaged vehicle crossing		5 Change (180 days)	13/07/2016 1:02 PM		07/07/2020 11:58 AM	15/01/2016 2:02 PM	13/07/2016 1:02 PM
WO5416	ASSESS	15/01/2016 1:59 PM	Dean Newman	Damaged vehicle crossing		5 Change (180 days)	13/07/2016 12:59 PM		07/07/2020 11:58 AM	15/01/2016 1:59 PM	13/07/2016 12:59 PM
WO7880	ASSESS	09/08/2016 3:13 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	08/02/2018 4:13 AM		07/07/2020 1:34 PM	09/08/2016 3:13 PM	05/02/2017 2:13 PM
WO18374	ASSESS	11/02/2019 2:35 PM	Michael Rootsey			Very Low Risk (18 4 months)	12/08/2020 1:35 AM	09/06/2021 11:17 AM	09/06/2021 11:17 AM	09/06/2021 12:00 AM	09/06/2021 12:00 AM
WO50230	ASSESS	01/03/2022 11:03 AM	Michael Rootsey	Damaged path opposite 35 Flinders Way in parkland adjacent playground, coldmix repairs to make safe		Very Low Risk (18 4 months)	30/08/2023 11:03 AM	04/05/2022 9:57 AM		01/03/2022 11:03 AM	30/08/2023 10:03 PM
WO50227	ASSESS	01/03/2022 10:58 AM	Michael Rootsey	Cycle & footpaths > Shared paths > Damage to path or other, 35 Flinders Way, Griffith		2 High Risk (14 days)	15/03/2022) 10:58 AM	02/08/2022 3:26 PM		09/05/2022 12:00 AM	30/06/2022 12:00 AM
WO8677	ASSESS	10/11/2016 2:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:36 AM		07/07/2020 2:06 PM	10/11/2016 2:36 PM	09/05/2017 1:36 PM
WO38548	PREP	23/04/2021 2:30 PM	Michael Rootsey	Roads, parking & vehicles; Roads & traffic; 37 FLINDERS WAY, GRIFFITH		5 Change (180 days)	20/10/2021 3:30 PM				
WO9447	ASSESS	10/11/2016 3:06 PM	Michael Rootsey	Displaced Paths		Very Low Risk (18 4 months)	12/05/2018 2:06 AM		07/07/2020 2:06 PM	10/11/2016 3:06 PM	20/11/2016 2:06 PM
WO50235	ASSESS	01/03/2022 11:17 AM	Michael Rootsey	Damaged path at 35 Flinders Way, 9.48m2		2 High Risk (14 days	15/03/2022) 11:17 AM	26/07/2022 12:13 PM		09/05/2022 12:00 AM	30/06/2022 12:00 AM
WO50236	ASSESS	01/03/2022 11:21 AM	Michael Rootsey	Damaged path at 35 Flinders Way, multiple coldmix repairs to make safe		2 High Risk (14 days)	15/03/2022) 12:21 AM	31/03/2022 11:27 AM		01/03/2022 11:21 AM	15/03/2022 11:21 AM
WO55418	ASSESS	13/07/2022 3:07 PM	Swadesh Khatri	Cracked and lifted footpath in front of 29 La Perouse Street, please		2 High Risk (14 days)	27/07/2022 3:07			17/03/2023 12:00 AM	09/06/2023 12:00 AM

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Creator	Work Order Brief Description	Work Order Priority	Work Order Priority Notation	Work Order SLA Date	Work Order TCOMP Date	Work Order COMP Date	Work Order Schedule Start	Work Order Schedule Finish
WO27720	ASSESS	30/10/2020 2:02 PM	Michael Rootsey	Damaged asphalt driveway, multiple coldmix repairs to make safe		5 Change (180 days)	28/04/2021 1:02 PM	20/11/2020 10:39 AM	03/12/2020 10:15 AM	02/11/2020 12:00 AM	02/12/2020 12:00 AM
VO71405	PREP	26/07/2023 11:26 AM	Michael Rootsey	Flinders Way, GRIFFITH > Damage to path or other		Very Low Risk (18 4 months)	24/01/2025 12:26 AM				
VO71406	INPRG	26/07/2023 11:35 AM	Michael Rootsey	Corner 27 Flinders Way and Bougainville streets up to 33 Flinders Way, Displaced paths,multiple grinds to make safe		Very Low Risk (18 4 months)	24/01/2025 12:35 AM			26/07/2023 11:35 AM	24/01/2025 12:35 AM
VO8831	ASSESS	10/11/2016 2:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:36 AM		07/07/2020 2:06 PM	10/11/2016 2:36 PM	09/05/2017 1:36 PM
VO19346	APPR	20/06/2019 3:41 AM	Historical IAMS User	Path - Concrete Disp (beyond repair)		Very Low Risk (18 4 months)	18/12/2020 4:41 PM				
VO19520	ASSESS	21/05/2019 3:25 AM	Historical IAMS User	Path - Concrete Displaced		Very Low Risk (18 4 months)	18/11/2020 4:25 PM	20/11/2020 10:54 AM	03/12/2020 10:16 AM	28/10/2020 12:00 AM	28/11/2020 12:00 AM
WO19330	APPR	02/07/2019 4:45 AM	Historical IAMS User	Path - Concrete Disp (beyond repair)		Very Low Risk (18 4 months)	30/12/2020 5:45 PM				
WO8021	ASSESS	09/08/2016 2:19 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	08/02/2018 3:19 AM		07/07/2020 1:34 PM	09/08/2016 2:19 PM	05/02/2017 1:19 PM
WO13276	ASSESS	15/11/2017 7:19 AM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	16/05/2019 6:19 PM		07/07/2020 4:16 PM	15/11/2017 7:19 AM	14/05/2018 6:19 AM
VO47014	ASSESS	07/12/2021 1:26 PM	Michael Rootsey	Cycle & footpaths > On road cycle lanes > Damage to path or other, 12 Grant Cres, Griffith	2	2 High Risk (14 days)	21/12/2021 1:26 PM	21/12/2021 10:35 AM	19/01/2022 1:19 PM	07/12/2021 1:26 PM	21/12/2021 1:26 PM
VO4692	ASSESS	15/01/2016 2:02 PM	Dean Newman	Damaged vehicle crossing		5 Change (180 days)	13/07/2016 1:02 PM		07/07/2020 11:58 AM	15/01/2016 2:02 PM	13/07/2016 1:02 PM
VO9065	ASSESS	10/11/2016 2:50 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:50 AM		07/07/2020 2:06 PM	10/11/2016 2:50 PM	20/11/2016 1:50 PM
VO4520	ASSESS	05/08/2015 3:05 PM	Michael Rootsey	Damaged Kerb and Gutter		Very Low Risk (18 4 months)	03/02/2017 4:05 AM		07/07/2020 11:26 AM	05/08/2015 3:05 PM	15/08/2015 2:05 PM

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Creator	Work Order Brief Description	Work Order Priority	Work Order Priority Notation	Work Order SLA Date	Work Order TCOMP Date	Work Order COMP Date	Work Order Schedule Start	Work Order Schedule Finish
WO17938	ASSESS	11/02/2019 2:41 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/08/2020 1:41 AM		07/07/2020 6:45 PM	11/02/2019 2:41 PM	21/02/2019 1:41 PM
WO19420	APPR	20/06/2019 3:39 AM	Historical IAMS User	Contact pcl prior to tree root removal		Very Low Risk (18 4 months)	18/12/2020 4:39 PM				
WO4463	ASSESS	05/08/2015 3:02 PM	Michael Rootsey	Displaced Path		Very Low Risk (18 4 months)	03/02/2017 4:02 AM		07/07/2020 11:26 AM	05/08/2015 3:02 PM	15/08/2015 2:02 PM
WO4850	ASSESS	15/01/2016 1:59 PM	Dean Newman	Damaged vehicle crossing		5 Change (180 days)	13/07/2016 12:59 PM		07/07/2020 11:58 AM	15/01/2016 1:59 PM	13/07/2016 12:59 PM
WO9425	ASSESS	10/11/2016 2:36 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	12/05/2018 1:36 AM		07/07/2020 2:06 PM	10/11/2016 2:36 PM	09/05/2017 1:36 PM
WO8357	ASSESS	09/08/2016 2:30 PM	Michael Rootsey	Displaced Paths		Very Low Risk (18 4 months)	08/02/2018 3:30 AM		07/07/2020 1:34 PM	09/08/2016 2:30 PM	19/08/2016 1:30 PM
WO200	ASSESS	21/05/2020 7:42 AM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	19/11/2021 8:42 PM	20/08/2020 2:23 PM	02/12/2020 10:34 AM	21/05/2020 7:42 AM	31/05/2020 6:42 AM
WO7669	ASSESS	09/08/2016 3:06 PM	Michael Rootsey	Damaged Path		Very Low Risk (18 4 months)	08/02/2018 4:06 AM		07/07/2020 1:34 PM	09/08/2016 3:06 PM	05/02/2017 2:06 PM
WO34507	ASSESS	12/02/2021 7:46 AM	Shane Cox	Roads, parking & vehicles Roads & traffic Potholes		3 Serious (10 days)	21/02/2021 8:46 PM	12/02/2021 10:35 AM	12/02/2021 10:58 AM	12/02/2021 12:00 AM	12/04/2021 12:00 AM
WO68136	INPRG	01/05/2023 1:51 PM	Michael Rootsey	69 Flinders Way, Griffith, damaged speed cushion x1 and 3m2 road pavement		3 Serious (10 days)	11/05/2023 1:51 PM			01/05/2023 1:51 PM	11/05/2023 1:51 PM
WO49421	ASSESS	11/02/2022 11:54 AM	Prakhar Srivastava	LINEMARKING - Fix the lines & pedestrian crossing on Captain Cook Cr entry and on drive through of the MC Donald's.		Non Critical (30 4 days)	13/03/2022 11:54 AM			03/01/2023 12:00 AM	03/01/2023 12:00 AM
WO58084	ASSESS	05/09/2022 12:20 PM	Tony Newman	Damaged asphalt pavement. Please repair multiple potholes.		2 Urgent (2 days)	07/09/2022 12:20 PM	30/09/2022 11:51 AM		09/09/2022 12:00 AM	07/10/2022 12:00 AM
WO68899	INPRG	19/05/2023 11:08 AM	Michael Rootsey	73 Flinders Way, damaged road pavement, 6m2 , 6m2 and 6m2		3 Serious (10 days)	29/05/2023 11:08 AM			19/05/2023 11:08 AM	29/05/2023 11:08 AM
WO48597	ASSESS	24/01/2022 11:21 AM	Michael Rootsey	Damaged road pavement at 65 Flinders Way, multiple coldmix repairs to make safe		3 Serious (10 days)	03/02/2022 12:21 AM	16/02/2022 11:03 AM		24/01/2022 11:21 AM	03/02/2022 11:21 AM

Work Order ID	Work Order Status	Work Order Creation Time	Work Order	Work Order Brief Description	Work Order Priority	Work Order Priority Notation	Work Order SLA	Work Order TCOMP Date	Work Order COMP	Work Order Schedule Start	Work Order Schedule Finish
Work Order ID	Status	Creation nine	Creator	Car parking lines faded on Flinders	THOTICY	Thority Notation	Date	Work Order Teolvii Date	Date	Schedule Start	Schedule Fillish
				Way Griffith between Murray Cres							
		22/03/2023		and Bougainville St - re-paint lines			18/09/2023 1:52			03/07/2023 12:00	31/07/2023 12:00
WO66935	PREP	2:52 PM	Neil Phillips	in this location		5 Change (180 days)	PM			AM	AM
		04 /05 /0000		81 Flinders Way, Griffith, damaged			44 /05 /0000 0 44			04 /05 /0000 0 44	/05 /0000 0
WOC0120	ACCECC	01/05/2023	Mishael Destant	speed cushion x1 and road		2 Caria (10 da (a)	11/05/2023 2:11	04/05/2022 10:45 484		01/05/2023 2:11	11/05/2023 2:11 PM
WO68138	ASSESS	2:11 PM	Michael Rootsey	pavement 3m2		3 Serious (10 days)	PM	04/05/2023 10:45 AM		PM	PIVI
		19/05/2023		67 FLINDERS WAY, GRIFFITH >			29/05/2023			19/05/2023 11:01	29/05/2023 11:01
WO68898	ASSESS	11:01 AM	Michael Rootsey	'		3 Serious (10 days)	11:01 AM	25/05/2023 10:14 AM		AM	AM
				81 Flinders Way, Griffith, damaged							
		01/05/2023		speed cushion and road pavement,			11/05/2023 2:19				11/05/2023 2:19
WO68139	ASSESS	2:19 PM	Michael Rootsey	coldmix repairs to make safe		3 Serious (10 days)	PM	04/05/2023 10:46 AM		PM	PM
				Roads, parking & vehicles > Roads &							
				traffic > Degrading pavement and	•						
		13/07/2022		Potholes 71 FLINDERS WAY,			23/07/2022 3:20			09/09/2022 12:00	30/09/2022 12:00
W055414	ASSESS	3:20 PM	Swadesh Khatri	GRIFFITH ACT 2603, please patch		3 Serious (10 days)	PM	23/09/2022 10:23 AM		AM	AM
		25/11/2021		Damaged road pavement at 67			05/12/2021				
WO46543	CAN	11:37 AM	Michael Rootsey	Flinders Way, 124m2		3 Serious (10 days)	11:37 AM				
		24/04/2022		Roads, parking & vehicles > Roads &	ı		02/02/2022			00/00/2022 42 00	20/00/2022 42 00
WO48596	ASSESS	24/01/2022 11:17 AM	Michael Rootsey	traffic > Potholes, 67 Flinders Way,		3 Serious (10 days)	03/02/2022 11:17 AM	23/09/2022 10:06 AM		09/09/2022 12:00 AM	AM
***************************************	7133233	11.17 / 111	Wilchael Rootsey	Gillian		5 Schous (10 days)	11.17 / ((1)	25/05/2022 10:0071141		7 11 1	71111
				67 and 83 Flinders Way, damaged							
		04/07/2023		speed cushions, coldmix repairs at			14/07/2023 3:08			04/07/2023 3:08	14/07/2023 3:08
WO70482	ASSESS	3:08 PM	Michael Rootsey	both locations to make safe		3 Serious (10 days)	PM	07/07/2023 1:49 PM		PM	PM
		25 /44 /2024		D			05 /42 /2024				
WO46544	CAN	25/11/2021 11:52 AM	Michael Rootsey	Damaged road pavement at 67 Flinders Way, 17.82m2		3 Serious (10 days)	05/12/2021 11:52 AM				
VVO46544	CAN	11.52 AIVI	Wilchael Rootsey	Filliders Way, 17.82III2		5 Serious (10 days)	11.52 AIVI				
				69 Flinders Way, Griffith, damaged							
		01/05/2023		speed cushion and road pavement,			11/05/2023 2:03			01/05/2023 2:03	11/05/2023 2:03
WO68137	ASSESS	2:03 PM	Michael Rootsey	coldmix repairs to make safe.		3 Serious (10 days)	PM	02/05/2023 12:11 PM		PM	PM
NO 45240	ACCECC	19/11/2021	C	Pothole @ bus stop Franklin St		2 (2012-1-140-1-1-1-1	29/11/2021	22/44/2024 2 22 014	25/11/2021 7:50	19/11/2021 11:07	
WO46340	ASSESS	11:07 AM	Garry George	opposite Shell.		3 Serious (10 days)	12:07 AM	23/11/2021 2:22 PM	AM	AM	AM
		20/11/2020		Roads, parking & vehicles; Roads &			30/11/2020		03/12/2020 10:11	20/11/2020 12:00	20/12/2020 12:00
WO29194	ASSESS	11:06 AM	Shane Cox	traffic; Potholes		3 Serious (10 days)		26/11/2020 8:36 AM	AM	AM	AM
						, ,,,,,		·			
		22/01/2021		Roads, parking & vehicles Roads &			31/01/2021		12/03/2021 11:03	22/01/2021 12:00	
WO32984	ASSESS	9:50 AM	Shane Cox	traffic Road condition & safety		3 Serious (10 days)	10:50 PM	27/01/2021 1:09 PM	AM	AM	AM
		22/02/2022		Banda and in a gradual and Banda			04/02/2022			22/02/2022 42 22	22/02/2022 62 22
WO49950	ASSESS	22/02/2022 3:11 PM	Shane Cox	Roads, parking & vehicles > Roads & traffic > Potholes	· ·	2 Carious (10 days)	04/03/2022 4:11 AM	24/02/2022 11:27 444		22/02/2022 12:00 AM	22/03/2022 12:00 AM
VV U4995U	ASSESS	2:11 LINI	Stratte COX	tranic > Potnoles		3 Serious (10 days)	Alvi	24/02/2022 11:27 AM		AIVI	Alvi
		16/12/2021		Roads, parking & vehicles > Roads &			25/12/2021			16/12/2021 12:00	24/02/2022 12:00
WO47370	ASSESS	10:39 AM	Shane Cox	traffic > Potholes		3 Serious (10 days)		28/01/2022 2:15 PM		AM	AM

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Creator	Work Order Brief Description	Work Order Priority	Work Order Priority Notation	Work Order SLA Date	Work Order TCOMP Date	Work Order COMP Date	Work Order Schedule Start	Work Order Schedule Finish
WO44663	ASSESS	07/10/2021 9:52 AM	Matthew Handley	Roads, parking & vehicles > Roads & traffic > Potholes	t	3 Serious (10 days)	16/10/2021 10:52 PM			07/10/2021 12:00 AM	05/11/2021 12:00 AM
WO44369	ASSESS	29/09/2021 8:49 AM	Matthew Handley	Roads, parking & vehicles > Roads & traffic > Potholes	i.	3 Serious (10 days)	09/10/2021 9:49 AM	19/10/2021 10:05 AM	19/10/2021 12:21 PM	29/09/2021 12:00 AM	08/10/2021 12:00 AM
WO32006	ASSESS	14/01/2021 8:19 AM	Shane Cox	Roads, parking & vehicles Roads & traffic Road condition & safety		3 Serious (10 days)	24/01/2021 8:19 AM	15/01/2021 11:05 AM	18/01/2021 10:05 AM	14/01/2021 12:00 AM	14/03/2021 12:00 AM
WO48209	ASSESS	17/01/2022 11:54 AM	Shane Cox	Roads, parking & vehicles > Roads & traffic > Potholes	i.	3 Serious (10 days)	27/01/2022 12:54 AM	03/02/2022 2:15 PM		17/01/2022 12:00 AM	24/03/2022 12:00 AM
WO42873	ASSESS	18/08/2021 1:00 PM	Matthew Handley	Roads, parking & vehicles > Roads & traffic > Potholes	i.	3 Serious (10 days)	28/08/2021 1:00 PM	26/08/2021 11:39 AM	17/09/2021 12:32 PM	18/08/2021 12:00 AM	03/09/2021 12:00 AM
WO36499	ASSESS	17/03/2021 1:00 PM	Shane Cox	Roads, parking & vehicles; Roads & traffic;		3 Serious (10 days)	27/03/2021 2:00 AM	09/04/2021 9:10 AM	20/04/2021 9:02 AM	17/03/2021 12:00 AM	17/05/2021 12:00 AM
WO29187	ASSESS	20/11/2020 10:40 AM	Shane Cox	Roads, parking & vehicles Roads & traffic Potholes		3 Serious (10 days)	30/11/2020 10:40 AM	20/11/2020 11:04 AM	03/12/2020 10:16 AM	20/11/2020 12:00 AM	20/12/2020 12:00 AM
WO29749	ASSESS	26/11/2020 12:10 PM	Neetu Sharma	Roads, parking & vehicles Roads & traffic Potholes		3 Serious (10 days)	06/12/2020 12:10 PM	08/12/2020 8:08 AM	08/12/2020 10:20 AM	26/11/2020 12:00 AM	26/12/2020 12:00 AM
WO43198	ASSESS	30/08/2021 9:46 AM	Matthew Handley	Roads, parking & vehicles > Roads & traffic > Potholes	·	3 Serious (10 days)	09/09/2021 9:46 AM	08/09/2021 9:11 AM	08/09/2021 12:24 PM	30/08/2021 12:00 AM	10/09/2021 12:00 AM
WO36275	ASSESS	15/03/2021 1:27 PM	Shane Cox	Roads, parking & vehicles; Roads & traffic;		3 Serious (10 days)	25/03/2021 2:27 AM	20/04/2021 1:56 PM	28/04/2021 2:04 PM	15/03/2021 12:00 AM	15/05/2021 12:00 AM
WO40325	ASSESS	17/06/2021 9:20 AM	Nathan Hart	24852-S622 P/O 3.2 L/G 2 bags of mix new sign fix foot		3 Serious (7 days)	24/06/2021 9:20 AM	01/07/2021 1:10 PM	01/07/2021 1:10 PM	02/07/2021 12:00 AM	30/07/2021 12:00 AM
WO34333	ASSESS	10/02/2021 1:13 PM		24852-S650 1x D4-1-3A 1x 800mm L/G 3x bag mix DMR		3 Serious (7 days)	17/02/2021 2:13 AM	30/04/2021 10:58 AM	25/05/2021 3:34 PM	03/03/2021 12:00 AM	03/03/2021 12:00 AM
WO45624	ASSESS	02/11/2021 3:05 PM	Henry Botha	24852 - S621 R4-8(40) SCHOOL ZONE TIME & SPEED		3 Serious (7 days)	09/11/2021 4:05 AM	20/11/2021 11:20 AM	06/01/2022 9:15 AM	04/11/2021 12:00 AM	06/12/2021 12:00 AM
WO45622	ASSESS	02/11/2021 2:49 PM	Henry Botha	24852 - S660 G2-1 P/O X2 DMR TRACK 4 BAG MIX		3 Serious (7 days)	09/11/2021 3:49 AM	08/12/2021 9:45 AM	07/01/2022 1:09 PM	04/11/2021 12:00 AM	06/12/2021 12:00 AM

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Creator	Work Order Brief Description	Work Order Priority	Work Order Priority Notation	Work Order SLA Date	Work Order TCOMP Date	Work Order COMP Date	Work Order Schedule Start	Work Order Schedule Finish
		12/01/2023					19/01/2023 2:24			01/02/2023 12:00	
WO63613	ASSESS	2:24 PM	Nathan Hart	24852-S621 B/O R1-3B		3 Serious (7 days)	PM	03/02/2023 8:44 AM		AM	AM
WO1196	ASSESS	11/03/2020 12:00 AM	Garry George	Relay pavers		5 Change (180 days)	06/09/2020 11:00 PM	26/05/2021 7:08 AM		03/07/2020 12:00 AM	31/12/2020 12:00 AM
		12/01/2021		Cycle & footpaths Fencing & bollards Report safety concern, 1, Manuka Plaza, Flinders Way,			11/07/2021 9:50			12/01/2021 12:00	22/01/2021 12:00
WO31803	TCOMP	10:50 AM	Michael Rootsey			5 Change (180 days)		20/01/2021 4:59 PM		AM	AM
WO45723	CAN	04/11/2021 2:39 PM	Henry Botha	24852 1x1'8		3 Serious (7 days)	11/11/2021 2:39 PM				
WO63614	ASSESS	12/01/2023 2:27 PM	Nathan Hart	24852-S611 B/O R5-1/1 (L) R5-16/1 (R)		2 Urgent (3 days)	15/01/2023 2:27 PM	16/02/2023 12:06 PM		30/01/2023 12:00 AM	28/02/2023 12:00 AM
WO73618	PREP	12/09/2023 2:24 PM	Michael Rootsey	37 Flinders Way, damaged concrete driveway crossover path, 18m2+ asphalt driveway 25.80m2		Very Low Risk (18 4 months)	13/03/2025 3:24 AM				
WO73733	PREP	13/09/2023 3:12 PM	Michael Rootsey	73-75 Flinders Way, damaged paths, 15m2+7.8m2, damaged pram ramp 4L/m and damaged road pavement 1m2, kerb and gutter 3L/m		2 High Risk (14 days)	27/09/2023 3:12 PM				
WO19152	ASSESS	02/07/2019 4:41 AM	Historical IAMS User	Path - Concrete Displaced		Very Low Risk (18 4 months)	30/12/2020 5:41 PM		07/07/2020 7:04 PM	02/07/2019 4:41 AM	12/07/2019 3:41 AM
WO25329	PREP	25/08/2020 11:07 AM	Michael Rootsey	Damaged asphalt path opposite 63 Flinders Way, 127m2		Very Low Risk (18 4 months)	24/02/2022 12:07 AM				
WO26851	ASSESS	07/10/2020 11:19 AM	Michael Rootsey	Damaged asphalt driveway at 79-81 Flinders Way, multiple coldmix repairs to make safe		Very Low Risk (18 4 months)	07/04/2022 10:19 PM	25/11/2020 8:45 AM	03/12/2020 10:20 AM	28/10/2020 12:00 AM	28/11/2020 12:00 AM
WO25330	ASSESS	25/08/2020 11:13 AM	Michael Rootsey	Damaged path opposite 63 Flinders Way, coldmix repairs to make safe		Very Low Risk (18 4 months)	24/02/2022 12:13 AM	20/11/2020 10:41 AM	03/12/2020 10:16 AM	28/10/2020 12:00 AM	28/11/2020 12:00 AM
NO70435	ASSESS	04/07/2023 10:52 AM	Nathan Hart	24852-S640 flood way sign 2 2 m L/G 2 bags of mix		3 Serious (7 days)	11/07/2023 10:52 AM	25/08/2023 12:42 PM		24/07/2023 12:00 AM	24/08/2023 12:00 AM

Work Order ID	Work Order Status	Work Order Creation Time	Work Order Creator	Work Order Brief Description	Work Order Priority		Work Order SLA Date	Work Order TCOMP Date	Work Order COMP Date	Work Order Schedule Start	Work Order Schedule Finish
WO70437	ASSESS	04/07/2023 10:59 AM	Nathan Hart	24852-S641 Flood way signs x 2		3 Serious (7 days)	11/07/2023 10:59 AM	25/08/2023 1:42 PM		24/07/2023 12:00 AM	24/08/2023 12:00 AM
W073735	ASSESS	13/09/2023 3:20 PM	Michael Rootsey	73-75 Flinders Way, damaged paths, multiple coldmix repairs to make safe		2 High Risk (14 days)	27/09/2023 3:20 PM	22/09/2023 10:17 AM		13/09/2023 3:20 PM	27/09/2023 3:20 PM
WO66425	ASSESS	10/03/2023 2:39 PM	Garry George	Relay pavers Flinders Way, Griffith (Manuka) Bougainville St to Franklir St 9 locations12sm		5 Change (180 days)	06/09/2023 1:39 PM	26/09/2023 10:13 AM		25/08/2023 12:00 AM	16/02/2024 12:00 AM
WO71667	ASSESS	02/08/2023 11:13 AM	Michael Rootsey	83 Flinders Way, damaged road pavement/ speed cushion, coldmix repairs to make safe		3 Serious (10 days)	12/08/2023 11:13 AM	06/10/2023 10:21 AM		02/08/2023 11:13 AM	12/08/2023 11:13 AM
WO27713	COMP	30/10/2020 10:12 AM	Michael Rootsey	large hole in the middle of the driveway near the road39 Flinders Way		3 Serious (10 days)	09/11/2020 10:12 AM	19/09/2023 11:39 AM	28/09/2023 7:12 AM	05/09/2023 12:00 AM	15/12/2023 12:00 AM
WO26850	COMP	07/10/2020 11:14 AM	Michael Rootsey	79 FLINDERS WAY, GRIFFITH			17/10/2020 11:14 AM	19/09/2023 11:38 AM	28/09/2023 7:08 AM	05/09/2023 12:00 AM	15/12/2023 12:00 AM

Work Order ID	Work Order Source	Work Order Work Group	Work Order Type	Work Order Failure Code	Work Order Cause Code	Work Order Remedy Code	Work Order Budget Type	Total Cost	Total Planned Cost	Asset Id
WO67899	Public Enquiry	Concrete - RM	CM - Corrective	DSP, DSP-01, Displaced,	ENV, ENV-02, Environmental, Vegetation	Coldmix	OPEX		0	D TRIS454
WO48295		Pavement	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	WER, WER-01, Wear, General Wear	Patch Asphalt	OPEX		0	ROAD_FRANKLIN_STREET_GRIFFI D H
WO63266	Public Enquiry	Pavement	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole RPV, RPV-03, Road	UNK, UNK-01, Unknown Cause, Unknown Cause MAT, MAT-01,	Coldmix	OPEX		0 1.0	ROAD_FRANKLIN_STREET_GRIFFI D H
WO68131	Public Enquiry	Pavement	CM - Corrective	Pavement Defect, Damaged	Material, Improper Material	Patching - Ashpalt	OPEX		0	ROAD_FRANKLIN_STREET_GRIFFI D H
WO68132	Public Enquiry	Pavement	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	MAT, MAT-01, Material, Improper Material	Coldmix	OPEX	1.0	0 1.0	ROAD_FRANKLIN_STREET_GRIFFI
W058545	Public Enquiry	Pavement	CM - Corrective	RPV, RPV-03, Road Pavement Defect, Damaged	ENV, ENV-01, Environmental, Weather	Coldmix	OPEX		0 1.0	ROAD_FRANKLIN_STREET_GRIFFI D H
WO64077	Safety Inspection	Pavement	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole		Coldmix	ОРЕХ		0 1.0	ROAD_FRANKLIN_STREET_GRIFFI D H
WO43210		Road Links	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	ENV, ENV-01, Environmental, Weather	Coldmix	OPEX		0 1.0	D ROAD024038
WO46512		Road Links	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	WER, WER-01, Wear, General Wear	Coldmix	OPEX		0	D ROAD024038
WO47238		Road Links	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	WER, WER-01, Wear, General Wear	Coldmix	OPEX		0	D ROAD024038
WO43211		Road Links	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	ENV, ENV-01, Environmental, Weather	Coldmix	OPEX		0 1.0	D ROAD024038
WO42707		Road Links	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	UNK, UNK-01, Unknown Cause, Unknown Cause	Coldmix	OPEX		0	D ROAD024038
WO46340	Routine Inspection	Road Links		RPV, RPV-02, Road Pavement Defect, Pothole	ENV, ENV-01, Environmental,	Coldmix	OPEX	1.0		0 ROAD005786

Work Order ID	Work Order Source	Work Order Work Group	Work Order Type	Work Order Failure Code	Work Order Cause Code	Work Order Remedy Code	Work Order Budget Type	Total Cost	Total Planned Cost	Asset Id
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
WO29194		Road Links	CM - Corrective	Pavement Defect, Pothole	Unknown Cause UNK, UNK-01,	Pothole-Coldmix	OPEX		0	0 ROAD00578
				RPV, RPV-02, Road	Unknown Cause,					
WO36499		Road Links	CM - Corrective	Pavement Defect, Pothole		Coldmix	OPEX		0 1.0	0 ROAD00578
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
WO11405	Public Enquiry	Concrete - RM	CM - Corrective	Horizontal displacement (15-35mm)	Unknown Cause, Unknown Cause	Panel replacement	OPEX		0	0 COPA17673
W011403	T done Enquiry	Concrete MV	CIVI COTTECTIVE	(13 3311111)	Onknown cause	runerreplacement	OTEX			0 0017117073
				CTU, CTU-02, Concrete -						
				Trip or undulation,	UNK, UNK-01,					
				Vertical displacement	Unknown Cause,					
WO55408	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA17944
				CTU, CTU-01, Concrete - Trip or undulation,	UNK, UNK-01,					
				Vertical displacement (15-						
WO4014	Public Enquiry	Concrete - RM	CM - Corrective	35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA17944
	4. /			CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO9326	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA18071
				DMG, DMG-01, Damaged,	UNK, UNK-01,					
WO11552	Public Enquiry	Concrete - RM	CM - Corrective	Damaged	Unknown Cause	Replace	OPEX		0	0 DRIV84569
11011332	T done Enquiry	Concrete MV	CIVI COTTECTIVE	Damagea	UNK, UNK-01,	перисе	OTEX			0 1111104303
				DMG, DMG-01, Damaged,						
WO10882	Public Enquiry	Concrete - RM	CM - Corrective	Damaged	Unknown Cause	Coldmix	OPEX		0	0 DRIV84569
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
WO12633	Public Enquiry	Concrete - RM	CM - Corrective	Horizontal displacement (15-35mm)	Unknown Cause, Unknown Cause	Grinding	OPEX		0	0 COPA17947
	r done Enquiry	CONCICTE - MIVI	Civi Corrective	CCK, CCK-01, Concrete -	C.Milowii Cause	Simoning	JI LA		,	5 501 A17 J47
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO8993	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA18071
				CCK, CCK-01, Concrete -	LINIK LINIK 04					
				Cracked or displaced, Horizontal displacement	UNK, UNK-01, Unknown Cause,					
WO4147	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA17944
				CTU, CTU-01, Concrete -						
				Trip or undulation,	UNK, UNK-01,					
				Vertical displacement (15-						
WO10228	Safety Inspection	Concrete - RM	CM - Corrective	35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA17631

		Work Order Work			Work Order Cause	Work Order Remedy	Work Order Budget	.		
Work Order ID	Work Order Source	Group	Work Order Type	Work Order Failure Code CCK, CCK-02, Concrete -	Code	Code	Туре	Total Cost	Total Planned Cost	Asset Id
				Cracked or displaced,	MAT, MAT-01,					
				Horizontal displacement	Material, Improper					
NO50234	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm)	Material	Panel replacement	OPEX		0	0 COPA17947
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO9557	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA1807
				DMC DMC 01 Damaged	UNK, UNK-01,					
WO4624	Public Enquiry	Concrete - RM	CM - Corrective	DMG, DMG-01, Damaged, Damaged	Unknown Cause,	Coldmix	OPEX		0	0 DRIV83187
VVO4024	Fublic Liiquii y	Concrete - Kivi	Civi - Corrective	Dalilageu	UNK, UNK-01,	Column	OFLX		U	0 DKIV63167
				DMG, DMG-01, Damaged,						
WO5416	Public Enquiry	Concrete - RM	CM - Corrective	Damaged	Unknown Cause	Replace	OPEX		0	0 DRIV83187
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO7880	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA1794
				CCK, CCK-01, Concrete -	LINIK LINIK 04					
				Cracked or displaced, Horizontal displacement	UNK, UNK-01, Unknown Cause,					
WO18374	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause,	Panel replacement	OPEX		0	0 COPA1776
WO10374	r ubile Eriquiry	CONCIECE - MW	CIVI - COTTECTIVE	CCK, CCK-01, Concrete -	OTIKITOWIT Cause	r aner replacement	OLEX		0	0 COI A1770
				Cracked or displaced,	ENV, ENV-02,					
				Horizontal displacement	Environmental,					
WO50230	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Vegetation	Coldmix	OPEX		0	0 COPA1776
				CCK, CCK-02, Concrete -						
				Cracked or displaced,	ENV, ENV-02,					
				Horizontal displacement	Environmental,					
WO50227	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm) CCK, CCK-01, Concrete -	Vegetation	Panel replacement	OPEX		0	0 COPA1776
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO8677	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA1807
-				/	MAT, MAT-01,					
				DMG, DMG-02, Damaged,						
WO38548	Public Enquiry	Concrete - RM	CM - Corrective	Damaged (Beyond Repair)	Material	Replace	OPEX		0	0 DRIV84429
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
WO9447	Public Enquiry	Concrete - RM	CM - Corrective	Horizontal displacement (15-35mm)	Unknown Cause, Unknown Cause	Grinding	OPEX		0	0 COPA1807
vv U3447	Public Enquiry	CONCIECE - KIVI	Civi - Corrective	CCK, CCK-02, Concrete -	Onknown Cause	Grinding	UPEA		U	o COPAI8U/
				Cracked or displaced,	MAT, MAT-01,					
				Horizontal displacement	Material, Improper					
WO50235	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm)	Material	Panel replacement	OPEX		0	0 COPA1771
				CCK, CCK-02, Concrete -						
				Cracked or displaced,	MAT, MAT-01,					
				Horizontal displacement	Material, Improper		0.051/			
WO50236	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm)	Material	Coldmix	OPEX		0	0 COPA1771
				CCK, CCK-02, Concrete - Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO55418	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA1794

		Work Order Work			Work Order Cause	Work Order Remedy	Work Order Budget			
Work Order ID	Work Order Source	Group	Work Order Type	Work Order Failure Code	Code	Code	Туре	Total Cost	Total Planned Cost	Asset Id
					MAT, MAT-01,					
				DMG, DMG-01, Damaged,	Material, Improper					
VO27720		Concrete - RM	CM - Corrective	Damaged	Material	Coldmix	OPEX		0	0 DRIV82331
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	MAT, MAT-01,					
				Horizontal displacement	Material, Improper					
VO71405	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Material	Panel replacement	OPEX		0	0 COPA17673
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	MAT, MAT-01,					
				Horizontal displacement	Material, Improper					
VO71406	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Material	Grinding	OPEX		0	0 COPA1763:
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO8831	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA18071
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,		0.051/			
NO19346	Safety Inspection	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA17944
				CCK, CCK-01, Concrete -	LINUX LINUX OA					
				Cracked or displaced,	UNK, UNK-01,					
NO10530	Cafatallagasatian	Communica DNA	CM Compositive	Horizontal displacement	Unknown Cause,	Caldusin	ODEV		0	0.000417040
WO19520	Safety Inspection	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA17948
				CCK, CCK-01, Concrete -	LINIK LINIK 04					
				Cracked or displaced,	UNK, UNK-01,					
W010330	Cafata Inanastian	Communica DNA	CM Compositive	Horizontal displacement	Unknown Cause,	Daniel saulanessaut	ODEV		0	0.00041704
WO19330	Safety Inspection	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA1794
				CCK, CCK-01, Concrete - Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO9021	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause,	Panel replacement	OPEX		0	0 COPA1776
WO8021	Fublic Eliquii y	COILCIELE - KIVI	Civi - Corrective	CCK, CCK-01, Concrete -	OHNHOWH Cause	ranerreplacement	OFEA		U	U CUPAI//b.
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO13276	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA1794
	i done Enquiry	CONCICCE - MVI	Sivi Corrective	CCK, CCK-02, Concrete -	C.IKIIOWII Cause	. and replacement	JI LA		-	5 COI A1734
				Cracked or displaced,	ENV, ENV-02,					
				Horizontal displacement	Environmental,					
WO47014	Public Enquiry	Concrete - RM	CM - Corrective	(>35mm)	Vegetation	Grinding	OPEX		0	0 COPA1794
	,			· ·····/	UNK, UNK-01,				-	
				DMG, DMG-01, Damaged,						
NO4692	Public Enquiry	Concrete - RM	CM - Corrective	Damaged	Unknown Cause	Coldmix	OPEX		0	0 DRIV83187
	1. /			CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO9065	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA1807
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO4520	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA1794

		Work Order Work			Work Order Cause	Work Order Remedy	Work Order Budget			
Work Order ID	Work Order Source	Group	Work Order Type	Work Order Failure Code	Code	Code	Туре	Total Cost	Total Planned Cost	Asset Id
				CCK, CCK-01, Concrete -	LINIK LINIK 04					
				Cracked or displaced, Horizontal displacement	UNK, UNK-01, Unknown Cause,					
WO17938	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA17761
WO17936	Fublic Liiquii y	Concrete - Kivi	Civi - Corrective	CCK, CCK-01, Concrete -	Olikilowii Cause	Column	OFLX		· ·	0 COFA17701
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO19420	Safety Inspection	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Panel replacement	OPEX		0	0 COPA17944
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO4463	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Grinding	OPEX		0	0 COPA17944
					UNK, UNK-01,					
				DMG, DMG-01, Damaged,						
WO4850	Public Enquiry	Concrete - RM	CM - Corrective	Damaged	Unknown Cause	Replace	OPEX		0	0 DRIV83187
				CCK, CCK-01, Concrete -	LINIK LINIK OA					
				Cracked or displaced, Horizontal displacement	UNK, UNK-01, Unknown Cause,					
WO9425	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause,	Panel replacement	OPEX		0	0 COPA18071
WO3423	Fublic Eliquity	Concrete - Kivi	Civi - Corrective	CCK, CCK-01, Concrete -	Olikilowii Cause	ranerreplacement	OFLX		· ·	0 COFA18071
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO8357	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Grinding	OPEX		0	0 COPA17762
				CCK, CCK-01, Concrete -		-				
				Cracked or displaced,	UNK, UNK-01,					
				Horizontal displacement	Unknown Cause,					
WO200	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause	Coldmix	OPEX		0	0 COPA17761
				CCK, CCK-01, Concrete -						
				Cracked or displaced,	UNK, UNK-01,					
1407660	D. I.P. Francisco	Community DNA	CNA Commention	Horizontal displacement	Unknown Cause,	Daniel and a constant	ODEV			0.000447672
WO7669	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Unknown Cause UNK, UNK-01,	Panel replacement	OPEX		0	0 COPA17673
				RPV, RPV-02, Road	Unknown Cause,					
WO34507		Pavement	CM - Corrective	Pavement Defect, Pothole		Coldmix	OPEX		0	0 CPAK627
		. aveillent	CIII COTTCCCTC	RPV, RPV-03, Road	MAT, MAT-01,	Column	0.24			0 0.711.027
				Pavement Defect,	Material, Improper					
WO68136	Public Enquiry	Pavement	CM - Corrective	Damaged	Material	Patching - Ashpalt	OPEX		0	0 ROAD_FLINDERS_WAY_GRIFFITH
				LMK, LMK-03, Linemarking						
WO49421	Public Enquiry	Pavement	CM - Corrective	Defect, Lines - LLM	General Wear	Repaint Lines	OPEX		0	0 ROAD_FLINDERS_WAY_GRIFFITH
				DDV DDV 02 5 1	ENV, ENV-01,					
WOE0004	Dublic Feering	Davisant	CNA Campatin	RPV, RPV-02, Road	Environmental,	Caldesia	ODEY			O DOAD FLINDERS WAY SPIEST
WO58084	Public Enquiry	Pavement	CM - Corrective	Pavement Defect, Pothole RPV, RPV-03, Road	MAT, MAT-01,	Coldmix	OPEX		0 4.0	0 ROAD_FLINDERS_WAY_GRIFFITH
				Pavement Defect,	Material, Improper					
WO68899	Public Enquiry	Pavement	CM - Corrective	Damaged	Material	Patching - Ashpalt	OPEX		0	0 ROAD FLINDERS WAY GRIFFITH
	. abile Eliquity	. avenient	c corrective	- Samagea	MAT, MAT-01,	. acoming / onput	O. LA		,	
				RPV, RPV-02, Road	Material, Improper					
NO48597	Public Enquiry	Pavement	CM - Corrective	Pavement Defect, Pothole		Coldmix	OPEX		0	0 ROAD FLINDERS WAY GRIFFITH

		Work Order Work			Work Order Cause	Work Order Remedy	Work Order Budget			
Work Order ID	Work Order Source	Group	Work Order Type	Work Order Failure Code	Code	Code	Туре	Total Cost	Total Planned Cost	Asset Id
				LMK, LMK-06, Linemarking	WER, WER-01, Wear,					
WO66935		Pavement	CM - Corrective	Defect, Lines - Other	General Wear	Repaint Lines	OPEX	()	ROAD_FLINDERS_WAY_GRIFFITH
				RPV, RPV-03, Road Pavement Defect,	MAT, MAT-01, Material, Improper					
WO68138	Public Enquiry	Pavement	CM - Corrective	Damaged	Material	Patching - Ashpalt	OPEX	C		ROAD_FLINDERS_WAY_GRIFFITH
					MAT, MAT-01,					
W0.0000	D. hills Exercise	Danisana	CM Commention	RPV, RPV-02, Road	Material, Improper	Caldada	ODEV	4.00	1.0	DOAD FUNDERS WAY SPIEST
WO68898	Public Enquiry	Pavement	CM - Corrective	Pavement Defect, Pothole	Material	Coldmix	OPEX	1.00	1.0	0 ROAD_FLINDERS_WAY_GRIFFITH
					MAT, MAT-01,					
				RPV, RPV-02, Road	Material, Improper					
WO68139	Public Enquiry	Pavement	CM - Corrective	Pavement Defect, Pothole	Material	Coldmix	OPEX	1.00	1.0	ROAD_FLINDERS_WAY_GRIFFITH
					MAT, MAT-01,					
				RPV, RPV-02, Road	Material, Improper					
W055414	Public Enquiry	Pavement	CM - Corrective	Pavement Defect, Pothole		Patching - Ashpalt	OPEX	C)	ROAD_FLINDERS_WAY_GRIFFITH
				RPV, RPV-03, Road Pavement Defect,	MAT, MAT-01, Material, Improper					
WO46543	Ministerial	Pavement	CM - Corrective	Damaged	Material	Patch Asphalt	OPEX	()	ROAD_FLINDERS_WAY_GRIFFITH
				RPV, RPV-03, Road	MAT, MAT-01,					
WO 4050C	D. hills E	Danisana	CM Commention	Pavement Defect,	Material, Improper	Datable a Asharah	ODEV			DOAD FUNDERS WAY CRIFFITI
WO48596	Public Enquiry	Pavement	CM - Corrective	Damaged	Material	Patching - Ashpalt	OPEX	()	0 ROAD_FLINDERS_WAY_GRIFFITH
					MAT, MAT-01,					
				RPV, RPV-02, Road	Material, Improper					
WO70482	Safety Inspection	Pavement	CM - Corrective	Pavement Defect, Pothole		Potholes - Coldmix	OPEX	2.00	2.0	ROAD_FLINDERS_WAY_GRIFFITH
				RPV, RPV-03, Road Pavement Defect,	MAT, MAT-01, Material, Improper					
WO46544	Ministerial	Pavement	CM - Corrective	Damaged	Material	Patch Asphalt	OPEX	()	ROAD_FLINDERS_WAY_GRIFFITH
				DDV DDV 03 D1	MAT, MAT-01,					
WO68137	Public Enquiry	Pavement	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole	Material, Improper	Coldmix	OPEX	1.00	1.0	ROAD FLINDERS WAY GRIFFITH
	r dono zniquiry	- dvement	CITI CONTECUTE	r avement bereet, r other	ENV, ENV-01,	Column	0.27	2.00	, 110	
				RPV, RPV-02, Road	Environmental,					
WO46340	Routine Inspection	Road Links	CM - Corrective	Pavement Defect, Pothole		Coldmix	OPEX	1.00	1.0	0 ROAD005786
				RPV, RPV-02, Road	UNK, UNK-01, Unknown Cause,					
WO29194		Road Links	CM - Corrective	Pavement Defect, Pothole	,	Pothole-Coldmix	OPEX	C		0 ROAD005786
					UNK, UNK-01,					
WO22094		Boad Links	CM - Corrective	RPV, RPV-02, Road	Unknown Cause,	Datch Acabalt	OPEX	5.00		D ROAD024506
WO32984		Road Links	Civi - Corrective	Pavement Defect, Pothole RPV, RPV-04, Road	UNK, UNK-01,	Patch Asphalt	UPEX	5.00	6.00	U NUADU245U0
				Pavement Defect,	Unknown Cause,					
WO49950		Road Links	CM - Corrective	Defective	Unknown Cause	Patch Asphalt	OPEX	C)	0 ROAD124708
				RPV, RPV-02, Road	W/ED W/ED 01 W/o					
WO47370		Road Links	CM Corrective	Pavement Defect, Pothole	WER, WER-01, Wear,	Coldmix	OPEX	_)	D ROAD005822

		Work Order Work			Work Order Cause	Work Order Remedy	Work Order Budget			
Work Order ID	Work Order Source	Group	Work Order Type	Work Order Failure Code	Code	Code	Туре	Total Cost	Total Planned Cost	Asset Id
				RPV, RPV-04, Road	UNK, UNK-01,					
				Pavement Defect,	Unknown Cause,					
VO44663		Road Links	CM - Corrective	Defective	Unknown Cause	Patch Asphalt	OPEX		0	0 ROAD02450
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
044369		Road Links	CM - Corrective	Pavement Defect, Pothole	Unknown Cause	Coldmix	OPEX		0 3.0	0 ROAD02450
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
O32006		Road Links	CM - Corrective	Pavement Defect, Pothole	Unknown Cause	Coldmix	OPEX		0	0 ROAD12470
				RPV, RPV-02, Road	WER, WER-01, Wear,					
VO48209		Road Links	CM - Corrective	Pavement Defect, Pothole	General Wear	Coldmix	OPEX		0	0 ROAD02458
					ENV, ENV-01,					
				RPV, RPV-02, Road	Environmental,					
VO42873		Road Links	CM - Corrective	Pavement Defect, Pothole	Weather	Coldmix	OPEX		0 1.0	0 ROAD02450
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
O36499		Road Links	CM - Corrective	Pavement Defect, Pothole	Unknown Cause	Coldmix	OPEX		0 1.0	0 ROAD00578
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
VO29187		Road Links	CM - Corrective	Pavement Defect, Pothole		Pothole-Coldmix	OPEX		0	0 ROAD02450
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
WO29749		Road Links	CM - Corrective	Pavement Defect, Pothole	Unknown Cause	Pothole-Coldmix	OPEX		0	0 ROAD02395
					ENV, ENV-01,					
				RPV, RPV-02, Road	Environmental,					
WO43198		Road Links	CM - Corrective	Pavement Defect, Pothole	Weather	Coldmix	OPEX		0 1.0	0 ROAD02395
					UNK, UNK-01,					
				RPV, RPV-02, Road	Unknown Cause,					
WO36275		Road Links	CM - Corrective	Pavement Defect, Pothole	Unknown Cause	Coldmix	OPEX		0 1.0	0 ROAD00585
					TPD, TPD-01, Third					
				SGN, SGN-10, Sign Defect,	Party Damage, Third					
WO40325	Routine Inspection	Signs	CM - Corrective	Pole Damaged	Party Damage	Replace	OPEX		0	0 SGNG17965
					TPD, TPD-01, Third					
				SGN, SGN-01, Sign Defect,	Party Damage, Third					
NO34333		Signs	CM - Corrective	Blade and Pole Damaged	Party Damage	Replace	OPEX		0	0 SGNG17868
					ENV, ENV-01,					
				SGN, SGN-03, Sign Defect,	Environmental,					
WO45624	Routine Inspection	Signs	CM - Corrective	Blade Defective	Weather	Replace	OPEX		0	0 SGNG78551
					TPD, TPD-01, Third					
				SGN, SGN-10, Sign Defect,	Party Damage, Third					
WO45622	Public Enquiry	Signs	CM - Corrective	Pole Damaged	Party Damage	Replace	OPEX		0	0 SGNG268

Work Order ID	Work Order Source	Work Order Work Group	Work Order Type	e Work Order Failure Code	Work Order Cause Code	Work Order Remedy Code	Work Order Budget Type	Total Cost	Total Planned Cost	Asset Id
				SGN, SGN-04, Sign Defect,						
WO63613	Routine Inspection	Signs	CM - Corrective	Sign Information Faded/Illegible	Environmental, Weather	Replace	OPEX		0	0 SGNG18106
					UNK, UNK-01,					
WO1196	Routine Inspection	Concrete - RM	CM - Corrective	DSP, DSP-01, Displaced, Displaced	Unknown Cause, Unknown Cause	Relay	OPEX		0	D PAVE2217
WO1130	Nouthe hispection	Concrete - Kivi	CIVI - COITECTIVE	ызрівсец	Olikilowii Cause	Relay	OLEX			J I AVLZZII
				DCD DCD 04 Disabased	MAT, MAT-01,					
WO31803	Public Enquiry	Concrete - RM	CM - Corrective	DSP, DSP-01, Displaced, Displaced	Material, Improper Material	Grind	OPEX		0	0 PAVE2217
				SGN, SGN-03, Sign Defect,	ENV, ENV-01, Environmental.					
WO45723		Signs	CM - Corrective	Blade Defective	Weather	Replace	OPEX		0	0 SGNG148
					TPD, TPD-01, Third					
				SGN, SGN-05, Sign Defect,						
WO63614	Routine Inspection	Signs	CM - Corrective	Graffiti	Party Damage	Replace	OPEX		0	0 SGNG18117
				CCK, CCK-01, Concrete - Cracked or displaced,	MAT, MAT-01,					
				Horizontal displacement	Material, Improper					
WO73618	Public Enquiry	Concrete - RM	CM - Corrective	(15-35mm)	Material	Panel replacement	OPEX		0	O COPA17947
				CCK, CCK-02, Concrete -						
				Cracked or displaced,	ENV, ENV-02,					
W073733		Concrete - RM	CM - Corrective	Horizontal displacement (>35mm)	Environmental, Vegetation	Panel replacement	OPEX		0 1.0	0 COPA18018
				ACCK, ACCK-01, AC -						
				Cracked or displaced, Horizontal displacement	UNK, UNK-01, Unknown Cause,					
WO19152	Safety Inspection	Concrete - RM	CM - Corrective	(15-50mm)	Unknown Cause	Grinding	OPEX		0	O COPA17937
				ACTU, ACTU-01, AC - Trip	ENV, ENV-02,					
				or undulation, Vertical	Environmental,					
WO25329		Concrete - RM	CM - Corrective	displacement (15-50mm)	Vegetation	Panel replacement	OPEX		0	O COPA17937
				ACTU, ACTU-01, AC - Trip	MAT, MAT-01,					
				or undulation, Vertical	Material, Improper					
WO26851		Concrete - RM	CM - Corrective	displacement (15-50mm)	Material	Coldmix	OPEX		0	O COPA18097
				ACTU, ACTU-01, AC - Trip	ENV, ENV-02,					
W025220		Consusts DA4	CM Compatible	or undulation, Vertical	Environmental,	Caldusin	ODEV		0	0.000417037
WO25330		Concrete - RM	CM - Corrective	displacement (15-50mm)	vegetation	Coldmix	OPEX		0	0 COPA17937
				SGN, SGN-04, Sign Defect,						
W070435	Public Enquiry	Signs	CM - Corrective	Sign Information	Environmental, Weather	Renlace	OPEX		0	0 SGNG18082
NO/0435	Public Enquiry	Signs	CM - Corrective	Faded/Illegible	weather	Replace	OPEX		U	U SGNG18082

		Work Order Work			Wash Order Cause	Warls Order Barrads	Wash Order Budest			
Work Order ID	Work Order Source	Group	Work Order Type	Work Order Failure Code	Work Order Cause Code	Work Order Remedy Code	Work Order Budget Type	Total Cost	Total Planned Cost	Asset Id
WO70437	Public Enquiry	Signs	CM - Corrective	SGN, SGN-04, Sign Defect, Sign Information Faded/Illegible	ENV, ENV-01, Environmental, Weather	Replace	OPEX) () SGNG18077
W073735	Public Enquiry	Concrete - RM	CM - Corrective	CCK, CCK-02, Concrete - Cracked or displaced, Horizontal displacement (>35mm)	MAT, MAT-01, Material, Improper Material	Coldmix	OPEX	() (O COPA18018
WO66425	Routine Inspection	Concrete - RM	CM - Corrective	DSP, DSP-01, Displaced, Displaced	WER, WER-01, Wear, General Wear	Relay	OPEX	1,320.00	1,320.00) PAVE2217
WO71667	Safety Inspection	Pavement	CM - Corrective	RPV, RPV-02, Road Pavement Defect, Pothole		Coldmix	OPEX	1.00	0 1.00) ROAD_FLINDERS_WAY_GRIFFITH
WO27713		Concrete - RM	CM - Corrective	DMG, DMG-02, Damaged, Damaged (Beyond Repair)	Material	Replace	OPEX	8.00	0 8.00	DRIV82331
WO26850		Concrete - RM	CM - Corrective	DMG, DMG-02, Damaged, Damaged (Beyond Repair)		Replace	OPEX	18.64	17.64	4 DRIV82612

						Maintenance Asset	Maintenance Assot	
Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Type	Sub Type	Asset Suburb
	FRANKLIN STREET SPLITTER		Traffic Management			Traffic Management		
WO67899	ISLAND	Active	Devices	Medium	Concrete - RM	Device	Concrete	GRIFFITH
WO07833	ISLAND	Active	Devices	Mediam	Concrete - Kivi	Device	Concrete	GKIFIIII
WO48295	FRANKLIN STREET (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO63266	FRANKLIN STREET (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO68131	FRANKLIN STREET (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO68132	FRANKLIN STREET (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
W000132	TRAINCEIN STREET (GRITTITI)	Active	Nodus	Wediam	ravement	Noau	Widilicipal	OMITTITI
WO58545	FRANKLIN STREET (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO64077	FRANKLIN STREET (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
	CAPTAIN COOK CRESCENT							
	(FRANKLIN ->							
WO43210	CANBERRA/MANUKA)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
	CAPTAIN COOK CRESCENT (FRANKLIN ->							
WO46512	CANBERRA/MANUKA)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
	CAPTAIN COOK CRESCENT			cuium	Jud Elling		a.neipui	S
	(FRANKLIN ->							
WO47238	CANBERRA/MANUKA)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
	CAPTAIN COOK CRESCENT							
	(FRANKLIN ->							
WO43211	CANBERRA/MANUKA)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
	CAPTAIN COOK CRESCENT							
WO42707	(FRANKLIN -> CANBERRA/MANUKA)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
VV U42/U/	CAINDERRA/IVIAINURA)	ACTIVE	nudus	ivieululli	NUGU LIIIKS	nudu	iviuilicipai	GNIFFIIFI
	FRANKLIN STREET (FLINDERS -							
WO46340	> CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb	
WO29194	FRANKLIN STREET (FLINDERS - > CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO36499	FRANKLIN STREET (FLINDERS - > CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
VO11405	BOUGAINVILLE STREET,FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO55408	LA PEROUSE STREET,FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
NO4014	LA PEROUSE STREET, FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO9326	HAYES CRESCENT,FLINDERS WAY,DURVILLE CRESCENT CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
VO11552	FLINDERS WAY CONCRETE DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH	
VO10882	FLINDERS WAY CONCRETE DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH	
VO12633	FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
VO8993	HAYES CRESCENT, FLINDERS WAY, DURVILLE CRESCENT CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
VO4147	LA PEROUSE STREET,FLINDERS WAY CONCRETE FOOTPATH		Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
VO10228	BOUGAINVILLE STREET,FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb
oraci ib	- Individual Control of the Control	- Laber Status	, isset outegory	Visite Greediney	- I soce Workgroup		урс	- Ascersasa s
	FLINDERS WAY CONCRETE							
WO50234	FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	HAYES CRESCENT, FLINDERS							
	WAY, DURVILLE CRESCENT							
WO9557	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY CONCRETE							
WO4624	DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH
	FLINDERS WAY CONCRETE							
WO5416	DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH
	FUNDERS WAY CONCESTS							
WO7880	FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY							
	NEIGHBOURHOOD PARK							
WO18374	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY							
WO50230	NEIGHBOURHOOD PARK CONCRETE FOOTPATH	Active	Dethursus	Medium	Concrete - RM	Community Doth	Concrete	GRIFFITH
WO30230	CONCRETE FOOTPATH	Active	Pathways	Mediaiii	Concrete - Kivi	Community Path	Concrete	GKIFFIITI
	FLINDERS WAY NEIGHBOURHOOD PARK							
WO50227	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	HAYES CRESCENT, FLINDERS							
	WAY, DURVILLE CRESCENT							
WO8677	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY CONCRETE							
WO38548	DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH
	HAYES CRESCENT, FLINDERS							
WO9447	WAY, DURVILLE CRESCENT CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
		-						
	FLINDERS WAY, MURRAY CRESCENT CONCRETE							
WO50235	FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY, MURRAY							
W050336	CRESCENT CONCRETE	A - 12	Bathanan	A A or all towards	Community DA4	Community Built	Community	CDIFFITH
WO50236	FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	LA DEDOLICE CEDEET EL TIMO							
WO55418	LA PEROUSE STREET, FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb
TOTAL OTTEN		rissee status	7 isset outegory	risset divisionity	7 isset Workgroup	1,460	Jab Type	/isseesabars
NO27720	FLINDERS WAY ASPHALT DRIVEWAY	Active	Hard Surfaces	N.A. adi	Company DNA	Hard Surface	Cananata	GRIFFITH
WU27720	DRIVEWAY	Active	nard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH
	BOUGAINVILLE							
WO71405	STREET,FLINDERS WAY CONCRETE FOOTPATH	Active	Dathwaye	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
WO71403	CONCRETE FOOTFAITI	Active	Pathways	Wediam	Concrete - Kivi	Community Fath	Concrete	GRIFFIIII
	2011041211111115							
	BOUGAINVILLE STREET,FLINDERS WAY							
WO71406	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	HAYES CRESCENT, FLINDERS WAY, DURVILLE CRESCENT							
WO8831	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	LA PEROUSE STREET,FLINDERS							
WO19346	WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	LA PEROUSE STREET,FLINDERS							
WO19520	WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY CONCRETE							
WO19330	FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY							
	NEIGHBOURHOOD PARK							
WO8021	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY CONCRETE							
WO13276	FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
NO 4701 4	LA PEROUSE STREET, FLINDERS	Action	Dathwei	Mading	Community DA4	Community Both	Company	CDIECITU
WO47014	WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	FLINDERS WAY CONCRETE							
WO4692	DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH
	HAYES CRESCENT, FLINDERS							
	WAY, DURVILLE CRESCENT							
WO9065	CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
	LA PEROUSE STREET, FLINDERS							

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb	
WO17938	FLINDERS WAY NEIGHBOURHOOD PARK CONCRETE FOOTPATH	Activo	Dathways	Medium	Concrete - RM	Community Dath	Concrete	GRIFFITH	
WU17938	CONCRETE FOOTPATH	Active	Pathways	iviedium	Concrete - RM	Community Path	Concrete	GRIFFIIH	
WO19420	LA PEROUSE STREET, FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO4463	LA PEROUSE STREET, FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO4850	FLINDERS WAY CONCRETE DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH	
WO9425	HAYES CRESCENT, FLINDERS WAY, DURVILLE CRESCENT CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
W08357	FLINDERS WAY NEIGHBOURHOOD PARK CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO200	FLINDERS WAY NEIGHBOURHOOD PARK CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO7669	BOUGAINVILLE STREET,FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO34507	FLINDERS WAY INDENTED ON ROAD CAR PARK	Active	Car Parks	Medium	Pavement	Car Park	Indented On Road Car Park		
NO68136	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH	
WO49421	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH	
NO58084	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH	
WO68899	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH	
WO48597	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH	

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb
Work Order ID	Asset Name	- Asset Status	- Abser caregory	Assertanticality	7.33et Workgroup	Турс	- Sab Type	Asset Suburb
WO66935	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO68138	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO08138	FLINDERS WAT (GRIFFITH)	Active	Rodus	Wedium	ravement	Noau	ividilicipal	GRIFFIIII
WO68898	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO68139	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
W000133	TEMPERS WAT (GRAFFITH)	retive	nodus	Wediani	ravement	Noud	Wallerpal	GIAII TTTT
W055414	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO46543	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO48596	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO70482	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO46544	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO68137	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
	FRANKLIN STREET (FLINDERS -							
WO46340	> CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
WO29194	FRANKLIN STREET (FLINDERS - > CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
VV U Z J 1 J 4		ACTIVE	nodus	Wediaiii	Modu LIIINS	nuau	wunicipar	GAIFFIIII
WO32984	FLINDERS WAY (LA PEROUSE (SW) -> DURVILLE)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
	FLINDERS WAY (MURRAY -> LA							
WO49950	PEROUSE (NE))	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH
	FLINDERS WAY (PALMERSTON							
WO47370	> BOUGAINVILLE)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb	
WO44663	FLINDERS WAY (LA PEROUSE (SW) -> DURVILLE)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO44369	FLINDERS WAY (LA PEROUSE (SW) -> DURVILLE)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
VO32006	FLINDERS WAY (LA PEROUSE (NE) -> LA PEROUSE (SW))	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO48209	FLINDERS WAY (HAYES -> MONARO)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO42873	FLINDERS WAY (LA PEROUSE (SW) -> DURVILLE)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO36499	FRANKLIN STREET (FLINDERS - > CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO29187	FLINDERS WAY (LA PEROUSE (SW) -> DURVILLE)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO29749	MANUKA CIRCLE (FLINDERS -> CANBERRA/CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Territory	GRIFFITH	
WO43198	MANUKA CIRCLE (FLINDERS -> CANBERRA/CAPTAIN COOK)	Active	Roads	Medium	Road Links	Road	Territory	GRIFFITH	
WO36275	MURRAY CRESCENT (FLINDERS -> CAPTAIN COOK/STUART)	Active	Roads	Medium	Road Links	Road	Municipal	GRIFFITH	
WO40325	LA PEROUSE STREET, FLINDERS WAY GALVANISED STEEL CIRCULAR HOLLOW SECTION SIGN POST - SIGN BLADE CODES R1-1,R2-3(L)	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	
WO34333	MONARO CRESCENT, FLINDERS WAY GALVANISED STEEL CIRCULAR HOLLOW SECTION SIGN POST - SIGN BLADE CODES D4-1-3	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	
WO45624	FLINDERS WAY ROAD VERGE GALVANISED STEEL CIRCULAR HOLLOW SECTION SIGN POST - SIGN BLADE CODES R4-8(40)	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	
WO45622	FLINDERS WAY ROAD VERGE MILD STEEL PIPE SIGN POST - SIGN BLADE CODES G2-1	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb	
	FLINDERS WAY, MURRAY CRESCENT GALVANISED STEEL CIRCULAR HOLLOW SECTION SIGN POST - SIGN BLADE								
VO63613	CODES R1-3	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	
WO1196	FLINDERS WAY ROAD VERGE SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Pavers	GRIFFITH	
WO31803	FLINDERS WAY ROAD VERGE SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Pavers	GRIFFITH	
	FLINDERS WAY ROAD VERGE MILD STEEL PIPE SIGN POST - SIGN BLADE CODES GE2-2,W3-								
NO45723	4	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	
WO63614	FLINDERS WAY ROAD VERGE UTILITY SIGN POST - SIGN BLADE CODES R5-1/1,R5-16/1	Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH	
W072648	FLINDERS WAY CONCRETE		Datharas	Mark	Samuel BM	Construction Both	Constant	CDIFFITH	
NO73618	FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
W073733	FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH	
WO19152	FLINDERS WAY NEIGHBOURHOOD PARK ASPHALT CYCLEPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Asphalt	GRIFFITH	
	FLINDERS WAY NEIGHBOURHOOD PARK		·						
WO25329	ASPHALT CYCLEPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Asphalt	GRIFFITH	
VO26851	FLINDERS WAY ROAD VERGE ASPHALT CYCLEPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Asphalt	GRIFFITH	
WO25330	FLINDERS WAY NEIGHBOURHOOD PARK ASPHALT CYCLEPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Asphalt	GRIFFITH	
NO70435	FLINDERS WAY GALVANISED STEEL CIRCULAR HOLLOW SECTION SIGN POST - SIGN BLADE CODES R5-3/1		. activays	Wedani	SHORE MI	community i dui	Sign Post	GRIFFITH	

Work Order ID	Asset Name	Asset Status	Asset Category	Asset Criticality	Asset Workgroup	Maintenance Asset Type	Maintenance Asset Sub Type	Asset Suburb
W070437	FLINDERS WAY ROAD VERGE GALVANISED STEEL CIRCULAR HOLLOW SECTION SIGN POST SIGN BLADE CODES R5-40	- Active	Signs	Medium	Signs	Sign	Sign Post	GRIFFITH
WO73735	FLINDERS WAY CONCRETE FOOTPATH	Active	Pathways	Medium	Concrete - RM	Community Path	Concrete	GRIFFITH
WO66425	FLINDERS WAY ROAD VERGE SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Pavers	GRIFFITH
WO71667	FLINDERS WAY (GRIFFITH)	Active	Roads	Medium	Pavement	Road	Municipal	GRIFFITH
WO27713	FLINDERS WAY ASPHALT DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH
WO26850	FLINDERS WAY ASPHALT DRIVEWAY	Active	Hard Surfaces	Medium	Concrete - RM	Hard Surface	Concrete	GRIFFITH

Work Request ID	Asset Id	Asset Name	Asset Status	Asset Category	Work Request Status
Work nequest is	Asset Id	FRANKLIN STREET STANDARD U	/ isset statas	7 isset eategory	Work Request Status
WR83523	BRCK854	SHAPED	Active	Street Furniture	CLOSED
		MANUKA SHOPPING CENTRE			
WR76395	OSBN2479	GARBAGE WHEELIE BIN	Active	Bins	CLOSED
		MANUKA SHOPPING CENTRE			
WR45248	PAVE759	SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	INPRG
		MANUKA SHOPPING CENTRE			
WR44058	PAVE759	SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	INPRG
		MANUKA SHOPPING CENTRE			
WR87881	PAVE759	SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	CLOSED
		MANUKA SHOPPING CENTRE			
WR93232	PAVE759	SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	CLOSED
	ROAD_FRANKLIN_				
WR41562	STREET_GRIFFITH	FRANKLIN STREET (GRIFFITH)	Active	Roads	INPRG
W.D.75.60.4	ROAD_FRANKLIN_	EDANIZIAN CEREET (CRIEFIELI)	A . 1.*	D I.	CLOSED
WR75684	_	FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
W/D7E2E2	ROAD_FRANKLIN_	FDANIZINI STREET (CRIEFITII)	A ativo	Doods	CLOSED
WR75353	ROAD_FRANKLIN_	FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
WR20421		FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
VVI\2U421	ROAD_FRANKLIN_	TRANSPORTED (ORITHII)	ACTIVE	Rodus	CLOSED
WR4918		FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
	ROAD_FRANKLIN_				
WR23137		FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
	ROAD_FRANKLIN_				
WR77134		FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
	ROAD_FRANKLIN_				
WR76688	STREET_GRIFFITH	FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED

Work Request ID	Asset Id	Asset Name	Asset Status	Asset Category	Work Request Status
	ROAD_FRANKLIN_				
WR52461	STREET_GRIFFITH	FRANKLIN STREET (GRIFFITH)	Active	Roads	CANCELLED
	ROAD_FRANKLIN_				
WR23140	STREET_GRIFFITH	FRANKLIN STREET (GRIFFITH)	Active	Roads	CANCELLED
	ROAD_FRANKLIN_				
WR52464	STREET_GRIFFITH	FRANKLIN STREET (GRIFFITH)	Active	Roads	INPRG
	ROAD_FRANKLIN_				
WR18871	STREET_GRIFFITH	FRANKLIN STREET (GRIFFITH)	Active	Roads	CLOSED
		MANUKA SHOPPING CENTRE QS			
WR78447	SMP24609	SUMP	Active	Stormwater Pits	CLOSED
		FRANKLIN STREET ASPHALT SPEED		Traffic Management	
WR62308	SPHU0146	TABLE	Active	Devices	CLOSED

Work Request ID	Work Request Stat		Risk Level	Work Request Brief Descriptio	r Asset Type	Asset Suburb
	22/05/2023 2:01			1-7 FRANKLIN ST, GRIFFITH >		
WR83523	PM	PM		Damage to path or other	BICYCLE RACK	GRIFFITH
	25/01/2023 9:27	11/01/2023		MANUKA - Flinders way -		
WR76395	AM	10:10 PM		Posters on bin shrouds	OPEN SPACE BIN	GRIFFITH
		03/03/2022 3:57		Displaced Pavers and fallen		
WR45248	PM	PM		tree > Shared paths > Damage	HARD SURFACE	GRIFFITH
	03/03/2022 11:25		_	Relay Pavers, Front of		
WR44058	AM	PM	Safety	Grillââ,¬â,,¢d restaurant,4	HARD SURFACE	GRIFFITH
		29/06/2023 2:56		Cycle & footpaths > Shared		
WR87881	PM	PM		paths > Blocking the path	HARD SURFACE	GRIFFITH
		15/09/2023 6:24		Cycle & footpaths > Shared		
WR93232	PM	PM		paths > Damage to path or	HARD SURFACE	GRIFFITH
	18/01/2022 8:57	17/01/2022		Roads, parking & vehicles >		
WR41562	AM	12:53 PM		Roads & traffic > Potholes	ROAD	GRIFFITH
	30/01/2023 12:58	04/01/2023 2:40		Roads, parking & vehicles >		
WR75684	PM	PM	Safety	Roads & traffic > Potholes	ROAD	GRIFFITH
	30/01/2023 12:58	01/01/2023 3:37		Roads, parking & vehicles >		
WR75353	PM	PM	Safety	Roads & traffic > Potholes	ROAD	GRIFFITH
	19/05/2021 3:22	06/04/2021 9:59		Roads, parking & vehicles		
WR20421	PM	AM		Roads & traffic Potholes	ROAD	GRIFFITH
	07/12/2020 10:00	21/10/2020		Roads, parking & vehicles;		
WR4918	AM	10:11 AM		Roads & traffic; Potholes	ROAD	GRIFFITH
	21/05/2021 8:39	17/05/2021 4:30		Roads, parking & vehicles >		
WR23137	AM	PM		Roads & traffic > Potholes	ROAD	GRIFFITH
	30/01/2023 12:58	21/01/2023 3:02		Roads, parking & vehicles >		
WR77134	PM	PM	Safety	Roads & traffic > Potholes	ROAD	GRIFFITH
	30/01/2023 12:58	16/01/2023		ENDEAVOUR HOUSE 7		
WR76688	PM	11:23 AM	Safety	FRANKLIN ST, GRIFFITH >	ROAD	GRIFFITH

Work Request ID	Work Request Stat	Work Request Cre	Risk Level	Work Request Brief Descriptio	Asset Type	Asset Suburb
	06/06/2022 12:41	24/05/2022 3:35		Roads, parking & vehicles >		
WR52461	PM	PM		Roads & traffic > Potholes	ROAD	GRIFFITH
	19/01/2022 11:41	17/05/2021 4:45		Request for a zebra pattern		
WR23140	AM	PM		on the footpath at the	ROAD	GRIFFITH
	26/05/2022 4:53	24/05/2022 3:45		Roads, parking & vehicles >		
WR52464	PM	PM	Safety	Roads & traffic > Potholes	ROAD	GRIFFITH
	19/05/2021 3:22	17/03/2021		Roads, parking & vehicles;		
WR18871	PM	12:14 PM		Roads & traffic;	ROAD	GRIFFITH
	05/09/2023 8:04	06/02/2023	No Immediate			
WR78447	AM	12:36 PM	Risk	48 FRANKLIN ST, GRIFFITH	SUMP	GRIFFITH
	28/09/2022 10:27	14/09/2022 3:48		SHOPS 24 FRANKLIN ST,	TRAFFIC CALMING	
WR62308	AM	PM	Safety	GRIFFITH > Potholes	DEVICE	GRIFFITH

Work Request ID	Asset Street Address
WR83523	FRANKLIN STREET
WR76395	FRANKLIN STREET
WR45248	FRANKLIN STREET
WR44058	FRANKLIN STREET
WR87881	FRANKLIN STREET
WR93232	FRANKLIN STREET
WR41562	FRANKLIN STREET
WR75684	FRANKLIN STREET
WR75353	FRANKLIN STREET
WR20421	FRANKLIN STREET
WR4918	FRANKLIN STREET
WR23137	FRANKLIN STREET
WR77134	FRANKLIN STREET
WR76688	FRANKLIN STREET

Work Request ID	Asset Street Address
WR52461	FRANKLIN STREET
WR23140	FRANKLIN STREET
WR52464	FRANKLIN STREET
WR18871	FRANKLIN STREET
WR78447	FRANKLIN STREET
WR62308	FRANKLIN STREET