




Asset Id	Asset Name	Asset Status	Asset Category	Work Request ID	Work Request Status	Work Request Status Date	Work Request Created Date	Risk Level	Work Request Brief Description	Asset Suburb	Work Request Defect Location	Work Request Inspection Date	Work Request Supporting Information	Work Order ID
PAVE1935	BLAXLAND PARK SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	WR399	CLOSED	09/11/2023 1:01 PM	19/06/2020 12:45 PM		Cycle & footpaths; Shared paths; Damage to path or other;	GRIFFITH	Shops, 10 Barker St, Griffith ACT 2603, Australia	08/07/2020 2:41 PM	<p>WR399 : Linked Work Order has been assessed.                      ***Last updated by Luke Halgren***9/11/2023 1:01:27 PM                      , WR399 : Displaced shop pavement in front of Butchery at Griffith shops, multiple grinds to make safe                      ***Last updated by Michael Rootsey***8/07/2020 2:41:08 PM                      , WR399 : CRM Reference : 200619-001367                      Derived location =                      Requester Contact Name: [REDACTED]                      Cycle &amp; footpaths                      Shared paths                      Damage to path or other                      What is the issue? *Cracked, broken or uneven                      What is the material? *Brick or concrete pavers                      Could it cause a trip, fall or injury?*Yes                      Is it causing traffic or cyclists to swerve?*Yes                      Please provide more information                      The customer has tripped over the raised section of the footpath. It is at the griffith shops near the butcher and the walkway to the back carpark.                      ***Last updated by TCCS.ICX Integrations***19/06/2020 12:45:46 PM</p>	WO23993
PAVE1935	BLAXLAND PARK SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	WR2663	CLOSED	09/11/2023 11:53 AM	28/09/2020 8:21 PM		Cycle & footpaths Shared paths Damage to path or other; Griffith shops	GRIFFITH	Shops, 10 Barker St, Griffith ACT 2603, Australia	29/09/2020 10:48 AM	<p>WR2663 : Linked Work Order has been assessed.                      ***Last updated by Luke Halgren***9/11/2023 11:53:36 AM                      , WR2663 : CRM Reference : 200928-003484                      Requester Contact Name: [REDACTED]                      Initial enquiry info only. See CRM for additional correspondence.                      Defect location info may be incorrect (address validation limitations).                      Can you provide any additional information about the location of the job to help us find the issue (i.e., intersections, buildings, landmarks, features)? : Outside Richard Odell Butchers at Griffith Shops                      What is the issue?: Damage to path or other                      What is the damage?: Cracked, broken or uneven                      What is the material?: Concrete                      Could it cause a trip, fall or injury?: Yes                      Is it causing traffic or cyclists to swerve?: Yes                      Please provide more information: Paving outside Griffith Butchery - Richard Odell caused me to fall and trip. It has been ground at the control joint but is very raised                      Phone Number: [REDACTED]                      Verify Email Address: [REDACTED]                      ***Last updated by TCCS.ICX Integrations***28/09/2020 8:21:08 PM</p>	WO26676
PAVE1935	BLAXLAND PARK SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	WR269	CLOSED	09/11/2023 1:01 PM	05/06/2020 1:30 PM		Cycle & footpaths Shared paths Damage to path or other	GRIFFITH	Shops, 10 Barker St, Griffith ACT 2603, Australia	03/07/2020 11:19 AM	<p>WR269 : Linked Work Order has been assessed.                      ***Last updated by Luke Halgren***9/11/2023 1:01:33 PM                      , WR269 : CRM Reference : 200605-001721                      Derived location = GRIFFITH SHOPPING CENTRE, STUART ST, GRIFFITH, CANBERRA CENTRAL                      Requester Contact Name: [REDACTED]                      What is the issue?: Damage to path or other                      What is the damage?: Cracked, broken or uneven                      What is the material?: Concrete                      Could it cause a trip, fall or injury?: Yes                      Is it causing traffic or cyclists to swerve?: No                      Please provide more information: My wife tripped on an uneven footpath outside Griffith Butchery in Barker St Griffith. She sustained a badly split lip, a couple of loose teeth and bruising around the ribs and knees.                      Phone Number [REDACTED]                      Verify Email Address: [REDACTED]                      ***Last updated by TCCS.ICX Integrations***5/06/2020 1:30:48 PM</p>	WO1522
PAVE1935	BLAXLAND PARK SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	WR119505	CLOSED	16/03/2026 1:34 PM	20/08/2024 7:32 AM		Cycle & footpaths > Shared paths > Damage to path or other	GRIFFITH	SHOPS 14 BARKER ST, GRIFFITH ACT 2603	21/08/2024 4:01 PM	<p>WR119505 : CSRM Case Number : 00451248                      Requester Contact Name: [REDACTED]                      Phone Number [REDACTED]                      Initial enquiry info only. See CSRM for additional correspondence.                      Defect location info may be incorrect (address validation limitations).                      More information                      Outside the front of the Griffith Shops, there are a number of concrete areas where there are trip hazards due to movement over a period of time. There's also pieces of concrete missing in spots as well. Given there's a lot of elderly people who frequent these shops, the risk of someone tripping and hurting themselves is high                      Is it causing traffic or cyclists to swerve? Yes                      What is the material? Concrete                      What is the damage? Cracked, broken or uneven                      Could it cause a trip, fall or injury? Yes                      ***Last updated by TCCS Asset Integrations***20/08/2024 7:32:56 AM</p>	WO87332
PAVE1935	BLAXLAND PARK SHOP/BUILDING PAVEMENT	Active	Hard Surfaces	WR150224	CLOSED	16/03/2026 1:34 PM	19/12/2025 9:50 PM	Safety	Cycle & footpaths > Shared paths > Damage to path or other	GRIFFITH	SHOPS 8 BARKER ST, GRIFFITH ACT 2603		<p>WR150224 : CSRM Case Number : 00599730                      Requester Contact Name: [REDACTED]                      Phone Number [REDACTED]                      Initial enquiry info only. See CSRM for additional correspondence.                      Defect location info may be incorrect (address validation limitations).                      What is the damage? Cracked, broken or uneven                      What is the material? Concrete                      Could it cause a trip, fall or injury? Yes                      Is it causing traffic or cyclists to swerve? No                      More information                      A broken and uneven path at the Griffith shops located at the laneway entrance near the Griffith Butchery. The raised concrete was marked with pink paint and patched with asphalt - it has been like this for some time. I tripped and fell hard on this broken concrete and injured my hand and knee and had to visit my GP for treatment. The failure to fix this is negligent and I would like the path fixed immediately. [REDACTED]                      ***Last updated by TCCS Asset Integrations***19/12/2025 9:50:37 PM</p>	WO87332



- 📍 Existing Prop.
- 📍 Existing Inprog
- 📍 28-3-24.

📍 New

No new displacements  
Wo 70473 remains work  
done since 4/7/23





# Griffith shops

- Prop
- Inpro
- New



Dec 7-3-25 Area 15

## Salesforce case report

As of 2026-05-14 10:09:36 Australian Eastern Standard Time/AEST • Generated by Paula Ludvigson • Sorted by Date/Time Opened (Ascending)

### Filtered By

Show: All cases

Units: Hours

Incident Address contains Barker

Suburb contains Griffith

Subject contains path

ACTCCS Description contains

Date/Time Op	Case Number	Subject	ACTCCS Description	Incident Address	Assetic Work Request ID	AC Case Number	Assetic Status Comments
27/09/2021 4:04 PM	00119255	Fix My Street > Cycle & footpaths > Shared paths > Blocking the path	<p>What is causing the obstruction? Other More Information Water has been seeping onto footpath for a couple of months Concerns are possible slip injury Is it causing traffic or cyclists to swerve? No Could it cause a trip, fall or injury? Yes</p>	SHOPS 4 BARKER ST, GRIFFITH ACT 2603	WR31428	00329357	WR31428 has been closed in Assetic by Jody Friend. Comments: Linked Work Order WO48642 has been assessed.
15/01/2022 4:14 PM	00153390	Fix My Street > Cycle & footpaths > Shared paths > Accessibility issues	<p>Issue Description Husband blind. Footpath outside Griffith shops an obstacle course of signs, tables, baskets etc. We've spoken to various shop owners but getting worse not better. Suggest raised blind people bumps be installed. Also, shop owners notified</p>	2-8 BARKER ST, GRIFFITH ACT 2603		00405957	WR41417 has been rejected in Assetic by Danielle McMahon. Rejection reason: not a tccs issue
11/10/2022 1:16 PM	00237134	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	<p>What is the material? Concrete What is the damage? Cracked, broken or uneven More Information elderly residents using the griffith shops have tripped repeatedly on this path Is it causing traffic or cyclists to swerve? Yes Could it cause a trip, fall or injury? Yes</p>	8-10 BARKER ST, GRIFFITH ACT 2603	WR65835	00591547	

Date/Time Op	Case Number	Subject	ACTCCS Description	Incident Address	Assetic Work Request ID	AC Case Number	Assetic Status Comments
6/12/2022 5:47 PM	00259715	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	<p>What is the material? Concrete</p> <p>What is the damage? Cracked, broken or uneven</p> <p>More Information uneven, raised concrete outside Shoprite, is dangerous, I could have been badly injured. I tripped, fell hard and hurt myself badly, two male witnesses, there's a CCTV camera. I'm in pain and injured, the damage is bad but could be worse.</p> <p>Is it causing traffic or cyclists to swerve? No</p> <p>Could it cause a trip, fall or injury? Yes</p>	2-8 BARKER ST, GRIFFITH ACT 2603	WR73791	00629688	
17/08/2024 9:22 AM	00450624	Fix My Street > Cycle & footpaths > Shared paths > Blocking the path	<p>More Information A sandwich board from Recess Cafe on Barker Street, Griffith, is blocking pedestrian movement by being placed in the middle of the path.</p> <p>Is it causing traffic or cyclists to swerve? Yes</p> <p>What is causing the obstruction? Other</p> <p>Could it cause a trip, fall or injury? Yes</p>	6B BARKER ST, GRIFFITH ACT 2603		00952048	WR119350 has been rejected in Assetic by Sukru Kazanc. Rejection reason: please refer to rangers
20/08/2024 7:28 AM	00451248	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	<p>More Information Outside the front of the Griffith Shops, there are a number of concrete areas where there are trip hazards due to movement over a period of time. There's also pieces of concrete missing in spots as well. Given there's a lot of elderly people who frequent these shops, the risk of someone tripping and hurting themselves is high</p> <p>Is it causing traffic or cyclists to swerve? Yes</p> <p>What is the material? Concrete</p> <p>What is the damage? Cracked, broken or uneven</p> <p>Could it cause a trip, fall or injury? Yes</p>	SHOPS 14 BARKER ST, GRIFFITH ACT 2603	WR119505	00953031	Workrequest WO87332 is in progress. WorkOrder Corrective Maintenance has been raised in Assetic with a priority of Serious (10 days)

Date/Time Op	Case Number	Subject	ACTCCS Description	Incident Address	Assetic Work Request ID	AC Case Number	Assetic Status Comments
12/02/2025 8:27 AM	00502664	Cycle & footpaths > Shared paths > Litter & illegal dumping	<p>What are you reporting? Other e.g. litter/material/debris Is it posing a safety hazard? No More Information I have seen park rangers out the back of the property a few times with tape and cameras trying to catch who is dumping milk crates. Now that whoever is doing it knows they can't put them there, they have now started dumping them behind 12 Barker St, as you will see in my photo. I suspect that they are either coming from Recess or the Supermarket. Are you able to assist with finding who is dumping these please as it's very frustrating and they are now trying to make it look like the little cafe</p>	SHOP 2 14 BARKER ST, GRIFFITH ACT 2603		01038880	WR130878 has been rejected in Assetic by Sukru Kazanc. Rejection reason: please forward to rangers
19/12/2025 9:47 PM	00599730	Fix My Street > Cycle & footpaths > Shared paths > Damage to path or other	<p>What is the damage? Cracked, broken or uneven What is the material? Concrete Could it cause a trip, fall or injury? Yes Is it causing traffic or cyclists to swerve? No More Information A broken and uneven path at the Griffith shops located at the laneway entrance near the Griffith Butchery. The raised concrete was marked with pink paint and patched with asphalt - it has been like this for some time. I tripped and fell hard on this broken concrete and injured my hand and knee and had to visit my GP for treatment. The failure to fix this is negligent and I would like the path fixed immediately.</p>	SHOPS 8 BARKER ST, GRIFFITH ACT 2603	WR150224	01197630	Workrequest WO87332 is in progress. WorkOrder Corrective Maintenance has been raised in Assetic with a priority of Serious (10 days)

Date/Time Op	Case Number	Subject	ACTCCS Description	Incident Address	Assetic Work Request ID	AC Case Number	Assetic Status Comments
21/02/2026 5:20 PM	00619945	Cycle & footpaths > Shared paths > Damage to path or other	<p>What is the damage? Cracked, broken or uneven</p> <p>What is the material? Concrete</p> <p>Could it cause a trip, fall or injury? Yes</p> <p>Is it causing traffic or cyclists to swerve? Yes</p> <p>More Information A strip of aluminium is protruding from a recently concreted section of walkway at the Griffith shops. It is a real trip hazard.</p>	SHOPS UNIT 1 10 BARKER ST, GRIFFITH ACT 2603		01229368	WR154378 has been cancelled in Assetic by Michael Rootsey. Cancelled reason: Work Request has been cancelled. Contractor [Paraco] has been instructed to bend corners down as they were originally to make safe, No further action required at this stage
<b>Total</b>	<b>10</b>						

Confidential Information - Do Not Distribute  
Copyright © 2000-2026 salesforce.com, inc. All rights reserved.