



Yarralumla Creek tree assessments




Yellow dots indicate removals that have been undertaken, and a high stump remains that requires lowering prior to stump removal. Stumps were left high to reduce trip hazards. Debris has not yet been removed due to waterlogged soils, but is programmed for week starting 6 July 2026 with alternate lighter machinery.

Yarralumla Creek tree assessments- North



Yarralumla Creek tree assessments- South



Yarralumla Creek tree removals – evidence of structural decline



